



U.S. Department of Transportation
Federal Aviation Administration
Washington, D.C.

Master Minimum Equipment List (MMEL)

Revision: 3B
Date: 01/26/2015

Cessna 525 **CE-525**

For Part 91 and Part 135 Use Only

Thomas Kieffaber
Chair, Flight Operations Evaluation Board

Federal Aviation Administration
Kansas City Aircraft Evaluation Group
901 Locust Street, Department of Transportation Building
Kansas City, MO 64106

Telephone: (816) 329-3233
FAX: (816) 329-3241

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

CESSNA 525

REVISION NO. 3B

DATE: 01/26/2015

PAGE NO.

I

TABLE OF CONTENTS / CONTROL PAGE

SYSTEM	PAGES	REVISION	DATE
-- Cover Page	-	3B	01/26/2015
-- Table of Contents / Control Page	I	3B	01/26/2015
-- Highlights of Change	II thru IV	3B	01/26/2015
-- Definitions and Preamble	V	03	12/19/2013
-- Guidelines for (M) & (O) Procedures	VI	3B	01/26/2015
-- Section One	VII	03	12/19/2013
21 AIR CONDITIONING	21-1 thru 21-11	3B	01/26/2015
22 AUTO FLIGHT	22-1 thru 22-7	3B	01/26/2015
23 COMMUNICATIONS	23-1 thru 23-7	3B	01/26/2015
24 ELECTRICAL POWER	24-1	03	12/19/2013
25 EQUIPMENT/FURNISHINGS	25-1 thru 25-8	3B	01/26/2015
26 FIRE PROTECTION	26-1	03	12/19/2013
27 FLIGHT CONTROLS	27-1	3A	04/07/2014
28 FUEL	28-1 thru 28-3	3B	01/26/2015
30 ICE AND RAIN PROTECTION	30-1 thru 30-3	3B	01/26/2015
31 INSTRUMENTS	31-1 thru 31-4	3B	01/26/2015
32 LANDING GEAR	32-1	3B	01/26/2015
33 LIGHTS	33-1 thru 33-4	3B	01/26/2015
34 NAVIGATION	34-1 thru 34-15	3B	01/26/2015
35 OXYGEN	35-1 thru 35-2	3B	01/26/2015
38 WATER/WASTE	38-1	3B	01/26/2015
45 CENTRAL MAINT. SYSTEM	45-1	03	12/19/2013
46 INFORMATION SYSTEMS	46-1	03	12/19/2013
52 DOORS	52-1 thru 52-3	3A	04/07/2014
73 ENGINE FUEL AND CONTROL	73-1	3A	04/07/2014
76 ENGINE CONTROLS	76-1	03	12/19/2013
78 ENGINE EXHAUST	78-1	3B	01/26/2015
-- Section Two	INT-1 thru INT-3	03	12/19/2013
-- CAS Relief	2-1 thru 2-3	03	12/19/2013

HIGHLIGHTS OF CHANGE

NOTE

Replaced all instances of "Remarks and Exceptions" with "Remarks or Exceptions".

ATA 21

-20-07

Added relief for Windshield Defog System.

-30-02-00A

Revised Remarks or Exceptions.

-30-02-00B

Revised Remarks or Exceptions.

-50-02

Separated relief by variant. Revised Remarks or Exceptions.

-50-03-05

Consolidated relief. Revised Remarks or Exceptions.

ATA 22

-10-01-00A

Revised Remarks or Exceptions.

ATA 23

-10-01-00B

Revised Remarks or Exceptions.

-50-01-02

Revised Title.

-50-01-03

Revised Title and Number Installed.

-50-01-04

Revised Title and Number Installed.

-50-01-05

Revised Title and Number Installed.

-50-01-06

Revised Title and Number Installed.

-50-01-07

Revised Title and Number Installed.

-50-01-08

Revised Title and Number Installed.

-50-07-04

Added relief for Remote Side Console Switch.

-60-01-01

Revised Title, Number Installed, Number Required, and Remarks or Exceptions.

-60-01-02

Revised Title, Number Installed, Number Required, and Remarks or Exceptions.

-60-01-05

Revised Title, Number Installed, Number Required, and Remarks or Exceptions.

-60-01-09

Revised Remarks or Exceptions.

-70-01-02

Revised Remarks or Exceptions. Removed Repair Category, Number Installed and Number Required to make an administrative note.

ATA 25

-10-05

Revised Title.

-10-05-01A

Revised Number Installed.

-10-05-01B

Revised Number Installed.

-10-05-02

Revised Number Installed.

-10-05-03

Revised Number Installed.

-10-05-04

Revised Number Installed.

-10-05-06

Revised Number Installed.

-20-06

Revised Title.

-20-06-04

Revised Number Installed.

-20-06-05

Revised Number Installed.

-50-02-00B

Revised Remarks or Exceptions.

ATA 28

-43-01

Revised Repair Category and Remarks or Exceptions.

ATA 30

Deleted Windshield Electric Anti-Ice System. Not used on aircraft. Consolidated Refreshment Center Drain Heater.

-10-02

Revised Remarks or Exceptions.

-10-04

Revised Title (Units -0001 thru -0701).

-10-04

Added relief for Wing Bleed Air Anti-Ice System (Units -0800 and on).

HIGHLIGHTS OF CHANGE

ATA 30**(Continued)**

- 20-01 Revised Title and Remarks or Exceptions.
- 40-01 Revised Title.
- 40-02 Revised Title.
- 40-03 Revised Title.
- 70-01 Revised Title, Repair Category, Number Installed, Number Required, and Remarks or Exceptions.

ATA 31

- 30-03-02A Revised Item, Repair Category, and Remarks or Exceptions.
- 30-03-02B Added relief for Underwater Locator Device.
- 50-01 Revised Title.
- 50-01-03 Revised Title.
- 50-01-07 Revised Remarks or Exceptions (Units -0001 thru -0558).
- 50-01-07 Revised Title (Units -0600 thru -0701).
- 50-01-14 Revised Title, and Remarks or Exceptions.

ATA 32

- 41-01 Revised Remarks or Exceptions.
- 44-01 Revised Title.

ATA 33

- 20-04-00A Revised Remarks or Exceptions.
- 40-10 Revised Remarks or Exceptions.

ATA 34

- 16-01-01 Revised Remarks or Exceptions.
- 16-01-02 Revised Remarks or Exceptions.
- 25-01-06 Revised Remarks or Exceptions.
- 25-01-07 Revised Remarks or Exceptions.
- 25-05 Revised Number Installed, Number Required and Remarks or Exceptions.
- 25-05-09 Revised Number Installed.
- 25-05-11 Revised Number Installed.
- 25-05-12 Revised Number Installed.
- 25-05-13 Revised Number Installed.
- 25-05-14 Revised Number Installed.
- 25-05-15 Revised Number Installed.
- 25-05-16 Revised Number Installed.
- 25-05-17 Revised Number Installed.
- 25-05-18 Revised Number Installed.
- 25-05-19 Revised Number Installed, Number Required and Remarks or Exceptions.
- 25-10 Revised Remarks or Exceptions.
- 45-01-01 Revised Title, and Remarks or Exceptions.
- 45-01-02A Revised Title.
- 45-01-02B Revised Title.
- 45-01-03A Added relief for Traffic Advisory (TA) and Resolution Advisory (RA) Displays Failed.
- 45-01-03B Revised Item, Title, and Remarks or Exceptions.
- 45-01-05 Revised Item and Title.
- 60-02-02 Added relief for Takeoff and Landing Data (TOLD) Calculation Function or Database.

AIRCRAFT:

CESSNA 525

REVISION NO. 3B

DATE: 01/26/2015

PAGE NO.

IV

HIGHLIGHTS OF CHANGE

ATA 35

-30-02 Revised Remarks or Exceptions.

ATA 38

-30-01 Revised Remarks or Exceptions.

-30-04 Added relief for Overboard Drain (Excluding drain heater).

ATA 78

-30-02 Revised Remarks or Exceptions.

U.S. DEPARTMENT OF TRANSPORTATION		MASTER MINIMUM EQUIPMENT LIST
FEDERAL AVIATION ADMINISTRATION		
AIRCRAFT: CESSNA 525	REVISION NO. 3 DATE: 12/19/2013	PAGE NO. V
DEFINITIONS AND PREAMBLE		

DEFINITIONS

The required definitions listed are listed in Appendix B of MMEL Policy Letter 25. Additional definitions may be included in an operators MEL as desired. Revision of PL-025 does not require revision to the operator's MEL.

PREAMBLE

The applicable preamble must be inserted in the operator's MEL from current FAA Policy Letter PL-34 or Policy Letter PL-36.

U.S. DEPARTMENT OF TRANSPORTATION		MASTER MINIMUM EQUIPMENT LIST
FEDERAL AVIATION ADMINISTRATION		
AIRCRAFT: CESSNA 525	REVISION NO. 3B DATE: 01/26/2015	PAGE NO. VI
GUIDELINES FOR (M) & (O) PROCEDURES		

The FOEB has identified a need for certain procedures to provide an adequate level of safety while providing relief for some items. These procedures must be established by the operator and may be based on the aircraft manufacturer's recommended procedures, Supplemental Type Certificate modifier's recommended procedures, or equivalent operator procedures. When recommended procedures are published the operator should comply with these procedures. If recommended procedures are not published, the following guidelines delineate the aspects to be considered by the operator in the development of required procedures.

Cessna has developed recommended (M) maintenance and (O) operational procedures for the Cessna 525 Master Minimum Equipment List (P/N 525COMP-3B-00, or later revision). Operator's MEL procedures should be based on the Cessna procedures.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

CESSNA 525

REVISION NO. 03

DATE: 12/19/2013

PAGE NO.

VII

SECTION ONE

COMPONENT ORIENTED MMEL RELIEF

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-20-01	Cabin Overhead Air Outlet	C	-	0	
-20-02	Cockpit Overhead Air Outlet	C	2	0	
-20-07	Windshield Defog System (Fan and / or diverter) (Units -0001 thru -0701)	C	1	0	(M) (O) May be inoperative provided: a) Defog fan is deactivated, b) Windshield bleed air anti-ice system is operative, c) Both glareshield fans are operative, d) DEFOG FAN is selected OFF, and e) Crew has a means to clear windshield of moisture.
-20-07	Windshield Defog System (Fan and / or diverter) (Units -0800 and on)	C	1	0	(M) (O) May be inoperative provided: a) Defog fan is deactivated, b) Windshield bleed air anti-ice system is operative, c) Both glareshield fans are operative, d) DEFOG is selected OFF on GTC Temperature Page, and e) Crew has a means to clear windshield of moisture.
-21-06	Glareshield Fan (Units -0001 thru -0359 excluding G1000-equipped aircraft)	C		1	
-21-06	Glareshield Fan (Units -0001 thru -0359 G1000-equipped aircraft)	C	2	1	One may be inoperative provided aircraft is operated in accordance with G1000 AFM supplement temperature limitations.
-21-06	Glareshield Fan (Units -0360 thru -0701)	C	2	1	One may be inoperative.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-21-07	Instrument Panel Cooling Fan (CNI-5000 communications rack) (Units -0001 thru -0359 excluding G1000-equipped aircraft and Units -0360 thru -0558)	B	2	0	NOTE: Radio service life may be extended by selecting unused radios OFF.
-01	FAN 1 Amber Light	C	1	0	(M) May be inoperative provided both cooling fans are verified operative.
-21-08	Nose Avionics Cooling Fan				
-01	Radome Bulkhead (RH FS 43) (Units -0001 thru -0359 excluding G1000-equipped aircraft)	C	1	0	May be inoperative provided aircraft is operated in accordance with AFM NOSE AVIONICS COOLING FAN abnormal procedure.
-01	Radome Bulkhead (RH FS 43) (Units -0001 thru -0359 G1000-equipped aircraft)	C	1	0	May be inoperative provided aircraft is operated in accordance with G1000 AFM supplement temperature limitations.
-01	Radome Bulkhead (LH FS 43) (Units -0360 and on)	C	1	0	May be inoperative provided ground operations with avionics ON are limited to 30 minutes.
-02	Vaneaxial Snorkel (MN001) (Units -0001 thru -0359)	C	1	0	

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-21-10	Ported Cooling Fan				
-01	Radio (KA 33 Panel Fan) (Units -0001 thru -0359 G1000-equipped aircraft)	C	1	0	May be inoperative provided aircraft is operated in accordance with G1000 AFM supplement temperature limitations.
-02	Integrated Avionics Unit (GIA FAN 1/2) (Units -0001 thru -0359 G1000-equipped aircraft)	C	2	1	May be inoperative provided aircraft is operated in accordance with G1000 AFM supplement temperature limitations.
-21-11	Display Fan (Units -0001 thru -0359 G1000-equipped aircraft)	C	3	0	May be inoperative provided aircraft is operated in accordance with G1000 AFM supplement temperature limitations.
-30-01	Cabin Dump Function (Unpressurized)	C	1	0	(M) May be inoperative provided: a) One outflow valve is removed, and b) Cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-30-02	Cabin Pressurization System				
-00A	(Unpressurized with cabin occupants) (Units -0001 thru -0558)	C	1	0	(O) May be inoperative provided: a) PRESS SYSTEM SELECT is selected to MANUAL, b) CABIN DUMP is selected ON, c) Aircraft is operated at 12,400 feet cabin altitude or below, and d) Flight crew oxygen system is used as required by 14 CFR. NOTE: CAB ALT 10,000 FT red annunciator may illuminate at 10,000 feet cabin altitude.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-4	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-30-02	Cabin Pressurization System (Continued)				
-00A	(Unpressurized with cabin occupants) (Units -0600 thru -0701)	C	1	0	(O) May be inoperative provided: a) PRESS SYSTEM SELECT is selected to MANUAL, b) CABIN DUMP is selected ON, c) Aircraft is operated at 12,400 feet cabin altitude or below, and d) Flight crew oxygen system is used as required by 14 CFR. NOTE: CABIN ALT red annunciator may illuminate at 10,000 feet cabin altitude.
-00A	(Unpressurized with cabin occupants) (Units -0800 and on)	C	1	0	(O) May be inoperative provided: a) PRESSURIZATION is selected to STBY, b) CABIN DUMP is selected ON, c) Aircraft is operated at 12,400 feet cabin altitude or below, and d) Flight crew oxygen system is used as required by 14 CFR. NOTE: PRESSURIZATION CTRL amber message may appear. CABIN ALTITUDE red message may appear and CABIN ALTITUDE aural warning may sound at 9,500 feet cabin altitude. (Continued)

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-5	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-30-02	Cabin Pressurization System (Continued)				
-00B	(Unpressurized without cabin occupants) (Units -0001 thru -0558)	C	1	0	(O) May be inoperative provided: a) PRESS SYSTEM SELECT is selected to MANUAL, b) CABIN DUMP is selected ON, c) OXYGEN CONTROL VALVE is selected to CREW ONLY, d) No cabin occupants are carried, e) Aircraft is operated at FL250 or below, and f) Flight crew oxygen system is used as required by 14 CFR. NOTE: CAB ALT 10,000 FT red annunciator may illuminate at 10,000 feet cabin altitude.
-00B	(Unpressurized without cabin occupants) (Units -0600 thru -0701)	C	1	0	(O) May be inoperative provided: a) PRESS SYSTEM SELECT is selected to MANUAL, b) CABIN DUMP is selected ON, c) OXYGEN CONTROL VALVE is selected to CREW ONLY, d) No cabin occupants are carried, e) Aircraft is operated at FL250 or below, and f) Flight crew oxygen system is used as required by 14 CFR. NOTE: CABIN ALT red annunciator may illuminate at 10,000 feet cabin altitude. (Continued)

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-6	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-30-02	Cabin Pressurization System (Continued)				
-00B	(Unpressurized without cabin occupants) (Units -0800 and on)	C	1	0	(O) May be inoperative provided: a) PRESSURIZATION is selected to STBY, b) CABIN DUMP is selected ON, c) OXYGEN CONTROL VALVE is selected to CREW ONLY, d) No cabin occupants are carried, e) Aircraft is operated at FL250 or below, and f) Flight crew oxygen system is used as required by 14 CFR. NOTE: PRESSURIZATION CTRL amber message may appear. CABIN ALTITUDE red message may appear and CABIN ALTITUDE aural warning may sound at 9,500 feet cabin altitude.
-30-03	Emergency Pressurization System (Failed closed)	C	1	0	(O) May be inoperative provided: a) Emergency pressurization valve is verified closed, and b) Aircraft is operated at FL250 or below.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-7	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-31-02	Cabin Pressurization System Mode				
-01	Automatic Schedule Mode (Units -0001 thru -0701)	C	1	0	May be inoperative provided: a) Isobaric mode is operative, b) Cabin differential pressure gauge / indication is operative, c) Cabin altitude gauge / indication is operative, and d) Cabin vertical speed gauge / indication is operative.
-01	Automatic Schedule Mode (NORM) (Units -0800 and on)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-03	Isobaric Mode (Units -0001 thru -0701)	C	1	0	May be inoperative provided automatic schedule mode is operative.
-04	Any Mode (Excluding manual) (Units -0001 thru -0701)	C	2	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-04	Any Mode (Excluding manual) (Units -0800 and on)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-8	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-32-01	Cabin Altitude Gauge/Indication				
-00A	(Pressurized)	C	1	0	(O) May be inoperative provided: a) Cabin pressurization system automatic schedule mode is operative and used, b) Cabin differential pressure gauge/indication is operative, and c) A chart is provided to convert differential pressure and aircraft altitude to cabin altitude.
-00B	(Unpressurized)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-01	Gauge Lighting (Units -0001 thru -0701)	C	1	0	May be inoperative provided flight crew determines adequate natural or artificial lighting exists to read gauge.
-32-02	Cabin Differential Pressure Gauge/Indication				
-00A	(Pressurized)	C	1	0	(O) May be inoperative provided: a) Cabin pressurization system automatic schedule mode is operative and used, b) Cabin altitude gauge/indication is operative, and c) A chart is provided to convert cabin and aircraft altitude to differential pressure.
-00B	(Unpressurized)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-9	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-32-03	Cabin Vertical Speed Gauge/Indication				
-00A	(Pressurized)	C	1	0	May be inoperative provided: a) Cabin pressurization system automatic schedule mode is operative and used, and b) Cabin altitude gauge/indication is operative.
-00B	(Unpressurized)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-33-01	Cabin Outflow Valve	C	2	0	(M) May be inoperative provided: a) One outflow valve is removed, and b) Cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-50-02	Vapor-cycle Air Conditioning System (Units -0001 thru -0359 excluding G1000-equipped aircraft and Units -0360 thru -0701)	C	1	0	(M) May be inoperative provided: a) Air conditioning system is deactivated, b) AIR CONDITIONING is selected OFF, c) Windshield defog system is considered inoperative (Refer to item 21-20-07), and d) Cabin and cockpit temperature control systems are operative.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-10	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-50-02	Vapor-cycle Air Conditioning System (Units -0001 thru -0359 G1000-equipped aircraft)	C	1	0	(M) May be inoperative provided: a) Air conditioning system is deactivated, b) AIR CONDITIONING is selected OFF, c) Windshield defog system is considered inoperative (Refer to item 21-20-07), d) Cabin and cockpit temperature control systems are operative, and e) Aircraft is operated in accordance with G1000 AFM supplement temperature limitations with air conditioning off.
-50-02	Vapor-cycle Air Conditioning System (Units -0800 and on)	C	1	0	(M) May be inoperative provided: a) Air conditioning system is deactivated, b) AIR COND is selected OFF on GTC Temperature page, c) Windshield defog system is considered inoperative (Refer to item 21-20-07), and d) Cabin and cockpit temperature control systems are operative.
-01 ***	Compressor Hour Meter	C	1	0	(O) May be inoperative provided compressor hours are tracked by alternate means.
-02	Compressor Light (COMPRESSOR ON) (Units -0001 thru -0701)	C	1	0	

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 21-11	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
21	AIR CONDITIONING				
-50-03	Evaporator Fan				
-05	Forward (FWD)	C	1	0	(M) May be inoperative provided: a) Aft evaporator fan is operative, b) Forward evaporator fan is deactivated, and c) Windshield defog system is considered inoperative (Refer to item 21-20-07).
-06	Aft (AFT)	C	1	0	(M) May be inoperative provided: a) Forward evaporator fan is operative, b) Aft evaporator fan is deactivated, and c) Cockpit and cabin temperature control system manual mode is operative and used.
-60-01	Cockpit and Cabin Temperature Control System	C	2	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-01	Automatic Mode	C	1	0	May be inoperative provided temperature control system manual mode is operative and used.
-02	Manual Mode	C	1	0	May be inoperative provided temperature control system automatic mode is operative and used.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 22-1	
SYSTEM, SEQUENCE NUMBERS & ITEM	1. REPAIR CATEGORY				
	2. NUMBER INSTALLED				
	3. NUMBER REQUIRED FOR DISPATCH				
	4. REMARKS OR EXCEPTIONS				
22	AUTO FLIGHT				
-10-01	Autopilot Disconnect Button (AP TRIM DISC) (Failed deselected) (Units -0001 thru -0359 excluding G1000-equipped aircraft)				
-10-01	Autopilot Disconnect Button (AP YD DISC/TRIM INT) (Failed deselected) (Units -0001 thru -0359 G1000-equipped aircraft)				
-10-01	Autopilot Disconnect Button (AP TRIM DISC) (Failed deselected) (Units -0360 thru -0701)				
-10-01	Autopilot Disconnect Button (AP DISC) (Failed deselected) (Units -0800 and on)				
-00A	Left Control Wheel	B	1	0	May be inoperative provided: a) Right control wheel button is operative, b) A pilot remains seated in right seat with seat belt fastened during all autopilot operations, c) Autopilot system is not used below AFM cruise minimum use height, and d) Approach minimums do not require use of autopilot system.
-00B	Right Control Wheel	C	1	0	May be inoperative for single-pilot operations. (Continued)

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 22-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
22	AUTO FLIGHT				
-10-01	Autopilot Disconnect Button (Failed deselected) (Continued)				
-00C	(All buttons failed)	B	2	0	May be inoperative provided: a) Autopilot system is considered inoperative (Refer to item 22-10-03), and b) Electric elevator trim is considered inoperative (Refer to item 27-31-01).
-10-02	Autopilot Interrupt/Flight Director Sync Button (A/P TCS) (Units -0001 thru -0359 excluding G1000-equipped aircraft)	C	2	0	
-10-02	Autopilot Interrupt/Flight Director Sync Button (A/P CWS) (Units -0001 thru -0359 G1000-equipped aircraft)	C	2	0	
-10-02	Autopilot Interrupt/Flight Director Sync Button (A/P TCS) (Units -0360 thru -0558)	C	2	0	
-10-02	Autopilot Interrupt/Flight Director Sync Button (A/P SYNC) (Units -0600 thru -0701)	C	2	0	
-10-02	Autopilot Interrupt/Flight Director Sync Button (CWS) (Units -0800 and on)	C	2	0	

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 22-3
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY		
		2. NUMBER INSTALLED		
		3. NUMBER REQUIRED FOR DISPATCH		
		4. REMARKS OR EXCEPTIONS		
22	AUTO FLIGHT			
-10-03	Autopilot System	B	1	0 (M) May be inoperative provided: a) Autopilot system is deactivated, b) Enroute procedures and approach minimums do not require use of autopilot system, c) Cabin pressurization system is operated in manual mode, d) Aircraft is not operated RVSM, e) Aircraft is not operated single-pilot, and f) Yaw damper is considered inoperative (Refer to item 22-10-05).
-10-04	Takeoff/Go-Around Button (GA)	C	1	0 May be inoperative provided: a) Flight director is not used during takeoff or go-around, b) Autopilot system is disconnected for go-around, and c) Autopilot interrupt/flight director sync button is operative on pilot flying side. NOTE: FMS missed approach procedure must be manually advanced.
-10-05	Yaw Damper (Units -0001 thru -0701)	B	1	0 (M) May be inoperative provided: a) Yaw damper is deactivated, and b) Autopilot system is considered inoperative (Refer to item 22-10-03).
-10-05	Yaw Damper (Units -0800 and on)	B	1	0 (M) May be inoperative provided: a) Yaw damper is deactivated, b) Autopilot system is considered inoperative (Refer to item 22-10-03), and c) Aircraft is operated at FL280 or below.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 22-4	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
22	AUTO FLIGHT				
-13-03	Flight Guidance Controller Annunciator (GMC 710) (Failed to illuminate) (Units -0001 thru -0359 G1000-equipped aircraft and Units -0800 and on)				
-01	Altitude (ALT button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-03	Approach (APR button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-04	Autopilot (AP button)	C	1	0	May be inoperative provided AP annunciation appears in PFD flight director mode box.
-05	Back Course (BC button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-07	Coupled Side (XFR Button - left or right arrow)	C	2	0	May be inoperative provided associated green coupled arrow appears in PFD flight director mode box.
-09	Flight Level Change (FLC button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-10	Half Bank (BANK button)	C	1	0	May be inoperative provided green bank limit arc appears on PFD attitude display.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 22-5	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
22	AUTO FLIGHT				
-13-03	Flight Guidance Controller Annunciator (Continued)				
-11	Heading (HDG button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-12	Navigation (NAV button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-13	Vertical Navigation (VNV button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-14	Vertical Speed (VS button)	C	1	0	May be inoperative provided appropriate annunciation appears in PFD flight director mode box.
-15	Yaw Damper (YD button)	C	1	0	May be inoperative provided YD annunciation appears in PFD flight director mode box.
-13-04	Flight Guidance Controller Function Control (GMC 710) (Units -0001 thru -0359 G1000-equipped aircraft and Units -0800 and on)				
-01	Altitude (ALT button)	B	1	0	May be inoperative provided: a) Procedures do not require its use, and b) Aircraft is not operated RVSM.
-02	Approach (APR button)	B	1	0	May be inoperative provided procedures do not require its use.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 22-6	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
22	AUTO FLIGHT				
-13-04	Flight Guidance Controller Function Control (Continued)				
-03	Autopilot (AP button)	B	1	0	May be inoperative provided autopilot system is considered inoperative (Refer to item 22-10-03).
-04	Back Course (BC button)	C	1	0	May be inoperative provided procedures do not require its use.
-05	IAS/Mach Change-over (SPD Button)	D	1	0	
-06	Coupled Side (XFR button)	C	1	0	May be inoperative provided arrow points to pilot-flying side.
-07	Course (CRS1 or CRS2 knob)	B	2	1	One may be inoperative provided procedures do not require its use.
-08	Course Direct (CRS1 or CRS2 PUSH DIR)	C	2	0	
-10	Flight Level Change (FLC button)	C	1	0	May be inoperative provided procedures do not require its use.
-11	Half Bank (BANK Button)	C	1	0	
-13	Heading Sync (HDG PUSH SYNC)	C	1	0	
-14	Navigation (NAV Button)	B	1	0	May be inoperative provided procedures do not require its use.
-16	Vertical Navigation (VNV button)	C	1	0	May be inoperative provided procedures do not require its use.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 22-7	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
22	AUTO FLIGHT				
-13-04	Flight Guidance Controller Function Control (Continued)				
-17	Vertical Speed (VS button)	C	1	0	May be inoperative provided procedures do not require its use.
-18	Yaw Damper (YD Button)	C	1	0	NOTE 1: Yaw damper may be engaged by engaging autopilot. NOTE 2: Yaw damper may be disengaged by pressing autopilot disconnect button.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 23-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
23 COMMUNICATIONS					
-00-01 ***	Flight Phone / SATCOM System	D	-	0	May be inoperative provided procedures do not require its use.
-01	Cockpit Handset	D	-	0	May be inoperative provided procedures do not require its use.
-02	Cabin Handset	D	-	0	
-10-01 ***	High Frequency (HF) Communication System				
-00A	(Dual LRCS not required)	D	-	-	Any in excess of those required by 14 CFR may be inoperative.
-00B	(Dual LRCS required)	C	-	1	(O) May be inoperative while conducting operations which require two Long-Range Communication Systems (LRCS) provided: a) Aircraft SATVOICE system operates normally, b) SATVOICE services are available as a LRCS over intended route of flight, and c) ICAO Flight Plan is updated, as required, to notify ATC of communications equipment status of aircraft, and d) Alternate procedures are established and used.
-01	Wire Antenna	C	1	0	(M) May be inoperative, missing, or damaged provided: a) Horizontal and vertical stabilizers are inspected for damage, b) Any remaining portion of wire antenna is removed, and c) HF communication system is considered inoperative (Refer to item 23-10-01).

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 23-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
23 COMMUNICATIONS					
-12-01	Very High Frequency (VHF) Communication System	D	-	-	Any in excess of those required by 14 CFR may be inoperative provided: a) Affected system is not on an emergency bus, and b) Procedures do not require its use.
-01 ***	VHF Datalink (VDL) (Units -0800 and on)	D	-	0	May be inoperative provided procedures do not require its use.
-20-01 ***	Satellite Datalink Service				
-01	Radio	D	-	0	
-02A	Weather	D	-	0	May be inoperative provided procedures do not require its use. NOTE: Any function(s) that operate normally may be used.
-02B	Weather	C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-03	Internet	D	-	0	
-20-02	Ground Avionics/Diagnostics Wi-Fi System (Units -0800 and on)	D	1	0	
-20-03 ***	Selective Call (SELCAL) (System or individual channel)				
-00A	(SELCAL not required)	D	-	0	May be inoperative provided procedures do not require its use.
-00B	(SELCAL required)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 23-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
23 COMMUNICATIONS					
-20-04 ***	SMS Text Message System (Units -0800 and on)	D	1	0	
-40-01 ***	Automatic Cabin Briefer	D	1	0	
-40-03	Passenger Address (PA) System	D	1	0	
-40-04	Passenger Seat Belt / Safety Chime	C	1	0	(O) May be inoperative provided cabin occupants are briefed by alternate means.
-50-01	Audio Panel (Units -0001 thru -0701)	C	2	1	Right side panel may be inoperative provided aircraft is operated single-pilot.
-02	Audio Selector / Volume Control (COM 1, COM 2, COM3, NAV 1, NAV 2, ADF 1, ADF 2, DME, MKR Button) (Units -0001 thru -0359 G1000-equipped aircraft)	C	-	-	Individual selectors may be inoperative provided associated system is not required by procedures or 14 CFR.
-03	Marker Beacon Mute (MKR/MUTE Button) (Units -0001 thru -0359 G1000-equipped aircraft)	C	2	0	
-04	Intercom (INTR COM Button) (Units -0001 thru -0359 G1000-equipped aircraft)	D	2	0	May be inoperative provided aircraft is operated single-pilot.
-05	Cabin Communication (CABIN Button) (Units -0001 thru -0359 G1000-equipped aircraft)	D	2	0	
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 23-4	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
23 COMMUNICATIONS					
-50-01	Audio Panel (Continued)				
-06	Clearance Playback (PLAY Button) (Units -0001 thru -0359 G1000-equipped aircraft)	D	2	0	
-07	Marker Beacon High Sensitivity (HI SENS Button) (Units -0001 thru -0359 G1000-equipped aircraft)	D	2	0	May be inoperative provided approach procedures do not require its use.
-08	Microphone Selector Annunciator (COM1 MIC, COM2 MIC Annunciator) (Units -0001 thru -0359 G1000-equipped aircraft)	C	4	0	May be inoperative provided crew refers to PFD frequency box for active transmit frequency (shown in green).
-50-05	Cockpit Headset and Boom Microphone	D	-	-	Any in excess of those required by 14 CFR may be inoperative.
-01A	Boom Microphone (For a holder of an Air Carrier or Commercial Operator Certificate)	A	-	0	May be inoperative provided: a) Associated hand microphone is installed and operative, and b) Repairs are made within three flight days.
-01B	Boom Microphone (For an operator other than a holder of an Air Carrier or Commercial Operator Certificate)	A	-	0	May be inoperative provided: a) Associated hand microphone is installed and operative, and b) Repairs are made in accordance with applicable 14 CFR.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 23-5	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
23 COMMUNICATIONS					
-50-05	Cockpit Headset and Boom Microphone (Continued)				
-02	Headset Earphones / Headphones	C	-	1	May be inoperative provided associated cockpit overhead communication speaker is operative.
-03 ***	Active Noise Reduction (ANR) Function	D	-	0	May be inoperative provided normal audio function of headset is operative.
-04	Powered Headset System (Units -0800 and on)	D	-	0	May be inoperative provided non-powered headset jack is operative or headset is not used.
-50-06	Cockpit Headset Audio System				
-00A		C	2	0	May be inoperative provided: a) Both cockpit overhead communication speakers are operative and used, b) Headset audio system is not required by 14 CFR or procedures, and c) Aircraft is not operated single-pilot.
-00B		C	2	1	One may be inoperative provided left side is operative for single-pilot operations.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 23-6	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
23 COMMUNICATIONS					
-50-07	Push-to-talk (PTT) Switch (Failed deselected)				
-01	Yoke Switch	B	2	1	(O) One may be inoperative provided alternate procedures are established and used for transmitting.
-01A	Right Yoke Switch	B	1	0	May be inoperative provided aircraft is operated single-pilot.
-04	Remote Side Console Switch (Units -0800 and on)	C	2	0	May be inoperative provided both yoke switches are operative.
-60-01	Static Wick				NOTE: May include mounting base provided no damage exists to attaching structure.
-01	Aileron	C	4	2	One per aileron may be damaged or missing provided outermost wick is installed and not damaged.
-02	Wing Tip Assembly (Units -0001 thru -0701)				NOTE 1: Wing tip assembly is entire removable section outboard of fuel closure rib. NOTE 2: These static wicks (one per wing tip assembly) are required to be installed and not damaged.
-05	Elevator	C	6	2	Two per elevator may be damaged or missing provided outermost wick is installed and not damaged.
-08	Rudder	C	2	1	One may be damaged or missing provided uppermost wick is installed and not damaged.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 23-7	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
23 COMMUNICATIONS					
-60-01	Static Wick (Continued)				
-09	Stinger				NOTE: This static wick is required to be installed and not damaged.
-70-01	Cockpit Voice Recorder (CVR)				
-00A	(Holder of management specifications, air carrier, or commercial operator certificate)	A	1	0	May be inoperative provided: a) Any Flight Data Recorder (FDR) required to be installed is operative, and b) Repairs are made within three flight days.
-00B	(Operator other than a holder of management specifications, air carrier, or commercial operator certificate)	A	1	0	May be inoperative provided repairs are made in accordance with applicable 14 CFR.
-00C ***	(All operators)	C	1	0	May be inoperative provided recorder is not required by 14 CFR.
-01 ***	Recorder Independent Power Supply (RIPS)	C	1	0	
-02	Underwater Locator Device (ULD)	D	1	0	May be inoperative or missing provided device is not required by 14 CFR.
-03A	Datalink Recording	C	1	0	May be inoperative provided datalink recording is not required by 14 CFR.
-03B	Datalink Recording	A	1	0	May be inoperative provided repairs are made within three flight days.

AIRCRAFT: CESSNA 525		REVISION NO. 3 DATE: 12/19/2013		PAGE NO. 24-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
24 ELECTRICAL POWER					
-22-01	AC Inverter (Units -0001 thru -0099 excluding G1000-equipped aircraft)	B	2	1	One may be inoperative provided: a) AC INV is selected to operative inverter, b) Aircraft is not operated at night, and c) Aircraft is not operated IFR.
-22-01	AC Inverter (Units -0100 thru -0359 excluding G1000-equipped aircraft)	B	2	1	One may be inoperative provided: a) INV is selected to operative inverter, b) Aircraft is not operated at night, and c) Aircraft is not operated IFR.
-31-02 ***	Battery Temperature Indicator	C	1	0	
-40-01	External Power System	D	1	0	
-50-01 ***	AC Cockpit Outlet				
-00A	(Outlet not required)	D	-	0	May be inoperative provided procedures do not require its use.
-00B	(Outlet required)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-60-01 ***	DC Cockpit Outlet				
-00A	(Outlet not required)	D	-	0	May be inoperative provided procedures do not require its use.
-00B	(Outlet required)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-60-02 ***	Ground Dispatch Power System	C	1	0	

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
25	EQUIPMENT / FURNISHINGS				
-00-01	Required Documents Holder (Airworthiness Certificate, Registration, etc)	D	1	0	(O) May be inoperative or missing provided an alternate means of securing and displaying documents is used.
-10-01	Cockpit Assist Handle	D	1	0	
-10-03	Cockpit Sunvisor System (Including attach mechanism)	D	-	0	May be inoperative or missing provided: a) Crewmember's field of vision is not obstructed, and b) Oxygen mask quick donning ability is not affected.
-10-05	Flight Crew Seat				
-01A	Armrest	C	4	0	May be inoperative provided affected armrest is stowed in retracted position.
-01B	Armrest	C	4	0	(M) May be inoperative provided affected armrest is removed.
-02 ***	Lumbar Support	D	1	0	
-03	Recline/Tilt Function	C	2	0	(M) (O) May be inoperative provided: a) Affected seat is secured or failed in a position that permits normal visibility, b) Full flight control movement is available, and c) Crewmember can reach all necessary controls and equipment while restrained.
-04 ***	Restraint Buckle Protective Padding	D	2	0	May be damaged or missing.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
25	EQUIPMENT / FURNISHINGS				
-10-05	Flight Crew Seat (Continued)				
-06	Vertical Adjustment	C	2	0	(M) (O) May be inoperative provided: a) Affected seat is secured or failed in a position that permits pilot normal visibility, b) Full flight control movement is available, and c) Crewmember can reach all necessary controls and equipment while restrained.
-07	Copilot Seat Belt / Shoulder Harness	C	1	0	May be inoperative provided seat remains unoccupied.
-08	Copilot Floor Tracking	C	1	0	May be inoperative provided seat remains unoccupied.
-10-08	Eye Reference Ball	C	3	0	(O) May be inoperative or missing provided alternate procedures are established and used for eye position reference.
-10-09 ***	Yoke-mounted Chart Holder	D	-	0	
-01 ***	Light	D	-	0	
-20-01 ***	Cabin Ashtray (Excluding lavatory door)	A	-	1	May be inoperative or missing provided ashtray is replaced within three calendar days.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
25 EQUIPMENT / FURNISHINGS					
-20-02 ***	Belted Lavatory Seat (Excludes lavatory waste system)				
-01	Seat Belt / Shoulder Harness	D	1	0	May be inoperative provided lavatory seat is placarded "DO NOT OCCUPY FOR TAXI, TAKEOFF, LANDING OR WHEN FASTEN SEAT BELT SIGN IS ILLUMINATED".
-02 ***	Seat Belt / Shoulder Harness Keeper	D	1	0	
-20-05	Non-essential Equipment and Furnishings (NEF)	-	-	0	May be inoperative, damaged or missing provided that item(s) is deferred in accordance with the operator's NEF deferral program. The NEF program procedures and processes are outlined in the operator's (insert name) Manual. (M) and (O) procedures, if required, must be available to the flight crew and included in the operator's appropriate document. NOTE: Exterior lavatory door ashtray is not considered an NEF item.
-20-06	Passenger Seat (Including side-facing seats, folding seats and couches)	D	-	0	May be inoperative provided: a) Seat does not block an emergency exit, b) Seat does not restrict any cabin occupant access to aisle, and c) Affected seat(s) are blocked and placarded "DO NOT OCCUPY". NOTE: Affected seat(s) may include seats near the inoperative seat(s). (Continued)

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-4	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
25	EQUIPMENT / FURNISHINGS				
-20-06	Passenger Seat (Including side-facing, folding seats and couches) (Continued)				
-01A	Armrest (With seat controls)	D	-	0	May be inoperative or missing with seat occupied provided: a) Armrest does not block an emergency exit, b) Armrest does not restrict any cabin occupant from access to aisle, and c) If armrest is missing, affected seat controls are considered inoperative (Refer to item 25-20-06-02).
-01B	Armrest (Without seat controls)	D	-	0	(M) May be missing, or inoperative with seat occupied provided: a) Armrest does not block an emergency exit, and b) Armrest does not restrict any cabin occupant from access to aisle.
-02A	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	(M) May be inoperative with seat occupied provided seat is secured in taxi, takeoff and landing position.
-02B	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	May be inoperative with seat occupied provided control is failed in taxi, takeoff and landing position.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-5	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
25	EQUIPMENT / FURNISHINGS				
-20-06	Passenger Seat (Including side-facing, folding seats and couches) (Continued)				
-02C	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	May be missing or inoperative in other than taxi, takeoff, and landing position provided affected seat is considered inoperative (Refer to item 25-20-06).
-03	Seat Belt / Shoulder Harness	D	-	0	May be inoperative provided affected seat is placarded "DO NOT OCCUPY FOR TAXI, TAKEOFF, LANDING OR WHEN FASTEN SEAT BELT SIGN IS ILLUMINATED".
-04 ***	Seat Belt / Shoulder Harness Keeper	D	-	0	
-05 ***	Lumbar Support	D	-	0	
-30-01 ***	Refreshment Center Hot Liquid Storage System Heater	C	-	0	(M) May be inoperative provided system is deactivated.
-50-01	Baggage Restraint System	D	-	0	Individual components may be inoperative or missing provided baggage is secured by other means or not carried.
-01A	Anchor Plate	C	-	0	Individual anchor plates may be inoperative provided: a) No visible damage exists, and b) Baggage is secured using remaining anchor plates or not carried.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-6	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
25	EQUIPMENT / FURNISHINGS				
-50-01	Baggage Restraint System (Continued)				
-01B	Anchor Plate	C	-	0	(M) Individual anchor plates may be damaged provided: a) Attaching structure is inspected for damage, and b) Baggage is secured using remaining anchor plates or not carried.
-50-02	Cabin Storage Compartment				
-00A		C	-	0	(M) May be inoperative provided: a) Compartment does not contain any aircraft system protection devices, b) Any emergency equipment located in affected compartment is considered inoperative, c) Affected compartment is not used for storage of any item except for those permanently affixed, d) Procedures are established and used to secure compartment closed, and e) Affected compartment is prominently placarded "DO NOT USE". (Continued)

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-7	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
25	EQUIPMENT / FURNISHINGS				
-50-02	Cabin Storage Compartment (Continued)				
-00B		C	-	0	(M) (O) May be inoperative provided: a) Affected door is removed, b) Affected compartment is not used for storage of any item, including those permanently affixed, c) Cabin occupants are briefed that affected compartment may not be used, and d) Affected compartment is prominently placarded "DO NOT USE".
-01	Shelving	D	-	0	(O) May be inoperative provided: a) Any permanently affixed emergency equipment located on affected shelf is relocated and available for use, and b) Cabin occupants are briefed on location of relocated equipment.
-02 ***	Key Lock	D	-	0	May be inoperative in unlocked position.
-60-03	Emergency Medical Equipment				
-01 ***	Automatic External Defibrillator (AED) (Includes associated equipment)	D	-	0	
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 25-8	
SYSTEM, SEQUENCE NUMBERS & ITEM	1. REPAIR CATEGORY				
	2. NUMBER INSTALLED				
	3. NUMBER REQUIRED FOR DISPATCH				
	4. REMARKS OR EXCEPTIONS				
25	EQUIPMENT / FURNISHINGS				
-60-03	Emergency Medical Equipment (Continued)				
-02 ***	Emergency Medical Kit (EMK) (Includes associated equipment)	D	-	0	
-03 ***	First Aid Kit (FAK) (Includes associated equipment)	D	-	-	Any in excess of those required by 14 CFR may be incomplete, missing, or inoperative.
-61-01 ***	Life Preserver (Crew and passenger)	D	-	-	Any in excess of those required by 14 CFR may be missing, or inoperative provided affected preserver is placarded "INOPERATIVE" or removed.
-62-01	Emergency Locator Transmitter (ELT)				
-01 ***	Survival Type	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing.
-02A	Fixed, Automatic	A	-	0	(M) May be inoperative provided: a) System is deactivated or removed, and b) Repairs are made within 90 calendar days.
-02B	Fixed, Automatic	D	-	-	(M) Any in excess of those required by 14 CFR may be inoperative provided system is deactivated or removed.
-64-01 ***	Life Raft	D	-	-	Any in excess of those required by 14 CFR may be missing or inoperative provided affected raft is placarded "INOPERATIVE" or removed.

AIRCRAFT: CESSNA 525		REVISION NO. 3 DATE: 12/19/2013		PAGE NO. 26-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
26	FIRE PROTECTION				
-22-01	Portable Fire Extinguisher	D	-	-	<p>Any in excess of those required by 14 CFR may be inoperative or missing provided:</p> <ul style="list-style-type: none"> a) Inoperative fire extinguisher is placarded "INOPERATIVE", removed from installed location, and placed out of sight so it cannot be mistaken for a functional unit, and b) Required distribution is maintained.

AIRCRAFT: CESSNA 525		REVISION NO. 3A DATE: 04/07/2014		PAGE NO. 27-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
27 FLIGHT CONTROLS					
-20-01	Rudder Pedal Adjustment System	B	4	2	(M) (O) Two may be inoperative provided: a) Two pedal adjustments are not inoperative at same pilot station, b) Affected pedal is positioned in a detent and adjustment mechanism is secured from movement, c) Unaffected pedal is adjusted to match affected pedal, and d) Crewmember seated at affected station verifies full control movement and brake application is available while restrained, prior to each flight.
-31-01	Electric Elevator Trim	B	1	0	(M) May be inoperative provided: a) Electric elevator trim system is deactivated, b) Manual trim is verified to operate normally, and c) Autopilot system is considered inoperative (Refer to item 22-10-03).
-70-02	Control / Gust Lock System (Failed unlocked)	C	1	0	(O) May be inoperative provided pilot verifies full flight control and throttle movement.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 28-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
28	FUEL				
-10-01	Over-wing Refueling Cap Lock (Failed unlocked)	D	-	0	
-41-01	Fuel Low Level Indicating System	A	2	1	(O) One may be inoperative provided: a) Procedures for monitoring fuel quantity are established and used, b) Both fuel quantity indicating systems are operative, and c) Repairs are made within three flight days.
-41-02	Fuel Quantity Indicating System (Wing tank) (Units -0001 thru -0359)	A	2	1	(O) One indication may be inoperative provided: a) Both fuel low level indicating systems and both fuel flow indicating systems are operative, b) Fuel required for route to be flown is increased by 10%, c) Flight is restricted to a maximum of three hours, remaining within one hour of a suitable airport at all points along route, d) Both fuel tanks are fueled over-wing to a known, balanced quantity, e) Fuel use is tracked, f) If autopilot is used, it is disconnected every twenty minutes to detect possible lateral fuel imbalance, monitor trim required, and g) Repairs are made within three flight cycles.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 28-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
28	FUEL				
-41-02	Fuel Quantity Indicating System (Wing tank) (Units -0360 thru -0701)	A	2	1	(O) One indication may be inoperative provided: a) Both fuel low level indicating systems and both fuel flow indicating systems are operative, b) Fuel required for route to be flown is increased by 10%, c) Flight is restricted to a maximum of three hours, remaining within one hour of a suitable airport at all points along route, d) Both fuel tanks are fueled over-wing to a known, balanced quantity, e) Fuel use is tracked, f) If autopilot is used, it is disconnected every twenty minutes to detect possible lateral fuel imbalance, monitor trim required and aileron mistrim PFD indication, and g) Repairs are made within three flight cycles.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 28-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
28 FUEL					
-41-02	Fuel Quantity Indicating System (Wing tank) (Units -0800 and on)	A	2	1	(O) One indication may be inoperative provided: a) Both fuel low level indicating systems and both fuel flow indicating systems are operative, b) Fuel required for route to be flown is increased by 10%, c) Flight is restricted to a maximum of three hours, remaining within one hour of a suitable airport at all points along route, d) Both fuel tanks are fueled over-wing to a known, balanced quantity, e) Fuel use is tracked, f) If autopilot is used, it is disconnected every twenty minutes to detect possible lateral fuel imbalance, monitor trim required and RETRIM L-R WING DOWN amber message, and g) Repairs are made within three flight cycles.
-43-01	Fuel Temperature Indication (Units -0600 and on)	A	2	1	One may be inoperative provided repairs are made within 10 calendar days.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 30-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
30	ICE AND RAIN PROTECTION				
-10-02	Stabilizer Pneumatic Boot De-Ice System (Failure to inflate) (Horizontal) (Automatic or manual mode failed)	B	1	0	(O) May be inoperative provided: a) All de-ice boots are verified to be deflated and held down when service air system is active, b) TAIL switch is selected OFF, and c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.
-10-04	Wing Bleed Air Anti-Ice System (Units -0001 thru -0701)	C	2	0	(M) May be inoperative provided: a) Both wing valves are secured for no flow, b) Both WING/ENG ANTI-ICE switches are selected OFF or ENG ON, and c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.
-10-04	Wing Bleed Air Anti-Ice System (Units -0800 and on)	C	2	0	(M) May be inoperative provided: a) Both wing valves are secured for no flow, b) Both WING/ENG ICE PROTECTION switches are selected OFF or ENG ONLY, and c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.
-20-01	Engine Anti-Ice System	A	2	1	(M) May be inoperative provided: a) Affected valve is secured for no flow, b) Affected WING/ENG switch is selected OFF, c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and d) Repairs are made within three flight days.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 30-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
30	ICE AND RAIN PROTECTION				
-30-03	Pitot Tube Heater (Copilot) (Units -0001 thru -0359)	B	1	0	May be inoperative provided: a) Pitot heater is not required by 14 CFR, b) Aircraft is not operated at night, c) Aircraft is not operated in Instrument Meteorological Conditions (IMC), and d) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.
-30-03	Pitot Tube Heater (Pilot) (Units -0360 and on)	B	1	0	May be inoperative provided: a) Pitot heater is not required by 14 CFR, b) Aircraft is not operated at night, c) Aircraft is not operated in Instrument Meteorological Conditions (IMC), and d) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.
-30-04	Static Port Heater (Copilot) (Units -0001 thru -0359)	B	2	1	One may be inoperative provided: a) Aircraft is not operated in Instrument Meteorological Conditions (IMC), b) Aircraft is not operated at night, c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and d) Aircraft is not operated RVSM.
-30-04	Static Port Heater (Pilot) (Units -0360 and on)	B	2	1	One may be inoperative provided: a) Aircraft is not operated in Instrument Meteorological Conditions (IMC), b) Aircraft is not operated at night, c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and d) Aircraft is not operated RVSM.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 30-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
30	ICE AND RAIN PROTECTION				
-40-01	Rain Removal System (Doors)	C	1	0	May be inoperative provided aircraft is not operated in precipitation within five nautical miles of airport used for takeoff, intended landing or any alternates required by 14 CFR.
-40-02	Windshield Bleed Air Anti-Ice System	C	1	0	(M) May be inoperative provided: a) Windshield anti-ice system is secured for no flow, b) Emergency pressurization system is considered inoperative (Refer to item 21-30-03), and c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.
-40-02	Windshield Electric Anti-Ice System				Deleted, Revision 3B. Not used on aircraft.
-40-03	Windshield Alcohol De-Ice System	C	1	0	(M) May be inoperative provided: a) Windshield de-ice system is deactivated, and b) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.
-70-01	Drain Heater (Evaporator fans, refreshment center, and / or toilet relief tube)	C	-	0	(M) May be inoperative provided: a) Drain heaters are deactivated, b) Flushing lavatory waste system, if installed, is considered inoperative (Refer to item 38-30-03), and c) Evaporator fans, refreshment center, and toilet relief tube overboard drains are considered inoperative (Refer to item 38-30-04).

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 31-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
31	INSTRUMENTS				
-20-02	Clock	D	-	-	Any in excess of those required by 14 CFR may be inoperative.
-20-04	Flight Hour Meter	C	1	0	(O) May be inoperative provided flight time is tracked by alternate means.
-30-03 ***	Flight Data Recorder				
-00A	(FDR not required)	C	1	0	May be inoperative provided recorder is not required by 14 CFR.
-00B	(Operator other than a holder of an Air Carrier or Commercial Operator Certificate)	A	1	0	May be inoperative provided repairs are made in accordance with applicable 14 CFR.
-00C	(Holder of an Air Carrier or Commercial Operator Certificate)	A	1	0	May be inoperative provided: a) Aircraft is not dispatched from an airport where repairs can be made unless, b) Flight Data Recorder (FDR) failure occurs after dispatch but prior to takeoff, or c) Flight Data Recorder (FDR) repair was attempted but not successful, d) In those cases where repair is attempted but not successful, aircraft may be dispatched on a flight or series of flights until arriving at next airport where repairs can be made at which the repair must be accomplished prior to dispatch, and e) Repairs are made within three flight days.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 31-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
31	INSTRUMENTS				
-30-03 ***	Flight Data Recorder (Continued)				
-01A	Flight Data Recorder (FDR) Parameters required by 14 CFR	A	-	-	Up to three (3) recording parameters may be inoperative provided: a) Cockpit Voice Recorder (CVR) operates normally, and b) Repair are made within 20 calendar days.
-01B	Flight Data Recorder (FDR) Parameters not required by 14 CFR	A	-	-	May be inoperative provided repairs are made prior to completion of next scheduled inspection / check of FDR.
-02A	Underwater Locator Device (ULD)	D	1	0	May be inoperative or missing provided device is not required by 14 CFR.
-02B	Underwater Locator Device (ULD)	A	1	0	May be inoperative or missing provided repairs are made within three flight days.
-30-04 ***	Quick Access Recorder (QAR)	D	1	0	May be inoperative provided recorder is not required by 14 CFR or procedures.
-40-02 ***	Electronic Checklist	D	-	0	May be inoperative, missing, or out of currency provided an approved checklist is available and used.
-50-01	Annunciator (Failed to illuminate) (Units -0001 thru -0701)				
-01	AC Power Fail (AC FAIL) (Units -0100 thru -0359 G1000-equipped aircraft)	D	1	0	
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 31-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
31	INSTRUMENTS				
-50-01	Annunciator (Failed to illuminate) (Continued)				
-03	Aft Baggage Door (BAGGAGE DOOR - AFT) (Units -0600 thru -0701)	C	1	0	May be inoperative provided aft baggage door warning system is considered inoperative (Refer to item 52-70-01-01).
-07	Cabin Door (DOOR NOT LOCKED) (Units -0001 thru -0558)	B	1	0	May be inoperative provided main cabin and aft baggage door warning systems are considered inoperative (Refer to items 52-70-01-01 and 52-70-01-07).
-07	Cabin Door (CABIN DOOR) (Units -0600 thru -0701)	B	1	0	May be inoperative provided main cabin door warning system is considered inoperative (Refer to item 52-70-01-07).
-09	Display Fan Fail (DISPLAY FAN FAIL) (Units -0032 thru -0359 G1000-equipped aircraft)	D	1	0	
-14	Forward Baggage Door (BAGGAGE DOOR - FWD) (Units -0600 thru -0701)	B	1	0	May be inoperative provided nose baggage door warning system is considered inoperative (Refer to item 52-70-01-06).
-20A	Inverter Fail Caution (Amber INVERTER FAIL – 1 / 2) (Units -0100 thru -0359 G1000-equipped aircraft)	D	3	0	
-20B	Inverter Fail Warning (Red INVERTER FAIL) (Units -0001 thru -0099 G1000-equipped aircraft)	D	1	0	
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 31-4	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
31	INSTRUMENTS				
-50-01	Annunciator (Failed to illuminate) (Continued)				
-23	Nose Avionics Fan Fail (NOSE AVN FAN FAIL) (Units -0032 thru -0359 G1000-equipped aircraft)	D	1	0	
-24	Nose Compartment Overtemp (NOSE COMP O'TEMP) (Units -0001 thru -0031 G1000-equipped aircraft)	D	1	0	
-50-02	Cabin Altitude Warning System (Aural and / or visual warning failed)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-50-03	Central Warning				
-01	Master Warning Light (Failed to illuminate)	C	2	1	Right side may be inoperative for single-pilot operations.
-02	Master Warning Cancel / Reset Function	C	2	1	Right side may be inoperative for single-pilot operations.
-03	Master Caution Light (Failed to illuminate)	C	2	1	Right side may be inoperative for single-pilot operations.
-04	Master Caution Cancel / Reset Function	C	2	1	Right side may be inoperative for single-pilot operations.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 32-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
32 LANDING GEAR					
-41-01	Anti-Skid System (Units -0001 thru -0558)	C	1	0	May be inoperative provided: a) Aircraft is operated in accordance with AFM DISPATCH WITH ANTISKID SYSTEM INOPERATIVE abnormal procedure, and b) Steep approaches are not conducted. NOTE: If thrust attenuators are also failed, takeoff and landing factors must be multiplied together.
-41-01	Anti-Skid System (Units -0600 and on)	C	1	0	May be inoperative provided: a) Aircraft is operated in accordance with AFM ANTISKID SYSTEM INOPERATIVE DISPATCH abnormal procedure, and b) Steep approaches are not conducted.
-44-01 ***	Tire Pressure Monitoring System (STC SA02272SE)	D	1	0	NOTE: Any individual wheel sensors which are operative may be used.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 33-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
33	LIGHTS				
-10-01	Cockpit and Instrument Lighting (Excluding button lights, standby flight instrument lighting, internally lighted annunciators, and required placard lighting)				
-00A	(Day)	C	-	0	May be inoperative provided aircraft is not operated at night.
-00B	(Night)	C	-	-	Individual lights may be inoperative provided: a) Cockpit emergency lighting is operative, b) Remaining lights are sufficient to clearly illuminate all required instruments, controls, and other devices for which it is provided, c) Remaining lights are positioned so that direct rays are shielded from crewmembers' eyes, and d) Lighting configuration and intensity is acceptable to flight crew.
-10-04	Standby ALT/AS Placard Lighting (Units -0001 thru -0359 G1000-equipped aircraft)	C	1	0	May be inoperative provided aircraft is not operated at night.
-10-05	Windshield Ice Detection Light				
-00A	(Single light failed)	C	2	1	(O) One may be inoperative provided alternate procedures are established and used to monitor ice accretion.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 33-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
33	LIGHTS				
-10-05	Windshield Ice Detection Light (Continued)				
-00B	(Both lights failed)	C	2	0	May be inoperative provided aircraft is not operated at night.
-00C	(Right side failed)	C	1	0	May be inoperative for single-pilot operations.
-20-02	Cabin Interior Lighting (Excluding cabin emergency lighting)				
-00A		C	-	-	(O) Individual lights may be inoperative provided: a) Sufficient lighting is operative for crew to perform required duties, b) Cabin emergency lighting is verified operative, and c) Sufficient lighting is operative for carrying cabin occupants at night.
-00B		D	-	0	(O) May be inoperative provided: a) Cabin emergency lighting is verified operative, and b) Aircraft is not operated at night or cabin occupants are not carried.
-20-04	Lighted Passenger Information Sign (Excluding cabin exit signs)				
-00A	(With cabin occupants)	C	-	0	(O) May be inoperative provided alternate procedures are established and used to notify cabin occupants.
-00B	(Without cabin occupants)	C	-	0	May be inoperative provided no cabin occupants are carried.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 33-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
33 LIGHTS					
-30-01	Aft Baggage Compartment Light	C	1	0	
-30-02	Nose Baggage Compartment Light	C	1	0	
-40-01	Anti-Collision Light System (Wing strobe)				
-00A		C	1	0	May be inoperative provided system is not required by 14 CFR.
-00B		A	1	0	May be inoperative provided: a) Position / navigation light system is operative, b) Ground recognition light is operative, and c) Repairs are made within three flight days.
-40-02	Ground Recognition Light (Beacon)	C	1	0	NOTE: Position / navigation or anti-collision lights may be used on ground to alert nearby aircraft or personnel when engines are running or prior to start.
-40-03	Landing Light				
-00A	(Single light failed)	B	2	1	One may be inoperative.
-00B	(Both lights failed)	C	2	0	May be inoperative provided aircraft is not operated at night.
-01	Recognition / Taxi Mode	C	1	0	(O) May be inoperative provided at least one landing light is verified operative for night operations.
-02 ***	Pulse Light Mode	D	1	0	(O) May be inoperative provided at least one landing light is verified operative for night operations.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 33-4	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
33	LIGHTS				
-40-05	Position / Navigation Light System	C	1	0	May be inoperative provided system is not operated at night.
-40-10	Wing Inspection Light	C	1	0	May be inoperative provided: a) Aircraft is not operated at night in known, forecast, or AFM-defined icing conditions, and b) Ground deicing procedures do not require its use.
-50-01	Cockpit Flashlight	C	-	-	Any in excess of those required by 14 CFR may be inoperative or missing.
-01 ***	Holder	C	-	0	May be inoperative provided associated flashlight is stowed by alternate means.
-50-04	Exterior Emergency Light	B	2	0	May be inoperative provided aircraft is not operated at night.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-1
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY		
		2. NUMBER INSTALLED		
		3. NUMBER REQUIRED FOR DISPATCH		
		4. REMARKS OR EXCEPTIONS		
34	NAVIGATION			
-16-01	Altitude Alerting System	A	-	0 (O) May be inoperative provided: a) Autopilot with altitude hold and capture operates normally, b) Aircraft does not depart from an airport where repair or replacement can be made, c) Aircraft is not operated RVSM, and d) Repairs are made within three flight days.
-01	Aural Alert	C	-	0 May be inoperative provided: a) Visual alert is operative, and b) Autopilot with altitude hold and capture operates normally.
-02	Visual Alert	C	-	0 May be inoperative provided: a) Aural alert is operative, and b) Autopilot with altitude hold and capture operates normally.
-18-01	Angle of Attack (AOA) System Indicator (Units -0001 thru -0701)	C	1	0 May be inoperative provided stick shaker is verified operative.
-18-02	Angle of Attack (AOA) Heater	C	1	0 May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-23-01	Non-stabilized Magnetic Compass (Units -0360 and on)				
-00A	(Day, VMC)	B	1	0	May be inoperative provided: a) Any combination of two gyro or AHRS-stabilized compass systems are operative, and b) Aircraft is not operated at night or in Instrument Meteorological Conditions (IMC).
-00B		B	1	0	May be inoperative provided: a) Any combination of two gyro or AHRS-stabilized compass systems are operative, b) Aircraft is operated with dual independent navigation capability, and c) Aircraft is operated under positive radar control by ATC on enroute portion of flight.
-01	Internal Lighting	C	1	0	May be inoperative provided flight crew determines adequate natural or artificial lighting exists to read compass.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-3	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34 NAVIGATION					
-24-01	Mechanical Slip/Skid Indicator (Units -0001 thru -0359 excluding G1000-equipped aircraft)	B	2	1	Pilot side must be operative for single-pilot operations.
-24-01	Mechanical Slip/Skid Indicator (Copilot's) (Units -0360 thru -0558 single PFD-equipped aircraft)	B	1	0	
-01	Internal Lighting	C	1	0	May be inoperative provided flight crew determines adequate natural or artificial lighting exists to read indicator.
-25-01 ***	Cursor Control Panel (Units -0360 thru -0701)	C	1	0	May be inoperate provided Class 3 EFB is considered inoperative (Refer to item 46-00-01).
-03	Memory Buttons (MEM1, MEM2, MEM3)	D	3	0	
-04	CHART Button	C	1	0	NOTE: Electronic charts will not be available, alternate charts must be carried.
-05	Rotate Button	C	1	0	NOTE: Some electronic charts may not be legible, alternate charts must be carried.
-06	ZOOM Button	C	1	0	NOTE 1: Some electronic charts may not be legible, alternate charts must be carried. NOTE 2: Graphic weather zoom function will not be available.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-4	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-25-01	Cursor Control Panel (Units -0360 thru -0701) (Continued)				
-07	Joystick	C	1	0	NOTE 1: Some electronic charts may not be legible, alternate charts must be carried. NOTE 2: Graphic weather pan function will not be available.
-25-05	Display Controller (GCU 275) (Units -0800 and on)	B	2	1	(M) Copilot's controller may be failed provided: a) Controller is deactivated, b) Both touchscreen controllers are operative, and c) Barometer synchronization is verified engaged.
-09	Barometer Standard (PUSH STD)	C	2	0	
-11	Range / Pan Control (Knob)	C	2	0	May be inoperative provided touchscreen controller for associated display is operative.
-12	Clear (CLR)	C	2	0	
-13	Enter (ENT)	C	2	0	
-14	Cursor / Select (PFD / PUSH CRSR)	C	6	0	
-15	Direct To (D>)	C	2	0	NOTE: Function may be selected on touchscreen controller.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-5	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34 NAVIGATION					
-25-05	Display Controller (GCU 275) (Units -0800 and on) (Continued)				
-16	Flight Plan (FPL)	C	2	0	NOTE: Function may be selected on touchscreen controller.
-17	Radio Control (COM/NAV)	C	2	0	NOTE: Function may be selected on touchscreen controller.
-18	Procedure (PROC)	C	2	0	NOTE: Function may be selected on touchscreen controller.
-19	Barometer Setting (BARO)	B	2	1	Copilot's setting may be inoperative provided barometer synchronization is enabled.
-25-07	Touchscreen Controller (Right GTC) (Units -0800 and on)	B	1	0	(M) May be inoperative provided controller is deactivated. NOTE: Any functions or controls that operate normally may be used.
-25-08	MFD Control Unit (GCU 475) (Units -0001 thru -0359 G1000-equipped aircraft)	B	1	0	(O) May be inoperative provided: a) Weather radar is considered inoperative (Refer to item 34-42-01), b) Datalink is considered inoperative (Refer to item 23-20-01), c) Electronic chart is considered inoperative, d) Procedures do not require use of MFD, e) Aircraft is operated in Visual Meteorological Conditions (VMC), f) Aircraft is not operated at night, g) PFD inset maps are used, and h) Alternate procedures are established and used.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-6	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34 NAVIGATION					
-25-10 ***	Synthetic Vision (Units -0001 thru -0359 G1000-equipped aircraft and Units -0800 and on)	C	1	0	May be inoperative provided: a) Procedures do not require its use, and b) Synthetic vision is selected OFF.
-31-01	Localizer System	C	-	-	May be inoperative provided: a) Affected system is not on an emergency bus, b) Associated glideslope is considered inoperative (Refer to item 34-32-01), c) Procedures do not require its use, and d) System is not required by 14 CFR.
-32-01	Glideslope System	C	-	-	May be inoperative provided: a) Procedures do not require its use, and b) System is not required by 14 CFR.
-34-01	Marker Beacon Receiver System	C	-	0	May be inoperative provided: a) Procedures do not require its use, and b) System is not required by 14 CFR.
-36-01 ***	Reactive Windshear System (Includes TAWS windshear mode)	C	1	0	(O) May be inoperative provided alternate procedures are established and used.
-42-01	Weather Radar System	C	1	0	May be inoperative provided system is not required by 14 CFR.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-7	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-44-01 ***	Radio Altimeter System (Units -0001 thru -0359)				
-44-01	Radio Altimeter System (Units -0360 and on)				
-00A	(TAWS and TCAS II not required) (Units -0001 -0701)	C	1	0	(M) May be inoperative provided: a) Radio altimeter system is deactivated, b) Approach minimums or operating procedures do not require its use, c) Basic TAWS modes are considered inoperative (Refer to item 34-44-03), and d) TCAS II is considered inoperative (Refer to item 34-45-01).
-00A	(TAWS and TCAS II not required) (Units -0800 and on)	C	1	0	(M) May be inoperative provided: a) Radio altimeter system is deactivated, b) Approach minimums or operating procedures do not require its use, c) Basic TAWS modes are considered inoperative (Refer to item 34-44-03), and d) TCAS II is considered inoperative (Refer to item 34-45-01). NOTE: Landing Operations Phase Inhibit (LOPI) operation will be affected. LOPI may not activate during approach or go-around. (Continued)

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-8	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-44-01	Radio Altimeter System (Continued)				
-00B	(TAWS or TCAS II required) (Units -0001 -0701)	A	1	0	(M) May be inoperative provided: a) Radio altimeter system is deactivated, b) Approach minimums or operating procedures do not require its use, c) Basic TAWS modes are considered inoperative (Refer to item 34-44-03), d) TCAS II is considered inoperative (Refer to item 34-45-01), and e) Repairs are made within two flight days.
-00B	(TAWS or TCAS II required) (Units -0800 and on)	A	1	0	(M) May be inoperative provided: a) Radio altimeter system is deactivated, b) Approach minimums or operating procedures do not require its use, c) Basic TAWS modes are considered inoperative (Refer to item 34-44-03), d) TCAS II is considered inoperative (Refer to item 34-45-01), and e) Repairs are made within two flight days.
					NOTE: Landing Operations Phase Inhibit (LOPI) operation will be affected. LOPI may not activate during approach or go-around.
-44-02 ***	Surface Awareness System (Runway Awareness and Advisory System RAAS) (Units -0001 thru -0701)	C	1	0	

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-9	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-44-02 ***	Surface Awareness System (SurfaceWatch) (Units -0800 and on)	C	1	0	
-44-03 ***	Terrain Awareness and Warning System (TAWS) (Class A or B TAWS not required)	C	1	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any mode that operates normally may be used.
-44-03	Terrain Awareness and Warning System (TAWS) (Including test mode) (Class A or B TAWS required)	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within two flight days.
-01	Forward Looking Terrain Avoidance Function and Premature Descent Alert Function	B	2	0	(O) May be inoperative provided alternate procedures are established and used.
-02	Excessive Rate of Descent (Mode 1) and Altitude Loss After Takeoff or Missed Approach (Mode 3)	A	2	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within two flight days.
-03A	Voice Callouts (Mode 6) ("Five-Hundred")	B	1	0	(O) May be inoperative provided alternate procedures are established and used.
-03B	Voice Callouts (Mode 6) (Other)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-04B	Excessive Closure Rate to Terrain (Mode 2) and Flight Into Terrain Not in Landing Configuration (Mode 4) (Class B TAWS required)	C	2	0	
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-10	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-44-03	Terrain Awareness and Warning System (TAWS) (Continued)				
-05	Excessive Downward Glideslope/Glidepath Deviation (Mode 5) (Class B TAWS required)	C	1	0	
-06 ***	Terrain Display (Class B TAWS required)	C	-	0	
-07	Switch (Any excluding TAWS Test) (Class B TAWS required)	C	-	0	
-08	Annunciator / Indication (Class B TAWS required)	C	-	0	
-45-01 ***	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II)				
-00A	(TCAS not required)	C	1	0	(M) May be inoperative provided: a) System is deactivated, b) System is not required by 14 CFR, and c) Enroute or approach procedures do not require its use.
-00B	(TCAS required)	B	1	0	(M) May be inoperative provided: a) System is deactivated, and b) Enroute or approach procedures do not require its use.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-11	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-45-01	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II) (Continued)				
-01	Traffic Advisory (TA) Display (TCAS II only)	C	-	0	(O) May be inoperative provided: a) Resolution Advisory (RA) display and audio function are operative, and b) Enroute or approach procedures do not require its use.
-02A	Resolution Advisory (RA) Display (TCAS II only)	C	2	1	One may be inoperative on pilot not flying side.
-02B	Resolution Advisory (RA) Display (TCAS II only)	C	2	0	(O) May be inoperative provided: a) Traffic Alert (TA) visual display and audio function are operative, b) TA-only mode is selected by flight crew, and c) Enroute or approach procedures do not require its use.
-03A	Traffic Advisory (TA) and Resolution Advisory (RA) Displays Failed (TCAS II only)	C	2	1	One side be inoperative provided: a) Traffic Advisory (TA) and Resolution Advisory (RA) displays are operative on pilot flying side, and b) Audio function is operative.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-12	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-45-01	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II) (Continued)				
-03B ***	Combined Traffic Advisory (TA) and Resolution Advisory (RA) Display (EVS I or equivalent) (TCAS II only) (Units -0001 thru -0359 excluding G1000-equipped aircraft)	C	2	1	One may be inoperative provided: a) Combined display is operative on pilot flying side, and b) Audio function is operative.
-04	Audio Function	B	1	0	May be inoperative provided enroute or approach procedures do not require use of TCAS.
-05 ***	Airspace Selection Function (Above / below)	C	-	0	
-45-02 ***	Traffic Collision Avoidance Device (TCAD)	D	1	0	
-46-01 ***	Lightning Detection System	D	1	0	May be inoperative provided system is not required by 14 CFR.
-50-01	Radio Magnetic Indicator (RMI) (Units -0001 thru -0359 excluding G1000-equipped aircraft)	C	-	0	May be inoperative provided procedures do not require its use.
-51-01	Distance Measuring Equipment (DME)	D	-	-	Any in excess of those required by 14 CFR may be inoperative.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-13	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34 NAVIGATION					
-52-01	ATC Transponder and Automatic Altitude Reporting System				
-00A	(Individual transponder failed)	D	-	1	May be inoperative provided system is not required by 14 CFR.
-00B	(All transponders failed)	B	-	0	May be inoperative provided: a) Operations do not require its use, b) Prior to flight, approval is obtained from ATC facilities having jurisdiction over planned route of flight, c) TCAS is considered inoperative (Refer to item 34-45-01), and d) Aircraft is not operated RVSM.
-01 ***	Elementary and Enhanced Downlink Aircraft Reportable Parameters (Not required by 14 CFR)	A	-	0	May be inoperative provided: a) Operations do not require their use, and b) Repairs are made prior to completion of next scheduled inspection/check of transponder.
-02	ADS-B Squitter Transmission (Units -0001 thru -0359 G1000-equipped aircraft and Units -0800 and on)	D	-	0	May be inoperative provided operations do not require its use.
-54-01	Very High Frequency Omni Range (VOR) System	C	-	0	May be inoperative provided: a) Affected system is not on an emergency bus, b) Procedures do not require its use, and c) System is not required by 14 CFR.
-55-01 ***	Automatic Direction Finder (ADF)	D	-	0	May be inoperative provided operations do not require its use.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-14	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34	NAVIGATION				
-57-01	Global Navigation Satellite System (GNSS) (Including SBAS)	C	-	0	<p>May be inoperative provided:</p> <ul style="list-style-type: none"> a) System is not required by 14 CFR, and b) Operations do not require its use. <p>NOTE 1: Enhanced function of TAWS may not be available.</p> <p>NOTE 2: ADS-B output may not be available.</p>
-60-01	Data Loader (SD card slot) (Units -0001 thru -0359 G1000-equipped aircraft and Units -0800 and on)	C	-	-	NOTE: Certain card slots are used for real-time data access. If inoperative, associated features are considered inoperative.
-60-01	Data Loader (Units -0001 thru -0359 excluding G1000-equipped aircraft and Units -0360 thru -0701)	C	-	0	
-60-02	Flight Management System (FMS)	C	-	0	<p>May be inoperative provided:</p> <ul style="list-style-type: none"> a) System is not required by 14 CFR, and b) Operations do not require its use. <p>NOTE: Enhanced function of TAWS may not be available.</p>
-02 ***	Takeoff and Landing Data (TOLD) Calculation Function or Database	D	1	0	Function may be inoperative or database may not be loaded.
-60-03 ***	Information Management Server (IMS-3500) (Units -0600 thru -0701)	D	1	0	May be inoperative provided navigation database, electronic charts, and performance database are loaded by alternate means.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 34-15	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
34 NAVIGATION					
-61-01 Navigation Database		C	-	-	(O) May be out of currency provided: a) Current aeronautical charts are used to verify navigation fixes prior to each flight, b) Procedures are established and used to verify status and suitability of navigation facilities used to define route of flight, and c) Approach navigation radios are manually tuned and identified.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 35-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
35	OXYGEN				
-00-03	Oxygen System				
-01	Fill Port	C	1	0	(M) May be inoperative provided bottle is filled using alternate means, if service is required.
-03	Blowout Disk / Green Label	C	1	0	(O) May be missing or damaged provided oxygen pressure is verified prior to each flight.
-10-01	Flight Crew Oxygen System				
-01	Copilot Oxygen Mask	C	1	0	May be inoperative provided copilot seat is not occupied.
-20-01	Passenger Oxygen System				
-00A	(With cabin occupants)	B	1	0	May be inoperative provided: a) Cabin pressurization system is operative, b) Portable oxygen system is available, c) Aircraft is able to descend within four minutes to a cabin pressure altitude of 13,000 feet at all points along route to be flown, and d) Aircraft is operated at FL250 or below.
-00B	(Without cabin occupants)	C	1	0	May be inoperative provided: a) OXYGEN CONTROL is selected to CREW ONLY, and b) No cabin occupants are carried.
-00C	(Cabin unpressurized)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative (Refer to item 21-30-02).
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 35-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
35	OXYGEN				
-20-01	Passenger Oxygen System (Continued)				
-01	Mask	C	-	0	(M) Individual oxygen masks or dispensers may be inoperative or missing provided: a) Affected mask pintle pin is installed, and b) Associated seat or lavatory is placarded "DO NOT OCCUPY".
-02	Drop-out Panel	C	-	0	(M) Individual panels may be out of normal position provided: a) Affected oxygen mask and drop out panel are removed, b) Affected mask pintle pin is installed, and c) Associated seat or lavatory is placarded "DO NOT OCCUPY".
-30-02 ***	Protective Breathing Equipment (PBE)	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing provided location placarding is removed or obscured.

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 38-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
38 WATER / WASTE					
-30-01 ***	Relief Tube (Toilet)	C	1	0	(M) May be damaged or inoperative provided: a) All liquid is removed from relief tube, and b) Relief tube is placarded "DO NOT USE".
-30-03	Lavatory Waste System	C	1	0	Individual components may be inoperative provided: a) Cabin occupants are briefed prior to each flight that lavatory is inoperative and unusable, and b) Lavatory is placarded "DO NOT USE".
-30-04	Overboard Drain (Excluding drain heater)				
-02	Evaporator Fan (Forward or aft)	C	2	0	May be damaged or obstructed provided affected evaporator fan is considered inoperative (Refer to item 21-50-03).
-03	Refreshment Center	C	1	0	(O) May be damaged or obstructed provided: a) All liquid is removed from refreshment center hot liquid storage and drip pan, b) Refreshment center hot liquid storage and drip pan are placarded "DO NOT USE", and c) Ice drawer drain valve remains closed.
-04	Relief Tube (Toilet)	C	1	0	May be damaged or obstructed provided toilet relief tube is considered inoperative (Refer to item 38-30-01).

AIRCRAFT: CESSNA 525		REVISION NO. 3 DATE: 12/19/2013		PAGE NO. 45-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
45	CENTRAL MAINTENANCE SYSTEM				
-00-01 ***	Aircraft Recording System (ARes)	D	1	0	

AIRCRAFT: CESSNA 525		REVISION NO. 3 DATE: 12/19/2013		PAGE NO. 46-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
46	INFORMATION SYSTEMS				
-00-01 ***	Electronic Flight Bag (EFB) System				
-00A	Class 3 EFB (Includes IFIS)	D	-	0	May be inoperative provided procedures do not require its use.
-00B	Class 3 EFB (Includes IFIS)	C	-	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any function, program, or document which operates normally may be used.
-01A	Data Connectivity (Class 2)	D	-	0	May be inoperative provided procedures do not require its use.
-01B	Data Connectivity (Class 2)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-02A	Power Connection (Class 1 & 2)	D	-	0	May be inoperative provided procedures do not require its use.
-02B	Power Connection (Class 1 & 2)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-03A	Mounting Device (Class 2)	D	-	0	(M) May be inoperative provided: a) Associated EFB and hardware is secured by alternate means or removed from aircraft, and b) Procedures do not require its use.
-03B	Mounting Device (Class 2)	C	-	0	(M) (O) May be inoperative provided: a) Associated EFB and hardware is secured by alternate means or removed from aircraft, and b) Alternate procedures are established and used.

AIRCRAFT: CESSNA 525		REVISION NO. 3A DATE: 04/07/2014		PAGE NO. 52-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
52	DOORS				
-10-01	Main Cabin Door				
-01	Key Lock (Failed unlocked)	D	1	0	
-04	Primary Seal (Cabin unpressurized)	C	1	0	May be inoperative provided: a) Primary seal does not interfere with door operation, and b) Cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-05A	Secondary Seal (Cabin pressurized)	C	1	0	May be damaged provided: a) Primary door seal is operative, b) Secondary seal does not interfere with door operation, and c) Aircraft is operated at FL250 or below.
-05B	Secondary Seal (Cabin unpressurized)	C	1	0	May be damaged provided: a) Secondary seal does not interfere with door operation, and b) Cabin pressurization system is considered inoperative (Refer to item 21-30-02).
-08	Gust Lock	B	1	0	(O) May be inoperative provided a procedure is established and used to prevent unrestricted movement of cabin door.
-20-01	Escape Hatch Lock Pin				Deleted, revision 3A

AIRCRAFT: CESSNA 525		REVISION NO. 3A DATE: 04/07/2014		PAGE NO. 52-2	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
52	DOORS				
-30-01	Aft Baggage Door				
-01	Key Lock (Failed unlocked)	D	1	0	May be inoperative provided door is verified closed and latched prior to each flight. NOTE: Aft baggage door warning system may activate.
-40-01	Nose Baggage Door				
-01A	Key Lock (Failed unlocked)	C	2	0	May be inoperative provided door is verified closed and latched prior to each flight. NOTE: Nose baggage door warning system may activate.
-01B	Key Lock (Failed locked)	C	2	1	(O) One may be inoperative provided alternate procedures are established and used to perform required preflight actions through operative door.
-70-01	Door Warning System				
-01	Aft Baggage	C	1	0	May be inoperative provided: a) Door is verified closed, latched, and locked prior to each flight, and b) Aircraft is operated at 200 KIAS or less.
-06	Nose Baggage	B	2	0	May be inoperative provided: a) Door is verified closed, latched, and locked prior to each flight, and b) Aircraft is operated at 200 KIAS or less.
(Continued)					

AIRCRAFT: CESSNA 525		REVISION NO. 3A DATE: 04/07/2014		PAGE NO. 52-3
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY		
		2. NUMBER INSTALLED		
		3. NUMBER REQUIRED FOR DISPATCH		
		4. REMARKS OR EXCEPTIONS		
52	DOORS			
-70-01	Door Warning System (Continued)			
-07	Main Cabin	B	1	0
				(O) May be inoperative provided: a) Door is verified closed and handle latched, b) All lock flags are visible in sight glass locations, c) Internal door handle is verified correctly stowed, d) Aircraft is operated at 200 KIAS or less, and e) Aircraft is operated at FL250 or below.

AIRCRAFT: CESSNA 525		REVISION NO. 3A DATE: 04/07/2014		PAGE NO. 73-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
73	ENGINE FUEL AND CONTROL				
-33-01	Fuel Flow Indicating System	A	2	1	One may be inoperative provided: a) Both fuel quantity indicating systems are operative, and b) Repairs are made within three flight days.

AIRCRAFT: CESSNA 525		REVISION NO. 3 DATE: 12/19/2013		PAGE NO. 76-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
76	ENGINE CONTROLS				
-01-01	Engine Synchronizer System (Failed off)	C	1	0	

AIRCRAFT: CESSNA 525		REVISION NO. 3B DATE: 01/26/2015		PAGE NO. 78-1	
SYSTEM, SEQUENCE NUMBERS & ITEM		1. REPAIR CATEGORY			
		2. NUMBER INSTALLED			
		3. NUMBER REQUIRED FOR DISPATCH			
		4. REMARKS OR EXCEPTIONS			
78	ENGINE EXHAUST				
-30-02	Thrust Attenuator (Units -0001 thru -0558)	C	2	0	<p>(M) May be inoperative provided:</p> <ul style="list-style-type: none"> a) Both attenuators are deactivated in stowed position, b) Aircraft is operated in accordance with AFM DISPATCH WITH ATTENUATOR STOWED abnormal procedure, and c) Steep approaches are not conducted. <p>NOTE: If anti-skid system is also failed, takeoff and landing factors must be multiplied together.</p>

U.S. DEPARTMENT OF TRANSPORTATION		MASTER MINIMUM EQUIPMENT LIST
FEDERAL AVIATION ADMINISTRATION		
AIRCRAFT: CESSNA 525	REVISION NO. 3 DATE: 12/19/2013	PAGE NO. INT-1

SECTION TWO

CAS MESSAGE ORIENTED MMEL RELIEF

(Units -0800 and on)

U.S. DEPARTMENT OF TRANSPORTATION		MASTER MINIMUM EQUIPMENT LIST
FEDERAL AVIATION ADMINISTRATION		
AIRCRAFT: CESSNA 525	REVISION NO. 3 DATE: 12/19/2013	PAGE NO. INT-2

INTRODUCTION

Two section MMELs are authorized by FAA PL 119. Section Two of two-section MMELs may grant relief for failure indications presented as CAS messages on Engine Indicating and Crew Alerting Systems (EICAS), or Electronic Centralized Aircraft Monitoring (ECAM), rather than the traditional relief (Section One) for failed equipment. New technology self-diagnostic tests eliminate the need for failure isolation procedures by maintenance personnel for many CAS messages. By using (O) procedures, the crew can complete selected system/component deactivation/re-configuration from the cockpit **for which the crew has been trained.**

Section Two will only contain CAS message relief if the crew can act on the item. CAS message relief must ensure safe operation of aircraft. Flight Operations Evaluation Boards (FOEB) will use the normal FOEB processes for determining which CAS messages go into each section.

TWO-SECTION MMEL GUIDANCE:

Modern technology CAS MMELs shall be divided into two sections.

- A. Section One.** Items which either require maintenance actions (this may include some CAS messages), or caution/advisory information. Section One will continue to use the existing Line Replaceable Units (LRU)-oriented MMEL format and should address the following type of equipment failures:
1. Failures which are not annunciated to crew; and
 2. Failures which are annunciated, but the failure indication by itself is not considered sufficient to determine the aircraft airworthiness status.
- B. Section Two.** Includes only items where flight members may act on CAS messages. MMEL items where CAS messages can be used to determine the aircraft airworthiness should be formatted as follows:
1. It should have only two columns:
 - a. Column one should list the failure indications (messages) for which relief is given (if desired, the messages may be listed in alphabetical order with no ATA break down).
 - b. Column two should include the corresponding MMEL limitations and/or procedures. The format of this column should be in line with the format requirements of the "Remarks or Exceptions" column of the conventional "LRU oriented" MMEL.
Note: In many cases, CAS messages will not require maintenance to perform fault analysis. Relief provisos for these CAS items are expected to be more restrictive in content and repair interval, as compared to Section One relief provisos.

U.S. DEPARTMENT OF TRANSPORTATION		MASTER MINIMUM EQUIPMENT LIST
FEDERAL AVIATION ADMINISTRATION		
AIRCRAFT: CESSNA 525	REVISION NO. 3 DATE: 12/19/2013	PAGE NO. INT-3

2. Section Two CAS message relief items require flight crews to accomplish one or more steps to deactivate/re-configure the affected system prior to flight. The “(O)” indicates the need for these tasks. Tasks include, but are not necessarily limited to the following duties:
 - a. Procedures accomplished using cockpit (or cabin) system controls.
 - b. Deactivation of affected systems (by pulling system breaker or use of remote electronic system isolation);
 - c. Visual confirmation of remote gauge indications, or valve positions as provided by integral external indicators; and
 - d. Visual inspection behind panels (internal or external).
 - 1) These panels must be accessible without tools via quick-release latches and must clearly indicate their unlocked or unsafe state (red/green safe window; flush fit latches - candidates to be verified at FOEB).
 - 2) The visual inspection of compartments accessed by the panels is within the normal crew duty requirements for which they have been trained; and
 - 3) The crew may use an external ladder for visual inspection behind panels as long as this procedure is within the normal crew duty requirements for which they have been trained. Special equipment such as maintenance stands and hydraulic lifts may not be used by the crew to perform visual inspections.

C. The following statement will be included on page 1 of Section Two in all two-section MMELs:

1. Section Two of the MMEL will list only Crew Alerting system (CAS) messages meeting the following requirements:
 - a. Equipment failure indications(s) that can be used to determine the airworthiness status of the airplane;
 - b. Messages that the crew can act upon from the cockpit with simple troubleshooting procedures without the assistance of a mechanic, and for which the crew has been trained.
 - c. Messages using the new self-diagnostic technology (virtual) actions for which the crew has been trained.
2. CAS message relief items not meeting these requirements will be listed in Section One of the MMEL.

AIRCRAFT: CESSNA 525	REVISION NO. 3 DATE: 12/19/2013	PAGE NO. 2-1
WHITE CAS Messages	Dispatch Consideration	
ADS-B FAIL	Aircraft may be dispatched provided Automatic Dependent Surveillance-Broadcast (ADS-B) Squitter Transmission is considered inoperative.	
AP FAIL	Aircraft may be dispatched provided autopilot system is considered inoperative.	
DIAGNOSTICS REC FAIL	Aircraft may be dispatched provided Aircraft Recording System (AReS) is considered inoperative.	
*** FDR FAIL	Aircraft may be dispatched provided Flight Data Recorder (FDR) is considered inoperative.	
*** SURFACEWATCH FAIL	Aircraft may be dispatched provided surface awareness system is considered inoperative.	
TRANSPONDER FAIL 1 or 2	Aircraft may be dispatched provided affected ATC transponder is considered inoperative.	
YD FAIL	Aircraft may be dispatched provided yaw damper is considered inoperative.	

AIRCRAFT: CESSNA 525	REVISION NO. 3 DATE: 12/19/2013	PAGE NO. 2-2
AMBER CAS Messages	Dispatch Consideration	
AFT DOOR OPEN	Aircraft may be dispatched provided aft baggage door warning system is considered inoperative.	
AOA HEATER FAIL	Aircraft may be dispatched provided Angle of Attack (AOA) vane heater is considered inoperative.	
CABIN DOOR OPEN	Aircraft may be dispatched provided main cabin door warning system is considered inoperative.	
CABIN DOOR SEAL	Aircraft may be dispatched provided main cabin door primary seal is considered inoperative.	
ELEC PIT TRIM FAIL	Aircraft may be dispatched provided electric elevator trim system is considered inoperative.	
ENGINE A/I COLD L or R	Aircraft may be dispatched provided engine inlet anti-ice is considered inoperative.	
FUEL LEVEL LOW L and/or R (when fuel quantity is known to be above threshold)	Aircraft may be dispatched provided fuel level low indicating system is considered inoperative.	
GMA FAIL 2	Aircraft may be dispatched provided copilot's audio panel is considered inoperative.	
GSD FAIL 1	Aircraft may be dispatched provided stabilizer pneumatic boot de-ice system, cockpit and cabin temperature control system automatic mode, cabin pressurization system automatic schedule mode, Distance Measuring Equipment (DME) 1, and Traffic Alert and Collision Avoidance (TCAS) are considered inoperative.	
GSD FAIL 2	Aircraft may be dispatched provided Traffic Alert and Collision Avoidance (TCAS), Distance Measuring Equipment (DME) 2, and satellite datalink are considered inoperative.	
NOSE DOOR OPEN L and/or R	Aircraft may be dispatched provided nose baggage door warning system is considered inoperative.	
P/S COLD L (when selected ON)	Aircraft may be dispatched provided pilot static port heater is considered inoperative.	
P/S COLD R (when selected ON)	Aircraft may be dispatched provided copilot pitot heater is considered inoperative.	

AIRCRAFT: CESSNA 525	REVISION NO. 3 DATE: 12/19/2013	PAGE NO. 2-3
AMBER CAS Messages	Dispatch Consideration	
PRESSURIZATION CNTRL	Aircraft may be dispatched provided cabin pressurization controller modes (excluding manual) are considered inoperative.	
RADAR FAIL	Aircraft may be dispatched provided weather radar system is considered inoperative.	
TAIL DE-ICE FAIL	Aircraft may be dispatched provided stabilizer pneumatic boot de-ice system is considered inoperative.	
TCAS FAIL	Aircraft may be dispatched provided traffic alert and collision avoidance system is considered inoperative.	
TERRAIN FAIL	Aircraft may be dispatched provided Terrain Awareness and Warning System (TAWS) forward looking terrain avoidance function and premature descent alert function are considered inoperative.	
TRANSPONDER FAIL 1 and 2	Aircraft may be dispatched provided both ATC transponders are considered inoperative.	
WINDSHEAR FAIL	Aircraft may be dispatched provided Terrain Awareness and Warning System (TAWS) windshear mode is considered inoperative.	
WING A/I COLD L or R	Aircraft may be dispatched provided wing bleed air anti-ice system is considered inoperative.	