



U.S. Department of Transportation
Federal Aviation Administration
Washington, DC

Master Minimum Equipment List (MMEL)

Revision: 10a
Date: 04/05/2019

Textron Aviation Model 500 Series Citation 500/501, 550/S550/551, 560

Victoria Linkous, Chair
Flight Operations Evaluation Board (FOEB)

Federal Aviation Administration (FAA)
Small Aircraft Evaluation Group (MKC-AEG)
901 Locust Street, Department of Transportation Building
Kansas City, MO 64106

Telephone: (816) 329-3233
Fax: (816) 329-3241
Email: 9-AVS-AFS-100@faa.gov

REVISION NO. 10a

PAGE NO. I

DATE: 04/05/2019

AIRCRAFT:

Textron Aviation 500 Series

TABLE OF CONTENTS AND CONTROL PAGE

SYSTEM NO.	SYSTEM	PAGE NO.	REV NO.	DATE
--	Cover Page	--	10a	04/05/2019
--	Table of Contents and Control Page	I	10a	04/05/2019
--	Highlights of Change	II thru III	10a	04/05/2019
--	Definitions and Preamble	IV	10a	04/05/2019
--	Guidelines for (M) and (O) Procedures	V	10a	04/05/2019
21	Air Conditioning	21-1 thru 10	10a	04/05/2019
22	Autoflight	22-1 thru 2	10a	04/05/2019
23	Communications	23-1 thru 8	10a	04/05/2019
24	Electrical Power	24-1	10	01/03/2018
25	Equipment/Furnishings	25-1 thru 9	10a	04/05/2019
26	Fire Protection	26-1	10	01/03/2018
27	Flight Controls	27-1	10	01/03/2018
28	Fuel	28-1 thru 2	10	01/03/2018
29	Hydraulic Power	29-1	10	01/03/2018
30	Ice and Rain Protection	30-1 thru 3	10	01/03/2018
31	Indicating/Recording Systems	31-1 thru 4	10a	04/05/2019
32	Landing Gear	32-1	10	01/03/2018
33	Lights	33-1 thru 6	10	01/03/2018
34	Navigation	34-1 thru 19	10a	04/05/2019
35	Oxygen	35-1 thru 2	10	01/03/2018
38	Water/Waste	38-1	10	01/03/2018
46	Information Systems	46-1 thru 2	10	01/03/2018
52	Doors	52-1 thru 3	10	01/03/2018
73	Engine Fuel and Control	73-1	10	01/03/2018
74	Ignition	74-1	10	01/03/2018
77	Engine Indicating	77-1	9a	02/13/2014
78	Engine Exhaust	78-1	10	01/03/2018

REVISION NO. 10a

PAGE NO. II

DATE: 04/05/2019

AIRCRAFT:

Textron Aviation 500 Series

HIGHLIGHTS OF CHANGE

The following changes are the Highlights of Changes for **Revision 10a**. It is the result of wording corrections and inadvertent omissions from Rev 9a. It includes Policy Letter (PL) updates and STC relief items.

ATA NO.	EXPLANATION OF CHANGE
General	Minor editorial corrections were made throughout the document that do not affect the relief and are not indicated with change bars. These editorial corrections may be adopted in Minimum Equipment Lists (MEL) at the operator's discretion.
ATA 21 AIR CONDITIONING	
21-20-01	Corrected to include all outlets in cockpit (Rev 9a).
21-22-01	Added relief for Flood Cooling System.
21-33-01	Sub-items -01 and -02. Changed wording on proviso to concur with (M) procedure in Textron's Procedures Manual.
ATA 22 AUTOFLIGHT	
22-10-03	Sub-item -00B Amended proviso.
ATA 23 COMMUNICATIONS	
23-70-01	Sub-item -00A. Removed a) FDR proviso is not applicable to this aircraft. Sub-item -00C relief moved to sub-items -00A and -00B. (Ref. 14 CFR 91.609)
ATA 25 EQUIPMENT/FURNISHINGS	
25-10-05	Amended Sub-items -01A and -01B for Number installed.
ATA 31 INDICATING/RECORDING SYSTEMS	
31-10-09 31-10-10 31-10-11	CORRECTION - Relief inadvertently removed in Rev 10 (previously in ATA 30). Amended relief to use AFM icing definition.
31-30-04	Revised FDR relief. Removed sub-items (Ref. 14 CFR 91.609).

REVISION NO. 10a

PAGE NO. III

DATE: 04/05/2019

AIRCRAFT:

Textron Aviation 500 Series

HIGHLIGHTS OF CHANGE

ATA NO.	EXPLANATION OF CHANGE
ATA 34 NAVIGATION	
34-36-01	CORRECTION - Relief inadvertently removed in Rev 10 (previously ATA 34-44-02-5).
34-52-03	Added relief for STCs.
34-52-03-02	Moved to ATA 34-58-02 –Revised PL-76 R7, moves the Automatic Dependent Surveillance-Broadcast (ADS-B) squitter transmissions relief (relief is provided in PL-105).
34-54-01	Relief inadvertently removed in Rev 10.
34-57-01	Added relief for STCs.
34-58-01	Added relief for ABS-B (PL-105 Rev 2). Added relief for STCs.

REVISION NO. 10a

PAGE NO. IV

DATE: 04/05/2019

AIRCRAFT:

Textron Aviation 500 Series

DEFINITIONS AND PREAMBLE

DEFINITIONS

The required definitions are listed in MMEL Policy Letter 25. Additional definitions may be included in an operators MEL as desired. Revision of PL-25 does not require revision to the operator's MEL.

PREAMBLE

The applicable preamble must be inserted in the operator's MEL from current FAA Policy Letter PL-34 or Policy Letter PL-36.

REVISION NO. 10a

PAGE NO. V

DATE: 04/05/2019

AIRCRAFT:

Textron Aviation 500 Series

GUIDELINES FOR (M) AND (O) PROCEDURES

The FOEB has identified a need for certain procedures to provide an adequate level of safety while providing relief for some items. These procedures must be established by the operator and may be based on the aircraft manufacturer's recommended procedures, Supplemental Type Certificate modifier's recommended procedures, or equivalent operator procedures. When recommended procedures are published, the operator should comply with these procedures. If recommended procedures are not published, the following guidelines delineate the aspects to be considered by the operator in the development of required procedures:

Cessna has developed recommended (M) maintenance and (O) operational procedures for the Cessna 500 Series Master Minimum Equipment List (P/N 500CPM-10-00, or later revision). Operator's MEL procedures should be based on the Cessna procedures.

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	Air Duct Overheat System	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Cabin pressurization source remains OFF, b) Flight is conducted unpressurized, c) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, and d) Aircraft is operated at 10,000 feet MSL or below. 	
-00-02	Precool System					
-01	Pressurized	C	2	1	(M) One may be inoperative provided: <ol style="list-style-type: none"> a) Affected system is deactivated, b) Pressurization Source Selector remains on the opposite source, and c) Flight is conducted at FL 250 or below. 	
-02	Unpressurized	C	2	0	(O) May be inoperative provided: <ol style="list-style-type: none"> a) Flow Control Valves are verified CLOSED, b) Cabin Pressurization Source Selector remains OFF, c) Flight is conducted unpressurized, d) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, and e) Aircraft is operated at 10,000 feet MSL or below. 	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Pilot Air Outlets (WEMACs)	C	-	0		
-20-02	Ground Flow Control Valve	C	1	0	(O) May be inoperative provided: a) Ground flow control valve is verified CLOSED, and b) BLEED AIR GND is not used.	
-21-01	Overhead Cabin Blower	C	1	0		
-22-01	Flood Cooling System Model 550-0356 & On, S550-0001 thru -0160 and 560-0001 thru -0538. And (550-0019, -0120, -0494, -0497, -0501, -0505).	D	1	0	(M) May be inoperative provided system is deactivated.	
-30-01	Cabin Pressurization System	C	1	0	May be inoperative provided: a) Flight is conducted unpressurized, b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, c) Cabin emergency dump is operative and selected to DUMP, d) Cabin altitude is set above 10,000 feet, e) Cabin rate is set to maximum, and f) Aircraft is operated at 10,000 feet MSL or below.	
-30-02	Emergency Pressurization Valve					
-01	Pressurized	C	1	0	May be inoperative provided: a) Air cycle machine is operative, b) Both bleed sources are operative, and c) Aircraft is operated at FL 250 or below.	

(Continued)

REVISION NO. 10a

PAGE NO. 21-3

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-30-02	Emergency Pressurization Valve					
-02	Unpressurized	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Flight is conducted unpressurized, b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, c) Cabin emergency dump is operative and selected to DUMP, d) Cabin altitude is set above 10,000 feet, e) Cabin rate is set to maximum, and f) Aircraft is operated at 10,000 feet MSL or below. 	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-31-01	Pressurization Control System					
-01	Auto-Schedule Mode (550 units 801 and on, 560 units 0539-5000)	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Isobaric control mode is operative, b) Manual control mode is operative, c) Cabin altimeter is operative, d) Cabin rate indicator is operative, and e) Aircraft is operated at FL 410 or below. 	
-02	Pressurization Control System Isobaric Mode (550 units 801 and on, 560 units 0539-5000)	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Auto-schedule mode is operative, b) Manual cabin pressure control system is operative, c) Cabin differential pressure gauge is operative, d) Cabin rate indicator is operative, and e) Aircraft is operated at FL 410 or below. 	
-03	Pressurization Control System Manual Control Mode (550 units 801 and on, 560 units 0539-5000)	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Flight is conducted unpressurized, b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, c) Cabin emergency Dump is operative and selected to DUMP, d) Cabin altitude is set above 10,000 feet MSL, e) Cabin rate is set to maximum, and f) Aircraft is operated at 10,000 feet MSL or below. 	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-32-01	Cabin Differential Pressure Gauge	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Flight is conducted unpressurized, b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, c) Cabin emergency dump is operative and selected to DUMP, d) Cabin altitude is set above 10,000 feet MSL, e) Cabin rate is set to maximum, and f) Aircraft is operated at 10,000 feet MSL or below. 	
-01	(500, 501, S550, 551, 550 units 0001 thru 0800, 560 units 0001 thru 0538)	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) All other components of the pressurization system are operative, b) Cabin altitude selector is set not to exceed maximum differential pressure, and c) A chart is provided to convert cabin and aircraft altitude to differential pressure. 	
-02	(550 units 0801 and on, 560 units 0539 thru 5000)	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) All other components of the pressurization system are operative, and b) A chart is provided to convert cabin and aircraft altitude to differential pressure. 	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-32-02	Cabin Vertical Speed or Cabin Rate Indicator	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Flight is conducted unpressurized, b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, c) Cabin emergency dump is operative and selected to DUMP, d) Cabin altitude is set above 10,000 feet MSL, e) Cabin rate is set to maximum, and f) Aircraft is operated at 10,000 feet MSL or below. 	
-32-03	Cabin Altimeter					
-01	Unpressurized	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Flight is conducted unpressurized, b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, c) Cabin emergency dump is operative and selected to DUMP, d) Cabin altitude is set above 10,000 feet MSL, e) Cabin rate is set to maximum, and f) Aircraft is operated at 10,000 feet MSL or below. 	
-02	Pressurized	C	1	0	May be inoperative provided all other pressurization system components are operative.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-33-01	Flow Control and Shutoff Valves					
-01	Unpressurized	C	2	0	(M) May be inoperative provided: a) Both flow control and shutoff valves are verified closed (no bleed air flow), b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes c) Cabin pressurization source selector remains OFF, and d) Aircraft is operated at 10,000 feet MSL or below.	
-02	Pressurized	C	2	1	(M) One may be inoperative provided: a) Failed valve is verified closed (no bleed air flow), b) Cabin pressurization source selector is selected to the opposite side, and c) Flight is conducted at FL 250 or below.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-33-02	Outflow Valves	C	2	0	(M) Both may be inoperative provided: <ol style="list-style-type: none"> a) At least one valve is removed from its location, b) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, c) Aircraft is operated unpressurized, and d) Aircraft is operated at 10,000 feet MSL or below. 	
-34-01	Cabin Altitude Warning System	C	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Flight planning must consider the fuel burn and range associated with flight at lower altitudes, and b) Aircraft is operated at 10,000 feet MSL or below. 	
-50-01	Air Cycle Machine					
-01		C	1	0	May be inoperative provided cabin pressurization is considered inoperative.	
-02 ***	STC03975AT Unpressurized	C	2	0	May be inoperative provided cabin pressurization is considered inoperative.	
-03 ***	STC03975AT Pressurized	C	2	1	(O) ACM #1 may in inoperative provided: <ol style="list-style-type: none"> a) ACM #1 is verified OFF, b) ACM #2 switch is ON, c) Vixen 500 RADAR is OFF, and d) WX RADAR is not required. <p>NOTE: ACM #2 temperature is always full cold.</p>	

(Continued)

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-50-01	Air Cycle Machine (Cont'd)					
-04 ***	STC03975AT Pressurized	C	2	1	(O) ACM #2 may be inoperative provided: a) ACM #2 is verified OFF, b) Vixen RADAR is OFF, and c) WX RADAR is not required.	
-05 ***	STC03975AT ACM #1 Switch (ACM 1 NORM/OFF)	C	1	0	(O) May be inoperative provided: a) ACM 1 switch remains OFF, b) ACM 1 is verified OFF, and c) ACM 2 switch is ON. NOTE: ACM #2 temperature is always full cold.	
-06 ***	STC03975AT ACM #2 Switch (ACM 2 ON/OFF)	C	1	0	(O) May be inoperative provided: a) ACM 2 switch remains OFF, b) ACM 2 is verified OFF, c) Vixen 500 RADAR remains OFF, and d) WX RADAR is not required.	
-07 ***	STC03975AT Air Cycle Machine #2 Overheat Light (Failure to Illuminate)	C	1	0	May be inoperative provided: a) ACM 2 switch remains OFF, b) Vixen 500 RADAR remains OFF, and c) WX RADAR is not required.	
-50-02 ***	Freon Air Conditioning System	C	1	0	(M) May be inoperative provided system is deactivated.	

REVISION NO. 10a

PAGE NO. 21-10

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-60-01	Automatic Cabin Air Temperature Control System	C	1	0	May be inoperative provided manual cabin air temperature control is operative.	
-60-02	Manual Cabin Air Temperature Control System	C	1	0	May be inoperative provided automatic cabin air temperature control is operative.	
-62-01 ***	Cabin Temperature Indicator	C	1	0		

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Autopilot	B	1	0	May be inoperative provided: a) Enroute operations do not require its use, b) Approach minimums do not require its use, c) Aircraft is operated with a minimum of two crew, and d) Aircraft is not operated RVSM.	
-10-02	YawDamper	B	1	0	May be inoperative provided: a) Autopilot is considered inoperative, and b) Aircraft is not operated RVSM.	
-10-03	Autopilot Disconnect Button (AP DISC) (Failed deselected)					
-00A	Left Disconnect Button	B	1	0	May be inoperative provided: a) Right disconnect button is operative, b) A pilot remains seated in right seat with seat belt fastened during all autopilot operations, c) Autopilot system is not used below AFM cruise minimum use height, and d) Approach minimums do not require use of autopilot system.	
-00B	Right Disconnect Button	C	1	0		

(Continued)

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-10-03	Autopilot Disconnect Button (AP DISC) (Failed deselected) (Cont'd)					
-00C	(All buttons failed)	B	2	0	May be inoperative provided: <ol style="list-style-type: none"> a) Autopilot system is considered inoperative, b) Electric elevator trim is considered inoperative, and c) Aircraft is not operated RVSM. 	
-13-01	Autopilot/Flight Director Touch Control Steering (TCS) or SYNC Switches	C	2	0		
-13-02	Flight Director Mode Selector Panel Functions	B	-	0	Individual functions may be inoperative provided procedures do not require their use.	
-13-03	Course Selector Knob(s)	B	2	1	One may be inoperative for the pilot not flying.	
-13-04	Go-Around Buttons					
-00A		C	-	1	May be inoperative for the pilot not flying.	
-00B		C	-	0	May be inoperative provided: <ol style="list-style-type: none"> a) Flight director is not used during a go-around, and b) Autopilot is disconnected for go-around. 	
					NOTE: FMS missed approach procedure must be activated via the FMS CDU.	

REVISION NO. 10a

PAGE NO. 23-1

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Radio Management Unit (RMU)	C	2	1	(O) One may be inoperative provided: a) Remaining RMU operates normally, and b) Auxiliary Com/Nav control display unit is verified to operate normally.	
-00-02 ***	Flight Phone / SATCOM System	D	-	0	May be inoperative provided procedures do not require its use.	
-01	Cockpit Handset	D	-	0	May be inoperative provided procedures do not require its use.	
-02	Cabin Handset	D	-	0		

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-10-01 ***	High Frequency (HF) Communication System					
-00A	(Dual LRCS not required)	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	
-00B	(Dual LRCS required)	C	-	1	(O) May be inoperative while conducting operations which require two Long-Range Communication Systems (LRCS) provided: <ul style="list-style-type: none"> a) Aircraft SATVOICE system operates normally, b) SATVOICE services are available as a LRCS over intended route of flight, and c) ICAO Flight Plan is updated, as required, to notify ATC of communications equipment status of aircraft, and d) Alternate procedures are established and used. 	
-01	Wire Antenna	C	1	0	(M) May be inoperative, missing, or damaged provided: <ul style="list-style-type: none"> a) Horizontal and vertical stabilizers are inspected for damage, b) Any remaining portion of wire antenna is removed, and c) HF communication system is considered inoperative. 	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-10-04 ***	Radio Package Cooling Fan (Com/NAV/XSPDR) (550 units 0801 thru 1136)					
-01	Fan 1	B	1	0	May be inoperative provided FAN 2 FAIL amber annunciator and fan are operative.	
-02	FAN 1 FAIL Amber Annunciator	C	1	0	(O) May be inoperative provided Fan 1 and Fan 2 are verified operative.	
-10-05 ***	STC03946AT VP-200 Voice Privacy Unit					
-01		D	1	0	May be inoperative provided unencrypted HF communications system remains operative.	
-02		D	1	0	May be inoperative provided HF communications system is considered inoperative.	
-11-01 ***	STC03975AT C-5000 UHF-VHF Transceiver	C	2	0		
-11-02 ***	STC03949AT ARC-210 UHF-VHF-FM SATCOM Transceiver	C	1	0		
-12-01	Very High Frequency (VHF) Communication System	D	-	-	Any in excess of those required by 14 CFR may be inoperative provided: a) Affected system is not on an emergency bus, and b) Procedures do not require its use.	

REVISION NO. 10a

PAGE NO. 23-4

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-20-01 ***	Selective Call (SELCAL) (System or individual channel)					
-00A	(SELCAL not required)	D	-	0	May be inoperative provided procedures do not require its use.	
-00B	(SELCAL required)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-40-01 ***	Automatic Cabin Briefer	D	1	0		
-40-02	Passenger Address (PA) System	D	1	0		
-40-03	Passenger Seat Belt / Safety Chime	C	1	0		

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-50-01	Cockpit Headset and Boom Microphone	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	
-01A	Boom Microphone (For a holder of an Air Carrier or Commercial Operator Certificate)	A	-	0	May be inoperative provided: a) Associated hand microphone is installed and operative, and b) Repairs are made within 3 flight-days.	
-01B	Boom Microphone (For an operator other than a holder of an Air Carrier or Commercial Operator Certificate)	A	-	0	May be inoperative provided: a) Associated hand microphone is installed and operative, and b) Repairs are made in accordance with applicable 14 CFR.	
-02	Headset Earphones / Headphones	C	-	1	May be inoperative provided associated cockpit overhead communication speaker is operative.	
-03 ***	Active Noise Reduction (ANR) Function	D	-	0	May be inoperative provided normal audio function of headset is operative.	

REVISION NO. 10a

PAGE NO. 23-6

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-50-02	Cockpit Headset Audio System					
-00A		C	2	0	May be inoperative provided: a) Both cockpit overhead communication speakers are operative and used, b) Headset audio system is not required by 14 CFR or procedures, and c) Aircraft is not operated single-pilot.	
-00B		C	2	1	One may be inoperative provided left side is operative for single-pilot operations.	
-50-03	Copilot's Audio Control Panel	C	1	0	May be inoperative for operations not requiring a second in command.	
-50-04	Cockpit Speakers	C	2	1	One may be inoperative provided an operative headset is used for the affected side.	
-50-05	Hand Held Microphone	C	2	0	May be inoperative provided associated headset microphone is operative and used.	

REVISION NO. 10a

PAGE NO. 23-7

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-60-01	Static Wicks	C	-	-	One may be missing or broken from each of the following areas, not to exceed a total of three: a) Right wing, wingtip, or aileron (560 units 0539 thru 5000 wingtip only), b) Left wing wingtip, or aileron (560 units 0539 thru 5000 wingtip only), and c) Vertical stabilizer, stinger, or rudder (560 units 0539 thru 5000 stinger only).	
-60-02 ***	AFIS Antenna Static Wick	C	1	0	May be missing or broken.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-70-01	Cockpit Voice Recorder (CVR)					
-00A	(Holder of management specifications, air carrier, or commercial operator certificate)	A	1	0	May be inoperative provided repairs are made within 3 flight-days.	
		C	1	0	Any in excess of those required by 14 CFR may be inoperative.	
-00B	(Operator other than a holder of management specifications, air carrier, or commercial operator certificate)	A	1	0	May be inoperative provided repairs are made in accordance with applicable 14 CFR operating rule.	
		C	1	0	Any in excess of those required by 14 CFR may be inoperative.	
-00C	(All operators)				Deleted Rev 10a (Relief moved to sub-items -00A and -00B above).	
-01 ***	Recorder Independent Power Supply (RIPS)	C	1	0		
-02 ***	Underwater Locator Device (ULD)	D	1	0	May be inoperative or missing provided device is not required by 14 CFR.	
-03A ***	Datalink Recording	C	1	0	May be inoperative provided datalink recording is not required by 14 CFR.	
-03B ***	Datalink Recording	A	1	0	May be inoperative provided repairs are made within 3 flight-days.	

REVISION NO. 10

PAGE NO. 24-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

24. Electrical Power

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Ground Power Dispatch Switch	D	1	0		
-22-01	Avionics A.C. Power inverters (All except 560 units 0751 thru 5000)	C	2	1	(M) One may be inoperative provided: a) Affected inverter is deactivated, and b) Flight is not conducted at night.	
-31-01 ***	Battery Temperature Indicator	C	1	0	NOTE: BATT O'HEAT or BATT O'TEMP annunciators combined with Battery Temperature Indicator REV 10.	
-37-01	D.C. Ammeter	C	2	1	One may be inoperative.	
-40-01	External Power Receptacle	C	1	0		

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	Required Documents Holder (Airworthiness Certificate, Registration, etc.)	D	1	0	(O) May be inoperative or missing provided an alternate means of securing and displaying documents is used.	
-10-01	Cockpit Assist Handle	D	1	0		
-10-03	Cockpit Sunvisor System (Including attach mechanism)	D	-	0	May be inoperative or missing provided: a) Crewmember's field of vision is not obstructed, and b) Oxygen mask quick donning ability is not affected.	
-10-05	Flight Crew Seat					
-01A	Armrest	C	-	0	May be inoperative provided affected armrest is stowed in retracted position.	
-01B	Armrest	C	-	0	(M) May be inoperative provided affected armrest is removed.	
-02 ***	Lumbar Support	D	1	0		
-03	Recline/Tilt Function	C	2	0	(M) (O) May be inoperative provided: a) Affected seat is secured or failed in a position that permits normal visibility, b) Full flight control movement is available, and c) Crewmember can reach all necessary controls and equipment while restrained.	

(Continued)

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-10-05	Flight Crew Seat (Cont'd)					
-04 ***	Thigh Support	C	2	0	May be inoperative provided full flight control movement is available.	
-05 ***	Restraint Buckle Protective Padding	D	2	0	May be damaged or missing.	
-06	Vertical Adjustment	C	2	0	(M) (O) May be inoperative provided: a) Affected seat is secured or failed in a position that permits pilot normal visibility, b) Full flight control movement is available, and c) Crewmember can reach all necessary controls and equipment while restrained.	
-07	Copilot Seat Belt / Shoulder Harness	C	1	0	May be inoperative provided seat remains unoccupied.	
-08	Copilot Floor Tracking	C	1	0	May be inoperative provided seat remains unoccupied.	
-10-08	Eye Reference Ball	C	3	0	(O) May be inoperative or missing provided alternate procedures are established and used for eye position reference.	
-10-09 ***	Yoke-mounted Chart Holder	D	-	0		
-01 ***	Light	D	-	0		

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-20-03 ***	Cabin Curtain	D	-	0	(M) May be missing, or inoperative provided curtain is secured open.	
-20-04	Cabin Window Shade					
-01	Failed Open	D	-	0		
-02	Failed Other Than Open	D	-	-	May be inoperative provided affected window is not adjacent to an escape hatch or main cabin door.	
-20-05	Non-essential Equipment and Furnishings (NEF)	-	-	0	May be inoperative, damaged, or missing provided that item(s) is deferred in accordance with operator's NEF deferral program. NEF program procedures and processes are outlined in operator's (insert name) Manual. (M) and (O) procedures, if required, must be available to flight crew and included in operator's appropriate document. NOTE: Exterior lavatory door ashtray is not considered an NEF item.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-20-06	Passenger Seat (Including side-facing seats, folding seats and couches)	D	-	0	May be inoperative provided: <ol style="list-style-type: none"> a) Seat does not block an emergency exit, b) Seat does not restrict any cabin occupant access to aisle, and c) Affected seat(s) are blocked and placarded "DO NOT OCCUPY". NOTE: Affected seat(s) may include seats near inoperative seat(s).	
-01	Armrest	D	-	0	May be missing, or inoperative with seat occupied provided: <ol style="list-style-type: none"> a) Armrest does not block an emergency exit, and b) Armrest does not restrict any cabin occupant from access to aisle. 	
-02A	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	(M) May be inoperative with seat occupied provided seat is secured in taxi, takeoff and landing position.	
-02B	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	May be inoperative with seat occupied provided control is failed in taxi, takeoff and landing position.	
(Continued)						

AIRCRAFT:
Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-20-06	Passenger Seat (Including side-facing seats, folding seats and couches) (Cont)					
-02C	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	May be missing or inoperative in other than taxi, takeoff, and landing position provided affected seat is considered inoperative.	
-03 ***	Seat Belt / Shoulder Harness (Forward and Aft Facing Seats)	D	-	0	May be inoperative provided affected seat is placarded "DO NOT OCCUPY FOR TAXI, TAKEOFF, LANDING OR WHEN FASTEN SEAT BELT SIGN IS ILLUMINATED".	
-03A	Seat Belt / Shoulder Harness (Side facing seats)	D	-	0	May be inoperative provided affected seat is placarded "DO NOT OCCUPY FOR TAXI, TAKEOFF, LANDING OR WHEN FASTEN SEAT BELT SIGN IS ILLUMINATED".	
-04 ***	Seat Belt / Shoulder Harness Keeper	D	-	0		
-05 ***	Lumbar Support	D	-	0		
-06 ***	Air Bag Restraint System	D	1	0	May be inoperative provided affected seat is blocked and placarded "DO NOT OCCUPY".	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-30-01	Refreshment Center Hot Liquid Storage System Heater	D	-	0	(M) May be inoperative provided system is deactivated.	
-30-02 ***	Refreshment Center Microwave / Oven	D	-	0	(M) May be inoperative provided system is deactivated.	
-40-01	Exterior Lavatory Door Ashtray	A	1	0	May be inoperative in accordance with AD 74-08-09 in its current revision.	
-50-01	Baggage Restraint System	D	-	0	Individual components may be inoperative or missing provided baggage is secured by alternate means or not carried.	
-01A	Anchor Plate	C	-	0	Individual anchor plates may be inoperative provided: a) No visible damage exists, and b) Baggage is secured using remaining anchor plates or not carried.	
-01B	Anchor Plate	C	-	0	(M) Individual anchor plates may be damaged provided: a) Attaching structure is inspected for damage, and b) Baggage is secured using remaining anchor plates or not carried.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-50-02	Cabin Storage Compartment					
-00A		C	-	0	(M) May be inoperative provided: a) Compartment does not contain any aircraft system protection devices, b) Any emergency equipment located in affected compartment is considered inoperative, c) Affected compartment is not used for storage of any item except for those permanently affixed, d) Procedures are established and used to secure compartment closed, and e) Affected compartment is prominently placarded "DO NOT USE".	
-00B		C	-	0	(M) May be inoperative provided: a) Affected door is removed, b) Affected compartment is not used for storage of any item, including those permanently affixed, c) Cabin occupants are briefed that affected compartment may not be used, and d) Affected compartment is prominently placarded "DO NOT USE".	
(Continued)						

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-50-02	Cabin Storage Compartment (Cont'd)					
-01	Shelving	C	-	0	(O) May be inoperative provided: a) Any permanently affixed emergency equipment located on affected shelf is relocated and available for use, and b) Cabin occupants are briefed on location of relocated equipment.	
-02	Key Lock	D	-	0	(M) May be inoperative in the unlocked position provided door can be secured by other means.	
-60-01 ***	Cockpit Smoke Vision System (CSVs)	D	-	0	May be missing or inoperative.	
-60-02 ***	Crash Axe / Survival Tool	D	-	-		
-60-03	Emergency Medical Equipment					
-01 ***	Automatic External Defibrillator (AED) (Includes associated equipment)	D	-	0	May be inoperative or missing.	
-02 ***	Emergency Medical Kit (EMK) (Includes associated equipment)	D	-	0	May be inoperative or missing.	
-03 ***	First Aid Kit (FAK) (Includes associated equipment)	D	-	-	Any in excess of those required by 14 CFR may be incomplete, missing, or inoperative.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-61-01 ***	Life Vest (Crew and passenger)	D	-	-	Any in excess of those required by 14 CFR may be missing, or inoperative provided affected preserver is placarded "INOPERATIVE" or removed.	
-62-01	Emergency Locator Transmitter (ELT)					
-01 ***	Survival Type	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing.	
-02A	Fixed, Automatic	A	-	0	(M) May be inoperative provided: a) System is deactivated or removed, and b) Repairs are made within 90 calendar days.	
-02B	Fixed, Automatic	D	-	-	(M) Any in excess of those required by 14 CFR may be inoperative provided system is deactivated or removed.	
-64-01 ***	Life Raft	D	-	-	Any in excess of those required by 14 CFR may be missing, or inoperative provided affected raft is placarded "INOPERATIVE" or removed.	

REVISION NO. 10

PAGE NO. 26-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

26. Fire Protection

Sequence No.	Item	1	2	3	4	Change Bar
-22-01	Portable Fire Extinguisher	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing provided: <ul style="list-style-type: none"> a) Inoperative fire extinguisher is placarded "INOPERATIVE", removed from installed location, and placed out of sight so it cannot be mistaken for a functional unit, and b) Required distribution is maintained. 	

REVISION NO. 10

PAGE NO. 27-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

27. Flight Controls

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Rudder Pedal Adjustment System	B	4	2	(M)(O) Two may be inoperative provided: a) Two pedal adjustments are not inoperative at same pilot station, b) Affected pedal is positioned in a detent and adjustment mechanism is secured from movement, c) Unaffected pedal is adjusted to match affected pedal, and d) Crewmember seated at affected station verifies full control movement and brake application are available while restrained, prior to each flight.	
-31-01	Electric Elevator Trim	B	1	0	(M) May be inoperative provided: a) Electric elevator trim system is deactivated, b) Autopilot is considered inoperative, and c) Aircraft is not operated RVSM.	
-41-01	Trim and Flap Position Indicator Tips (All except 560 units 0751 thru 5000)	C	4	0	(M) May be missing or inoperative provided alternate means of marking pointer is established and used.	
-70-01	Control/Gust Lock System (Failed Unlocked)	C	1	0	(O) May be inoperative provided pilot verifies full flight control and throttle movement.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Single Point Refueling System	C	1	0		
-40-01	Fuel Low Level Indicating System	B	2	1	One may be inoperative provided both fuel quantity indicating systems are operative.	
-41-01	Fuel Quantity Indicating System	A	2	1	One indication may be inoperative provided: <ol style="list-style-type: none"> a) Both fuel low level indicating systems and both fuel flow indicating systems are operative, b) Fuel required for route to be flown is increased by 10%, c) Flight is restricted to a maximum of three hours, remaining within one hour of a suitable airport at all points along route, d) Both fuel tanks are fueled over-wing to a known, balanced quantity, e) Fuel use is tracked, f) If autopilot is used, it is disconnected every twenty minutes to detect possible lateral fuel imbalance, monitor trim required, and g) Repairs are made within three flight cycles. 	

REVISION NO. 10

PAGE NO. 28-2

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
-42-01 ***	Fuel Remaining/Fuel Used Indicating System	C	1	0	May be inoperative provided both fuel quantity indicating systems are operative.	
-43-01	L/R Fuel temperature Indication (560 units -0539 thru 5000)	C	2	1		

REVISION NO. 10

PAGE NO. 29-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

29. Hydraulic Power

Sequence No.	Item	1	2	3	4	Change Bar
-30-01	Low Hydraulic Fluid Annunciator/Light				Moved to ATA 31 Rev 10.	
-30-02	LO HYD FLOW L/R HYD FLOW LOW LH/RH Annunciator				Moved to ATA 31 Rev 10.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	ENG ANTI-ICE Annunciator				Moved to ATA 31 Rev 10.	
-00-02	WING ANTI-ICE Annunciators (560 units -0539 thru -5000)				Moved to ATA 31 Rev 10.	
-00-03	Pitot/Static Heater OFF Annunciators				Moved to ATA 31 Rev 10.	
-10-01	Wing and Tail De-Ice or Anti-Ice System					
-01	Pneumatic De-Ice System (500/501, 550/551, 560)	C	-	0	May be inoperative provided aircraft is not operated into AFM defined icing conditions.	
-02	Surface Anti-Ice Pumps (S550)	C	2	1	May be inoperative provided aircraft is not operated into AFM defined icing conditions.	
-03	Wing Electrical Systems (500/501, 550/551)	C	2	1	May be inoperative provided aircraft is not operated into AFM defined icing conditions.	
-04	Wing Bleed Air Anti-Ice Systems (560 units -0001 thru -0538)	C	2	1	May be inoperative provided aircraft is not operated into AFM defined icing conditions.	
-05	Wing Bleed Air Anti-Ice Systems (560 units -0539 thru -5000)	C	2	0	May be inoperative provided aircraft is not operated into AFM defined icing conditions.	
-20-01	Engine Anti-Ice System	C	2	1	May be inoperative provided aircraft is not operated into AFM defined icing conditions.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
-20-02	Engine Anti-Ice Valves	C	2	1	One may be inoperative provided: <ol style="list-style-type: none"> a) Engine anti-ice valve remains OPEN, and b) Takeoff and landing field temperatures are not in excess of +10 degrees C. NOTE: See AFM Performance Data.	
-30-01	Pitot Heaters	B	-	-	One may be inoperative provided: <ol style="list-style-type: none"> a) Flight is not conducted in AFM defined icing conditions, b) Flight is not conducted at night, c) Aircraft is not operated in visible moisture, and d) Aircraft is not operated RVSM. 	
-30-02	Static Pressure Port Heaters	B	-	-	One may be inoperative provided: <ol style="list-style-type: none"> a) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, b) Flight is not conducted at night, c) Flight is not conducted in visible moisture, and d) Aircraft is not operated RVSM. 	
-30-03	Angle of Attack Probe/Vane Heater	C	-	0	May be inoperative provided: <ol style="list-style-type: none"> a) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, b) Flight is not conducted at night, and c) Aircraft is operated VMC only. 	

REVISION NO. 10

PAGE NO. 30-3

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
-40-01	Windshield Anti-Ice System	C	2	1	One may be inoperative provided: a) Left windshield anti-ice system must be operative for single pilot operations, and b) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-40-02	Windshield Alcohol System	C	1	0	May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-40-03	Rain Removal System	C	2	0	May be inoperative provided flight is not conducted in precipitation within 5 nautical miles of the airport for takeoff and landing.	
-70-01	Drain Mast Heaters	C	-	0	May be inoperative provided: a) Affected basins are not used, and b) Any ice or fluid is emptied from basin.	
-80-01	Surface Ice Detection System (S550)	B	1	0	May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	

AIRCRAFT:
Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	Angle of Attack (AOA) System					
-01	Indicator	C	1	0		
-02 ***	Indexer	C	1	0		
-00-02	N1 Reminder (Mechanical and Electric) All Except 560 units -0751 thru -5000	D	1	0		
-10-01	Low Hydraulic Fluid Amber Annunciator/ Light Failure to Illuminate or Extinguish	C	1	0	(O) May be inoperative provided adequate fluid level is verified before each takeoff.	
-10-02	LO HYD FLOW L/R HYD FLOW LOW LH/RH Amber Annunciator Failure to Illuminate or Extinguish	C	2	1	(O) May be inoperative provided: a) Adequate fluid level is verified prior to each takeoff, and b) Hydraulic system operation is verified operative on the affected side,	
-10-03	PRECOOL FAIL Amber Annunciator Failure to Illuminate or Extinguish (550 units -0001 thru -0549)	C	1	0	May be inoperative provided precool system is considered inoperative.	
-10-04	Nose Baggage Doors Amber Annunciator System Fails to Illuminate/Display (550 units -0801 thru 1136, 560 units -0260 thru -5000)	C	2	0	(O) May be inoperative provided affected door(s) are verified closed, latched and locked prior to each takeoff.	

AIRCRAFT:
Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-10-05	Aft Baggage or Tailcone Door Amber Annunciator System Fails to Illuminate/Display (550 units -0801 thru -1136, 560 units -0260 thru -5000)	C	1	0	(O) May be inoperative provided affected door is verified closed, latched and locked prior to each takeoff.	
-10-06	DOOR SEAL Amber Annunciator System Fails to Illuminate/Display (550 units -0801 thru -1136, 560)					
-01	Pressurized	C	1	0	(O) May be inoperative provided: a) Primary door seal is verified operative, and b) Flight is conducted at FL 250 or below.	
-02	Unpressurized	C	1	0	May be inoperative provided pressurization is considered inoperative.	
-10-07	Cabin Door Amber Annunciator System Fails to Illuminate/Display (550 units -0801 thru -1136, 560 units -0260 thru -5000)	B	1	0	(O) May be inoperative provided: a) All door lock flags are visible in the sight glass locations on the door, and b) Interior door handle securing pin is verified engaged (unable to rotate handle without depressing push button).	
-10-08	Engine Igniter Lights/Annunciators Fails to Illuminate/Display (All except 560 units -0751 thru -5000)	B	2	1	One may be inoperative provided igniter snapping is verified audibly prior to engine start.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-10-09	ENG ANTI-ICE Annunciators	C	2	1	One may be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-10-10	WING ANTI-ICE Annunciators (560 units 0539 - 5000)	C	2	0	May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-10-11	Pitot/Static Heater Off Annunciators	B	-	0	(O) May be inoperative provided: a) All other components of the Pitot Heat system are verified operative before each takeoff, and b) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-20-01	Clocks	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	
-20-02	Flight Hour Meter	C	1	0	(O) May be inoperative provided flight time is tracked by other means.	
-30-04 ***	Flight Data Recorder (FDR) System					
	FDR not required	C	1	0	Any in excess of those required by 14 CFR may be inoperative.	
	Sub-items 00A, 00B, 00C, 01A, 01B				Removed Rev 10a.	

(Continued)

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-30-04 ***	Flight Data Recorder (FDR) System (Cont'd)					
-02A ***	Underwater Locator Device (ULD)	D	1	0	May be inoperative or missing provided device is not required by 14 CFR.	
-02B ***	Underwater Locator Device (ULD)	A	1	0	May be inoperative or missing provided repairs are made within 3 flight-days.	
-30-05 ***	Quick Access Recorder (QAR)	D	1	0	May be inoperative provided recorder is not required by 14 CFR or procedures.	
-50-03	Central Warning					
-01	Master Warning Light (Failed to illuminate)	C	2	1	Right side may be inoperative for single-pilot operations.	
-02	Master Warning Cancel/Reset Function	C	2	1	Right side may be inoperative for single-pilot operations.	
-03	Master Caution Light (Failed to illuminate) (550 units -0801 thru 1136, 560 units -0539 thru -5000)	C	2	1	Right side may be inoperative for single-pilot operations.	
-04	Master Caution Cancel/Reset Function (550 units -0801 thru 1136, 560 units -0539 thru -5000)	C	2	1	Right side may be inoperative for single-pilot operations.	

REVISION NO. 10

PAGE NO. 32-1

DATE: 01/03/2018

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

32. Landing Gear

Sequence No.	Item	1	2	3	4	Change Bar
-41-01 ***	Anti-Skid System (All except 560 units -0539 thru -5000)	C	1	0	May be inoperative provided AFM Abnormal Procedures are followed.	
-41-02 ***	Skid Warning System (500/501)	C	1	0		

REVISION NO. 10

PAGE NO. 33-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Cockpit and Instrument Lighting (Excluding button lights, standby flight instrument lighting, internally lighted annunciators, and required placard lighting)					
-00A		C	-	0	May be inoperative provided aircraft is not operated at night.	
-00B		C	-	-	Individual lights may be inoperative provided: <ol style="list-style-type: none"> a) Cockpit emergency lighting is operative, b) Remaining lights are sufficient to clearly illuminate all required instruments, controls, and other devices for which it is provided, c) Remaining lights are positioned so that direct rays are shielded from crewmembers' eyes, and d) Lighting configuration and intensity is acceptable to flight crew. 	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-10-02 ***	Windshield Ice Detection System (Glareshield Mounted) Stalk Lights					
-00A		C	2	1	(O) One may be inoperative provided: a) Aircraft is operated with two pilots, and b) Alternate procedures are established and used to monitor ice accretion.	
-00B		C	2	0	May be inoperative provided aircraft is not operated at night.	
-00C	Right Side Failed	C	1	0	May be inoperative for single-pilot operations.	
-20-01	Cabin Interior Lighting (Excluding cabin emergency lighting)					
-00A		C	-	-	(O) Individual lights may be inoperative provided: a) Sufficient lighting is operative for crew to perform required duties, b) Cabin emergency lighting is verified operative, and c) Sufficient lighting is operative for carrying cabin occupants at night.	
-00B		D	-	0	(O) May be inoperative provided: a) Cabin emergency lighting is verified operative, and b) Aircraft is not operated at night or cabin occupants are not carried.	

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-20-02	Lighted Passenger Information Sign (Excluding cabin exit signs)					
-00A	(With cabin occupants)	C	-	0	(O) May be inoperative provided alternate procedures are established and used to notify cabin occupants.	
-00B	(Without cabin occupants)	D	-	0		May be inoperative provided no cabin occupants are carried.
-20-03 ***	LED Light Elements for EXIT Signs	C	23	7		
-20-04 ***	Incandescent Light Bulbs for EXIT Signs (Per sign)	C	4	1		
-30-01	Tailcone Lights	C	-	0		
-30-02	Nose Baggage Compartment Light	C	1	0		
-40-01	Anti-Collision Light System (Wing strobe)	C	1	0	May be inoperative provided: a) Position / navigation light system is operative, b) Ground recognition light (Flashing/Rotating Red Beacon) is operative, and c) Not required by 14 CFR.	

REVISION NO. 10

PAGE NO. 33-4

DATE: 01/03/2018

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-40-02	Position Lights	C	3	0	May be inoperative provided aircraft is not operated sunset to sunrise.	
-40-03	Wing Inspection Light					
-01	Both Lights	C	-	0	May be inoperative provided: a) Aircraft is not operated at night in known, forecast, or AFM-defined icing conditions, and b) Ground deicing procedures do not require its use.	
-02	Right Light	C	-	0	May be inoperative provided: a) Aircraft is not operated at night in known, forecast, or AFM-defined icing conditions, and b) Left wing inspection light is operative.	
-40-04	Main Gear Mounted Landing Lights	C	2	0	May be inoperative provided aircraft is not operated at night.	

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-40-05	Wingtip Mounted Landing Lights					
-00A		C	2	0	May be inoperative provided aircraft is not operated at night.	
-00B		C	2	1	One may be inoperative for night provided main gear mounted landing/taxi lights are operative.	
-40-06	Main Gear Mounted Taxi Lights 550 units -0801 thru 1136, 560 units -0260 thru -5000)					
-00A		C	2	0	May be inoperative provided aircraft is not operated at night.	
-00B		C	2	1	One may be inoperative for night provided the wing tip mounted landing light on the affected side is operative.	
-40-07 ***	Strobe Light System (Supplemental System)	C	1	0		
-40-08 ***	Recognition Lights	C	2	0		
-40-09 ***	Logo Lights	C	2	0		
-40-10	Ground Recognition Light (Flashing/Rotating Red Beacon)	C	1	0	May be inoperative provided wing strobe lights are operative.	

REVISION NO. 10

PAGE NO. 33-6

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-40-11 ***	Pulselite System	D	1	0		
-50-01 ***	Cockpit Flashlight	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing.	
-01 ***	Holder	D	-	-	May be inoperative provided associated flashlight is stowed by alternate means.	
-50-02 ***	Exterior Emergency Lighting System	D	1	0	May be inoperative provided aircraft is not operated at night.	
-50-03 ***	Cabin Dropped Aisle Lighting System	C	-	-		

REVISION NO. 10a

PAGE NO. 34-1

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Moving Map Display	C	-	0		
-00-02 ***	SkyWatch Traffic Advisory System	C	1	0		
-10-01	Air Data Computer (550 units -0801 thru 1136, 560 units -0260 thru -0750)	A	2	1	One may be inoperative for 1 flight-day provided: a) Flight is not conducted at night, b) Aircraft is operated in VMC only, and c) Aircraft is not operated RVSM.	
-12-01	Outside Air Temperature Indicating System(s)	C	-	1		
-13-01	Vertical Speed Indicator					
-00A		B	2	1	May be inoperative on the right side.	
-00B		B	2	0	May be inoperative on the left side except for 14 CFR Part 135 IFR passenger carrying operations.	

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-16-01	Altitude Alerting System	A	-	0	May be inoperative provided: a) Operations do not require its use, b) Autopilot with altitude hold and capture operates normally, c) Aircraft does not depart from an airport where repair or replacement can be made, d) Aircraft is not operated RVSM, and e) Repairs are made within 3 flight-days.	
-01	Aural Alert	C	-	0	May be inoperative provided: a) Visual alert is operative, and b) Autopilot with altitude hold and capture operates normally.	
-02	Visual Alert	C	-	0	May be inoperative provided: a) Aural alert is operative, and b) Autopilot with altitude hold and capture operates normally.	
-22-01 ***	Radio Magnetic Indicator (RMI)	C	-	-	May be inoperative provided: a) Affected instrument is a repeater of the Horizontal Situation Indicator (HSI), and b) Aircraft is not equipped with dual EFIS.	

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-23-01 ***	Non-Stabilized Magnetic Compass	B	1	0	May be inoperative provided: a) Aircraft is equipped with dual AHRS, b) Both AHRS heading information sources are operative, and c) Aircraft is equipped with an electronic standby instrument system and the heading information is operative.	
-23-02 ***	Turn and Slip Indication					
-01	Mechanical Indicators	B	2	1		
-02	Bezel Mounted Inclinometer	B	-	1		
-25-01	Primus 1000 Display Controller (PFD)					
-01	VOR/Localizer Source Selector Switches (NAV)	C	2	-	May be inoperative provided procedures do not require their use. NOTE: NAV source cannot be changed. Aircraft powers up on the onside VHF.	
-02	FMS Source Selector Switches	C	2	0	May be inoperative provided procedures do not require their use.	
-03	Elapsed Time (ET) Function Switch	C	2	0		

(Continued)

REVISION NO. 10a

PAGE NO. 34-4

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-25-01	Primus 1000 Display Controller (PFD) (Cont'd)					
-04	Horizontal Indicator Mode Select Switches	C	2	0	NOTE: Weather radar requirement must be considered if ARC display modes are inoperative on both PFDs. May be inoperative provided approach minimums do not require its use.	
-05	Radio Altitude Knob	C	2	0		
-06	Single Cue/Cross Pointer Switch (SC/CP)	C	2	0		
-07	Groundspeed/Time To Go Switch (GSPD/TTG)	C	2	0		

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-25-02	Symbol Generators for Electronic Flight Information System (EFIS)					
-01	5 Tube System	C	3	2	One may be inoperative provided: <ol style="list-style-type: none"> a) EFIS displays at pilot and co-pilot stations are operated from independent symbol generators, b) Radar is displayed on the EHSI if required, and c) Enroute or approach procedures do not require use of MFD. 	
-02	3 Tube System					
	550 units -0001 thru -0733, 551, S550	C	2	1	One may be inoperative provided: <ol style="list-style-type: none"> a) Radar is displayed on the EHSI if required, and b) Enroute or approach procedures do not require use of the MFD. <p>NOTE: If the symbol generator is inoperative, select SG on the MFD mode selector. This will restore function to the EADI and EHSI, and will render the MFD unusable.</p>	
	550 units -0801 thru 1136	B	2	1	One may be inoperative provided: <ol style="list-style-type: none"> a) Flight is not conducted at night, and b) Aircraft is operated in VMC only. 	
(Continued)						

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-25-02	Symbol Generators for Electronic Flight Information System (EFIS) (Cont'd)					
-02	3 Tube System (Cont'd)					
	560 units -0001 thru -0259	C	2	1	One may be inoperative provided: a) Radar is displayed on the EHSI if required, and b) Enroute or approach procedures do not require use of the MFD. NOTE: If the symbol generator is inoperative, select SG on the MFD mode selector. This will restore function to the EADI and EHSI, and will render the MFD unusable.	
	560 units -0260 thru -0750	B	2	1	One may be inoperative provided: a) Flight is not conducted at night, and b) Aircraft is operated in VMC only.	
-25-03	Multifunction Display (MFD) Honeywell EDZ-605 EFIS System	C	1	0	May be inoperative provided radar is displayed on the EHSI if required.	

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-25-04	Multifunction Display (MFD) Honeywell Primus 1000 System	C	1	0	May be inoperative provided: a) Aircraft is operated by a crew of two, b) TCAS display is considered inoperative, and c) Radar is displayed on the PFD in the 60-degree arc presentation if required. May be inoperative provided at least one PFD Horizontal Indicator Mode Select Switch switch operates normally.	
-25-05	Primus 1000 Multifunction Display Controller					
-01	MAP/PLAN Switch	C	1	0		
-02	WX Switch	C	1	0		
-03	Range Selector	C	1	0		
-04	Checklist Function Buttons (NORM, EMER, RCL, PAG, SKIP, ESC or ENT)	C	6	0		
-05	Joystick Controller	C	1	0		
-06	Symbol Display Buttons (APT, VOR, DAT)	C	3	0		

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-25-06 ***	Flight Director/Guidance Computer(s) (FDC/FGC) (All except 560 units -0751 thru -5000)					
-01		B	-	0	May be inoperative provided: a) Autopilot is operative, b) Indicators are retracted from view, and c) Approach minimums do not require its use.	
-02		B	-	0	May be inoperative provided: a) Autopilot is considered inoperative, b) Indicators are retracted from view, c) Approach minimums do not require its use, and d) Aircraft is not operated RVSM.	
-25-07	Flight Director Mode Selector Annunciators	C	-	0	(O) May be inoperative provided: a) Corresponding mode function displays on PFD/MFD, and b) Crew verifies mode displayed is appropriate to that selected.	
-25-08 ***	GH-3000 Electronic Standby Instrument System Heading Information	C	1	0	May be inoperative provided: a) Pilot's PFD heading information is operative, and b) Magnetic compass is installed and operative.	
-01	Internal Cooling Fan	C	1	0		

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-31-01	Localizer System	C	-	-	May be inoperative provided: a) Affected system is not on an emergency bus, b) Associated glideslope is considered inoperative , c) Procedures do not require its use, and d) System is not required by 14 CFR.	
-32-01	Glideslope System	C	-	-	May be inoperative provided: a) Procedures do not require its use, and b) System is not required by 14 CFR.	
-34-01	Marker Beacon Receiver System	D	-	0	May be inoperative provided: a) Procedures do not require its use, and b) System is not required by 14 CFR.	
-35-01 ***	Head Up Display (HUD)	D	-	0		
-36-01 ***	Reactive Windshear System (Includes TAWS windshear mode)	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-42-01	Weather Radar System	C	1	0	As required by 14 CFR.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-44-01 ***	Surface Awareness System (Runway Awareness and Advisory System RAAS)	C	1	0		
-44-02 ***	Terrain Awareness and Warning System (TAWS) (Class A or B TAWS not required)	C	1	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any mode that operates normally may be used.	
-44-03	Terrain Awareness and Warning System (TAWS) (Including test mode) (Class A or B TAWS required)	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
-01	Forward Looking Terrain Avoidance Function and Premature Descent Alert Function	B	2	0	(O) May be inoperative provided alternate procedures are established and used.	
-02	Excessive Rate of Descent (Mode 1) and Altitude Loss After Takeoff or Missed Approach (Mode 3)	A	2	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
-03A	Voice Callouts (Mode 6) ("Five-Hundred")	B	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-03B	Voice Callouts (Mode 6) (Other)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
(Continued)						

REVISION NO. 10a

PAGE NO. 34-11

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-44-03	Terrain Awareness and Warning System (TAWS) (Including test mode) (Class A or B TAWS required) (Cont'd)					
-04B	Excessive Closure Rate to Terrain (Mode 2) and Flight Into Terrain Not in Landing Configuration (Mode 4) (Class B TAWS required)	C	2	0		
-05	Excessive Downward Glideslope/Glidepath Deviation (Mode 5) (Class B TAWS required)	C	1	0		
-06 ***	Terrain Display (Class B TAWS required)	C	-	0		
-07	Switch (Any excluding TAWS Test) (Class B TAWS required)	C	-	0		
-08	Annunciator / Indication (Class B TAWS required)	C	-	0		

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-44-04	Radio Altimeter System	A	-	0	May be inoperative provided: a) GPWS is considered inoperative, b) TCAS II is considered inoperative, c) Approach minimums or operating procedures do not require its use, and d) Repairs are made within 2 flight-days.	
-45-01 ***	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II)					
-00A	(TCAS not required)	C	1	0	(M) May be inoperative provided: a) System is deactivated, b) System is not required by 14 CFR, and c) Enroute or approach procedures do not require its use.	
-00B	(TCAS required)	B	1	0	(M) May be inoperative provided: a) System is deactivated, and b) Enroute or approach procedures do not require its use.	
-01	Traffic Advisory (TA) Display (TCAS II only)	C	-	0	(O) May be inoperative provided: a) Resolution Advisory (RA) display and audio function are operative, and b) Enroute or approach procedures do not require its use.	
(Continued)						

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-45-01 ***	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II) (Cont'd)					
-02A	Resolution Advisory (RA) Display (TCAS II only)	C	2	1	One may be inoperative on pilot not flying side.	
-02B	Resolution Advisory (RA) Display (TCAS II only)	C	2	0	(O) May be inoperative provided: a) Traffic Alert (TA) visual display and audio function are operative, b) TA-only mode is selected by flight crew, and c) Enroute or approach procedures do not require its use.	
-03A	Traffic Advisory (TA) and Resolution Advisory (RA) Displays Failed (TCAS II only)	C	2	1	One side be inoperative provided: a) Traffic Advisory (TA) and Resolution Advisory (RA) displays are operative on pilot flying side, and b) Audio function is operative.	
-03B ***	Combined Traffic Advisory (TA) and Resolution Advisory (RA) Display (EVS I or equivalent) (TCAS II only) (Units -0001 thru -0359 excluding G1000-equipped aircraft)	C	2	1	One may be inoperative provided: a) Combined display is operative on pilot flying side, and b) Audio function is operative.	
(Continued)						

REVISION NO. 10a

PAGE NO. 34-14

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-45-01 ***	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II) (Cont'd)					
-04	Audio Function	B	1	0	May be inoperative provided enroute or approach procedures do not require use of TCAS.	
-05 ***	Airspace Selection Function (Above / below)	C	-	0		
-45-02 ***	Traffic Collision Avoidance Device (TCAD)	D	1	0		
-46-01 ***	Stormscope or Lightning Detection System	D	1	0		May be inoperative provided system is not required by 14 CFR.
-51-01	Distance Measuring Equipment (DME)	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	
-52-02 ***	TACAN	D	-	0	May be inoperative provided approach procedures do not require its use.	

AIRCRAFT: Textron Aviation 500 Series	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
--	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-52-03	ATC Transponders and Automatic Altitude Reporting System Including STCs: ACSS ST02609LA, ST02632LA ST02635LA	B	-	0	May be inoperative provided: a) Operations do not require its use, b) Prior to flight, approval is obtained from ATC facilities having jurisdiction over planned route of flight, c) TCAS is considered inoperative, and d) Aircraft is not operated RVSM.	
		D	-	1	Any in excess of those required by 14 CFR may be inoperative.	
-01	Elementary and Enhanced Downlink Aircraft Reportable Parameters Not required by 14 CFR	A	-	0	May be inoperative provided: a) Operations do not require their use, and b) Repairs are made prior to completion of next scheduled inspection/check of transponder.	
-02	ADS-B Squitter Transmission				Moved to ATA 34-58-01, Rev 10a.	
-54-01	Very High Frequency Omni Range (VOR) System	C	-	0	May be inoperative provided: a) Affected system is not on an emergency bus, b) Procedures do not require its use, and c) System is not required by 14 CFR.	
-55-01 ***	Automatic Direction Finder (ADF) System	D	-	0	May be inoperative provided approach procedures do not require its use.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-57-01 ***	Global Navigation Satellite System (GNSS) (Including SBAS) Including STCs: ACSS ST02609LA, ST02632LA, ST02635LA	C	-	0	May be inoperative provided: a) System is not required by 14 CFR, and b) Operations do not require its use. NOTE 1: Enhanced function of TAWS may not be available. NOTE 2: ADS-B output may not be available.	
-58-01 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) System Including STCs: ACSS ST02609LA, ST02632LA, ST02635LA BHE SA11222DS ST11216DS Peregrine ST00892DE	C	-	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) It is not required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
		D	-	0	May be inoperative provided: a) Enroute operations do not require its use, and b) It is not required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
		C	-	1	One may be inoperative as required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	

(Continued)

REVISION NO. 10a

PAGE NO. 34-17

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-58-01 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) System (Cont'd)					
***	ADS-B Out Extended Squitter Transmissions	C	-	0	(O) May be inoperative provided: <ol style="list-style-type: none"> a) Alternate procedures are established and used, b) Authorization is obtained from ATC facilities having jurisdiction over planned route of flight, and c) It is not required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
		C	-	1	One must be operative as required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
(Continued)						

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-58-01 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) System (Cont'd)					
***	ADS-B Out UAT Transmissions	C	-	0	(O) May be inoperative provided: a) Enroute operations do not require its use, b) Authorization is obtained from ATC facilities having jurisdiction over planned route of flight, and c) It is not required by 14 CFR. NOTE: Any ADS-B Out function that operates normally may be used.	
		C	-	1	One must be inoperative as required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
***	ADS-B In Transmissions	C	-	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any ADS-B In function that operates normally may be used.	
		D	-	0	May be inoperative provided operations do not require its use. NOTE: Any ADS-B function that operates normally may be used.	

REVISION NO. 10a

PAGE NO. 34-19

DATE: 04/05/2019

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-60-01 ***	SD card slot	D	-	0		
-60-02	Flight Management System (FMS)	C	-	0	May be inoperative provided: a) System is not required by 14 CFR, and b) Operations do not require its use. NOTE: Enhanced function of TAWS may not be available.	
-01	Fuel Planning Function	C	-	0		
-61-01	Navigation Database				DELETED REV 10 (Refer to Policy Letter 98 Rev 1)	

REVISION NO. 10

PAGE NO. 35-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

35. Oxygen

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	Oxygen System					
-01	Fill Port	C	1	0	(M) May be inoperative provided bottle is filled using alternate means, if service is required.	
-02	Blowout Disk / Green Label	C	1	0	(O) May be missing or damaged provided oxygen pressure is verified prior to each flight.	
-10-01	Copilot Oxygen Mask	C	1	0	May be inoperative provided copilot seat is not occupied.	
-20-01	Passenger Oxygen System					
-00A	Pressurized (With cabin occupants)	B	1	0	May be inoperative provided: a) Cabin pressurization system is operative, b) Portable oxygen system is available, c) Aircraft is able to descend within four minutes to a cabin pressure altitude of 10,000 feet at all points along route to be flown, and d) Aircraft is operated at FL 250 or below.	
-00B	Pressurized (Without cabin occupants)	C	1	0	May be inoperative provided: a) OXYGEN CONTROL is selected to CREW ONLY, and b) No cabin occupants are carried.	
-00C	Unpressurized	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

35. Oxygen

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Passenger Oxygen System (Cont'd)					
-01	Mask	C	-	0	(M) Individual oxygen masks or dispensers may be inoperative or missing provided: <ol style="list-style-type: none"> a) Affected mask pintle pin is installed, and b) Associated seat or lavatory is placarded "DO NOT OCCUPY". 	
-02	Drop-out Panel	C	-	0	(M) Individual panels may be out of normal position provided: <ol style="list-style-type: none"> a) Affected oxygen mask and drop out panel are removed, b) Affected mask pintle pin is installed, and c) Associated seat or lavatory is placarded "DO NOT OCCUPY". 	
-30-02 ***	Protective Breathing Equipment (PBE)	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing provided: <ol style="list-style-type: none"> a) Inoperative PBE remains in a certified location or is removed from the aircraft, b) Location placarding is removed or obscured, and c) Required distribution is maintained. <p>NOTE: Inoperative PBE units removed from a certified location, or removed from the aircraft, are subject to 49 CFR dangerous goods regulations.</p>	

REVISION NO. 10

PAGE NO. 38-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

38. Water/Waste

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Potable Water System					
-00A		C	-	-	(M) Individual components may be inoperative provided: <ul style="list-style-type: none"> a) Associated components are deactivated or isolated, and b) Associated system components are verified not to have leaks. NOTE: Any portion of the system that works normally may be used.	
-00B		C	-	-	(M) May be inoperative provided: <ul style="list-style-type: none"> a) System is drained, and b) System is not serviced. 	
-30-01	Lavatory Waste System	C	-	-	(M) Individual components may be inoperative provided: <ul style="list-style-type: none"> a) Associated components are deactivated or isolated, and b) Associated system components are verified not to have leaks. NOTE: Any portion of the system that works normally may be used.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

46. Information Systems

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Electronic Checklist System	D	1	0	May be inoperative.	
-00-02 ***	Airborne Flight Information System (VHF or SATCOM Data Link, XM/NEXRAD/Satellite Weather)	D	-	0		
-00-03 ***	Electronic Flight Bag System (EFB)					
-00A	Class 3 EFB (Includes IFIS)	D	-	0	May be inoperative provided procedures do not require its use.	
-00B	Class 3 EFB (Includes IFIS)	C	-	0	(O) May be inoperative provided alternate procedures are used.	
					NOTE: Any function, program, or document which operates normally may be used.	
-01A	Data Connectivity (Class 2)	D	-	0	May be inoperative provided procedures do not require its use.	
-01B	Data Connectivity (Class 2)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-02A	Power Connection (Class 1 & 2)	D	-	0	May be inoperative provided procedures do not require its use.	
-02B	Power Connection (Class 1 & 2)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
					(Continued)	

REVISION NO. 10

PAGE NO. 46-2

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

46. Information Systems

Sequence No.	Item	1	2	3	4	Change Bar
-00-03 ***	Electronic Flight Bag System (EFB) (Cont'd)					
-03A	Mounting Device (Class 2)	D	-	0	(M) May be inoperative provided: a) Associated EFB and hardware is secured by alternate means or removed from aircraft, and b) Procedures do not require its use.	
-03B	Mounting Device (Class 2)	C	-	0	(M) (O) May be inoperative provided: a) Associated EFB and hardware is secured by alternate means or removed from aircraft, and b) Alternate procedures are established and used.	

REVISION NO. 10

PAGE NO. 52-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

52. Doors

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Cabin Door Key Lock	D	1	0	May be inoperative in the unlocked position.	
-10-02	Cabin Door Seal (500/501, S550, 551, 550 units -0001 thru -0733)	C	1	0	(O) May be inoperative or sections missing provided: a) Door seal does not interfere with door operation, and b) Pressurization is considered inoperative.	
-10-03	Cabin Door Secondary Seal (550 units -0801 thru -1136, 560)					
-00A		C	1	0	(O) May be inoperative or sections missing provided: a) Secondary seal does not interfere with door operation, b) Primary seal is operative, and c) Flight is conducted at FL 250 or below.	
-00B		C	1	0	(O) May be inoperative or sections missing provided: a) Secondary door seal does not interfere with door operation, and b) Pressurization is considered inoperative.	

REVISION NO. 10

PAGE NO. 52-2

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

52. Doors

Sequence No.	Item	1	2	3	4	Change Bar
-10-04	Cabin Door Primary Seal (550 units -0801 thru 1136, 560)					
-00A		C	1	0	(O) May be inoperative or sections missing provided: a) Primary seal does not interfere with door operation, b) Secondary seal is operative, and c) Flight is conducted at FL 250 or below.	
-00B		C	1	0	(O) May be inoperative or sections missing provided: a) Primary door seal does not interfere with door operation, and b) Pressurization is considered inoperative.	
-30-01	Nose Baggage Door Gust Locks	C	-	0		
-30-02	Aft Baggage/Tailcone Door Key Lock	D	1	0	(O) May be inoperative in the unlocked position provided the door is verified closed and latched prior to each takeoff.	
-30-03	Nose Baggage Door Key Locks	C	2	1	One may be inoperative in the locked position provided preflight actions are performed through the unaffected side.	

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

52. Doors

Sequence No.	Item	1	2	3	4	Change Bar
-46-01 ***	Single Point Refueling Door Key Lock	D	1	0	(O) May be inoperative provided door is verified closed and latched.	
-60-01 ***	Entry Step Support Components					
-01	Rate Controllers	C	2	0	May be inoperative provided step is lowered with caution.	
-02	Cables/Chains	C	-	0	(O) May be inoperative provided: a) Cables/chains do not interfere with door operation, b) Alternate procedures are used for safe entry/egress.	
-70-01	Nose Baggage Doors Annunciator System (550 units -0801 thru 1136, 560 units -0260 thru -5000)				Moved to ATA 31 REV 10.	
-70-02	Aft Baggage or Tailcone Door Annunciator System (550 units -0801 thru -1136, 560 units -0260 thru -5000)				Moved to ATA 31 REV 10.	
-70-03	DOOR SEAL Amber Annunciator System (550 units -0801 thru -1136, 560)				Moved to ATA 31 REV 10.	
-70-04	Cabin Door Amber Annunciator System (550 units -0801 thru -1136, 560 units -0260 thru -5000)				Moved to ATA 31 REV 10.	

REVISION NO. 10

PAGE NO. 73-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

73. Engine Fuel and Control

Sequence No.	Item	1	2	3	4	Change Bar
-21-01	Engine Synchronizer System (550 units -0801 thru -1136, 560)	C	1	0		
-30-01	Fuel Flow Indicating System	B	2	1	One may be inoperative provided both fuel quantity indicating systems are operative.	

REVISION NO. 10

PAGE NO. 74-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

74. Ignition

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	Engine Igniter Lights/Annunciators (All except 560 units -0751 thru -5000)				Moved to ATA 31 Rev 10.	

REVISION NO. 9a

PAGE NO. 77-1

DATE: 02/13/2014

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

77. Engine Indicating

Sequence No.	Item	1	2	3	4	Change Bar
-14-01	N1 Indicators					
-01	N1 Digital Display (All except 550 and 560)	B	2	1	One may be inoperative provided: a) Corresponding N1 tape display is operative, and b) All other engine indicators on both engines are operative.	
-02	N1 Tape Display (All except 550 and 560)	B	2	1	One may be inoperative provided: a) Corresponding N1 digital display is operative, and b) All other engine indicators on both engines are operative.	
-22-01	ITT Indicating System Digital Function (All except 560 units -0751 thru -5000)	C	2	1	One may be inoperative provided both analog indicators are operative.	
-22-02	Standby Engine ITT Indicating System (560 units -0751 thru -5000)	C	2	1	One may be inoperative provided: a) Corresponding ITT indicator on the EICAS display is operating normally, b) Standby N1 and N2 indicators are operating normally, and c) All other engine indicators are operative.	

REVISION NO. 10

PAGE NO. 78-1

DATE: 01/03/2018

AIRCRAFT:
 Textron Aviation 500 Series

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

78. Engine Exhaust

Sequence No.	Item	1	2	3	4	Change Bar
-30-00 ***	Thrust Reverser	C	2	0	(M) May be inoperative provided affected reverser is disabled using the Maintenance Manual procedure.	