



U.S. Department of Transportation
Federal Aviation Administration
Washington, DC

Master Minimum Equipment List (MMEL)

Revision: 11
Date: 11/10/2020

Textron Aviation Model 650 (Citation CIII, CVI, CVII)

Jeffrey Rock, Chair
Flight Operations Evaluation Board (FOEB)

Federal Aviation Administration (FAA)
Small Aircraft Branch (MKC-AEG)
901 Locust Street, Department of Transportation Building
Kansas City, MO 64106

Telephone: (816) 329-3233
Fax: (816) 329-3241
Email: 9-AVS-AFS-100@faa.gov

REVISION NO. 11

PAGE NO. I

DATE: 11/10/2020

AIRCRAFT:

Textron Aviation Model 650

TABLE OF CONTENTS AND CONTROL PAGE

SYSTEM NO.	SYSTEM	PAGE NO.	REV NO.	DATE
--	Cover Page	--	11	11/10/2020
--	Table of Contents and Control Page	I	11	11/10/2020
--	Log of Revisions	II thru III	11	11/10/2020
--	Highlights of Change	IV thru IX	11	11/10/2020
--	Definitions and Preamble	X	11	11/10/2020
--	Guidelines for (M) and (O) Procedures	XI thru XVI	11	11/10/2020
21	Air Conditioning	21-1 thru 9	11	11/10/2020
22	Autoflight	22-1 thru 7	11	11/10/2020
23	Communications	23-1 thru 7	11	11/10/2020
24	Electrical Power	24-1 thru 2	11	11/10/2020
25	Equipment/Furnishings	25-1 thru 9	11	11/10/2020
26	Fire Protection	26-1	11	11/10/2020
27	Flight Controls	27-1	11	11/10/2020
28	Fuel	28-1 thru 3	11	11/10/2020
29	Hydraulic Power	29-1	11	11/10/2020
30	Ice and Rain Protection	30-1 thru 4	11	11/10/2020
31	Indicating/Recording Systems	31-1 thru 7	11	11/10/2020
32	Landing Gear	32-1	11	11/10/2020
33	Lights	33-1 thru 6	11	11/10/2020
34	Navigation	34-1 thru 16	11	11/10/2020
35	Oxygen	35-1 thru 2	11	11/10/2020
36	Pneumatic	36-1	11	11/10/2020
38	Water/Waste	38-1 thru 3	11	11/10/2020
46	Information Systems	46-1	11	11/10/2020
49	Airborne Auxiliary Power	49-1	11	11/10/2020
52	Doors	52-1 thru 3	11	11/10/2020
57	Wings	57-1	11	11/10/2020
73	Engine Fuel and Control	73-1	11	11/10/2020
76	Engine Control	76-1	11	11/10/2020
77	Engine Indicating	77-1	11	11/10/2020
78	Engine Exhaust	78-1	11	11/10/2020

REVISION NO. 11

PAGE NO. II

DATE: 11/10/2020

AIRCRAFT:

Textron Aviation Model 650

LOG OF REVISIONS

REV NO.	DATE	PAGE NO.
1	04/10/1987	All Pages.
2	04/15/1993	HIGHLIGHTS OF REV., DEFINITIONS, PREAMBLE, 21-1, 21-2, 21-3, 21-4, 21-5, 21-6, 21-7, 21-8, 21-9, 22-1, 23-1, 23-2, 24-1, 25-1, 25-2, 26-1, 26-2, 27-1, 27-2, 28-1, 28-2, 30-1, 30-2, 30-3, 30-4, 31-1, 31-2, 33-1, 33-2, 33-3, 33-4, 33-5, 34-1, 34-2, 34-3, 34-4, 34-5, 34-6, 34-7, 35-1, 49-1, 52-1, 73-1, 77-1, 78-1.
2a	11/30/1993	HIGHLIGHTS OF REV., DEFINITIONS, 21-1, 21-2, 21-3, 21-4, 21-5, 21-6, 21-7, 22-1, 23-1, 23-2, 24-1, 25-1, 25-2, 26-1, 26-2, 27-1, 28-1, 30-1, 30-2, 30-3, 30-4, 31-1, 33-1, 33-2, 33-3, 34-1, 34-2, 34-3, 34-4, 34-5, 34-6, 35-1, 49-1, 52-1, 73-1, 77-1, 78-1.
2b	07/19/1996	HIGHLIGHTS OF REV., DEFINITIONS, 32-1.
2c	10/25/1996	HIGHLIGHTS OF REV., DEFINITIONS, 21-2, 21-4, 21-5, 21-6, 23-1, 23-2, 25-2, 26-1, 26-2, 26-3, 28-1, 28-2, 30-1, 30-2, 33-1, 33-2, 33-3, 34-1, 34-2, 34-4, 34-5, 34-6.
2d	01/08/1998	HIGHLIGHTS OF REV., DEFINITIONS, 34-1, 34-2, 34-4, 34-5, 34-6.
3	10/04/1999	HIGHLIGHTS OF REV., DEFINITIONS, 21-7, 22-1, 27-2, 30-1, 33-1, 33-2, 33-3, 34-1, 34-3, 34-5, 34-6.
4	10/18/2001	HIGHLIGHTS OF REV., DEFINITIONS, 21-1, 21-2, 21-3, 21-4, 21-5, 21-6, 21-7, 21-8, 22-1, 22-2, 23-1, 23-2, 23-3, 23-4, 24-1, 25-1, 25-2, 25-3, 26-1, 26-2, 26-3, 27-1, 27-2, 28-1, 28-2, 30-1, 30-2, 30-3, 30-4, 30-5, 31-1, 32-1, 33-1, 33-2, 34-1, 34-2, 34-3, 34-4, 34-5, 34-6, 34-7, 34-8, 34-9, 35-1, 38-1, 38-2, 49-1, 52-1, 73-1, 77-1, 78-1.
4a	11/23/2001	HIGHLIGHTS OF REV., DEFINITIONS, 33-2.
4b	10/17/2002	HIGHLIGHTS OF REV., DEFINITIONS, 23-1, 23-2, 23-3, 23-4, 24-1, 27-2, 33-2, 33-3, 34-2, 34-3, 34-4, 34-5, 34-6, 34-7, 34-9, 38-1.
4c	10/25/2002	HIGHLIGHTS OF REV., DEFINITIONS, 23-1, 23-2, 23-3, 23-4.
5	05/28/2003	HIGHLIGHTS OF REV., DEFINITIONS, 21-5, 25-3, 30-5, 38-2.
6	05/29/2007	HIGHLIGHTS OF REV., DEFINITIONS, 21-1, 21-2, 21-5, 21-6, 22-1, 22-2, 23-1, 23-2, 23-3, 23-5, 25-1, 25-2, 25-3, 25-4, 25-5, 25-6, 25-7, 25-8, 26-1, 26-2, 28-1, 30-1, 31-1, 31-2, 33-1, 33-2, 34-1, 34-2, 34-3, 34-4, 34-5, 34-6, 34-7, 34-8, 34-9, 34-10, 34-11, 34-12, 34-13, 34-14, 34-15, 34-16, 34-17, 35-1, 38-1, 38-2, 46-1, 46-2, 49-1.
7	09/27/2007	HIGHLIGHTS OF CHANGE, 33-1.

REVISION NO. 11

PAGE NO. III

DATE: 11/10/2020

AIRCRAFT:

Textron Aviation Model 650

LOG OF REVISIONS

REV NO.	DATE	PAGE NO.
8	11/14/2008	COVER PAGE, TABLE OF CONTENTS, LOG OF REVISIONS, CONTROL PAGES, HIGHLIGHTS OF CHANGE, DEFINITIONS, GUIDELINES FOR (O) & (M) PROCEDURES, 21-1 thru 78-1.
9	10/18/2014	All Pages.
10	12/18/2019	HIGHLIGHTS OF CHANGE, DEFINITIONS & PREAMBLE, GUIDELINES FOR (M) & (O) PROCEDURES, 22-1, 23-1, 23-4 thru 5, 23-8, 25-3 and 4, 25-6 thru 10, 28-2, 30-4, 31-2, 32-1, 33-4 thru 6, 34-4 thru 9, 34-12 thru 16, 35-2, 38-1 and 2, 46-1.
11	11/10/2020	All Pages.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. IV

AIRCRAFT:
 Textron Aviation Model 650

HIGHLIGHTS OF CHANGE

The following changes are the Highlights of Changes for **Revision 11**.

PAGE NO.	EXPLANATION OF CHANGE
General	Minor editorial corrections were made throughout the document that do not affect the reliefs and are not indicated with change bars. These editorial corrections may be adopted in Minimum Equipment Lists (MEL) at the operator's discretion.
Throughout	All pages have been revised to update the Type Certificate Holder from Textron Aviation to Textron Aviation as published in FAA Type Certificate Data Sheet (TCDS) A9NM.
Throughout	The Textron Aviation Model 650 is known by the following marketing names: Citation C-III Citation C-VI Citation VII
Throughout	All instances of "14 CFR" have been replaced with "14 CFR operating rule".
ATA 21	Air Conditioning
-21-01	Renumbered.
-21-02	Renumbered.
-21-03	Renumbered.
-21-04	Renumbered.
-31-01	Renumbered.
-32-03	Removed names of sub-items.
-33-01	Removed reference in item.
-33-02	Renumbered.
-40-02	Renumbered.
-50-01	Renumbered.
-50-02	Renumbered.
-50-03	Renumbered. Removed names of sub-items. Removed reference in relief.
-60-01	Removed reference in item.
-62-01	Removed reference in item.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. V

AIRCRAFT:
 Textron Aviation Model 650

HIGHLIGHTS OF CHANGE

PAGE NO.	EXPLANATION OF CHANGE
ATA 22 Autoflight	
-10-01-00A thru -00B	Returned relief to AFM Limitation.
-13-01	Renumbered.
-13-01-15	Removed reference in item.
ATA 23 Communications	
-10-01-01	Removed reference in item.
-12-01-01	Renumbered.
-20-01	Renumbered all sub-items.
-20-02	Renumbered.
-40-02	Renumbered.
-40-03	Renumbered.
-50-01	Renumbered.
-50-02	Renumbered. Revised relief and all sub-items. "Flight Deck Headsets Earphones/Headphones and Boom Microphones" relief removed.
-50-03	Renumbered.
-50-03-01	NO. Installed changed from "-" to "2".
-50-03-02	Removed reference in item.
-50-04	Renumbered and merged with sub-item.
-50-05	Renumbered.
-70-01-00A thru -00B	Revised items and sub-items. Removed -70-01-00C.
ATA 24 Electrical Power	
-20-01	Removed references in item.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. VI

AIRCRAFT:
 Textron Aviation Model 650

HIGHLIGHTS OF CHANGE

PAGE NO.	EXPLANATION OF CHANGE
ATA 25 Equipment/Furnishings	
-10-02	Renumbered.
-10-03	Renumbered.
-10-04	Renumbered.
-10-05	Renumbered.
-20-02	Renumbered.
-20-03	Renumbered. Removed and revised Note(s).
-20-03-01A	Revised proviso.
-20-03-01B	Revised proviso.
-50-02-00A	Revised proviso.
-50-02-00B	Revised proviso.
-60-02	Renumbered. Revised proviso.
-62-01-02B	Renumbered.
-62-01-02C	Renumbered and revised item to be in proper compliance with Policy Letter.
-62-01-02D	Renumbered and revised item to be in proper compliance with Policy Letter.
-62-01-03	Renumbered.
-62-01-04	Renumbered.
-62-01-05	Renumbered.
ATA 26 Fire Protection	
-11-02	Renumbered.
-12-01	Removed reference.
-20-01	Renumbered and removed reference.
ATA 27 Flight Controls	
-50-01	Renumbered.
-60-01	Renumbered.

REVISION NO. 11

PAGE NO. VII

DATE: 11/10/2020

AIRCRAFT:

Textron Aviation Model 650

HIGHLIGHTS OF CHANGE

PAGE NO.	EXPLANATION OF CHANGE
ATA 28 Fuel	
-10-03	Renumbered.
-41-02	Amended proviso item i).
-41-02-02	Removed reference.
ATA 29 Hydraulic Power	
-20-01	Removed reference.
ATA 30 Ice and Rain Protection	
-10-01	Renumbered.
-10-02	Renumbered.
-10-03	Renumbered.
-30-01	Renumbered.
-30-02	Renumbered.
-30-03	Renumbered.
-40-04	Renumbered.
ATA 31 Indicating/Recording Systems	
-20-03	Renumbered.
-30-01	Renumbered.
-30-02	Renumbered.
-50-01	Renumbered all sub-items and references.
-50-04	Combined item and sub-item into one.
ATA 32 Landing Gear	
-41-01	Removed (O) as AFM provided required information. Combined item and first sub-item, deleted second sub-item.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. VIII

AIRCRAFT:
 Textron Aviation Model 650

HIGHLIGHTS OF CHANGE

PAGE NO.	EXPLANATION OF CHANGE
ATA 33 Lights	
-10-04	Renumbered.
-20-01	Renumbered.
-20-02	Renumbered.
-30-02	Renumbered.
-40-04	Renumbered.
-40-05	Renumbered.
-40-06	Renumbered.
-40-07	Renumbered and removed all sub-item titles.
-40-08	Renumbered and split into two sub-items.
-50-02	Renumbered.
ATA 34 Navigation	
-24-01	Renumbered.
-25-01	Renumbered and removed reference.
-25-02	Renumbered.
-25-03	Renumbered.
-25-04	Renumbered and removed original relief for "MFD".
-31-01	Removed reference.
-44-01	Combined with sub-item.
-44-02	Renumbered item and sub-items. Combined some sub-items and removed others.
-44-03	Renumbered. Sub-items -05 through -08B deleted.
-52-02	Renumbered.
-52-03	Renumbered all and adjusted sub-items.
-60-03 thru -08	Added Relief for Universal InSight STC ST02654LA.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. IX

AIRCRAFT:
 Textron Aviation Model 650

HIGHLIGHTS OF CHANGE

PAGE NO.	EXPLANATION OF CHANGE
ATA 35 Oxygen	
-00-01	Renumbered.
-20-01-00C	Removed reference.
ATA 36 Pneumatic	
-10-01-02	Removed reference.
ATA 38 Water/Waste	
-10-01	Reordered item and sub-item content. Added name to sub-item -01 and changed NO. Required for Dispatch to "0".
-30-02	Renumbered sub-items -05 and -06.
-30-03	Modified item.
-30-04	Removed references.
ATA 49 Airborne Auxiliary Power	
-50-01	Renumbered.
ATA 52 Doors	
-10-01	Renumbered sub-items and removed references.
-30-01-02	Renumbered.
-70-01	Renumbered sub-items.

REVISION NO. 11

PAGE NO. X

DATE: 11/10/2020

AIRCRAFT:

Textron Aviation Model 650

DEFINITIONS AND PREAMBLE

DEFINITIONS

Refer to the current FAA MMEL Policy Letter 25, MMEL and MEL Definitions, found on the FAA Flight Standards Information Management System (FSIMS) website.

PREAMBLE

For operations under 14 CFR operating rule parts 91 subpart K (part 91K), 121, 125, 125 LODA, 129, and 135, refer to the current FAA MMEL Policy Letter PL-34, MMEL and MEL Preamble. For operations under 14 CFR operating rule part 91, refer to current FAA MMEL Policy Letter PL-36, 14 CFR operating rule Part 91 MEL Approval and Preamble. Both Policy Letters are found on the FAA Flight Standards Information Management System (FSIMS) website.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. XI

AIRCRAFT:
 Textron Aviation Model 650

GUIDELINES FOR (M) AND (O) PROCEDURES

The FOEB has identified a need for certain procedures to provide an adequate level of safety while providing relief for some items. These procedures must be established by the operator and may be based on the aircraft manufacturer's recommended procedures, Supplemental Type Certificate modifier's recommended procedures, or equivalent operator procedures. When recommended procedures are published the operator should comply with these procedures. If recommended procedures are not published, the following guidelines delineate the aspects to be considered by the operator in the development of required procedures.

SEQUENCE NO.	PROCEDURE
ATA 21	Air Conditioning
-30-01	(M) Procedure to remove outflow valve.
-30-02-00A	(O) Procedure to configure the aircraft for unpressurized flight.
-30-02-00B	(M) Procedures to deactivate emergency pressurization. (O) Procedure to configure aircraft for unpressurized flight.
-32-01-00A	(O) Procedure to develop a chart to convert differential pressure and aircraft altitude to cabin altitude.
-32-02-00A	(O) Procedure to develop a chart to convert cabin and aircraft altitude to differential pressure.
-33-01	(M) Procedure to remove outflow valve.
-33-02	(O) Procedure to verify isolation valve is closed.
-40-01	(M) Procedure to deactivate baggage heat system.
-50-01	(M) Procedure to deactivate air conditioning system.
-50-02-01	(M) Procedure to deactivate forward evaporator fan.
-50-02-02	(M) Procedure to deactivate aft evaporator fan.
ATA 22	Autoflight
-10-01-00A	(O) Procedure to disconnect nose wheel steering for ground operations.
-10-03 (all)	(M) Procedure to deactivate autopilot system.
-10-05	(M) Procedure to deactivate yaw damp system.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. XII

AIRCRAFT:
 Textron Aviation Model 650

GUIDELINES FOR (M) AND (O) PROCEDURES

SEQUENCE NO.	PROCEDURE
ATA 23	Communications
-10-01-00B	(O) Procedure for operator to develop alternate procedures for operations requiring dual LRCS communications.
-10-01-01	(M) Procedure to remove antenna.
-20-01-01B	(O) Procedure for operators to obtain alternate weather information.
-20-02-00B	(O) Procedure for operators to develop alternate methods of communications for required SELCAL.
-40-03	(O) Procedure to brief cabin occupants to fasten seat belts.
-50-03-03	(O) Procedure to secure the affected hand-held microphone.
-50-04	(O) Procedure to develop alternate transmitting method.
-50-05	(O) Procedure to verify COM 1 is operative.
ATA 24	Electrical Power
-32-01	(M) Procedure to disconnect affected battery and secure connector.
ATA 25	Equipment/Furnishings
-00-01	(O) Procedure to display required documents.
-10-03-01B	(M) Procedure to remove affected armrest.
-10-03-03 & -06	(M) Procedure to secure affected seat in a position acceptable to the flightcrew member. (O) Procedure for the affected flightcrew member to verify the secured seat position allows for full flight control movement and control/equipment manipulation with seat restraint engaged.
-10-04	(O) Procedure for flightcrew to verify all controls are visible and each crewmember has adequate forward visibility.
-20-03-02A	(M) Procedure to secure affected seat in the taxi, takeoff, and landing position.
-40-02	(M) Procedure to deactivate aft vanity heater.
-50-01-01B	(M) Procedure to inspect affected area for damage.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. XIII

AIRCRAFT:
 Textron Aviation Model 650

GUIDELINES FOR (M) AND (O) PROCEDURES

SEQUENCE NO.	PROCEDURE
-50-02-00A	(M) Procedure to secure the affected location closed.
-50-02-00B	(M) Procedure to remove affected door.
-50-02-01	(O) Procedure to brief cabin occupants of relocated equipment or items.
-62-01-02A	(M) Procedure to deactivate ELT.
-62-01-02B	(M) Procedure to secure lose connectors.
-62-01-02C	(M) Procedure to deactivate ELT.
-62-01-03	(M) Procedure to deactivate switch.
ATA 27 Flight Controls	
-20-01	(M) Procedure to position affected rudder pedal with unaffected and secure. (O) Procedure for flightcrew member to verify secured rudder pedals allow for adequate movement and braking while restrained.
-60-01	(O) Procedure to verify speed brake actuation prior to flight.
-70-01	(O) Procedure to verify full flight control and throttle movement.
ATA 28 Fuel	
-10-03	(M) Procedure to verify fuselage fuel tank is empty.
-41-01	(O) Procedure to monitor fuel quantity.
-41-02	(O) Procedure to plan fuel requirements for mission using guidance provided in proviso.
ATA 29 Hydraulic Power	
-30-01	(M) Procedure to verify hydraulic fluid quantity prior to flight.
ATA 30 Ice and Rain Protection	
-10-01	(M) Procedure to deactivate horizontal stabilizer electric anti-ice system.
-10-02	(M) Procedure to secure wing bleed air valves for no-flow.
-10-03	(M) Procedure to deactivate affected wing cuff.
-20-01	(M) Procedure to secure affected valve for no-flow.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. XIV

AIRCRAFT:
 Textron Aviation Model 650

GUIDELINES FOR (M) AND (O) PROCEDURES

SEQUENCE NO.	PROCEDURE
-40-02	(M) Procedure to deactivate windshield anti-ice system.
-40-03	(M) Procedure to deactivate windshield de-ice system.
-70-01	(M) Procedure to deactivate heater system.
ATA 31 Indicating/Recording Systems	
-20-01	(O) Procedure to track APU times.
-20-03	(O) Procedure to track aircraft operating times.
-50-01-07	(O) Procedure to monitor PAC temperatures.
-50-01-08	(O) Procedure to monitor PAC temperatures.
-50-01-12	(O) Procedure to monitor generator voltage and amperage.
ATA 33 Lights	
-10-04-00A	(O) Procedure to monitor ice accretion in flight.
-20-01 (all)	(O) Procedure to verify cabin emergency lighting operation.
-20-02-00A	(O) Procedure to notify cabin occupants on interior signage.
-40-03-02	(M) Procedure to deactivate pulse light system. (O) Procedure to verify at least one landing light is operative for night operations.
-40-05-01	(M) Procedure to deactivate pulse light system. (O) Procedure to verify landing lights are operative for night operations.
ATA 34 Navigation	
-16-01	(O) Procedure to plan for non-RVSM flight.
-36-01	(O) Procedure to address windshear concerns.
-44-01	(M) Procedure to deactivate radio altimeter.
-44-02-01	(O) Procedure for GPWS awareness.
-44-02-02	(O) Procedure for flightcrew to address inoperative callout(s).

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. XV

AIRCRAFT:
 Textron Aviation Model 650

GUIDELINES FOR (M) AND (O) PROCEDURES

SEQUENCE NO.	PROCEDURE
-44-02-05-0A	(O) Procedure for flightcrew to address inoperative callout(s).
-44-02-05-00B	(O) Procedure for flightcrew to address inoperative callout(s).
-44-02-05-00C	(O) Procedure for flightcrew to address inoperative callout(s).
-44-02-06	(O) Procedure for flightcrew to address inoperative callout(s).
-44-03-01	(O) Procedure for GPWS awareness.
-44-03-01-00A	(O) Procedure for flightcrew to address inoperative callout(s).
-44-03-01-00D	(O) Procedure for flightcrew to address inoperative callout(s).
-44-03-01-00D	(O) Procedure for flightcrew to address inoperative callout(s).
-44-03-01-00E	(O) Procedure for flightcrew to address inoperative callout(s).
-45-01-00A	(M) Procedure to deactivate system.
-45-01-00B	(M) Procedure to deactivate system.
-45-01-01	(O) Procedure to monitor display.
-45-01-02B	(O) Procedure to monitor display.
-52-03 (all)	(O) Procedure to coordinate with ATC prior to flight.
ATA 35 Oxygen	
-00-01-01	(M) Procedure to service oxygen bottles by alternate method.
-20-01-01	(M) Procedure to make sure the pintle pin is installed prior to flight.
-20-01-02	(M) Procedure to make sure the pintle pin is installed prior to flight.
ATA 38 Water/Waste	
-10-01	(M) Procedure to drain the system and make sure it is not re-serviced.
-10-01-01	(M) Procedure to deactivate system and inspect for leaks.
-30-01	(M) Procedure to clear tube from all liquids.
-30-02	(M) Procedure to deactivate system and inspect for leaks.

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. XVI

AIRCRAFT:
 Textron Aviation Model 650

GUIDELINES FOR (M) AND (O) PROCEDURES

SEQUENCE NO.	PROCEDURE
-30-02-04	(O) Procedure to service toilet by alternate method.
-30-02-05	(M) Procedure to drain system of all liquids and deactivate heater.
-30-02-06	(O) Procedure to service toilet by alternate method.
-30-04-01	(O) Procedure to remove all liquid from basin.
-30-04-03	(O) Procedure to remove all liquid from storage area and drip pan.
ATA 46 Information Systems	
-00-01-00A	(O) Procedure to develop alternate methods to access operational data.
-00-01-01A	(O) Procedure to develop alternate methods to access operational data.
-00-01-02A	(O) Procedure to make sure EFB has adequate power or have alternate access to operational data.
-00-01-03A	(M) Procedure to stow and secure mounting system. (O) Procedure to secure EFB for use.
-00-01-03B	(M) Procedure to stow and secure mounting system.
ATA 49 Airborne Auxiliary Power	
-20-01	(M) Procedure to deactivate APU.
-50-01	(O) Procedure to verify APU bleed air valve is closed.
ATA 52 Doors	
10-01-05	(O) Procedure to assist passengers during entry/exit to prevent falling.
-70-01-03	(O) Procedure to verify all door locks flags are visible through sight glass and internal door handle is stowed prior to aircraft operation.
ATA 78 Engine Exhaust	
-30-01	(M) Procedure to deactivate affected thrust reverser prior to flight.

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Cabin Overhead Air Outlet	C	-	0		
-20-02	Cockpit Overhead Air Outlet	C	2	0		
-20-01	Cockpit Torso Air Outlet	C	2	0		
-21-01	Cabin Recirculation Fan (WEMAC Boost) (Units -0001 thru -0104 Incorporating SB650-21-22 and Units -0105 and on)	C	1	0		
-21-02	Defog Fan (Units -0001 thru -0241)	C	1	0	May be inoperative provided: a) Auxiliary heater is operative, b) Both PACs are operative, and c) A means to clear windshield of moisture is readily available.	
-21-03	Defog Fan (Units -7001 thru -7119)	C	1	0	May be inoperative provided windshield electric anti-ice system is operative.	
-21-04	Hydraulic Fan (Units -0001 thru -0104)	C	1	0	May be inoperative provided: a) Both CKPT PAC and CAB PAC selectors remain in OFF position for all ground operations including takeoff and landing roll, and b) Auxiliary heater is operative.	
-30-01	Cabin Dump Function	C	1	0	(M) May be inoperative provided: a) One outflow valve is removed, and b) Cabin pressurization system is considered inoperative.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-30-02	Cabin Pressurization System					
-00A		C	1	0	(O) May be inoperative provided: <ol style="list-style-type: none"> a) PRESSURIZATION NORM/MANUAL switch is selected to MANUAL, b) CABIN DUMP is selected ON, c) Aircraft is operated at 13,000 ft. cabin altitude or below, and d) Flightcrew oxygen system is used as required by 14 CFR operating rule. NOTE: The amber CABIN ALT 8500 FT annunciator may illuminate at 8,500 ft. cabin altitude. Cabin altitude warning horn may sound at 10,000 ft. cabin altitude.	
-00B		C	1	0	(M)(O) May be inoperative provided: <ol style="list-style-type: none"> a) PRESSURIZATION NORM/MANUAL switch is selected to MANUAL, b) Emergency pressurization system is deactivated, c) CABIN DUMP is selected ON, d) PASS OXY is selected OFF, e) No cabin occupants are carried, f) Aircraft is operated at FL 250 or below, and g) Flightcrew oxygen system is used as required by 14 CFR operating rule. NOTE: The amber CABIN ALT 8500 FT annunciator may illuminate at 8,500 ft. cabin altitude. Cabin altitude warning horn may sound at 10,000 ft. cabin altitude.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-30-03	Emergency Pressurization System (Failed Closed)	C	2	0	(O) May be inoperative provided: a) Emergency pressurization valve is verified closed, and b) Aircraft is operated at FL 250 or below.	
-31-01	Cabin Pressurization System Mode					
-01	Automatic Schedule Mode (AUTO SCHED)	C	1	0	May be inoperative provided: a) Altitude select mode is operative, b) PRESSURIZATION AUTO SCHED/ALTITUDE SELECT switch is selected to ALTITUDE SELECT, c) Cabin differential pressure gauge/indication is operative, d) Cabin altitude gauge/indication is operative, e) Cabin vertical speed gauge/indication is operative, and f) Aircraft is operated at FL 410 or below.	
(Continued)						

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-31-01	Cabin Pressurization System Mode Continued					
-02	Altitude Select Mode (ALTITUDE SELECT)	C	1	0	May be inoperative provided: a) Automatic schedule mode is operative, b) PRESSURIZATION AUTO SCHED/ALTITUDE SELECT switch is selected to AUTO SCHED, c) Cabin differential pressure gauge/indication is operative, d) Cabin altitude gauge/indication is operative, e) Cabin vertical speed gauge/indication is operative, and f) Aircraft is operated at FL 410 or below.	
-03	Any Mode (Excluding Manual)	C	2	0	May be inoperative provided: a) Autopilot system is operative, b) PRESSURIZATION NORM/MAN switch is selected to MAN, and c) Aircraft is operated using manual pressurization.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-32-01	Cabin Altitude Gauge/Indication					
-00A		C	1	0	(O) May be inoperative provided: a) Cabin pressurization system automatic schedule mode is operative and used, b) Cabin differential pressure gauge/indication is operative, and c) A chart is provided to convert differential pressure and aircraft altitude to cabin altitude.	
-00B		C	1	0	May be inoperative provided cabin pressurization system is considered inoperative.	
-01	Gauge Lighting	C	1	0	May be inoperative provided flightcrew determines adequate natural or artificial lighting exists to read gauge.	
-32-02	Cabin Differential Pressure Gauge/Indication					
-00A		C	1	0	(O) May be inoperative provided: a) Cabin pressurization system automatic schedule mode is operative and used, b) Cabin altitude gauge/indication is operative, and c) A chart is provided to convert cabin and aircraft altitude to differential pressure.	
-00B		C	1	0	May be inoperative provided cabin pressurization system is considered inoperative.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-32-03	Cabin Vertical Speed Gauge/Indication					
-00A		C	1	0	May be inoperative provided: a) Cabin pressurization system automatic schedule mode is operative and used, and b) Cabin altitude gauge/indication is operative.	
-00B		C	1	0	May be inoperative provided cabin pressurization system is considered inoperative.	
-01	Gauge Lighting	C	1	0	May be inoperative provided flightcrew determines adequate natural or artificial lighting exists to read gauge.	
-33-01	Cabin Outflow Valve	C	2	0	(M) May be inoperative provided: a) One outflow valve is removed, and b) Cabin pressurization system is considered inoperative.	
-33-02	PAC Isolation Valve	C	1	0	(O) May be inoperative provided: a) Isolation valve is verified closed, and b) Both PACs are operative.	
-40-01	Baggage Heat System (Fan or Heater Element) (Units -0001 thru -0241)	C	1	0	(M) May be inoperative provided system is deactivated.	
-40-01 ***	Baggage Heat System (Fan or Heater Element) (Units -7001 thru -7119)	C	1	0	(M) May be inoperative provided system is deactivated.	
-40-02	Auxiliary Heater (Cockpit) (Units -0001 thru -0241)	C	1	0	May be inoperative provided: a) Defog fan is operative, and b) Both PACs are operative.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-50-01 ***	Vapor-Cycle Air Conditioning System	C	1	0	(M) May be inoperative provided air conditioning system is deactivated.	
-50-02 ***	Evaporator Fan					
-01	Forward	C	1	0	(M) May be inoperative provided: a) Aft evaporator fan is operative, and b) Forward evaporator fan is deactivated.	
-02	Aft	C	1	0	(M) May be inoperative provided: a) Forward evaporator fan is operative, and b) Aft evaporator fan is deactivated.	
-50-03	Pressurization Air Conditioning (PAC) System					
-00A		C	2	1	One may be inoperative provided: a) Affected PAC is selected OFF, and b) Aircraft is operated at FL 410 or below.	
-00B		C	2	0	May be inoperative provided cabin pressurization system is considered inoperative.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-50-03	Pressurization Air Conditioning (PAC) System (Cont'd)					
-01	Bi-Level Flow Control Valve	C	2	1	One may be inoperative provided: a) Associated ENG BLD AIR is selected OFF, b) ISOL VALVE is selected to SHUT, c) APU BLEED VALVE is selected to CLOSE, d) Affected PAC is considered inoperative, e) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and f) Aircraft is operated at FL 410 or below.	
-60-01	Cockpit and Cabin Temperature Control System	C	4	0	May be inoperative provided cabin pressurization system is considered inoperative.	
-01	Automatic Mode	C	2	0	May be inoperative provided associated temperature control system manual mode is used.	
-02	Manual Mode	C	2	0	May be inoperative provided associated temperature control system automatic mode is used.	
-61-01 ***	Cabin Temperature Remote Control	D	1	0	May be inoperative provided CABIN TEMP CTL is selected to NORM.	

REVISION NO. 11

PAGE NO. 21-9

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
-62-01	Temperature Indication System					
-01	Cabin	C	1	0		
-02	Cockpit	C	1	0		
-03	Supply Duct	C	2	1	One may be inoperative provided: a) Associated air temperature control system automatic mode is considered inoperative, and b) Associated duct overheat amber annunciator is monitored during temperature adjustment.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Autopilot Disconnect Button (AP/TRIM/NWS DISC) (Failed Deselected)					
-00A	Left Control Wheel	C	1	0	(O) May be inoperative provided: a) Right control wheel button is operative, b) Alternate procedures for disconnecting nose wheel steering during ground operations are established and used, c) A pilot remains seated in right seat with seat belt fastened during all autopilot operations, d) Autopilot system is not used below AFM cruise minimum use height, and e) Approach minimums do not require use of autopilot system.	
-00B	Right Control Wheel	C	1	0	May be inoperative provided: a) Left control wheel button is operative, b) A pilot remains seated in left seat with seat belt fastened during all autopilot operations, c) Autopilot system is not used below AFM cruise minimum use height, and d) Approach minimums do not require use of autopilot system.	
-10-02	Autopilot Interrupt/Flight Director Sync Button (TCS)	C	2	0		

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-10-03	Autopilot System (Single Channel Autopilot-Equipped Aircraft)	B	1	0	(M) May be inoperative provided: a) Autopilot system is deactivated, b) Enroute procedures and approach minimums do not require use of autopilot system, c) Cabin pressurization system is not operated in manual mode, and d) Aircraft is not operated RVSM.	
-10-03	Autopilot System (Dual Channel Autopilot-Equipped Aircraft)					
-00A		C	2	1	(M) One may be inoperative provided associated autopilot channel is deactivated.	
-00B		B	2	0	(M) May be inoperative provided: a) Autopilot system is deactivated, b) Enroute procedures and approach minimums do not require use of autopilot system, c) Cabin pressurization system is not operated in manual mode, and d) Aircraft is not operated RVSM.	
-10-04	Takeoff/Go-Around Button (GA)					
-00A		C	2	1	One may be inoperative.	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-10-04	Takeoff/Go-Around Button(GA) (Cont'd)					
-00B		C	2	0	May be inoperative provided: a) Flight director is not used during takeoff or go-around, b) Autopilot system is disconnected for go-around, and c) Autopilot interrupt/flight director sync button is operative on pilot-flying side. NOTE: FMS missed approach procedure must be manually advanced.	
-10-05	Yaw Damper	B	1	0	(M) May be inoperative provided: a) Yaw damper is deactivated, and b) Autopilot system is considered inoperative.	
-13-01	Flight Guidance Controller Annunciator (MS-500A) (Failed to Illuminate)					
-13-01	Flight Guidance Controller Annunciator (GC-810) (Failed to Illuminate)					
-01	Altitude (ALT Button)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-13-01	Flight Guidance Controller Annunciator (GC-810) (Failed to Illuminate) (Cont'd)					
-02	Altitude Select (ALTSEL Button) (MS-500A-Equipped Aircraft)	C	2	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-03	Approach (APP Button) (GC-810-Equipped Aircraft)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box.	
-03	Approach (APP Button) (MS-500A-Equipped Aircraft)	C	2	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-04	Autopilot (AP Button - A or B Annunciation) (GC-810-Equipped Aircraft)	C	2	0	May be inoperative provided AP ENG annunciation appears in EADI flight director mode box.	
-05	Back Course (BC Button) (GC-810-eEquipped Aircraft)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box.	
(Continued)						

REVISION NO. 11

PAGE NO. 22-5

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-13-01	Flight Guidance Controller Annunciator (GC-810) (Failed to Illuminate) (Cont'd)					
-05	Back Course (BC Button) (MS-500A-Equipped Aircraft)	C	2	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-06	IAS/Mach Change-Over (C/O Button) (GC-810-Equipped Aircraft)	D	1	0		
-07	Coupled Side (HSI Button - Left or Right Arrow) (GC-810-Equipped Aircraft)	C	2	1	One may be inoperative provided operative arrow points to pilot-flying side.	
-08	Flight Director (FD OFF Button) (MS-500A-Equipped Aircraft)	C	1	0	May be inoperative provided associated command bars appear on EADI display (EFIS-equipped) or ADI (non EFIS-equipped).	
-09	Flight Level Change (IAS or MACH Button) (MS-500A-Equipped Aircraft)	C	2	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-09	Flight Level Change (FLC Button) (GC-810-Equipped Aircraft)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box.	
(Continued)						

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-13-01	Flight Guidance Controller Annunciator (GC-810) (Failed to Illuminate) (Cont'd)					
-10	Half Bank (BANK Button) (GC-810-Equipped Aircraft)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box.	
-11	Heading (HDG Button)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-12	Navigation (NAV Button) (GC-810-Equipped Aircraft)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box.	
-12	Navigation (NAV Button) (MS-500A-Equipped Aircraft)	C	2	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-13	Vertical Navigation (VNAV Button) (MS-500A-Equipped Aircraft)	C	2	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-13	Vertical Navigation (VNAV Button) (GC-810-Equipped Aircraft)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box.	
(Continued)						

REVISION NO. 11

PAGE NO. 22-7

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
-13-01	Flight Guidance Controller Annunciator (GC-810) (Failed to Illuminate) (Cont'd)					
-14	Vertical Speed (VS Button)	C	1	0	May be inoperative provided appropriate annunciation appears in EADI flight director mode box (EFIS-equipped) or on mode annunciation panel (non EFIS-equipped).	
-15	Yaw Damper (YD Button - A or B Annunciation) (GC-810-Equipped Aircraft)	B	2	0	May be inoperative provided yaw damper is considered inoperative.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Flight Phone/SATCOM System	D	-	0	May be inoperative provided procedures do not require its use.	
-01	Cockpit Handset	D	-	0	May be inoperative provided procedures do not require its use.	
-02	Cabin Handset	D	-	0		
-10-01 ***	High Frequency (HF) Communication System					
-00A	(Dual LRCS Not Required)	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative.	
-00B	(Dual LRCS Required)	C	-	1	(O) May be inoperative while conducting operations that require two LRCS provided: <ol style="list-style-type: none"> a) Aircraft SATVOICE system operates normally, b) SATVOICE services are available as a LRCS over the intended route of flight, c) The ICAO Flight Plan is updated (as required) to notify ATC of the communications equipment status of the aircraft, and d) Alternate procedures are established and used. 	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-10-01 ***	High Frequency (HF) Communication System Continued					
-01	Wire Antenna	C	1	0	(M) May be inoperative, missing, or damaged provided: a) Horizontal and vertical stabilizers are inspected for damage, b) Any remaining portion of wire antenna is removed, and c) HF communication system is considered inoperative.	
-11-01 ***	Ultra High Frequency (UHF) Communication System (Units -7001 thru -7119)	D	-	0	May be inoperative provided procedures do not require its use.	
-12-01	Very High Frequency (VHF) Communication System	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative provided: a) Affected system is not on an emergency bus, and b) Procedures do not require its use.	
-01 ***	Airborne Flight Information System (AFIS) (VHF AFIS-Equipped Sircraft)	D	1	0	May be inoperative provided procedures do not require its use.	
-20-01 ***	Satellite Data Link Service					
-01A	Weather	D	-	0	May be inoperative provided procedures do not require its use. NOTE: Any function(s) that operate normally may be used.	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-20-01 ***	Satellite Data Link Service Continued					
-01B	Weather	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-02	Internet	D	-	0		
-03 ***	Airborne Flight Information System (AFIS) (SAT AFIS-Equipped Aircraft)	D	1	0	May be inoperative provided procedures do not require its use.	
-20-02 ***	Selective Call (SELCAL) (System or Individual Channel)					
-00A	(SELCAL Not Required)	D	-	0	May be inoperative provided procedures do not require its use.	
-00B	(SELCAL Required)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-40-01 ***	Automatic Cabin Briefer	D	1	0		
-40-02	Passenger Address (PA) System	D	1	0		
-40-03	Passenger Seat Belt/Safety Chime	C	1	0	(O) May be inoperative provided: a) Passenger address system is operative, and b) Cabin occupants are briefed by alternate means.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-50-01	Cockpit Overhead Communication Speaker	C	2	1	One may be inoperative provided: a) Affected speaker is not required for procedures, and b) A headset is used for associated inoperative speaker.	
-50-02	Cockpit Headset and Boom Microphone	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative.	
-01A	Boom Microphone (For a holder of an Air Carrier or Commercial Operator Certificate)	A	-	0	May be inoperative provided: a) Associated hand microphone is installed and operative, and b) Repairs are made within 3 flight-days.	
-01B	Boom Microphone (For an operator other than a holder of an Air Carrier or Commercial Operator Certificate)	A	-	0	May be inoperative provided: a) Associated hand microphone is installed and operative, and b) Repairs are made in accordance with 14 CFR operating rule.	
-02	Headset Earphones/ Headphones	C	-	1	May be inoperative provided associated cockpit overhead communication speaker is operative.	
-03 ***	Active Noise Reduction (ANR) Function	D	-	0	May be inoperative provided normal audio function of headset is operative.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-50-03	Flight Deck Hand Microphones	D	2	-	Any in excess of those required by 14 CFR operating rule may be inoperative.	
-01		C	2	0	May be inoperative provided associated boom microphone is operative.	
-02	Jack	C	-	0	May be inoperative provided associated hand microphone is considered inoperative.	
-03	Holder	D	-	0	(O) May be inoperative provided associated hand microphone is secured by alternate means.	
-50-04	Push-to-talk (PTT) Switch (Failed Deselected) Yoke Switch	B	2	1	(O) One may be inoperative provided alternate procedures are established and used for transmitting.	
-50-05 ***	Radio Management Unit (RMU) (Primus II-Equipped Aircraft)	C	2	1	(O) One may be inoperative provided: a) Standby radio control unit is verified operative, and b) COM 1 is verified operative.	
-60-01	Static Wick				NOTE: May include mounting base provided no damage exists to attaching structure.	
-01	Aileron (Each Side)	C	2	1	One may be damaged or missing provided outermost wick is installed and not damaged.	
-02	Wing Tip Assembly (Each Side)	C	2	1	One may be damaged or missing provided outermost wick is installed and not damaged. NOTE: Wing tip assembly is entire removable section outboard of fuel closure rib.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-60-01	Static Wick (Cont'd)					
-04	Wing Trailing Edge (Each Side)	C	2	1	One may be damaged or missing provided outermost wick is installed and not damaged. NOTE: Wing trailing edge is area between aileron and wing tip assembly.	
-05	Elevator (Each Side)	-	1	1	NOTE: This static wick is required. Relief should not be taken under another installation area.	
-06	Horizontal Stabilizer Trailing Edge (Each Side)	C	2	1	One may be damaged or missing provided outermost wick is installed and not damaged.	
-07	Vertical Stabilizer	C	2	1	One may be damaged or missing provided uppermost wick is installed and not damaged.	
-08	Rudder	C	2	1	One may be damaged or missing provided uppermost wick is installed and not damaged.	
-09	Stinger	-	1	1	NOTE: This static wick is required. Relief should not be taken under another installation area.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
-70-01	Cockpit Voice Recorder (CVR) with Flight Data Recorder (FDR) Installed					
-00A	(Holder of an Air Carrier or Commercial Operator Certificate)	A	1	0	May be inoperative provided: a) Any Flight Data Recorder (FDR) required to be installed is operative, and b) Repairs are made within 3 flight-days.	
-00B	(Operator other than a holder of an Air Carrier or Commercial Operator Certificate)	A	1	0	May be inoperative provided repairs are made in accordance with applicable 14 CFR operating rule.	
-01 ***	Recorder Independent Power Supply (RIPS)	C	1	0		
-02	Underwater Locator Device (ULD)	D	1	0	May be inoperative provided device is not required by 14 CFR operating rule.	
-03A	Data Link Recording	C	1	0	May be inoperative provided data link recording is not required by 14 CFR operating rule.	
-03B	Data Link Recording	A	1	0	May be inoperative provided repairs are made within 3 flight-days.	

<p>AIRCRAFT: Textron Aviation Model 650</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

24. Electrical Power

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Engine AC Generating System (Units -7001 thru -7119)	C	2	1	One may be inoperative provided: a) Affected windshield electric anti-ice system is considered inoperative, and b) Affected horizontal stabilizer anti-ice system is considered inoperative.	
-22-01	AC Inverter (Units -0001 thru -0178, -0200 thru -0202, and -0207 thru -0241)	B	2	1	One may be inoperative provided: a) Aircraft is not operated at night, and b) Aircraft is not operated IFR.	
-22-01	AC Inverter (Units -0179 thru -0199, -0203 thru -0206, and -7001 thru -7119)	B	2	1	One may be inoperative provided: a) AVIONICS POWER XOVER is selected to appropriate position, b) Aircraft is not operated at night, and c) Aircraft is not operated IFR.	
-25-01	AC Amperage Gauge/Indication	C	2	0	May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-25-02	AC Voltage Gauge/Indication	C	1	0	May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-01	Inverter Select Switch (LH ALT-RH ALT)	C	1	0	May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-30-01	APU DC Generating System (APU-Equipped Aircraft)	C	1	0	May be inoperative provided APU SYSTEM GENERATOR is selected OFF.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

24. Electrical Power

Sequence No.	Item	1	2	3	4	Change Bar
-30-02	Engine DC Generating System (APU-Equipped Aircraft)	A	2	1	One may be inoperative provided: a) Associated GEN switch is selected OFF, b) APU DC generating system is used throughout flight, c) Aircraft is operated at FL 300 or below, and d) Repairs are made within 3 flight-days. NOTE: GEN OFF L or R amber annunciator may illuminate.	
-31-02 ***	Battery Temperature Indicator	C	1	0		
-32-01	Main Battery (Dual 40 or 44 Amp Battery-Equipped Aircraft)	B	2	1	(M) One may be inoperative provided affected battery is disconnected and connector is secured.	
-37-01	APU DC Amperage Gauge/Indication (APU-Equipped Aircraft)	C	1	0	May be inoperative provided APU SYSTEM GENERATOR is selected OFF.	
-40-01	External Power System	D	1	0		
-50-01 ***	AC Cockpit Outlet	D	-	0	May be inoperative provided procedures do not require its use.	
-60-01 ***	DC Cockpit Outlet	D	-	0	May be inoperative provided procedures do not require its use.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	Required Documents Holder (Airworthiness Certificate, Registration, etc.)	D	1	0	(O) May be inoperative or missing provided an alternate means of securing and displaying documents is used.	
-10-01 ***	Cockpit Assist Handle	D	1	0		
-10-02	Cockpit Sunvisor System (Including Attach Mechanism)	D	-	0	May be missing, or inoperative provided: a) Crewmember's field of vision is not obstructed, and b) Oxygen mask quick donning ability is not affected.	
-10-03	Flightcrew Seat (Per Seat)					
-01A	Armrest	C	2	0	May be inoperative provided affected armrest is stowed in retracted position.	
-01B	Armrest	C	2	0	(M) May be missing, or inoperative provided affected armrest is removed.	
-02 ***	Lumbar Support	D	1	0		
-03	Recline/Tilt Function	C	1	0	(M)(O) May be inoperative provided: a) Affected seat is secured or failed in a position that permits normal visibility, b) Full flight control movement is available, and c) Crewmember can reach all necessary controls and equipment while restrained.	
-04 ***	Restraint Buckle Protective Padding	D	1	0	May be damaged or missing.	

(Continued)

REVISION NO. 11

PAGE NO. 25-2

DATE: 11/10/2020

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-10-03	Flightcrew Seat (Per Seat) (Cont'd)					
-05 ***	Thigh Support	D	1	0	May be inoperative provided full flight control movement is available.	
-06	Vertical Adjustment	C	1	0	(M)(O) May be inoperative provided: a) Affected seat is secured or failed in a position that permits normal visibility, b) Full flight control movement is available, and c) Crewmember can reach all necessary controls and equipment while restrained.	
-10-04	Eye Reference Ball	C	3	0	(O) May be inoperative or missing provided alternate procedures are established and used for eye position reference.	
-10-05 ***	Yoke-Mounted Chart Holder	D	-	0		
-01 ***	Light	D	-	0		
-20-01 ***	Cabin Ashtray (Excluding Lavatory Door)	A	-	1	May be inoperative or missing provided ashtray is replaced within 3 calendar-days.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-20-02	Non-Essential Equipment and Furnishings (NEF)	-	-	0	May be inoperative, damaged or missing provided that item(s) is deferred in accordance with operator's NEF deferral program. NEF program procedures and processes are outlined in operator's (insert name) Manual. (M) and (O) procedures, if required, must be available to flightcrew and included in operator's appropriate document. NOTE: Exterior lavatory door ashtray is not considered an NEF item.	
-20-03	Passenger Seat (Including side-facing seats, folding seats and couches) (Per seat)	D	-	0	May be inoperative provided: <ol style="list-style-type: none"> a) Seat does not block an emergency exit, b) Seat does not restrict any cabin occupant access to aisle, and c) Affected seat(s) are blocked and placarded "DO NOT OCCUPY". NOTE: Affected seat(s) may include seats near inoperative seat(s).	
-01A	Armrest (With seat controls)	D	-	0	May be inoperative or missing with seat occupied provided: <ol style="list-style-type: none"> a) Armrest does not block an emergency exit, b) Armrest does not restrict any cabin occupant from access to aisle, and c) If armrest is missing, affected seat controls are considered inoperative. 	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-20-03	Passenger Seat (Including Side-Facing Seats, Folding Seats and Couches) (Per Seat) (Cont'd)					
-01B	Armrest (Without seat controls)	D	-	0	May be missing, or inoperative with seat occupied provided: a) Armrest does not block an emergency exit, and b) Armrest does not restrict any cabin occupant from access to aisle.	
-02A	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	(M) May be inoperative with seat occupied provided seat is secured in taxi, takeoff and landing position.	
-02B	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	May be inoperative with seat occupied provided control is failed in taxi, takeoff and landing position.	
-02C	Seat Controls (Includes recline, headrest, footrest, floor tracking, pedestal tracking, swivel, and other positioning controls)	D	-	0	May be missing or inoperative in other than taxi, takeoff, and landing position provided affected seat is considered inoperative.	
(Continued)						

REVISION NO. 11

PAGE NO. 25-5

DATE: 11/10/2020

AIRCRAFT:
Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-20-03	Passenger Seat (Including Side-Facing Seats, Folding Seats and Couches) (Per Seat) (Cont'd)					
-03	Seat Belt/Shoulder Harness	D	-	0	May be inoperative provided affected seat is placarded "DO NOT OCCUPY FOR TAXI, TAKEOFF, LANDING OR WHEN FASTEN SEAT BELT SIGN IS ILLUMINATED".	
-04 ***	Seat Belt/Shoulder Harness Keeper	D	1	0		
-05 ***	Lumbar Support	D	1	0		
-40-01 ***	Exterior Lavatory Door Ashtray	A	1	0	May be inoperative in accordance with AD 74-08-09 in its most current revision.	
-40-02 ***	Aft Vanity Hot Liquid Storage System Heater	C	1	0	(M) May be inoperative provided system is deactivated.	
-50-01	Baggage Restraint System	D	-	0	Individual components may be inoperative or missing provided baggage is secured by alternate means or not carried.	
-01A	Anchor Plate	C	-	0	Individual anchor plates may be inoperative provided: a) No visible damage exists, and b) Baggage is secured using remaining anchor plates or not carried.	
-01B	Anchor Plate	C	-	0	(M) Individual anchor plates may be damaged provided: a) Attaching structure is inspected for damage, and b) Baggage is secured using remaining anchor plates or not carried.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-50-02	Cabin Storage Compartment					
-00A		C	-	0	(M) May be inoperative provided: a) Procedures are established to secure the affected compartment or closet in the closed position, b) Affected compartment or closet is prominently placarded DO NOT USE, c) Any emergency equipment located in affected compartment is considered inoperative, and d) Affected compartment or closet is not used for storage of any items except for those permanently affixed. NOTE: Proviso is not intended to preclude crewmember inspections if required.	
-00B		C	-	0	(M) May be inoperative provided: a) Affected door is removed, b) Affected compartment is not used for storage of any item, including those permanently affixed, c) Cabin occupants are briefed that affected compartment may not be used, and d) Affected compartment is prominently placarded "DO NOT USE".	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-50-02	Cabin Storage Compartment (Cont'd)					
-01	Shelving	D	-	0	(O) May be inoperative provided: a) Any permanently affixed emergency equipment located on affected shelf is relocated and available for use, and b) Cabin occupants are briefed on location of relocated equipment.	
-02 ***	Key Lock	D	-	0	May be inoperative in unlocked position.	
-60-01 ***	Cockpit Smoke Vision System (CSVs)	D	-	0	May be inoperative or missing.	
-60-02	Emergency Medical Equipment					
-01 ***	Automatic External Defibrillator (AED) (Includes Associated Equipment)	D	-	0	Any in excess of those required by CFR may be incomplete, missing, or inoperative.	
-02 ***	Emergency Medical Kit (EMK) (Includes Associated Equipment)	D	-	-	Any in excess of those required by CFR may be incomplete, missing, or inoperative.	
-03 ***	First Aid Kit (FAK) (Includes Associated Equipment)	D	-	-	Any in excess of those required by 14 CFR operating rule may be incomplete, missing, or inoperative.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-61-01 ***	Life Preserver (Crew and Passenger)	D	-	-	Any in excess of those required by 14 CFR operating rule may be missing, or inoperative provided affected preserver is placarded "INOPERATIVE" or removed.	
-62-01	Emergency Locator Transmitter (ELT)					
-01 ***	Survival Type	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative or missing.	
-02A	Fixed, Automatic	A	-	0	(M) May be inoperative provided: a) System is deactivated, and b) Repairs are made within 90 days.	
-02B		A	-	0	(M) May be missing provided: a) Repairs are made within 90 days, and b) Placard stating "ELT not installed" is placed in view of the pilot.	
-02C		D	-	-	(M) Any in excess of those required by 14 CFR may be inoperative provided system is deactivated.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
-62-01	Emergency Locator Transmitter (ELT) (Cont'd)					
-02D		D	-	-	Any in excess of those required by 14 CFR operating rule may be missing.	
-03 ***	Remote ELT Switch	D	-	0	(M) May be inoperative provided: a) Remote ELT switch is deactivated, and b) ELT switch is placed in the ARMED mode.	
-04 ***	ELT Indicator Light	D	-	0		
-05 ***	ELT Aural Alarm	D	-	0		
-64-01 ***	Life Raft	D	-	-	Any in excess of those required by 14 CFR operating rule may be missing, or inoperative provided affected raft is placarded "INOPERATIVE" or removed.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

26. Fire Protection

Sequence No.	Item	1	2	3	4	Change Bar
-11-01 ***	Baggage Compartment Smoke Detection System (Units -7001 thru -7119)	C	1	0	May be inoperative provided: a) Baggage compartment remains empty (excluding ballast and/or fly away kits), and b) BAG HTR is selected OFF. NOTE: Operator's MEL should define which items are approved for inclusion in fly away kits and which materials can be used as ballast.	
-11-02 ***	Cabin Smoke Detector	C	1	0		
-12-01	APU Fire Detection System (APU-Equipped Aircraft)	C	1	0	May be inoperative provided APU is considered inoperative.	
-20-01	APU Fire Extinguishing System (APU-Equipped Aircraft)	C	1	0	May be inoperative provided APU is considered inoperative.	
-22-01	Portable Fire Extinguisher	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative or missing provided: a) Inoperative fire extinguisher is placarded "INOPERATIVE", removed from installed location, and placed out of sight so it cannot be mistaken for a functional unit, and b) Required distribution is maintained.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

27. Flight Controls

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Aileron Boost System	C	1	0	May be inoperative provided aircraft is operated in accordance with AFM AILERON BOOST SYSTEM OFF abnormal procedure.	
-20-01	Rudder Pedal Adjustment System	B	4	2	(M)(O) Two may be inoperative provided: <ol style="list-style-type: none"> a) Two pedal adjustments are not inoperative at same pilot station, b) Affected pedal is positioned in a detent and adjustment mechanism is secured from movement, c) Unaffected pedal is adjusted to match affected pedal, and d) Crewmember seated at affected station verifies full control movement and brake application is available while restrained, prior to each flight. 	
-50-01	Flap System (Units -0200 thru -0202, -0207 thru -0221, and -7001 thru -7019 Incorporating SB 650-27-42 and Units -0222 and -7020 and on)	B	1	0	May be inoperative provided aircraft is operated in accordance with AFM DISPATCH WITH FLAPS IN THE UP POSITION supplement.	
-60-01	Speed Brake Position Indication	C	1	0	(O) May be inoperative provided speed brakes are verified operative, prior to flap extension, before each flight.	
-01	SPOILERS UP Light	C	2	0		
-70-01	Control/Gust Lock System (Failed Unlocked)	C	1	0	(O) May be inoperative provided pilot verifies full flight control and throttle movement.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
-10-01 ***	Over-Wing Refueling Cap Lock					
-00A	(Failed Unlocked)	D	-	0		
-00B	(Failed Locked)	C	-	0	NOTE: If Single-Point Refueling (SPR) door lock is also failed in locked position or SPR system is inoperative, refueling will not be possible.	
-10-02	Single-point Refueling (SPR) System	C	1	0		
-01	Manual Defuel Select Valve	C	2	0	May be inoperative provided aircraft is not defueled using SPR system.	
-10-03	Fuselage Fuel System	C	1	0	(M) May be inoperative provided fuselage fuel tank is verified empty.	
-41-01	Fuel Low Level Indicating System	A	2	1	(O) One may be inoperative provided: a) Procedures for monitoring fuel quantity are established and used, b) Both wing fuel quantity indicating systems are operative, and c) Repairs are made within 3 flight-days.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
-41-02	Fuel Quantity Indicating System					
-01	Wing Tank	A	2	1	(O) One indication may be inoperative provided: <ol style="list-style-type: none"> a) Both fuel low level indicating systems and both fuel flow indicating systems are operative, b) Fuel required for route to be flown is increased by 10%, c) Flight is restricted to a maximum of three hours, remaining within one hour of a suitable airport at all points along route, d) Both wing fuel tanks are fueled over-wing to a known, balanced quantity, e) Fuselage tank is verified empty, f) APU use is limited to thirty cumulative minutes if RH indicator is inoperative, g) WING FUEL XFER remains OFF, h) Fuel use is tracked, i) If autopilot is used, it is disconnected every twenty minutes to detect possible lateral fuel imbalance, monitor trim required, and j) Repairs are made within three flight cycles. 	
-02	Fuselage Tank	C	1	0	May be inoperative provided fuselage fuel system is considered inoperative.	
-03	Wing Tank Indicator Tape	B	2	1	One may be inoperative provided fuel totalizer is operative.	
-04	Fuselage Tank Indicator Tape	B	1	0	May be inoperative provided the fuel totalizer is operative.	

REVISION NO. 11

PAGE NO. 28-3

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
-41-03	Fuel Totalizer	C	1	0		
-43-01	Fuel Temperature Indication	C	2	1	One may be inoperative.	

REVISION NO. 11

PAGE NO. 29-1

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

29. Hydraulic Power

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	APU Hydraulic Pump (Units -0001 thru -0104)	C	1	0	May be inoperative provided: a) APU is not used, and b) Hydraulic Fan is considered inoperative.	
-30-01	Hydraulic Reservoir Quantity Indication (Gauge)	B	1	0	(M) One may be inoperative provided: a) Quantity in reservoir is verified adequate on reservoir sight gauge prior to every flight, and b) Hydraulic pressure indication is monitored.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Horizontal Stabilizer Electric Anti-Ice System	C	2	1	(M) May be inoperative provided: a) System is deactivated, b) Affected STAB switch is selected OFF, and c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-10-02	Wing Bleed Air Anti-Ice System	C	2	0	(M) May be inoperative provided: a) Both wing valves are secured for no flow, b) Both WING ANTI-ICE switches are selected OFF, and c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-10-03	Wing Root Cuff Electric Anti-Ice System	A	2	0	(M) May be inoperative provided: a) Affected wing cuff is deactivated, b) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and c) Repairs are made within 3 flight-days.	
-20-01	Engine Anti-Ice System	A	2	1	(M) One may be inoperative provided: a) Affected valve is secured for no flow, b) Affected ANTI-ICE ENGINE switch is selected OFF, c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and d) Repairs are made within 3 flight-days.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
-30-01	Pitot Tube Heater (Copilot)	B	1	0	May be inoperative provided: a) Aircraft is not operated at night, b) Aircraft is not operated in Instrument Meteorological Conditions (IMC), c) Pitot heater is not required by 14 CFR operating rule, and d) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-30-02	Static Port Heater (Copilot)	B	3	2	One may be inoperative provided: a) Aircraft is not operated at night, b) Aircraft is not operated in Instrument Meteorological Conditions (IMC), c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and d) Aircraft is not operated RVSM.	
-30-03	Temperature Probe Heater (RAT)	C	1	0	May be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-40-01	Rain Removal System (Bleed Air and/or Doors) (Units -0001 thru -0241)	A	1	0	May be inoperative provided: a) Both W/S BLEED AIR valves are selected OFF, b) W/S BLEED switch is selected OFF, c) Aircraft is not operated in precipitation within five nautical miles of airport used for takeoff, intended landing or any alternates required by 14 CFR operating rule, and d) Repairs are made within 2 flight-days.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
-40-01	Rain Removal System (Bleed Air and/or Doors) (Units -7001 thru -7119)	A	1	0	May be inoperative provided: a) Both W/S BLEED AIR valves are selected OFF, b) W/S BLD switch is selected OFF, c) Aircraft is not operated in precipitation within five nautical miles of airport used for takeoff, intended landing or any alternates required by 14 CFR operating rule, and d) Repairs are made within 2 flight-days.	
-40-02	Windshield Bleed Air Anti-Ice System (Units -0001 thru -0241)	C	1	0	(M) May be inoperative provided: a) Windshield anti-ice system is deactivated, and b) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-40-02	Windshield Electric Anti-Ice System (Units -7001 thru -7119)	C	2	1	(M) One may be inoperative provided: a) Affected windshield anti-ice system is deactivated, b) Affected ANTI-ICE WINDSHIELD switch is selected OFF, c) A means to clear windshield of moisture is readily available, and d) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-40-03	Windshield Alcohol De-Ice System (Units -0001 thru -0241)	C	1	0	(M) May be inoperative provided: a) Windshield de-ice system is deactivated, and b) Aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-40-04	Frost Pane Defog System (Units -7001 thru -7119)	C	2	0		

REVISION NO. 11

PAGE NO. 30-4

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
-70-01 ***	Drain Heater (Forward and Aft Evaporator Fans, Refreshment Center, Aft Vanity Basin and/or Relief Tube)	C	-	0	(M) May be inoperative provided: a) Drain heaters are deactivated, and b) Forward and aft evaporator fans, refreshment center, aft vanity basin, and relief tube, overboard drains are considered inoperative.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-20-01 ***	APU Hour Meter	C	1	0	(O) May be inoperative provided APU operation time is tracked by alternate means.	
-20-02	Clock	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative.	
-20-03	Flight Hour Meter	C	1	0	(O) May be inoperative provided flight time is tracked by alternate means.	
-20-04 ***	Engine Takeoff Target Power Indicator/Computer	D	1	0		
-30-01 ***	Flight Data Recorder (FDR)					
-00A	(Flight Data Recorder (FDR) Not Required)	C	1	0	May be inoperative provided recorder is not required by 14 CFR operating rule.	
-00B	(Operator other than a Holder of an Air Carrier or Commercial Operator Certificate)	A	1	0	May be inoperative provided repairs are made in accordance with 14 CFR operating rule.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-30-01 ***	Flight Data Recorder (FDR) Continued					
-00C	(Holder of an Air Carrier or Commercial Operator Certificate)	A	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) Aircraft is not dispatched from an airport where repairs can be made unless, <ol style="list-style-type: none"> 1) Flight Data Recorder (FDR) failure occurs after dispatch but prior to takeoff, or 2) Flight Data Recorder (FDR) repair was attempted but not successful, b) In those cases where repair is attempted but not successful, aircraft may be dispatched on a flight or series of flights until arriving at next airport where repairs can be made at which the repair must be accomplished prior to dispatch, and c) Repairs are made within 3 flight-days. 	
-01A	Flight Data Recorder (FDR) Parameters Required by 14 CFR operating rule	A	-	-	Up to three (3) recording parameters may be inoperative provided: <ol style="list-style-type: none"> a) Cockpit Voice Recorder (CVR) operates normally, and b) Repairs are made within 20 calendar-days. 	
-01B	Flight Data Recorder (FDR) Parameters Not Required by 14 CFR operating rule	A	-	-	May be inoperative provided repairs are made prior to completion of next scheduled inspection/check of FDR.	
-02	Underwater Locator Device (ULD)	D	1	0	May be inoperative provided device is not required by 14 CFR operating rule.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-30-02 ***	Quick Access Recorder (QAR)	D	1	0	May be inoperative provided recorder is not required by procedures.	
-40-01 ***	Audio Checklist	D	1	0	May be inoperative provided procedures do not require its use.	
-40-02 ***	Electronic Checklist	D	-	0	May be inoperative, missing, or out of currency provided an approved checklist is available and used.	
-01 ***	Remote Controller	D	-	0		
-50-01	Annunciator (Failed to Illuminate)					
-01A	Accessory Door (ACC DOOR UNLOCKED - NOSE/BAG) (Units -0001 thru -0161 Incorporating SB 650-52-19 and Units -0162 and on)	C	3	0	May be inoperative provided associated door warning systems are considered inoperative. NOTE: Refer to airframe maintenance manual for doors monitored.	
-01B	Accessory Door (DOOR UNLOCKED - ACC) (Units -0001 thru -0161 Not Incorporating SB 650-52-19)	C	2	0	May be inoperative provided associated door warning systems are considered inoperative. NOTE: Refer to airframe maintenance manual for doors monitored.	
-02A	Autopilot Disengage (AUTO PILOT OFF) (SPZ-650-Equipped Aircraft)	B	2	0	May be inoperative provided autopilot system is considered inoperative.	
-02A	Autopilot Disengage (AP OFF) (SPZ-8000-Equipped Aircraft)	B	2	0	May be inoperative provided autopilot system is considered inoperative.	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-50-01	Annunciator (Failed to Illuminate) (Cont'd)					
-03B	Autopilot Disengage (AP OFF) (SPZ-8000-Equipped Aircraft)	C	2	1	One may be inoperative provided annunciator is operative on pilot-flying side.	
-03B	Autopilot Disengage (AUTO PILOT OFF) (SPZ-650-Equipped Aircraft)	C	2	1	One may be inoperative provided annunciator is operative on pilot-flying side.	
-04	Cabin Altitude (CABIN ALT 8500 FT)	C	1	0	May be inoperative provided: a) Cabin pressurization system is operative, b) Cabin altitude horn is verified operative, and c) Aircraft is operated at FL 250 or below.	
-05	Cabin Door (DOOR UNLOCKED - CAB) (Units -0001 thru -0161 Not Incorporating SB 650-52-19)	B	2	0	May be inoperative provided main cabin door warning system is considered inoperative.	
-06	Cabin Door (CAB DOOR UNLOCKED) (Units -0001 thru -0161 Incorporating SB 650-52-19 and Units -0162 and on)	B	1	0	May be inoperative provided main cabin door warning system is considered inoperative.	
(Continued)						

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-50-01	Annunciator (Failed to Illuminate) (Cont'd)					
-07	Duct Overheat (DUCT O'HT - CKPT/CAB) (Units -0001 thru -0241)	C	3	2	(O) One position annunciation may be inoperative provided: a) Associated PAC supply temperature indicating system is operative and monitored to ensure temperature remains at 250 °F (121 °C) or below, and b) Cockpit and cabin automatic temperature control systems are operative.	
-08	Duct Overheat (DUCT O'HEAT - LH/RH) (Units -7001 thru -7119)	C	3	2	(O) One position annunciation may be inoperative provided: a) Associated PAC supply temperature indicating system is operative and monitored to ensure temperature remains at 250 °F (121 °C) or below, and b) Cockpit and cabin automatic temperature control systems are operative.	
-09	Engine Anti-Ice (ENG ANTI-ICE - LH/RH)	C	3	2	One position annunciation may be inoperative provided associated engine anti-ice system is considered inoperative.	
-10	Fuselage Fuel Quantity Full (FUS TANK FULL) (Units -0001 thru -0241)	C	1	0		
-11	Fuselage Fuel Quantity Low (FUS TANK LOW)	C	1	0	May be inoperative provided fuselage fuel quantity is monitored.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-50-01	Annunciator (Failed to Illuminate) (Cont'd)					
-12	Generator Off/Fail (GEN OFF - LH/RH)	C	3	2	(O) One position annunciation may be inoperative provided affected generator voltage and amperage is monitored.	
-13	Hydraulic Volume Low (HYD VOL LOW)	C	1	0	May be inoperative provided hydraulic volume is monitored.	
-14	PAC Overheat (PAC O'HT - CKPT/CAB) (Units -0001 thru -0241)	C	3	2	One position annunciation may be inoperative provided associated PAC is considered inoperative.	
-15	PAC Overheat (PAC O'HEAT - LH/RH) (Units -7001 thru -7119)	C	3	2	One position annunciation may be inoperative provided associated PAC is considered inoperative.	
-16	Pitot/Static Heater Off/Fail (P/S HTR OFF - LH/RH)	B	3	2	One position annunciation may be inoperative provided pitot tube and static port heater are considered inoperative.	
-17	SPOILERS UP	C	1	0	May be inoperative provided both flap/speed brake indicator SPOILERS UP lights are operative and monitored.	
-18	Stabilizer Anti-Ice (STAB ANTI-ICE - LH/RH) (Units -0001 thru -0172 Incorporating SB 650-31-09 and Units -0173 and on)	C	3	2	One position annunciation may be inoperative provided associated stabilizer anti-ice system is considered inoperative.	
(Continued)						

AIRCRAFT:
Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
-50-01	Annunciator (Failed to Illuminate) (Cont'd)					
-18	Stabilizer Anti-Ice (STAB DE-ICE - LH/RH) (Units -0001 thru -0172 Not Incorporating SB 650-31-09)	C	3	2	One position annunciation may be inoperative provided associated stabilizer anti-ice system is considered inoperative.	
-19	Wing Anti-Ice (WING ANTI-ICE - LH/RH)	C	3	2	One position annunciation may be inoperative provided associated wing anti-ice system is considered inoperative.	
-50-02	Cabin Altitude Warning System (Aural and/or Visual Warning Failed)	C	1	0	May be inoperative provided cabin pressurization system is considered inoperative.	
-50-03	Central Warning					
-01	Master Warning Light (Failed to Illuminate)	C	2	1	One may be inoperative.	
-02	Master Warning Cancel/Reset Function	C	2	1	One may be inoperative.	
-03	Master Caution Light (Failed to Illuminate)	C	2	1	One may be inoperative.	
-04	Master Caution Cancel/Reset Function	C	2	1	One may be inoperative.	
-50-04	Aural Warnings Autopilot Disengage	B	1	0	May be inoperative provided autopilot is considered inoperative.	

REVISION NO. 11

PAGE NO. 32-1

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

32. Landing Gear

Sequence No.	Item	1	2	3	4	Change Bar
-41-01	Anti-Skid System	C	1	0	May be inoperative provided aircraft is operated in accordance with AFM DISPATCH WITH ANTISKID SYSTEM INOP supplement.	
-44-01 ***	Tire Pressure Monitoring System (STC ST02127LA)	D	1	0	NOTE: Any individual wheel sensors which are operative may be used.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Cockpit and Instrument Lighting (Excluding Button Lights, Standby Flight Instrument Lighting, Internally Lighted Annunciators, and Required Placard Lighting)					
-00A		C	-	0	May be inoperative provided aircraft is not operated at night.	
-00B		C	-	-	Individual lights may be inoperative provided: <ol style="list-style-type: none"> a) Cockpit emergency lighting is operative, b) Remaining lights are sufficient to clearly illuminate all required instruments, controls, and other devices for which it is provided, c) Remaining lights are positioned so that direct rays are shielded from crewmembers' eyes, and d) Lighting configuration and intensity is acceptable to flightcrew. 	
-10-02	Cockpit Flood Light					
-00A		C	2	1	One may be inoperative.	
-00B		C	2	0	May be inoperative provided aircraft is not operated at night.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-10-03	Cockpit Map Light					
-00A		C	2	1	One may be inoperative provided a cockpit flood light is operative.	
-00B		C	2	0	May be inoperative provided: a) A cockpit flood light is operative, and b) A flashlight is available to affected crewmember.	
-10-04	Windshield Ice Detection Light					
-00A		C	2	1	(O) One may be inoperative provided alternate procedures are established and used to monitor ice accretion.	
-00B		C	2	0	May be inoperative provided aircraft is not operated at night.	
-20-01	Cabin Interior Lighting (Excluding Cabin Emergency Lighting) (Includes Footwell Lights unless Part of Emergency Lighting System)					
-00A		C	-	-	(O) Individual lights may be inoperative provided: a) Sufficient lighting is operative for crew to perform required duties, b) Cabin emergency lighting is verified operative, and c) Sufficient lighting is operative for carrying cabin occupants at night.	
-00B		D	-	0	(O) May be inoperative provided: a) Cabin emergency lighting is verified operative, and b) Aircraft is not operated at night or cabin occupants are not carried.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-20-02	Lighted Passenger Information Sign (Excluding Cabin Exit Signs)					
-00A		C	-	0	(O) May be inoperative provided alternate procedures are established and used to notify cabin occupants.	
-00B		C	-	0	May be inoperative provided no cabin occupants are carried.	
-30-01	Aft Baggage Compartment Light (Units -0001 thru -0241)	C	1	0		
-30-01	Aft Baggage Compartment Light (Units -7001 thru -7119)	C	2	0		
-01	Door Proximity Switch (Failed to Extinguish Light)	C	1	0	May be inoperative provided BAGGAGE LIGHT switch is selected OFF prior to baggage door closure.	
-30-02	Tailcone Maintenance Light	C	1	0		
-01	Door Proximity Switch (Failed to Extinguish Light)	C	1	0	May be inoperative provided TAILCONE LIGHT switch is selected OFF prior to tailcone access door closure.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-40-01	Anti-Collision Light System (Wing Strobe)					
-00A		C	1	0	May be inoperative provided system is not required by 14 CFR operating rule.	
-00B		A	1	0	May be inoperative provided: a) Position/navigation light system is operative, b) Ground recognition light is operative, and c) Repairs are made within 3 flight-days.	
-40-02	Ground Recognition Light (Beacon)	C	-	0	May be inoperative provided Wing Strobe is operative. NOTE: Position/navigation or anticollision lights may be used on ground to alert nearby aircraft or personnel when engines are running or prior to start.	
-40-03	Landing Light					
-01A		C	2	1	One may be inoperative provided a taxi light is operative on same side of aircraft as inoperative landing light.	
-01B		C	2	0	May be inoperative provided aircraft is not operated at night.	
-02 ***	Pulse Light Mode	D	1	0	(M)(O) May be inoperative provided: a) Pulse light system is deactivated, and b) At least one landing light is verified operative for night operations.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-40-03	Landing Light (Cont'd)					
-03A	Landing Light Extension/Retraction System (Failed Extended)	C	2	0	May be inoperative provided aircraft is operated in accordance with AFM limitations.	
-03B	Landing Light Extension/Retraction System (Failed Retracted)	C	2	0	May be inoperative provided: a) Associated landing light is considered, and b) Associated LANDING LIGHTS switch is selected OFF.	
-40-04	Position/Navigation Light System	C	1	0	May be inoperative provided aircraft is not operated between sunset and sunrise.	
-40-05	Recognition Light	C	2	0	May be inoperative provided aircraft is not operated at night.	
-01 ***	Pulse Light Mode	D	1	0	(M)(O) May be inoperative provided: a) Pulse light system is deactivated, and b) Both recognition lights are verified operative for night operations.	
-40-06 ***	Tail Flood Light	D	2	0		
-40-07	Taxi Light					
-00A		C	2	1	One may be inoperative.	
-00B		C	2	0	May be inoperative provided both landing lights are operative.	
-00C		C	2	0	May be inoperative provided aircraft is not operated at night.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
-40-08	Wing Inspection Lights					
-00A		C	2	1	One may be inoperative provided ground deicing procedures do not require its use.	
-00B		C	2	0	May be inoperative provided: a) Aircraft is not operated at night in known, forecast, or AFM-defined icing conditions, and b) Ground deicing procedures do not require its use.	
-50-01	Cockpit Flashlight	C	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative or missing.	
-01 ***	Holder	C	-	0	May be inoperative provided associated flashlight is stowed by alternate means.	
-50-02	Exterior Emergency Light	B	3	0	May be inoperative provided aircraft is not operated at night.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-12-01	Air Temperature Gauge/Indication (SAT/TAT)	C	1	0	May be inoperative provided temperature is available by alternate means.	
-13-01	Mechanical Vertical Speed Indicator (Units -0001 thru -0241)	C	2	1	May be inoperative provided all remaining instruments on associated air data system are operative.	
-13-01 ***	Mechanical Vertical Speed Indicator (Units -7001 thru -7119)	C	1	0		
-16-01	Altitude Alerting System	A	-	0	(O) May be inoperative provided: a) Autopilot with altitude hold and capture operates normally, b) Enroute operations, ie RVSM, do not require its use, c) Airplane does not depart from a designated airport where repair or replacement can be made, and d) Repairs are made within 3 flight-days.	
-01		C	-	1	As listed in operators MEL.	
-02	Aural Alert	C	-	0	May be inoperative provided: a) Visual alert operates normally, and b) Autopilot with altitude hold and capture operates normally.	
-03	Visual Alert	C	-	0	May be inoperative provided: a) Aural alert operates normally, and b) Autopilot with altitude hold and capture operates normally.	
-17-01 ***	Air Data Computer (ADC) (Pilot's Standby) (Units -0001 thru -0199 and -0203 thru -0206)	C	1	0	May be inoperative provided pilot's primary ADC is verified operative and selected.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-18-01	Angle of Attack (AOA) System					
-01 ***	Indexer	C	-	0		
-02	Indicator	C	1	0	May be inoperative provided both stick shakers are verified operative.	
-18-02	Angle of Attack (AOA) Heater					
-01	Probe	C	2	1	One may be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-02	Case	C	2	1	One may be inoperative provided aircraft is not operated in known, forecast, or AFM-defined icing conditions.	
-23-01	Non-Stabilized Magnetic Compass					
-00A		B	1	0	May be inoperative provided: a) Any combination of two gyro, AHRS or INS-stabilized compass systems are operative, and b) Aircraft is not operated at night or in Instrument Meteorological Conditions (IMC).	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-23-01	Non-Stabilized Magnetic Compass (Cont'd)					
-00B		B	1	0	May be inoperative provided: a) Any combination of two gyro, AHRS or INS-stabilized compass systems are operative, b) Aircraft is operated with dual independent navigation capability, and c) Aircraft is operated under positive radar control by ATC on enroute portion of flight.	
-24-01	Rate of Turn Indicator (AD-650 Attitude Director Indicator-Equipped Aircraft)	C	2	1		
-25-01	Flight Director System					
-00A		C	2	1	One side may be inoperative provided: a) Command bars are not present on affected side, and b) Approach or departure procedures do not require its use.	
-00B		B	2	0	May be inoperative provided: a) Command bars are not present, b) Approach or departure procedures do not require its use, and c) Autopilot system is considered inoperative.	
-25-02 ***	Multi-Function Display (ED102D or MDZ-816)	C	1	0		

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-25-03	EFIS Symbol Generator (MDZ-816 MFD-Equipped Aircraft)	C	3	2	One may be inoperative provided pilot and copilot EFIS displays are driven by independent symbol generators.	
-25-04 ***	Course/Heading Panel Function Control (RI-206)					
-01	Course	B	2	1	One may be inoperative provided procedures do not require its use.	
-02	Course Direct (PUSH DIR)	C	2	0		
-03	Heading Sync (PULL SYNC)	C	1	0		
-31-01	Localizer System	C	-	-	May be inoperative provided: a) Affected system is not on an emergency bus, b) Associated glideslope is considered inoperative, c) Procedures do not require its use, and d) System is not required by 14 CFR operating rule.	
-32-01	Glideslope System	C	-	-	May be inoperative provided: a) Procedures do not require its use, and b) System is not required by 14 CFR operating rule.	
-33-01 ***	Microwave Landing System (MLS)	D	-	0	May be inoperative provided procedures do not require its use.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-34-01	Marker Beacon Receiver System	C	-	0	May be inoperative provided: a) Procedures do not require its use, and b) System is not required by 14 CFR operating rule.	
-36-01 ***	Reactive Windshear System (Includes TAWS Windshear Mode)	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-42-01	Weather Radar System	C	1	0	May be inoperative provided system is not required by 14 CFR operating rule.	
-44-01	Radio Altimeter System (TAWS or TCAS II Required)	A	1	0	(M) May be inoperative provided: a) Radio altimeter is deactivated, b) Approach minimums or operating procedures do not require its use, c) Basic TAWS modes are considered inoperative, d) TCAS II is considered inoperative, e) Aircraft is operated in accordance with AFM radio altimeter limitations, and f) Repairs are made within 2 flight-days.	
NOTE: Landing gear warning system will function differently without radio altimeter input. Landing gear warning may occur at higher altitudes above ground with flaps extended.						

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-44-02 ***	Class A TAWS Equipment required					
-01	GPWS	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
-02	Mode 1-4	A	4	0	(O) May be inoperative provided: a) Alternate procedures are established and used, b) Repairs are made within 2 flight-days.	
-03	Test Mode	A	1	0	May be inoperative provided: a) GPWS is considered inoperative, and b) Repairs are made within 2 flight-days.	
-04	Glideslope Deviation(s) Mode 5	C	-	1		
-05	Advisory Callouts					
-00A		B	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-00B		C	-	0	(O) May be inoperative provided: a) Advisory callout not required by operating rule, and b) Alternate procedures are established and used.	
-00C	Windshear Mode (Reactive)	B	1	0	(O) May be inoperative provided alternate procedures are established and used.	
					NOTE: Operator's alternate procedures should include reviewing windshear avoidance and windshear recovery procedures.	
					(Continued)	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-44-02 ***	Class A TAWS Equipment required (Cont'd)					
-06	Terrain System-Forward Looking Terrain Avoidance (FLTA) And Premature Descent Alert (PDA) Functions	B	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-07	Terrain Displays	C	-	1		
-08 ***	Runway Awareness & Advisory System (RAAS)	C	1	0		
-44-03 ***	Class B TAWS Equipment Required					
-01	GPWS	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
-00A	Modes 1 & 3	A	2	0	(O) May be inoperative provided: a) Alternate procedures are established and used, b) Repairs are made within 2 flight-days.	
-00B	Test Mode	A	1	0	May be inoperative provided: a) GPWS is considered inoperative, and b) Repairs are made within 2 flight-days.	
-00C ***	Modes 2, 4 & 5	C	3	0		
-00D	Advisory Callouts	B	-	0	(O) May be inoperative provided alternate procedures are established and used.	
(Continued)						

REVISION NO. 11

PAGE NO. 34-8

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-44-03 ***	Class B TAWS Equipment Required (Cont'd)					
-01	GPWS (Cont'd)					
-00E		C	-	0	(O) May be inoperative provided: a) Advisory callout not required by operating rule, and b) Alternate procedures are established and used.	
-00F ***	Windshear Mode (Reactive)	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-02	Terrain System-Forward Looking Terrain Avoidance (FLTA) And Premature Descent Alert (PDA) Funtion	B	1	0		
-03 ***	Terain Displays	C	-	0		
-04 ***	Runway Awareness & Advisory System (RAAS)	C	1	0		

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-45-01 ***	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II)					
-00A	(TCAS Not Required)	C	1	0	(M) May be inoperative provided: a) System is deactivated, b) System is not required by 14 CFR operating rule, and c) Enroute or approach procedures do not require its use.	
-00B	(TCAS Required)	B	1	0	(M) May be inoperative provided: a) System is deactivated, and b) Enroute or approach procedures do not require its use.	
-01	Traffic Advisory (TA) Display (TCAS II Only)	C	-	0	(O) May be inoperative provided: a) Resolution Advisory (RA) display and audio function are operative, and b) Enroute or approach procedures do not require use of TCAS.	
-02A	Resolution Advisory (RA) Display (TCAS II Only)	C	2	1	One may be inoperative on pilot not flying side.	
-02B	Resolution Advisory (RA) Display (TCAS II Only)	C	2	0	(O) May be inoperative provided: a) TA display and audio function are operative, b) TA-only mode is selected on TCAS controller or menu, and c) Enroute or approach procedures do not require use of TCAS.	
(Continued)						

AIRCRAFT:
Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-45-01 ***	Traffic Alert and Collision Avoidance System (TCAS I or TCAS II) (Cont'd)					
-03A	Traffic Advisory (TA) and Resolution Advisory (RA) Displays Failed (TCAS II Only)	C	2	1	One side may be inoperative provided: a) TA and RA displays are operative on pilot-flying side, and b) Audio function is operative.	
-03B ***	Combined Traffic Advisory (TA) and Resolution Advisory (RA) Display (EVSI or Equivalent) (TCAS II Only) (Excluding EFIS-Equipped Aircraft)	C	2	1	One may be inoperative provided: a) Combined display is operative on pilot-flying side, and b) Audio function is operative.	
-04	Audio Function	B	1	0	May be inoperative provided enroute or approach procedures do not require use of TCAS.	
-05 ***	Airspace Selection Function (Above/Below)	C	-	0		
-45-02 ***	Traffic Collision Avoidance Device (TCAD)	D	1	0		
-46-01 ***	Lightning Detection System	D	1	0	May be inoperative provided system is not required by 14 CFR operating rule.	
-50-01	Radio Magnetic Indicator (RMI) (Copilot)	C	1	0		
-51-01	Distance Measuring Equipment (DME)	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-52-01	ATC Transponder and Automatic Altitude Reporting System					
-00A	ATC Transponders and Automatic Altitude Reporting Systems	B	-	0	May be inoperative provided: a) Operations do not require its use, and b) Prior to flight, approval is obtained from ATC facilities having jurisdiction over the planned route of flight.	
-00B		D	-	1	Any in excess of those required by 14 CFR operating rule may be inoperative.	
-01 ***	Elementary and Enhanced Downlink Aircraft Reportable Parameters (Not required By 14 CFR operating rule)	A	-	0	May be inoperative provided: a) Operations do not require their use, and b) Repairs are made prior to completion of next scheduled inspection/check of transponder.	
-52-02	Transponder Ident Button (XDPR IDNT)	C	2	1	One may be inoperative.	

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. 34-12

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-52-03 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) System					
-00A		C	-	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) It is not required by 14 CFR operating rule. NOTE: Any ADS-B function that operates normally may be used.	
-00B		D	-	0	May be inoperative provided: a) Enroute operations do not require its use, and b) It is not required by 14 CFR operating rule. NOTE: Any ADS-B function that operates normally may be used.	
-00C		C	-	1	One must be operative as required by 14 CFR operating rule. NOTE: Any ADS-B function that operates normally may be used.	
01A ***	ADS-B Out Extended Squitter Transmissions	C	-	0	(O) May be inoperative provided: a) Alternate procedures are established and used, b) Authorization is obtained from ATC facilities having jurisdiction over planned route of flight, and c) It is not required by 14 CFR operating rule. NOTE: Any ADS-B function that operates normally may be used.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-52-03 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) System (Cont'd)					
-01B		C	-	1	One must be operative as required by 14 CFR operating rule. NOTE: Any ADS-B function that operates normally may be used.	
-02A ***	ADS-B Out UAT Transmissions	C	-	0	(O) May be inoperative provided: a) Enroute operations do not require its use, b) Authorization is obtained from ATC facilities having jurisdiction over planned route of flight, and c) It is not required by 14 CFR operating rule. NOTE: Any ADS-B Out function that operates normally may be used.	
-02B		C	-	1	One must be operative as required by 14 CFR operating rule. NOTE: Any ADS-B function that operates normally may be used.	
(Continued)						

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-52-03 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) System (Cont'd)					
-03A ***	ADS-B In Transmissions	C	-	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any ADS-B In function that operates normally may be used.	
-03B ***		D	-	0	May be inoperative provided operations do not require its use. NOTE: Any ADS-B function that operates normally may be used.	
-54-01	Very High Frequency Omni Range (VOR) System	C	-	0	May be inoperative provided: a) Affected system is not on an emergency bus, b) Procedures do not require its use, and c) System is not required by 14 CFR operating rule.	
-55-01 ***	Automatic Direction Finder (ADF)	D	-	0	May be inoperative provided operations do not require its use.	
-57-01	Global Navigation Satellite System (GNSS) (Including SBAS)	C	-	0	May be inoperative provided: a) System is not required by 14 CFR operating rule, and b) Operations do not require its use. NOTE 1: Enhanced function of TAWS may not be available. NOTE 2: ADS-B output may not be available.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-60-01	Data Loader	C	-	0		
-60-02	Flight Management System (FMS)	C	-	0	May be inoperative provided: a) System is not required by 14 CFR operating rule, and b) Operations do not require its use. NOTE: Enhanced function of TAWS may not be available.	
-60-03	Universal InSight Flight Mangement System (FMS) STC ST02654LA	C	-	0	May be inoperative provided: a) System is not required by 14 CFR operating rule, and b) Operations do not require its use. NOTE: In dual FMS installations with a single FMS failure the aircraft may not be able to fly LPV approaches. ADS-B function is inoperative if the aircraft is operated with no FMS.	
-60-04	Universal InSight Cursor Control Device (CCD) STC ST02654LA	C	-	0	May be Inoperative.	
-60-05	Universal InSight Alpha-Numeric Keypad (Dual FMS Installations) STC ST02654LA	C	2	1	One may be Inoperative.	
-60-06	Universal InSight Data Concentrator Unit (DCU) (Dual FMS Installations) STC ST02654LA	B	2	1	One may be inoperative.	

REVISION NO. 11

PAGE NO. 34-16

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
-60-07	Universal InSight EFIS Control Display (ECDU) (Dual FMS Instalations) STC ST02654LA	C	2	1	One may be inoperative. NOTE: Clearence Control Head (CTL) must be tested operative prior to dispatch.	
-60-08	Universal InSight MFD STC ST02654LA	C	-	0	May be inoperative. NOTE: If there is no MFD display the pilot-flying's PFD must have the engine instruments selected on.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

35. Oxygen

Sequence No.	Item	1	2	3	4	Change Bar
-00-01	Oxygen System					
-01	Fill Port	C	1	0	(M) May be inoperative provided bottle is filled using alternate means, if service is required.	
-02	Blowout Disk/Green Label	C	1	0	May be missing or damaged provided oxygen pressure is verified prior to each flight.	
-20-01	Passenger Oxygen System					
-00A		B	1	0	May be inoperative provided: a) Cabin pressurization system is operative, b) Aircraft is able to descend within four minutes to a cabin pressure altitude of 13,000 ft. at all points along route to be flown, and c) Aircraft is operated at FL 250 or below.	
-00B		C	1	0	May be inoperative provided: a) PASS OXY is selected OFF, and b) No cabin occupants are carried.	
-00C		C	1	0	May be inoperative provided cabin pressurization system is considered inoperative.	
-01	Mask	C	-	0	(M) Individual oxygen masks or dispensers may be inoperative or missing provided: a) Affected mask pintle pin is installed, and b) Associated seat or lavatory is placarded "DO NOT OCCUPY".	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

35. Oxygen

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Passenger Oxygen System (Cont'd)					
-02	Drop-Out Panel	C	-	0	(M) Individual panels may be out of normal position provided: <ol style="list-style-type: none"> a) Affected oxygen mask and drop-out panel are removed, b) Affected mask pintle pin is installed, and c) Associated seat or lavatory is placarded "DO NOT OCCUPY". 	
-30-01 ***	Portable Oxygen System	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative provided: <ol style="list-style-type: none"> a) Inoperative oxygen bottle is placarded "INOPERATIVE", removed from installed location, and placed out of sight so it cannot be mistaken for a functional unit, and b) Bottles not properly serviced are replaced, serviced, or removed at next available maintenance facility. 	
-30-02 ***	Protective Breathing Equipment (PBE)	D	-	-	Any in excess of those required by 14 CFR operating rule may be inoperative or missing provided: <ol style="list-style-type: none"> a) Inoperative PBE remains in a certified location or is removed from the aircraft, b) Location placarding is removed or obscured, and c) Required distribution is maintained. <p>NOTE: Inoperative PBE units removed from a certified location, or removed from the aircraft, are subject to 49 CFR dangerous goods regulations.</p>	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

36. Pneumatic

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Bleed Air Shutoff Valve					
-01	High-Pressure (HP)	C	2	1	One may be inoperative provided: a) PAC HP VLV OPEN annunciator is not illuminated, b) PAC BLD SELECT is selected to LP, c) Aircraft is not operated in known, forecast, or AFM-defined icing conditions, and d) Aircraft is operated at FL 450 or below.	
-02	Low-Pressure (LP)	C	2	1	One may be inoperative provided: a) Emergency pressurization system is operative, b) Associated ENG BLD AIR is selected OFF, c) ISOL VALVE is selected to SHUT, and d) Affected PAC is considered inoperative.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

38. Water/Waste

Sequence No.	Item	1	2	3	4	Change Bar
-10-01 ***	Potable Water System	C	-	0	(M) May be inoperative provided: a) System is drained, and b) Procedures are established and used to ensure system is not serviced.	
-01	Individual Components	C	-	0	(M) Individual components may be inoperative provided: a) Associated components are deactivated or isolated, and b) Associated system components are verified not to have leaks. NOTE: Any portion of system operating normally may be used.	
-30-01 ***	Relief Tube	C	-	0	(M) May be damaged or inoperative provided: a) All liquid is removed from relief tube, and b) Relief tube is placarded "DO NOT USE".	
-30-02 ***	Lavatory External Service System	C	1	0	(M) Individual components may be inoperative provided: a) Associated components are deactivated or isolated, and b) Associated system components are verified not to have leaks.	
-01A	Dump Cable	C	1	0	May be inoperative provided lavatory is not serviced or used.	
-01B	Dump Cable	C	1	0	(M) May be inoperative provided lavatory is serviced by alternate means.	
-04	System Precharge Annunciator (Green PRECHARGE)	C	1	0	(O) May be inoperative provided alternate procedures are established and used for filling toilet.	
(Continued)						

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

38. Water/Waste

Sequence No.	Item	1	2	3	4	Change Bar
-30-02 ***	Lavatory External Service System (Cont'd)					
-05	Heater Gasket	C	1	0	(M) May be inoperative provided: a) Waste line is drained of all fluids, b) Heater gasket is deactivated, and c) Toilet is not serviced within four hours of landing or at surface temperatures below +10 °C.	
-06	System Overfill Annunciator (Red OVERFILL)	C	1	0	(O) May be inoperative provided alternate procedures are established and used for filling toilet.	
-30-03	Lavatory Waste System	C	1	0	Individual components may be inoperative provided: a) Cabin occupants are briefed prior to each flight that lavatory is inoperative and unusable, and b) Lavatory is placarded "DO NOT USE".	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

38. Water/Waste

Sequence No.	Item	1	2	3	4	Change Bar
-30-04	Overboard Drain (Excluding Drain Heater)					
-01	Aft Vanity Basin	C	1	0	(O) May be damaged or obstructed provided: a) All liquid is removed from basin, and b) Basin is placarded "DO NOT USE".	
-02 ***	Evaporator Fan (Forward or Aft)	C	2	0	May be damaged or obstructed provided affected evaporator fan is considered inoperative.	
-03	Refreshment Center	C	1	0	(O) May be damaged or obstructed provided: a) All liquid is removed from refreshment center hot liquid storage and drip pan, b) Refreshment center hot liquid storage and drip pan are placarded "DO NOT USE", and c) Ice drawer drain valve remains closed.	
-04 ***	Relief Tube	C	1	0	May be damaged or obstructed provided toilet relief tube is considered inoperative.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

46. Information Systems

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Electronic Flight Bag Systems (EFBs)					
-00A	EFB System (Installed EFB System)	C	-	-	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any function, program or document which operates normally may be used.	
-00B		D	-	0	May be inoperative provided procedures do not require its use.	
-01A	Data Connectivity	C	-	-	(O) May be inoperative provided alternate procedures are established and used.	
-01B		D	-	0	May be inoperative provided procedures do not require its use.	
-02A	Power Supply/Power Connection	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-02B		D	-	0	May be inoperative provided procedures do not require its use	
-03A	Mounting Devices	C	-	0	(M)(O) May be inoperative provided: a) Associated EFB and hardware is stowed, secured by an alternate means, or removed from the aircraft, b) Alternate procedures are established and used.	
-03B		D	-	0	(M) May be inoperative provided: a) Associated EFB and hardware is stowed, secured by an alternate means, or removed from the aircraft, b) Procedures do not require its use.	

AIRCRAFT: Textron Aviation Model 650	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

49. Airborne Auxiliary Power

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Auxiliary Power Unit (APU) (APU-Equipped Aircraft)	C	1	0	(M) May be inoperative provided: a) APU is deactivated, and b) Procedures do not require its use.	
-50-01	APU Bleed Air System	C	1	0	(O) May be inoperative provided: a) BLEED VALVE is selected CLOSE, and b) APU bleed air valve is verified closed.	
-70-01	APU Exhaust Gas Temperature (EGT) Display (APU-Equipped Aircraft)	C	1	0	May be inoperative provided: a) APU performed normal start and shutdown on prior use, and b) APU FAIL amber annunciator is operative and does not illuminate during APU start.	
-70-02	APU Speed (RPM %) Display (APU-Equipped Aircraft)	C	1	0	May be inoperative provided: a) APU performed normal start and shutdown on prior use, and b) APU FAIL amber annunciator is operative and does not illuminate during APU start.	

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

52. Doors

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Main Cabin Door					
-01	Key Lock (Failed Unlocked)	D	1	0		
-02	Acoustic Seal	C	1	0	May be damaged provided seal does not interfere with door operation.	
-03A	Primary Seal (Cabin Pressurized)	B	1	0	May be inoperative provided: a) Primary seal does not interfere with door operation, b) Secondary door seal is verified intact, and c) Aircraft is operated at FL 250 or below.	
-03B	Primary Seal (Cabin Unpressurized)	C	1	0	May be inoperative provided: a) Primary seal does not interfere with door operation, and b) Cabin pressurization system is considered inoperative.	
-04A	Secondary Seal (Cabin Pressurized)	C	1	0	May be damaged provided: a) Primary door seal is operative, b) Secondary seal does not interfere with door operation, and c) Aircraft is operated at FL 250 or below.	
-04B	Secondary Seal (Cabin Unpressurized)	C	1	0	May be damaged provided: a) Secondary seal does not interfere with door operation, and b) Cabin pressurization system is considered inoperative.	

(Continued)

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

52. Doors

Sequence No.	Item	1	2	3	4	Change Bar
-10-01	Main Cabin Door (Cont'd)					
-05	Handrail	C	1	0	(O) May be inoperative or damaged provided: a) Door operates and latches normally, and b) Alternate procedures are established and used for assisting passengers during entry and exit.	
-30-01	Aft Baggage Door					
-01	Key Lock (Failed Unlocked)	D	1	0	May be inoperative provided door is verified closed and latched prior to each flight.	
-02	Door Cable	B	2	1	One may be inoperative or missing provided: a) Affected cable is removed, and b) Door steps are not used.	
-40-01	Nose Access Door (Per Side)					
-01	Key Lock (Failed Unlocked)	D	1	0	May be inoperative provided door is verified closed and latched prior to each flight.	
-02	Gas Spring	D	1	0	May be inoperative or removed.	
NOTE: Precautions should be taken when opening door(s).						

REVISION NO. 11

PAGE NO. 52-3

DATE: 11/10/2020

AIRCRAFT:
Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

52. Doors

Sequence No.	Item	1	2	3	4	Change Bar
-46-01 ***	Single-point Refueling (SPR) Access Door Key Lock					
-00A	(Failed Unlocked)	D	1	0	May be inoperative provided door is verified closed and latched prior to each flight.	
-00B	(Failed Locked)	C	1	0	NOTE: If over-wing refueling cap locks are also failed in locked position, refueling will not be possible.	
-48-01	Tail Cone Access Door Key Lock (Failed Unlocked)	D	1	0	May be inoperative provided door is verified closed and latched prior to each flight.	
-70-01	Door Warning System					
-01	Aft Baggage	C	1	0	May be inoperative provided door is verified closed, latched, and locked prior to each flight.	
-02	Nose Access	C	2	0	May be inoperative provided door is verified closed, latched, and locked prior to each flight.	
-03	Main Cabin	B	1	0	(O) May be inoperative provided: a) Lock flags are visible in all door sight glass locations, b) Internal door handle is verified correctly stowed, and c) Seat(s) immediately adjacent to or across from door are blocked and placarded "DO NOT OCCUPY".	
-04	Single-Point Refueling (SPR)	C	1	0	May be inoperative provided door is verified closed and latched prior to each flight.	
-05	Toilet External Service	C	1	0	May be inoperative provided door is verified closed and latched prior to each flight.	

REVISION NO. 11

PAGE NO. 57-1

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

57. Wings

Sequence No.	Item	1	2	3	4	Change Bar
-20-01	Wing Vortex Generator (Per Side)	C	11	10	One may be missing or damaged.	

REVISION NO. 11

PAGE NO. 73-1

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

73. Engine Fuel and Control

Sequence No.	Item	1	2	3	4	Change Bar
-33-01	Fuel Flow Indicating System	A	2	1	One may be inoperative provided: a) All fuel quantity indicating systems are operative, and b) Repairs are made within 3 flight-days.	

REVISION NO. 11
 DATE: 11/10/2020

PAGE NO. 76-1

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

76. Engine Control

Sequence No.	Item	1	2	3	4	Change Bar
-00-01 ***	Automatic Performance Reserve (Units -0001 thru -0241)	C	1	0		
-00-01	Automatic Performance Reserve (Units -7001 thru -7119)	C	1	0		
-01-01	Engine Synchronizer System (Failed Off)	C	1	0		
-01	ON Light	D	1	0	May be inoperative provided ENGINE SYNC selector is verified OFF prior to takeoff and landing.	

REVISION NO. 11

PAGE NO. 77-1

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

77. Engine Indicating

Sequence No.	Item	1	2	3	4	Change Bar
-14-01	Engine RPM Gauge/Indication (N ₁ Tape or Digital Indicator)	B	4	3	One may be inoperative.	
-22-01	Engine ITT Gauge/Indication (N ₁ Tape or Digital Indicator)	B	4	3	One may be inoperative.	
-01	Ignition Light (Green IGN L-R)	C	2	1	One may be inoperative.	

REVISION NO. 11

PAGE NO. 78-1

DATE: 11/10/2020

AIRCRAFT:
 Textron Aviation Model 650

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

78. Engine Exhaust

Sequence No.	Item	1	2	3	4	Change Bar
-30-01	Thrust Reverser	C	2	0	(M) May be inoperative provided affected thrust reverser is deactivated and secured in forward thrust position.	