



U.S. Department of Transportation
Federal Aviation Administration
Washington, DC

Master Minimum Equipment List (MMEL)

Revision: 8
Date: 09/18/2020

Dassault Aviation **Falcon 2000EX EASy/DX/LX/S/LXS**

Chad S. Shackford, Chair
Flight Operations Evaluation Board (FOEB)

Federal Aviation Administration (FAA)
Transport Aircraft Seattle Aircraft Evaluation Group (SEA-AEG)
2200 S. 216th St, 2nd Floor, North Wing
Des Moines, WA 98198

Telephone: (206) 231-3914

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. I

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE OF CONTENTS AND CONTROL PAGE

SYSTEM NO.	SYSTEM	PAGE NO.	REV NO.	DATE
--	Cover Page	--	8	09/18/2020
--	Table of Contents and Control Page	I	8	09/18/2020
--	Log of Revisions	II	8	09/18/2020
--	Highlights of Change	III thru V	8	09/18/2020
--	Definitions and Preamble	VI	8	09/18/2020
21	Air Conditioning	21-1 thru 8	8	09/18/2020
22	Autoflight	22-1 thru 6	8	09/18/2020
23	Communications	23-1 thru 9	8	09/18/2020
24	Electrical Power	24-1	6	11/18/2016
25	Equipment/Furnishings	25-1 thru 15	8	09/18/2020
26	Fire Protection	26-1	6	11/18/2016
27	Flight Controls	27-1 thru 3	7	07/05/2018
28	Fuel	28-1 thru 8	7a	07/24/2018
29	Hydraulic Power	29-1, 2	8	09/18/2020
30	Ice and Rain Protection	30-1 thru 4	8	09/18/2020
31	Indicating/Recording Systems	31-1 thru 5	8	09/18/2020
32	Landing Gear	32-1 thru 3	8	09/18/2020
33	Lights	33-1 thru 5	7	07/05/2018
34	Navigation	34-1 thru 17	8	09/18/2020
35	Oxygen	35-1	6	11/18/2016
36	Pneumatic	36-1 thru 4	8	09/18/2020
38	Water/Waste	38-1, 2	6	11/18/2016
45	Central Maintenance System	45-1	7	07/05/2018
46	Information Systems	46-1, 2	8	09/18/2020
49	Airborne Auxiliary Power	49-1, 2	6	11/18/2016
52	Doors	52-1	6	11/18/2016
73	Engine Fuel and Control	73-1	7	07/05/2018
74	Ignition	74-1	6	11/18/2016
77	Engine Indicating	77-1	7	07/05/2018
78	Engine Exhaust	78-1	7	07/05/2018
79	Engine Oil	79-1	8	09/18/2020
80	Starting	80-1, 2	6	11/18/2016

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. II

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

LOG OF REVISIONS

REV NO.	DATE	PAGE NO.
Original	09/13/2004	All Pages
1	02/06/2006	Cover Page, Table of Contents, Log of Revisions, Control Page, 21-5, 21-13 thru 14, 23-1 thru 4, 28-15, 31-1 thru 14, 32-6, 33-3, 34-2, 34-6, 49-2, 74-1, 80-1
2	12/14/2006	Cover Page, Table of Contents, Log of Revisions, Control Page, 21-1, 21-6, 21-11, 21-15, 22-1, 22-3, 23-3 thru 4, 25-8, 27-1 thru 2, 28-3 thru 27, 30-2 thru 3, 31-1 thru 6, 31-8 thru 13, 32-1 thru 8, 34-1, 34-3, 34-7 thru 8, 36-4 thru 11, 49-1
3	01/25/2008	Cover Page, Table of Contents, Log of Revisions, Control Page, Highlights of Change, 21-3 thru 25, 21-28, 22-1, 23-1 thru 6, 25-2 thru 6, 25-8 thru 11, 26-1, 27-4, 28-10, 28-20 thru 21, 29-2, 30-1 thru 2, 31-2, 31-7, 31-11, 32-3 thru 8, 33-2, 33-4, 34-1, 34-4 thru 11, 36-2 thru 5, 36-10, 46-1 thru 2, 49-1, 73-1
4	11/11/2009	Cover Page, Table of Contents, Highlights of Change, Definitions, Preamble, 21-1 thru 28, 22-1 thru 3, 23-1 thru 6, 25-1 thru 10, 27-1 thru 4, 28-1 thru 21, 29-1 thru 2, 30-1 thru 3, 31-1 thru 13, 32-1 thru 9, 33-1 thru 3, 34-1 thru 12, 35-1, 36-1 thru 11, 38-1 thru 2, 46-1 thru 2, 49-1 thru 2, 74-1, 77-1, 78-1, 79-1
5	04/04/2013	Cover Page, Table of Contents, Highlights of Change, Definitions, Preamble, 21-1 thru 7, 22-1 thru 3, 23-1 thru 9, 24-1, 25-1 thru 11, 27-1 thru 4, 28-1 thru 7, 29-1 thru 2, 30-1 thru 4, 31-1 thru 2, 32-1 thru 4, 33-1 thru 5, 34-1 thru 12, 36-1 thru 6, 45-1, 49-1 thru 2, 52-1, 73-1 thru 2, 78-1 thru 2, 79-1
6	11/18/2016	All Pages
7	07/05/2018	Cover Page, Table of Contents and Control Page, Log of Revisions, Highlights of Change, 21-1 thru 8, 22-1 thru 6, 23-1 thru 8, 25-1 thru 14, 27-1 thru 3, 28-1 thru 8, 30-1 thru 3, 31-1 thru 5, 32-1 thru 3, 33-1 thru 5, 34-1 thru 15, 36-1 thru 4, 45-1, 46-1, 46-2, 73-1, 77-1, 78-1
7a	07/24/2018	Cover Page, Table of Contents and Control Page, Log of Revisions, Highlights of Change, 28-1 thru 8, 30-1 thru 3
8	09/18/2020	Cover Page, Table of Contents and Control Page, Log of Revisions, Highlights of Change, Definitions and Preamble, 21-5, 21-7, 22-1, 23-9, 25-10, 25-12, 25-13, 25-14, 29-1, 30-1, 30-4, 31-3, 32-1, 34-2 thru 6, 36-1, 46-1, 46-2, 79-1

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. III

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

HIGHLIGHTS OF CHANGE

The following changes are the Highlights of Changes for **Revision 8**.

PAGE NO.	EXPLANATION OF CHANGE
General	Minor editorial corrections were made throughout the document that do not affect the reliefs and are not indicated with change bars. These editorial corrections may be adopted in minimum equipment lists (MEL) at the operator's discretion.
ATA 21 Air Conditioning 21-5 21-5 21-5 21-7	Item 21-32-06: Deleted item. Item 21-52-00: Modified item. Item 21-60-00: Modified item, dispatch case deleted, sub-items unchanged. Item 21-64-02: Modified item, second dispatch case deleted.
ATA 22 Autoflight 22-1	Item 22-10-00-30: Modified item, new dispatch cases pending applicability.
ATA 23 Communications 23-9	Item 23-70-00: Modified item, 2 dispatch cases pending applicability.
ATA 25 Equipment/Furnishings 25-10 25-12 25-13 25-14	Item 25-50-00: Added item. Item 25-61-00 and subitems: Modified according to PL-120. Item 25-61-00 and subitems: Modified according to PL-120. Item 25-63-00: Modified item, added ***.
ATA 29 Hydraulic Power 29-1	Item 29-13-09: Corrected typo.

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. IV

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

HIGHLIGHTS OF CHANGE

PAGE NO.	EXPLANATION OF CHANGE
ATA 30 Ice and Rain Protection 30-1 30-4 30-4	Item 30-20-01: Modified dispatch cases A and B, added dispatch case C. Item 30-43-00: Modified item, (O) added for both dispatch case proviso b). Item 30-90-01: Corrected typo "secured in closed position."
ATA 31 Indicating/Recording Systems 31-3	Item 31-57-10-21: Corrected typo.
ATA 32 Landing Gear 32-1	Item 32-30-00: Modified item.
ATA 34 Navigation 34-2, 34-3 34-3 34-4, 34-5 34-5 34-6	Item 34-31-01-10: Modified item, 2 dispatch cases pending applicability. Item 34-31-01-20: Added item. Item 34-32-00-10: Modified item, 4 dispatch cases pending applicability. Added ***. Item 34-32-00-20: Modified item, 2 dispatch cases pending applicability. Item 34-32-00-30: Added item.
ATA 36 Pneumatic 36-1	Item 36-00-01: Modified item, sub-items unchanged.

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. V

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

HIGHLIGHTS OF CHANGE

PAGE NO.	EXPLANATION OF CHANGE
ATA 46 Information Systems 46-1 46-1 46-1 46-2 46-2 46-2 46-2	Item 46-20-00: Modified item name, added ***. Item 46-20-00-01: Deleted item, added ***. Item 46-20-00-02: Deleted item. Item 46-20-00-03: Modified item, added ***. Item 46-20-00-04: Modified item, added ***. Item 46-20-00-05: Modified item, added ***. Item 46-50-01: Modified item, applicability removed, corrected typo, added ***.
ATA 79 Engine Oil 79-1	Item 79-30-03: Modified item.

Definitions

Refer to the current FAA MMEL Policy Letter (PL) 25, MMEL and MEL Definitions, found on the FAA Flight Standards Information Management System (FSIMS) website at:

[FSIMS - Publications - MMEL Policy Letters](#)

In addition to the definitions contained in PL-25, for the purpose of this document, the following definitions apply.

“Icy Runway,” means a runway on which there is ice, as defined hereafter: Water, which has frozen on the runway surface, including the condition where compacted snow transitions to a polished ice surface.

Preamble

For operations under Title 14 of the Code of Federal Regulations (14 CFR) parts 91 subpart K (part 91K), 121, 125, 125 LODA, 129, and 135, refer to the current FAA MMEL PL-34, MMEL and MEL Preamble. For operations under 14 CFR part 91, refer to current FAA MMEL PL-36, 14 CFR Part 91 MEL Approval and Preamble. Both PLs are found on the FAA Flight Standards Information Management System (FSIMS) website.

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 21-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-20-05	Cockpit Gasper	C	2	0	One or more may be inoperative provided at least one Cockpit Gasper remains in open position.	
21-20-10	Cold Fan Pressure Control Valve	C	1	0	May be inoperative provided all display units (DU) are operative.	
21-20-15	Glare Shield Cold Air Manual Control	C	1	0	May be inoperative.	
21-20-16	Air Conditioning Distribution Lever	C	2	0	One or more may be inoperative provided affected lever is set to windshield position.	
21-30-00	Cabin Temperature Indicator	C	1	0	May be inoperative.	
21-30-05	UP-DN Manual Controller					
21-30-05-A		C	1	0	(M)(O) May be inoperative provided: a) Flight level is limited to FL 250 or below, b) Cabin Pressure Controller (CPC) is verified operative, c) UP-DN Manual Controller is set in the green index mark, and d) DUMP mode is verified operative before each departure.	
21-30-05-B		C	1	0	(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, and b) All DUs are operative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 21-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-30-09	Triple Cabin Indication					
21-30-09-01	Cabin Altitude Indication					
21-30-09-01-A		C	1	0	(O) May be inoperative provided: a) Cabin Differential Pressure Indication is verified operative, and b) CPC is verified operative.	
21-30-09-01-B		C	1	0	(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, and b) All DUs are operative.	
21-30-09-02	Cabin Differential Pressure Indication					
21-30-09-02-A		C	1	0	(O) May be inoperative provided the Cabin Altitude Indication is verified operative.	
21-30-09-02-B		C	1	0	(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, and b) All DUs are operative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 21-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-30-09-03	Cabin Vertical Speed Indication					
21-30-09-03-A		C	1	0	(O) May be inoperative provided the Cabin Altitude Indication and Cabin Differential Pressure Indication are verified operative.	
21-30-09-03-B		C	1	0	(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, and b) All DUs are operative.	
21-31-09	Nose Cone Fan	C	1	0	(M)(O) May be inoperative provided: a) High Frequency (HF) Radio is not used below 10,000 ft, b) Duration of ground operations is limited, c) Nose Cone optional pieces of equipment are considered inoperative and associated breakers are pulled and collared, d) NOSE CONE OVHT Warning System is verified operative, and e) NOSE CONE OVHT amber CAS message is not displayed.	

REVISION NO. 8
DATE: 09/18/2020

PAGE NO. 21-4

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-32-00	Cabin Pressure Controller (CPC)					
21-32-00-A		C	1	0	(M)(O) May be inoperative provided: <ol style="list-style-type: none"> a) Flight level is limited to FL 250 or below, b) Departure and destination airfield elevations are below 8,000 ft, c) MAN amber label is displayed on ECS synoptic page, d) CABIN ALTITUDE red CAS message and Aural Warning are verified operative, e) UP-DN Manual Controller and DUMP mode are verified operative before each departure, f) Cabin Altitude, Cabin Differential Pressure, and Cabin Vertical Speed Indications are verified operative, g) UP-DN Manual Controller is set to the RH part of the white arc for takeoff, and h) Cabin Altitude, Cabin Differential Pressure, and Cabin Vertical Speed Indications are closely monitored during the flight. 	
21-32-00-B		C	1	0	(O) May be inoperative provided: <ol style="list-style-type: none"> a) Flight is conducted in an unpressurized configuration, and b) All DUs are operative. 	
21-32-00-01	ARINC Input Data Bus Function	C	3	-	May be inoperative.	
21-32-00-02	Discrete Input Data Function	C	2	0	One or more may be inoperative.	

REVISION NO. 8

PAGE NO. 21-5

DATE: 09/18/2020

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-32-06	Outflow Pressurization Valve				DELETED Revision 8.	
21-32-10	Cabin Pressurization LOW Rate Control	C	1	0	May be inoperative provided it remains off.	
21-51-13	Cabin Air Recirculation Valve	C	1	0	(O) May be inoperative provided: a) RECIRC switch is set to ISOL, and b) Recirculation Valve is verified in closed position before each departure.	
21-52-00	Environmental Control Unit (ECU)	C	1	0	(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, b) MANUAL Mode of Air Conditioning Valves is verified operative, c) Hot air flow is verified blowing at crew air distribution outlets, and d) All DUs are operative.	
21-52-11	Jet Pump Valve	C	1	0	(O) May be inoperative provided: a) Jet Pump Valve is verified in closed position, b) All DUs are operative, c) BLEED AIR CABIN and CKPT pushbuttons are set to OFF on ground and in flight when TAS is below 300 kts, and d) BLEED AIR CABIN and CKPT pushbuttons are set to AUTO in flight only when TAS is above 300 kts.	
21-52-31	ECU Bypass Valve	C	1	0	May be inoperative.	
21-60-00	Temperature Control System (TCS)				DELETED Revision 8.	

REVISION NO. 8
DATE: 09/18/2020

PAGE NO. 21-6

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-60-00-10	Alarm Light Command Function (Auto Cockpit, Auto Cabin, and Manual Mode)	A	3	0	One or more may be inoperative provided: a) TCS fault codes are considered before each departure, and b) Repairs are made within 3 consecutive calendar-days.	
21-60-00-20	Turbine Temperature Control Function (Auto and Manual Mode)	A	6	0	One or more may be inoperative provided repairs are made within 2 consecutive calendar-days.	
21-60-00-30	AUTO Mode	A	2	0	(O) One or more may be inoperative provided: a) MANUAL mode is verified operative, and b) Repairs are made within 3 consecutive calendar-days.	
21-60-00-31	Thrust Lever Position Function	A	2	1	One may be inoperative provided: a) Thrust Levers are operative, and b) Repairs are made within 3 consecutive calendar-days.	
21-60-00-32	Computer Dialog Function (Cockpit and Cabin)	A	2	1	One may be inoperative provided repairs are made within 3 consecutive calendar-days.	
21-60-00-33	Compressor Overheat Sensor Function (Cockpit and Cabin)	A	2	1	One may be inoperative provided repairs are made within 3 consecutive calendar-days.	
21-60-00-34	CREW and PAX Auto Temperature Potentiometer Function	A	2	0	One or more may be inoperative provided repairs are made within 3 consecutive calendar-days.	
21-60-00-35	Cockpit and Cabin Duct Temperature Sensor Function	A	2	1	One may be inoperative provided repairs are made within 2 consecutive calendar-days.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 21-7

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-60-00-40	MANUAL Mode	C	1	0	(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, and b) All DUs are operative.	
21-60-00-41	CREW and PAX Manual Temperature Potentiometer Function	A	2	1	One may be inoperative provided repairs are made within 3 consecutive calendar-days.	
21-60-05	Cabin Duct Temperature Indication	C	1	0	May be inoperative.	
21-64-00	Cabin Temperature Remote Control	C	1	0	May be inoperative.	
21-64-02	Hot Conditioning Valve	C	2	1	(M) One may be inoperative provided: a) Flight level is limited to FL 410 or below, b) Manual Air Conditioning Interconnect Valve is set in open position, and c) Affected Hot Conditioning Valve is secured in closed position.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 21-8

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

21. Air Conditioning

Sequence No.	Item	1	2	3	4	Change Bar
21-64-03	Cold Conditioning Valve					
21-64-03-A		C	2	1	(M) One may be inoperative provided: a) Flight level is limited to FL 410 or below, and b) Affected Cold Conditioning Valve is secured in closed position.	
21-64-03-B		C	2	0	(M)(O) Both may be inoperative provided: a) Flight is conducted in an unpressurized configuration, b) All DUs are operative, and c) Both Cold Conditioning Valves are secured in closed position.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 22-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
22-10-00	Autopilot (AP) Computer					
22-10-00-10	AP Function					
22-10-00-10-A		C	2	1	One may be inoperative.	
22-10-00-10-B		B	2	0	(O) Both may be inoperative provided: a) Enroute operations or approaches do not require its use, b) Number of flight legs and flight leg durations are acceptable to the flightcrew, and c) Flying Duration Limitations of the operating procedure are applied.	
22-10-00-20	Flight Director (FD) Function	C	2	0	One or more may be inoperative provided AP Function is not used (item 22-10-00-10).	
22-10-00-30	Yaw Damper (YD) Function					
22-10-00-30-A		C	2	1	One may be inoperative.	
22-10-00-30-B	A/C without M-OPT0063	C	2	0	(O) Both may be inoperative provided rudder is verified centered before each departure. NOTE: AP can be used without YD.	
22-10-00-30-C	A/C with M-OPT0063	C	2	0	(O) Both may be inoperative provided: a) Approaches with Enhanced Vision System (EVS) operational credit are not conducted, and b) Rudder is verified centered before each departure. NOTE: AP can be used without YD.	

REVISION NO. 8

PAGE NO. 22-2

DATE: 09/18/2020

AIRCRAFT:
Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
22-10-00-40	Mach Trim (MT) Function					
22-10-00-40-A		C	2	1	One may be inoperative.	
22-10-00-40-B		C	2	0	One or more may be inoperative provided flight envelope is limited to MI 0.80.	
22-10-00-60	Autothrottle (AT) Function	C	1	0	May be inoperative.	
22-10-01	Flight Guidance Panel					
22-10-01-01	FD/TD Pushbuttons					
22-10-01-01-A		C	2	1	(O) One may be inoperative provided FD and TD symbols are verified operative.	
22-10-01-01-B		C	2	0	(O) Both may be inoperative provided: a) FD and TD symbols are verified operative, and b) Approaches do not require its use.	
22-10-01-02	APP Pushbutton	C	1	0	(O) May be inoperative provided approaches do not require its use.	
22-10-01-03	AP Pushbutton	B	1	0	May be inoperative provided AP Function is not used (item 22-10-00-10).	
22-10-01-05	AT Pushbutton	C	1	0	May be inoperative provided AT Function is not used (item 22-10-00-60).	
22-10-01-06	Lateral Navigation (LNAV) Pushbutton	C	1	0	(O) May be inoperative provided: a) FD Heading/Track (HDG/TRK) select mode is operative, and b) Enroute operations do not require its use.	
22-10-01-08	YD Pushbutton	C	1	0	May be inoperative.	

REVISION NO. 8
DATE: 09/18/2020

PAGE NO. 22-3

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
22-10-01-09	CLB Pushbutton	C	1	0	(O) May be inoperative provided enroute operations do not require its use.	
22-10-01-10	VS Pushbutton	C	1	0	(O) May be inoperative provided enroute operations do not require its use.	
22-10-01-11	Vertical Navigation (VNAV) Pushbutton	C	1	0	(O) May be inoperative provided enroute operations do not require its use.	
22-10-01-13	ALT Pushbutton	C	1	0	May be inoperative provided Airplane Single-Engine Land (ASEL) Control is operative.	
22-10-01-40	MACH/KTS SPEED Control					
22-10-01-41	SPEED Readout	C	1	0	May be inoperative.	
22-10-01-42	MAN/FMS Selector	C	1	0	May be inoperative.	
22-10-01-43	SPEED Rotactor	C	1	0	May be inoperative provided: a) AT Function is not used (item 22-10-00-60), and b) FD CLB mode is not used.	
22-10-01-44	PUSH CHG Pushbutton					
22-10-01-44-A		C	1	0	May be inoperative with display in KTS.	
22-10-01-44-B		C	1	0	May be inoperative with display in MACH provided: a) AT Function is not used below MI 0.50 (item 22-10-00-60), and b) FD CLB mode is not used below MI 0.50.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 22-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
22-10-01-70	HDG/TRK					
22-10-01-71	HDG/TRK Readout	C	1	0	May be inoperative.	
22-10-01-72	HDG/TRK Selector	C	1	0	May be inoperative with HDG select.	
22-10-01-73	PUSH SYNC Pushbutton	C	1	0	May be inoperative.	
22-10-01-80	ASEL Control					
22-10-01-81	ASEL Readout	C	1	0	May be inoperative provided ASEL is displayed on PDU.	
22-10-01-82	100FT/1000FT Selector	C	1	0	May be inoperative provided 100FT selection is operative.	
22-10-02	AP Rudder Linear Actuator	C	1	0	(O) May be inoperative provided: a) Rudder is visually verified centered before each departure, b) YD Function is considered inoperative (item 22-10-00-30), and c) AP Function is not used (item 22-10-00-10).	

REVISION NO. 8

PAGE NO. 22-5

DATE: 09/18/2020

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
22-10-03	Actuator Input/Output Processor (AIOP) Module					
22-10-03-01	AIOP 1A and/or AIOP 1B	B	2	0	One or more may be inoperative provided: a) AP Function (AP1) is considered inoperative (item 22-10-00-10), b) YD Function (YD1) is considered inoperative (item 22-10-00-30), and c) AT Function is considered inoperative (item 22-10-00-60).	
22-10-03-02	AIOP 2A and/or AIOP 2B	B	2	0	One or more may be inoperative provided: a) AP Function (AP2) is considered inoperative (item 22-10-00-10), and b) YD Function (YD2) is considered inoperative (item 22-10-00-30).	
22-10-03-03	AIOP 1A and/or AIOP 1B and AIOP 2A and/or AIOP 2B	A	4	0	One or more may be inoperative provided: a) AP Function is considered inoperative (item 22-10-00-10), b) YD Function is considered inoperative (item 22-10-00-30), c) AT Function is considered inoperative (item 22-10-00-60), d) MT Function is considered inoperative (item 22-10-00-40), and e) Repairs are made within 3 consecutive calendar-days.	

REVISION NO. 8

PAGE NO. 22-6

DATE: 09/18/2020

AIRCRAFT:
Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

22. Autoflight

Sequence No.	Item	1	2	3	4	Change Bar
22-10-05	Servomotor (Pitch and Roll)	B	2	0	One or more may be inoperative provided AP Function is considered inoperative (item 22-10-00-10).	
22-10-10	AP Quick Disconnect Pushbutton					
22-10-10-A		C	2	1	(O) One may be inoperative provided: a) AP is not used at or below 1,500 ft above ground level (AGL), and b) Approach minimums do not require the use of the AP.	
22-10-10-B		B	2	0	Both may be inoperative provided AP Function is not used (item 22-10-00-10).	
22-10-11	Go-Around (GA) or Takeoff/Go-Around (TOGA) Pushbutton	C	2	1	One may be inoperative provided approaches are conducted on the non-affected side.	
22-10-12	Touch Control Steering (TCS) Pushbutton	C	2	0	One or more may be inoperative provided the associated AP Quick Disconnect Pushbutton is operative.	
22-30-10	AT Quick Disconnect Pushbutton	C	2	0	One or more may be inoperative provided: a) AT Pushbutton on Flight Guidance Panel is operative, and b) AT is not used below 1,500 ft AGL.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 23-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-11-00	Very/Ultra High Frequency (VHF/UHF) Communication System	D	-	-	Any in excess of those required by 14 CFR may be inoperative provided: a) VHF #1 is operative, and b) Affected VHF is not powered by the emergency bus, battery bus, battery direct bus, or the direct current (DC) transfer bus and not required for emergency procedures. NOTE 1: Controller-Pilot Data Link Communications (CPDLC)/Aeronautical Telecommunications Network (ATN) B1 function (Aircraft with M3309) is not used if VHF #3 is inoperative. NOTE 2: CPDLC/Future Air Navigation System (FANS)-1A VHF #3-based function (Aircraft with M3402) may be affected.	
23-11-05	VHF Tuning Knobs (on Guidance Panel)	C	2	1	One may be inoperative provided both VHF may be tuned by Cursor Control Device (CCD) and Multi-functions Keyboards (MKB).	
23-12-00	HF Communication System					
23-12-00-A		D	-	-	Any in excess of those required by 14 CFR may be inoperative.	

(Continued)

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-12-00	HF Communication System (Cont'd)					
23-12-00-B		C	-	1	(O) May be inoperative while conducting operations that require two long-range communication system (LRCS) provided: <ol style="list-style-type: none"> a) Aircraft Satellite Voice (SATVOICE) system operates normally, b) SATVOICE services are available as an LRCS over the intended route of flight, c) The International Civil Aviation Organization (ICAO) Flight Plan is updated (as required) to notify air traffic control (ATC) of the communications equipment status of the aircraft, and d) Alternate procedures are established and used. 	
23-15-00 ***	Satellite Communications (SATCOM)	D	-	0	May be inoperative provided procedures do not require its use.	
23-15-15 ***	Flight Phone	D	-	0	May be inoperative.	
23-20-05	Cockpit Voice Recorder (CVR)					
23-20-05-A ***	With Flight Data Recorder (FDR) Installed	A	1	0	May be inoperative provided: <ol style="list-style-type: none"> a) FDR operates normally, and b) Repairs are made within 3 flight-days. 	
23-20-05-B	Without FDR Installed	A	1	0	May be inoperative provided repairs are made within 3 flight-days.	
23-20-05-C	For an Operator Other Than a Holder of an Air Carrier or Commercial Operator Certificate	A	1	0	May be inoperative provided repairs are made in accordance with applicable 14 CFRs.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 23-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-20-05-30 ***	Recorder Independent Power Supply (Aircraft with M3315)	C	1	0	May be inoperative.	
23-20-10 ***	Selective Call (SELCAL) System					
23-20-10-A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
23-20-10-B		D	1	0	May be inoperative provided procedures do not require its use.	
23-20-10-01	Channel					
23-20-10-01-A		C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
23-20-10-01-B		D	-	0	May be inoperative provided procedures do not require its use.	
23-20-11 ***	Aircraft Communications Addressing and Reporting System (ACARS)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
23-20-15 ***	Controller-Pilot Data Link Communication (CPDLC)					
23-20-15-01	ATN B1 Function (Aircraft with M3309)					
23-20-15-01-A		D	1	0	May be inoperative provided enroute operations do not require its use.	
23-20-15-01-B		C	1	0	(O) May be inoperative provided alternate procedures are established and used.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 23-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-20-15-02	FANS-1A Function (Aircraft with M3402)					
23-20-15-02-A		D	1	0	(O) May be inoperative provided enroute operations do not require its use.	
23-20-15-02-B		C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
23-20-25 ***	Airborne Flight Information System (AFIS)	D	1	0	May be inoperative.	
23-20-25-10	AFIS Uplink Weather Function (Aircraft with M2765)	D	1	0	May be inoperative.	
23-21-00 ***	Data Transmission Unit (DTU) System (A/C with M3158)	D	1	0	(M) May be inoperative or removed provided: a) "DTU" C/B is pulled and collared, and b) Engine data download is performed as per the Pratt & Whitney Canada (P&WC) Engine Maintenance Manual.	
23-50-00	Audio Panel					
23-50-00-05	ST Pushbutton	C	-	0	May be inoperative.	
23-50-00-10	Automatic Direction Finder (ADF) Pushbutton					
23-50-00-10-A		C	-	1	Any in excess of one may be inoperative.	
23-50-00-10-B		C	-	0	May be inoperative provided the associated ADF is considered inoperative (item 34-53-00).	

REVISION NO. 8
DATE: 09/18/2020

PAGE NO. 23-5

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-50-00-20	MKR Pushbutton					
23-50-00-20-A		C	-	1	Any in excess of one may be inoperative.	
23-50-00-20-B		C	-	0	May be inoperative provided approaches do not require use of the Marker Beacon System.	
23-50-00-25	MUTE Pushbutton					
23-50-00-25-A		C	-	1	Any in excess of one may be inoperative.	
23-50-00-25-B		C	-	0	May be inoperative provided approaches do not require use of the Marker Beacon System.	
23-50-00-35	VCE Pushbutton					
23-50-00-45	SPKR Pushbutton					
23-50-00-55	VHF Pushbutton (MIC or AUD)	D	-	0	May be inoperative provided the associated VHF/UHF is considered inoperative (item 23-11-00).	
23-50-00-60	HF Pushbutton (MIC or AUD)	D	-	0	May be inoperative provided the associated HF is considered inoperative (item 23-12-00).	
23-50-00-65	SAT Pushbutton (MIC or AUD)	D	-	0	May be inoperative provided SATCOM is considered inoperative (item 23-15-00).	
23-50-00-70	Distance Measuring Equipment (DME) Pushbutton	D	-	0	May be inoperative provided the associated DME is considered inoperative (item 34-52-00).	
23-50-00-80	CONF Pushbutton	C	-	0	May be inoperative.	

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-50-00-85	XFER Pushbutton	C	-	0	May be inoperative.	
23-50-00-90	HDPH Pushbutton	D	-	0	May be inoperative provided associated Headset is considered inoperative (item 23-50-80).	
23-50-00-95	GRND Pushbutton	C	-	1	Any in excess of one may be inoperative.	
23-50-02 ***	Third Audio Panel (Aircraft with M2689 or M3426)					
23-50-02-A		A	1	0	May be inoperative provided: a) Forward Observer Seat is considered inoperative (item 25-11-20), and b) Repairs are made within 2 flight-days.	
23-50-02-B		D	1	0	May be inoperative provided Forward Observer Seat is not required by 14 CFR.	
23-50-75	Cockpit Speaker	C	2	0	One or more may be inoperative provided: a) Procedures do not require its use, and b) Associated Headset is installed and used.	
23-50-80	Headset, Microphone					
23-50-80-10	Headset Boom Microphone					
23-50-80-10-A	Holder of an Air Carrier or Commercial Operator Certificate	A	-	0	May be inoperative provided: a) Associated Hand Microphone is installed and operates normally, and b) Repairs are made within 3 flight-days.	
23-50-80-10-B	Holder of an Air Carrier or Commercial Operator Certificate	D	-	-	Any in excess of those required by regulation may be inoperative.	

(Continued)

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 23-7

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-50-80	Headset, Microphone (Cont'd)					
23-50-80-10	Headset Boom Microphone (Cont'd)					
23-50-80-10-C	Operator Other Than a Holder of an Air Carrier or Commercial Certificate	A	-	0	May be inoperative provided: a) Associated Hand Microphone is installed and operates normally, and b) Repairs are made in accordance with applicable regulations.	
23-50-80-10-D	Operator Other Than a Holder of an Air Carrier or Commercial Certificate	D	-	-	Any in excess of those required by regulation may be inoperative.	
23-50-80-20	Headset Earphones/Headphones					
23-50-80-20-A	Holder of an Air Carrier or Commercial Operator Certificate	C	-	1	May be inoperative provided associated Cockpit Speaker operates normally.	
23-50-80-20-B	Holder of an Air Carrier or Commercial Operator Certificate	D	-	-	Any in excess of those required by regulation may be inoperative.	
23-50-80-20-C	Operator Other Than a Holder of an Air Carrier or Commercial Certificate	C	-	1	May be inoperative provided associated Cockpit Speaker operates normally.	
23-50-80-30	Hand Microphone					
23-50-80-30-A	Holder of an Air Carrier or Commercial Operator Certificate	C	-	0	May be inoperative provided associated Boom Microphone operates normally.	
23-50-80-30-B	Holder of an Air Carrier or Commercial Operator Certificate	D	-	0	Any in excess of those required by regulation may be inoperative.	
(Continued)						

REVISION NO. 8

PAGE NO. 23-8

DATE: 09/18/2020

AIRCRAFT:
Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-50-80	Headset, Microphone (Cont'd)					
23-50-80-30	Hand Microphone (Cont'd)					
23-50-80-30-C	Operator Other Than a Holder of an Air Carrier or Commercial Certificate	C	-	0	May be inoperative provided associated Boom Microphone operates normally.	
23-50-80-30-D	Operator Other Than a Holder of an Air Carrier or Commercial Certificate	D	-	0	Any in excess of those required by regulation may be inoperative.	
23-50-95	Public Address (PA) System					
23-50-95-A	Passenger Configuration	B	1	0	(O) May be inoperative provided: a) Alternate, normal, and emergency procedures and/or operating restrictions are established and used, and b) Flight attendant alerting (audio and visual) system operates normally. NOTE: Any station function(s) that operates normally may be used.	
23-50-95-B		C	1	0	(O) May be inoperative provided: a) PA not required by 14 CFR, and b) Alternate, normal, and emergency procedures and/or operating restrictions are established and used.	
23-50-95-C	Cargo Configuration	D	1	0	May be inoperative provided procedures do not require its use.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 23-9

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

23. Communications

Sequence No.	Item	1	2	3	4	Change Bar
23-70-00 ***	Video System (Aircraft with M2516)					
23-70-00-A ***	A/C without M-OPT0063	D	1	0	May be inoperative.	
23-70-00-B ***	A/C with M-OPT0063	D	1	0	(O) May be inoperative provided approaches with EVS operational credit are not conducted.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 24-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

24. Electrical Power

Sequence No.	Item	1	2	3	4	Change Bar
24-32-05	Battery Fan					
24-32-05-A	Aircraft without M2674	C	1	0	(O) May be inoperative provided BAT .. TEMP INOP amber CAS message is not displayed.	
24-32-05-B ***	Aircraft with M2674	D	1	0	May be inoperative.	
24-33-01	Auxiliary Power Unit (APU) Starter Generator	C	1	0	(O) Electrical Generator function may be inoperative.	
24-40-05	EXT PWR Switch					
24-40-05-10	Light Bulb	C	4	2	One or two may be inoperative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-11-00	Crewmember Seat					
25-11-00-10	Vertical Adjustment	B	2	0	(M)(O) One or more may be inoperative provided: a) Seat is secured at the individual crewmember's requirements, and b) Associated CREW SEATS C/B is pulled and collared.	
25-11-00-15	Recline Adjustment	B	2	0	One or more may be inoperative provided: a) Seat is able to move full Fore and Aft on its track, and b) Seat is secured at a position acceptable to the affected crewmember.	
25-11-00-20	Armrest					
25-11-00-20-A		C	4	0	One or more may be inoperative provided: a) Affected Armrest is in the up position, and b) Seat is acceptable to the affected crewmember.	
25-11-00-20-B		C	4	0	(M) One or more may be inoperative provided: a) Affected Armrest is removed, and b) Seat is acceptable to the affected crewmember.	
25-11-00-30	Headrest	C	2	0	(O) One or more Headrests fairing only may be damaged provided: a) Seat is acceptable to the affected crewmember, and b) Headrest structure is verified adequate.	
25-11-10	Crewmember Inertial Reel	C	2	1	One may be jammed in locked position provided the tension of the harness is adequate.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-11-20 ***	Forward Observer Seat (Including Associated Equipment)					
25-11-20-A		A	1	0	May be inoperative provided: a) A passenger seat in the passenger cabin is made available to an FAA inspector for the performance of official duties, and b) Repairs are made within 2 flight-days.	
25-11-20-B		A	1	0	May be inoperative provided: a) Required minimum safety equipment (oxygen and safety belt) is available, b) Seat is acceptable to the FAA inspector for performance of official duties, and c) Repairs are made within 2 flight-days. NOTE 1: These provisos are intended to provide for occupancy of the seats by an FAA inspector when the minimum safety equipment (oxygen and safety belt) is functional and the inspector determines the conditions to be acceptable. NOTE 2: The pilot in command (PIC) will determine if the minimum safety equipment is functional for other persons authorized to occupy an observer seat.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-11-20 ***	Forward Observer Seat (Including Associated Equipment) (Cont'd)					
25-11-20-C	Observer Seat Not Required by 14 CFR (Including Associated Equipment)	D	1	0	May be inoperative. NOTE: The PIC will determine if the minimum safety equipment is functional for other persons authorized to occupy an observer seat.	
25-13-31	Rudder Pedal Adjustment	C	2	0	One or more may be inoperative provided: a) Position of pedals permits normal full flight and brake control movement, and b) Adjustments are secured in a position that suits individual pilot's requirements.	
25-20-10 ***	Wi-Fi Router (Aircraft with M2718)	D	1	0	(M) May be inoperative provided: a) Ethernet Wire Router is not used, and b) Associated C/B is pulled and collared.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-21-01	Passenger Seat					
25-21-01-A	A/C without M-OPT178	D	-	-	May be inoperative provided: a) Seat does not restrict access to any emergency exit, egress route, or main aisle, and b) The affected seat(s) is blocked and placarded "DO NOT OCCUPY." NOTE: A seat with an inoperative seat belt or shoulder harness is considered inoperative.	
25-21-01-B	A/C with M-OPT178	A	-	-	(O) One or more may be inoperative provided: a) Emergency Exit access volume is verified acceptable, b) It does not restrict any passenger from access to the main aircraft aisle, c) Affected seat is blocked and placarded, and d) Repairs are made within 10 consecutive calendar-days. NOTE: A seat with an inoperative seat belt is considered inoperative.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-5

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-21-01	Passenger Seat (Cont'd)					
25-21-01-12	Swivel Mechanism					
25-21-01-12-A		D	-	-	(M) May be inoperative and the affected seat occupied provided: a) Affected seat is secured in taxi, takeoff, and landing (TTOL) position, b) Affected seat does not block an Emergency Exit, and c) Affected seat does not restrict any passenger from access to the main aircraft aisle.	
25-21-01-12-B		C	-	-	May be inoperative and the affected seat occupied provided the affected seat is immovable in TTOL position.	
25-21-01-13	Forward/Aft Tracking Mechanism	C	-	-	May be inoperative and seat occupied provided: a) Associated seat does not block an Emergency Exit, b) Associated seat does not restrict any passenger from access to main aisle, and c) Associated seat remains in TTOL position for takeoff and landing.	
25-21-01-15	Recline Mechanism					
25-21-01-15-A		D	-	-	(M) May be inoperative and affected seat occupied provided seat is secured in TTOL position.	
25-21-01-15-B		C	-	-	May be inoperative and affected seat occupied provided seat back is immovable in TTOL position.	

REVISION NO. 8
DATE: 09/18/2020

PAGE NO. 25-6

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-21-01	Passenger Seat (Cont'd)					
25-21-01-20	Armrest	D	-	-	(M) May be inoperative or missing and seat occupied provided: a) Armrest does not restrict access to any emergency exit, egress route, or main aisle, and b) If Armrest with seat control is missing or removed, seat is secured in TTOL position.	
25-21-01-30	Headrest	C	-	-	May be inoperative and seat occupied provided the associated Passenger Seat and Headrest are in TTOL position.	
25-21-01-35	Seat Belt/Air Bag Restraint Systems					
25-21-01-35-A	Seat Belt/Air Bags Required by 14 CFR	D	-	-	May be inoperative provided affected seat is blocked and placarded "DO NOT OCCUPY."	
25-21-01-35-B ***	Seat Belt/Air Bags Not Required by 14 CFR	D	-	-	(M) May be inoperative or disconnected provided seat belt operates normally.	
25-22-01 ***	Cabin Configuration Monitoring System - Cabin Annunciation (A/C with M3557)					
25-22-01-10	"STOW TABLE" Ordinance Sign (A/C without M-OPT 178)	A	1	0	(O) May be inoperative provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded "DO NOT USE," and c) Repairs are made within 10 consecutive calendar-days.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-7

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-22-01 ***	Cabin Configuration Monitoring System - Cabin Annunciation (A/C with M3557) (Cont'd)					
	“EXIT TABLE DEPLOYED” Light				Relief moved to ATA 31, item 31-53-10-10, Revision 7.	
25-22-01-20	“EXIT ACCESS NOT READY” Ordinance Sign (A/C with M-OPT 178)	A	1	0	(O) May be inoperative provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded “DO NOT USE,” c) Affected Passenger Seats are considered inoperative (item 25-21-01), and d) Repairs are made within 10 consecutive calendar-days.	
25-22-01-30	Cabin Sonalert					
25-22-01-31	Cabin Sonalert (A/C without M-OPT 178)					
25-22-01-31-A		A	1	0	(O) May be inoperative, if acceptable for crew, provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded “DO NOT USE,” and c) Repairs are made within 10 consecutive calendar-days.	

(Continued)

REVISION NO. 8

PAGE NO. 25-8

DATE: 09/18/2020

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-22-01 ***	Cabin Configuration Monitoring System - Cabin Annunciation (A/C with M3557) (Cont'd)					
25-22-01-31	Cabin Sonalert (A/C without M-OPT 178) (Cont'd)					
25-22-01-31-B		A	1	0	(M)(O) May be inoperative provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded "DO NOT USE," c) It is deactivated, and d) Repairs are made within 10 consecutive calendar-days.	
25-22-01-32	Cabin Sonalert (A/C with M-OPT 178)					
25-22-01-32-A		A	1	0	(O) May be inoperative, if acceptable for crew, provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded "DO NOT USE," c) Affected Passenger Seats are considered inoperative (item 25-21-01), and d) Repairs are made within 10 consecutive calendar-days.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-9

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-22-01 ***	Cabin Configuration Monitoring System - Cabin Annunciation (A/C with M3557) (Cont'd)					
25-22-01-32	Cabin Sonalert (A/C with M-OPT 178) (Cont'd)					
25-22-01-32-B		A	1	0	(M)(O) May be inoperative provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded "DO NOT USE," c) Affected Passenger Seats are considered inoperative (item 25-21-01) d) It is deactivated, and e) Repairs are made within 10 consecutive calendar-days.	
25-23-05	Keyed Lock	C	-	0	May be inoperative provided the associated door, compartment, or cap is verified secured prior to each departure.	
25-28-10	Aircraft Ladder					
25-28-10-01	Forward/Aft Service Compartment Ladder					
25-28-10-01-A		C	2	0	One or more may be inoperative in stowed position.	
25-28-10-01-B		C	2	0	(M) One or more may be removed.	
(Continued)						

REVISION NO. 8

PAGE NO. 25-10

DATE: 09/18/2020

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-28-10	Aircraft Ladder (Cont'd)					
25-28-10-10	Portable Ladder	D	-	0	May be removed or inoperative in the stowed position.	
25-40-05	Lavatory Door Ashtray					
25-40-05-A	Airplanes with Multiple Lavatory Doors with Ashtrays Installed	A	-	-	Up to and including 50% may be missing or inoperative for 10 calendar-days.	
25-40-05-B		A	-	-	More than 50% may be missing or inoperative for 3 calendar-days. NOTE: Crew lavatories are included in the total aircraft lavatory door ashtray count.	
25-40-05-C	Airplanes with Only One Lavatory Door with Ashtray Installed	A	1	0	May be missing or inoperative for 10 calendar-days.	
25-50-00	Baggage Compartment Restraint Nets and Anchors System					
25-50-00-A		D	-	-	May be inoperative or missing provided only the areas with operative restraint nets and anchors are used.	
25-50-00-B		C	-	-	(O) May be inoperative or missing provided baggage compartment remains empty.	
25-50-05	Baggage Compartment Shelf					
25-50-05-01	Shelf Stowage Strap	D	2	0	One or more may be inoperative or removed provided the shelves remain in the down position.	
(Continued)						

REVISION NO. 8

PAGE NO. 25-11

DATE: 09/18/2020

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-50-05	Baggage Compartment Shelf (Cont'd)					
25-50-05-02	Shelf Support Strap	D	4	0	One or more may be inoperative or removed provided the shelves remain in the stowed (up) position and are not used.	
25-50-05-03	Shelf	D	2	0	One or more may be removed or inoperative provided the shelf remains in the stowed (up) position and is not used.	
25-60-01	Crewmember Flashlight Holder Assembly (Including Flashlight)	C	-	-	May be inoperative or missing provided each required crewmember has an operative independent portable light readily available.	
25-60-10	Automated External Defibrillator (AED) and/or Associated Equipment					
25-60-10-A		D	-	-	Any in excess of those required by 14 CFR may be incomplete, missing, or inoperative.	
25-60-10-B		A	-	0	May be incomplete, missing, or inoperative provided: <ol style="list-style-type: none"> a) AED is resealed in a manner that will identify it as a unit that cannot be mistaken for a fully serviceable unit, and b) Repairs or replacements are made within one flight. 	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-12

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-60-11	Emergency Medical Kit (EMK) and/or Associated Equipment					
25-60-11-A		D	-	-	Any in excess of those required by 14 CFR may be incomplete, missing, or inoperative.	
25-60-11-B		A	-	-	(O) May be incomplete, missing, or inoperative provided: a) EMK is sealed in a manner that will identify it as a unit that cannot be mistaken for a fully serviceable unit, and b) Repairs or replacements are made within one flight.	
25-61-00	Emergency Locator Transmitter (ELT)					
25-61-00-05 ***	Fixed ELTs					
25-61-00-05-A		A	-	0	(M) May be inoperative provided: a) System is deactivated, and b) Repairs are made within 90 calendar-days.	
25-61-00-05-B		A	-	0	(M) May be missing provided: a) Placard stating "ELT not installed" is placed in view of the pilot, and b) Repairs are made within 90 calendar-days.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-13

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-61-00	Emergency Locator Transmitter (ELT) (Cont'd)					
25-61-00-05-C		D	-	-	(M) Any in excess of those required by 14 CFR may be inoperative provided system is deactivated.	
25-61-00-05-D		D	-	-	Any in excess of those required by 14 CFR may be missing.	
25-61-00-10 ***	Survival Type ELTs	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing.	
25-61-00-15 ***	Remote ELT Switch	D	-	0	(M) May be inoperative provided: a) Remote ELT Switch is deactivated, and b) ELT Switch is placed in the ARMED mode.	
25-61-00-20 ***	ELT Indicator Light	D	-	0		
25-61-00-25 ***	ELT Aural Alarm	D	-	0		

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-14

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-63-00 ***	Emergency Vision Assurance System (EVAS) (Supplemental Type Certificate (STC) #SA00892LA or M2821)					
25-63-00-A ***		C	2	0	May be inoperative provided the EVAS ON/OFF switch is in the OFF position.	
25-63-00-B ***		D	2	0	(M) May be inoperative provided the EVAS is removed from the cockpit.	
25-64-05	Lifeline (Overwater Operations Survival Equipment)	D	-	-	May be inoperative or missing provided overwater operations are not conducted.	
25-64-13	Overwater Equipment (Flotation Device/Raft)	D	-	-	Any in excess of those required may be inoperative provided: a) Required distribution is maintained, b) Inoperative life raft and its installed location are placarded inoperative, c) When practical, the inoperative life raft is secured out of sight, and d) Procedures are established and used to alert crewmembers of inoperative or missing equipment.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 25-15

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

25. Equipment/Furnishings

Sequence No.	Item	1	2	3	4	Change Bar
25-64-21	First Aid Kit (FAK) and/or Associated Equipment					
25-64-21-A		D	-	-	Any in excess of those required by 14 CFR may be incomplete, missing, or inoperative.	
25-64-21-B		A	-	-	(O) If more than one is required by 14 CFR, only one of the required FAK may be incomplete, missing, or inoperative provided: a) FAK is resealed in a manner that will identify it as a unit that cannot be mistaken for a fully serviceable unit, and b) Repairs or replacements are made within one flight.	
25-99-99 ***	Nonessential Equipment and Furnishing (NEF)/NEF Items	-	-	0	May be inoperative, damaged, or missing provided that the item(s) is deferred in accordance with the operator's NEF deferral program. The NEF program, procedures, and processes are outlined in the operator's (insert name) Manual. (M) and (O) procedures, if required, must be available to the flightcrew and included in the operator's appropriate document. NOTE: Exterior lavatory door ashtrays are not considered NEF items.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 26-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

26. Fire Protection

Sequence No.	Item	1	2	3	4	Change Bar
26-10-25 ***	Lavatory Smoke Detector (Aircraft with M2607)	D	-	0	Any in excess of those required by 14 CFR may be inoperative.	
26-20-15	Hand Fire Extinguisher	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing provided: a) Inoperative Hand Fire Extinguisher is placarded inoperative, removed from the installed location, and placed out of sight so that it cannot be mistaken for a functional unit, and b) Required distribution is maintained.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 27-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

27. Flight Controls

Sequence No.	Item	1	2	3	4	Change Bar
27-00-05	Servo-Actuator Integrated Anti-Flutter Function	A	8	7	(M) One may be inoperative for three flights or 10 flying-hours, whichever occurs first, provided the associated servo-actuator is verified before each flight.	
27-14-01	Roll Trim Control System	C	1	0	(M)(O) May be inoperative provided: a) Fuel Quantity Indications are operative, b) Roll Trim is verified in neutral position before each departure, c) Rudder Trim Control System is verified operative, d) TRIM AILERON C/B is pulled and collared, and e) Fuel imbalance is limited to 500 lb or less.	
27-14-10	Roll Trim Position Indication	C	1	0	(O) May be inoperative provided: a) Fuel Quantity Indications are operative, b) Roll Trim Control System is verified operative, c) Ailerons are verified in the same position, and d) Fuel imbalance is limited to 500 lb or less.	
27-15-01	Roll Arthur Variable Bellcrank	C	1	0	(M)(O) May be inoperative provided: a) Approaches do not require its use, b) Airplane Flight Manual (AFM) procedure is applied, c) Roll Arthur Variable Bellcrank is secured in low-speed position, and d) AIL FEEL C/B is pulled and collared.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 27-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

27. Flight Controls

Sequence No.	Item	1	2	3	4	Change Bar
27-24-01	Rudder Trim Control System	A	1	0	(M)(O) May be inoperative provided: a) Fuel Quantity Indications are operative, b) Roll Trim Control System is verified operative, c) Rudder Trim is verified in neutral position before each departure, d) TRIM RUDDER C/B is pulled and collared, e) Fuel imbalance is limited to 500 lb or less, and f) Repairs are made within 2 consecutive calendar-days.	
27-24-10	Rudder Trim Position Indication	C	1	0	(O) May be inoperative provided Rudder is verified in neutral position before each departure.	
27-35-01	Elevator Arthur Variable Bellcrank	B	1	0	(M)(O) May be inoperative provided: a) Approaches do not require its use, b) AFM procedure is applied, c) Touch-and-go training maneuvers are prohibited, d) Horizontal Stabilizer is verified and adjusted between the two takeoff reference marks before each departure, e) Elevator Arthur Variable Bellcrank is verified in low-speed position before each departure, and f) PITCH FEEL C/B is pulled and collared.	
27-35-11	PITCH Artificial Feel Unit (AFU) Heating System	D	1	0	(M) May be inoperative provided it is secured.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 27-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

27. Flight Controls

Sequence No.	Item	1	2	3	4	Change Bar
27-40-10	Horizontal Stabilizer Position Indication	A	1	0	(M)(O) May be inoperative provided: a) Touch-and-go training maneuvers are prohibited, b) AP Function is not used (see item 22-10-00-10), c) Horizontal Stabilizer is verified operative, d) Horizontal Stabilizer is verified and adjusted between the two takeoff reference marks before each departure, e) T/O CONFIG Warning System is verified operative, and f) Repairs are made within 2 consecutive calendar-days.	
27-80-02	Emergency Slat Extension (EMER SLATS)	B	1	0	(M) May be inoperative provided manual and automatic Slat Controls are verified operative before each departure.	

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-21-01	Booster Pump					
28-21-01-A	A/C without M5000 or M5001	C	4	3	(M)(O) One may be inoperative provided: <ol style="list-style-type: none"> a) Normal Booster Pump 2 is operative, b) XBP Crossfeed Valves are verified operative, c) XTK Valve is verified operative, d) Associated Booster Pump C/B is pulled and collared, and e) Fuel Quantity Indications are closely monitored during flight. 	
28-21-01-A	A/C with M5000 or M5001	C	4	3	(M)(O) One may be inoperative provided: <ol style="list-style-type: none"> a) Normal Booster Pump 2 is operative, b) XBP Crossfeed Valves are verified operative, c) XTK Valve is verified operative, d) Associated Booster Pump C/B is pulled and collared, e) Departure airfield is below 13,000 ft if fuels JetB or JP-4 are used, and f) Fuel Quantity Indications are closely monitored during flight. 	
28-21-01-10	Normal Booster Pump Automatic Setting	C	2	0	One or more may be inoperative provided the associated NORMAL Booster Pump is manually operated.	
28-21-25	XBP Crossfeed Valve	A	2	0	(M) One or more may be inoperative in closed position provided: <ol style="list-style-type: none"> a) All Booster Pumps are operative, b) Affected XBP Crossfeed Valve is secured in closed position, and c) Repairs are made within 3 consecutive calendar-days. 	

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-21-29	Transfer Valve	B	3	0	(M)(O) One or more may be inoperative provided: a) Fuel quantity is limited to 6,000 lb in each wing tank, b) Forward and rear fuel tanks are verified empty before each departure, and c) TRANSFER C/B is pulled and collared.	
28-22-01	XTK Valve	C	1	0	(O) May be inoperative in closed position provided: a) All Booster Pumps are operative, and b) XBP Crossfeed Valves are verified operative.	
28-30-10 ***	Fuel Tank Sump Drain Valve (A/C with M3844)	A	-	-	(M) One or more may be inoperative leaking provided: a) Affected Fuel Tank Sump Drain Valve is in an authorized position in accordance with the MAINT 28-30-10-b procedure, b) Affected Fuel Tank Sump Drain Valve is sealed with an approved cap, and c) Repairs are made before the next fuel tank sump draining operation. NOTE: The fuel tank sump draining operation interval is provided by Aircraft Maintenance Manual (AMM) 05-10-28 (Scheduled Maintenance – Aircraft Maintenance Operations – ATA View – Fuel) or Operator’s documentation.	

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-40-10	Fuel Quantity Indication	C	2	1	(O) Fuel Quantity Indication for one group of tanks may be inoperative provided: a) FULL refueling mode is used when refueling to any fuel level, b) Fuel quantity is determined by other acceptable means, c) Fuel Flow (FF) and Fuel Used (FU) Indications are operative, and d) FUEL LEVEL ... white CAS messages are verified operative.	
28-41-02	Fuel Quantity Management Computer (FQMC) Channel	A	2	1	(M)(O) One may be inoperative provided: a) Remaining FQMC Channel is verified operative, b) Associated C/B is pulled and collared, and c) Repairs are made within 3 consecutive calendar-days. NOTE: For failure of FQMC Engine OIL or APU indications, refer to dedicated items.	
28-41-02-03	ARINC Input Data Bus Function					
28-41-02-03-A		B	2	1	One may be inoperative.	
(Continued)						

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-41-02	Fuel Quantity Management Computer (FQMC) Channel (Cont'd)					
28-41-02-03-B		C	2	0	Both may be inoperative provided: a) Actual fuel quantity is considered 400 lb lower than the displayed quantity for range performance purposes, and b) Fuel Quantity Indications are operative. NOTE 1: APU oil level test may only be performed automatically at FQMC startup. NOTE 2: FU can no longer be reset.	
28-41-02-04	Fuel Level Monitoring Function (1,000 lb Fuel Level)	A	2	1	One may be inoperative provided: a) FF, FU, and Fuel Quantity are operative and monitored at least every 30 minutes in flight, and b) Repairs are made within 3 consecutive calendar-days.	
28-41-05	Fuel Gauging System					
28-41-05-01	LH/RH Wing Outer Fuel Tank Gauge	C	4	2	One per wing may be inoperative provided associated fuel tank quantity is considered 300 lb higher than the displayed fuel quantity for takeoff and landing performance purposes. NOTE: Refueling of FRONT and REAR tanks is not possible.	
(Continued)						

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-41-05	Fuel Gauging System (Cont'd)					
28-41-05-02	LH/RH Wing Inner Fuel Tank Gauge	C	2	0	One or more may be inoperative provided: a) Associated tank is considered full for takeoff and landing performance purposes, and b) Associated Wing Center Fuel Tank Gauge is operative. NOTE 1: PARTIAL refueling may lead to wing asymmetry. NOTE 2: Refueling of FRONT and REAR tanks is not possible.	
28-41-05-03	LH/RH Wing Center Fuel Tank Gauge	C	2	0	One or more may be inoperative provided: a) Associated tank is considered full for takeoff and landing performance purposes, and b) Associated Wing Inner Fuel Tank Gauge is operative. NOTE 1: PARTIAL refueling may lead to wing asymmetry. NOTE 2: Refueling of FRONT and REAR tanks is not possible.	
28-41-05-21	Front Tank Fuel Gauge	C	2	1	One may be inoperative provided associated fuel tank quantity is considered 100 lb higher than the displayed fuel quantity for takeoff and landing performance purposes.	
28-41-05-22	Rear Tank Fuel Gauge	C	2	1	One may be inoperative provided associated fuel tank quantity is considered 100 lb higher than the displayed fuel quantity for takeoff and landing performance purposes.	

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-41-09	Fuel Density Compensation					
28-41-09-04	LH/RH Density Compensator Probe	C	2	1	One may be inoperative.	
28-41-15	Fuel Flow (FF)	B	2	1	One may be inoperative provided all other engine indications and the associated Fuel Quantity Indications are operative.	
28-42-10	Fuel High Level Detection System	A	1	0	May be inoperative provided: a) FULL Pressure Refueling is not used, b) Cockpit Fuel Quantity Indications are verified operative and monitored during refueling operation, and c) Repairs are made within 3 consecutive calendar-days.	
28-43-01	Fuel Temperature Indication (TEMP)	C	1	0	May be inoperative provided: a) Airplane is not operated with outside temperature below ISA -20°C, and b) Initial fuel tank temperature is above -30°C.	
28-50-00	Pressure Refueling System	C	1	0	May be inoperative provided FUELING amber CAS message is operative and not displayed.	
28-50-01	Refueling Control Panel					
28-50-01-01	FULL/PARTIAL Refueling Selection Channel					
28-50-01-01-A		B	2	1	One may be inoperative.	
28-50-01-01-B		B	2	0	Both may be inoperative provided Pressure Refueling is not used.	
(Continued)						

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-50-01	Refueling Control Panel (Cont'd)					
28-50-01-02	TOTAL QTY Digital Display	B	1	0	May be inoperative provided: a) Cockpit Fuel Quantity Indications are operative, and b) Cockpit Fuel Quantity Indications are monitored during refueling operation.	
28-50-01-03	TOTAL QTY SELECTED Digital Display	B	1	0	May be inoperative provided PARTIAL refueling is not used.	
28-50-01-04	INC/DEC Switch	B	1	0	May be inoperative provided FULL refueling mode is used when refueling to any fuel level.	
28-50-01-05	LAMP TEST Pushbutton	B	1	0	May be inoperative provided the HIGH LEVEL TEST Pushbutton and STOP FUELING Red Light are operative.	
28-50-01-06	FULL Amber Light	B	2	0	One or more may be inoperative provided HIGH LEVEL TEST Pushbutton is operative.	
28-50-01-07	STOP FUELING Red Light	C	1	0	(O) May be inoperative provided: a) Pressure Refueling is not used, and b) Fuel tanks are verified unpressurized before gravity refueling operation.	
28-50-01-08	FAULT Amber Light	B	1	0	May be inoperative provided the HIGH LEVEL TEST Pushbutton and STOP FUELING Red Light are operative.	
28-50-01-09	HIGH LEVEL TEST Pushbutton	A	1	0	(O) May be inoperative provided: a) Pressure Refueling is not used, b) Fuel tanks are verified unpressurized before gravity refueling operation, and c) Repairs are made within 3 consecutive calendar-days.	

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

28. Fuel

Sequence No.	Item	1	2	3	4	Change Bar
28-50-02	Pressure Refueling Gauging System	C	2	0	One or more may be inoperative provided: a) FULL refueling mode is used when refueling to any fuel level, and b) FULL Amber Lights are operative.	
28-50-09	Refueling Valve	A	4	3	(M) May be inoperative provided: a) Pressure Refueling is not used, b) Inoperative Refueling Valve is verified in closed position, and c) Repairs are made within 3 consecutive calendar-days.	
28-70-21	Vent Valve	C	3	0	(M) One or more may be inoperative provided: a) Affected Vent Valve is manually operated before/after refueling, b) If STOP FUELING Red Light (fueling panel) remains lighted after opening of the Vent Valves, presence of airflow at each air outlet is verified during pressure refueling, and c) FUELING amber CAS message is operative and not displayed after closing sequence of Vent Valves.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 29-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

29. Hydraulic Power

Sequence No.	Item	1	2	3	4	Change Bar
29-11-11	Hydraulic Pressure Indication (PSI on HYD Synoptic Page)	C	2	1	(O) One may be inoperative provided: a) Associated HYDR...FAIL white CAS message is not displayed, b) Associated Hydraulic Tank Quantity Indication is operative, and c) Standby pump is verified operative.	
29-11-25	Hydraulic Pressure Switch (L/R30GJ and 35GJ)	C	3	0	(O) May be inoperative provided: a) Associated Hydraulic Pressure and Tank Quantity Indications are operative, b) Standby pump is verified operative, and c) Associated hydraulic indications are monitored every 30 minutes in flight.	
29-13-09	Hydraulic Filter Clogging Indicator	A	9	8	(M) One may be tripped red provided: a) Associated HYDR...FAIL white CAS message is not displayed, b) Affected Clogging Indicator is reset once at the beginning of the repair interval and is verified to not be tripped red before each departure, and c) Repairs are made within 10 consecutive calendar-days.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 29-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

29. Hydraulic Power

Sequence No.	Item	1	2	3	4	Change Bar
29-14-01	HYD 1 Tank Quantity (QTY) Indication	C	1	0	(O) May be inoperative provided the tank fluid level is verified before engine start.	
29-14-10 ***	Hydraulic Accumulator Pressure Indicator (Aircraft with M2446)	C	3	0	(M) One or more may be inoperative provided associated accumulator pressure inflation is verified adequate.	
29-14-11	Main Hydraulic Accumulator	C	2	1	Hydraulic System No. 1 Accumulator may be inoperative.	
29-14-12	Thrust Reverser Hydraulic Accumulator	C	2	0	One or more may be inoperative provided Thrust Reverser System is not used (item 78-30-00).	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 30-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
30-12-00	Wing Anti-Icing System	C	1	0	(M)(O) May be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, and b) Wing Anti-Icing Valve is secured in closed position.	
30-20-01	Engine Anti-Ice Valve					
30-20-01-A		B	2	1	(O) One may be jammed in closed position provided: a) Airplane is not operated in known or forecast icing conditions, and b) Associated ANTI-ICE ENG is set to off for the entire flight.	
30-20-01-B		B	2	1	(O) One may be leaking in closed position provided: a) Outside Air Temperature (OAT) at the departure airport is at or below -7°C (20°F), b) Performance data is applied, and c) Associated ANTI-ICE ENG is set to ON for the entire flight.	
30-20-01-C		B	2	1	(O) One may be leaking in closed position provided: a) Affected Engine Anti-Ice Valve regulation function is verified operative, b) OAT at the departure airport is at or below +10°C (50°F), c) Performance data is applied, and d) Associated ANTI-ICE ENG is set to ON for the entire flight.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 30-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
30-30-05	Normal Static Port Heating System	B	2	1	(O) One may be inoperative provided: a) Airplane is not operated into visible moisture or in known or forecast icing conditions, and b) Enroute operations do not require its use.	
30-30-10	Normal Pitot Probe Heating System	B	2	1	(O) One may be inoperative provided: a) Airplane is not operated into visible moisture or in known or forecast icing conditions, b) Enroute operations do not require its use, and c) Pilot Flying (PF) is on the non-affected side.	
30-30-10-10	Normal/Standby Pitot Probe Heating System Automatic Overhead Setting On Mode	C	2	0	One or more may be inoperative OFF provided the associated Manual Mode is operative and used.	
30-30-13	Ground Automatic Probe Preheating (Aircraft with M3663)	C	2	0	One or more may be inoperative off.	

REVISION NO. 8
DATE: 09/18/2020

PAGE NO. 30-3

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
30-30-15	Angle of Attack (AoA) Heating System	C	2	1	(O) One may be inoperative provided: <ol style="list-style-type: none"> a) Airplane is not operated into visible moisture or in known or forecast icing conditions, b) Pitot Probe Heating System is operative, and c) Normal Static Port Heating System is operative. 	
30-30-20	Total Air Temperature (TAT) Probe Heating System	B	1	0	(O) May be inoperative provided the airplane is not operated in known or forecast icing conditions.	
30-41-00	Windshield Deicing System	C	2	1	(O) One side may be inoperative provided: <ol style="list-style-type: none"> a) Airplane is not operated in known or forecast icing conditions, b) Remaining side is verified operative, and c) Windshield Demisting System is verified operative. 	
30-41-00-10	Automatic Setting	C	2	0	One or more may be inoperative provided the associated Windshield Deicing System Manual Mode is operative and used.	
30-41-10	Side and Rear Window Heating	C	1	0	May be inoperative.	
30-42-00	Windshield Demisting System	C	2	0	One or more may be inoperative provided Windshield Deicing System is operative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 30-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

30. Ice and Rain Protection

Sequence No.	Item	1	2	3	4	Change Bar
30-43-00	Windshield Wiper					
30-43-00-A		C	2	0	(O) One or more may be inoperative in rest position or missing provided: a) Airplane is not operated in known or forecast precipitation within arrival and departure areas, and b) Approaches do not require its use.	
30-43-00-B		B	2	1	(M)(O) One may be inoperative in non-rest position provided: a) Airplane is not operated in known or forecast precipitation within arrival and departure areas, b) Approaches do not require its use, c) PF is on the non-affected side, d) Flight envelope is limited to 215 knots indicated airspeed (KIAS), and e) Associated C/B is pulled and collared.	
30-43-00-01	FAST Mode	C	2	0	One or more may be inoperative provided the associated SLOW Mode is operative.	
30-43-00-02	SLOW Mode	C	2	0	One or more may be inoperative provided the associated FAST Mode is operative.	
30-80-00 ***	Ice Detection System (Aircraft with M2533)	D	1	0	(M) May be inoperative provided ICE DETECTOR C/B is pulled and collared.	
30-90-01 ***	Brake Heating System (Aircraft with M2529)	D	1	0	(M) May be inoperative provided: a) Brake Heating System is not used, and b) Brake Heating Valves are secured in closed position.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 31-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
31-21-00	Clock	C	2	1	One may be inoperative.	
31-31-32	Digital Flight Data Recorder (DFDR) For a Holder of an Air Carrier or Commercial Operator Certificate					
31-31-32-A		C	-	-	Any in excess of those required by 14 CFR may be inoperative.	
31-31-32-B		A	-	0	May be inoperative provided: a) CVR operates normally, b) Airplane is not dispatched from a designated airport as listed in the operator's MEL unless: 1) FDR failure occurs after pushback but prior to takeoff, or 2) FDR repair was attempted but not successful. c) In those cases where repair is attempted but not successful, the aircraft may be dispatched on a flight or series of flights until the next designated airport where repair must be accomplished prior to dispatch, and d) Repairs are made within 3 flight-days.	
31-31-32-01	FDR Recording Parameters Required by 14 CFR	A	-	-	Up to three recording parameters may be inoperative provided: a) CVR operates normally, and b) Repairs are made within 20 consecutive calendar-days.	
31-31-32-02	FDR Recording Parameters Not Required by 14 CFR	A	-	-	May be inoperative provided repairs are made prior to the completion of the next heavy maintenance visit.	
(Continued)						

REVISION NO. 8
DATE: 09/18/2020

PAGE NO. 31-2

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
31-31-32	Digital Flight Data Recorder (DFDR) (Cont'd)					
31-31-32-03	For an Operator Other Than a Holder of an Air Carrier or Commercial Operator Certificate					
31-31-32-03-A		C	-	1	Any in excess of those required by 14 CFR may be inoperative.	
31-31-32-03-B		A	-	0	May be inoperative provided repairs are made in accordance with 14 CFRs.	
31-32-00	Quick Access Recorder (QAR) (Aircraft with M1896)					
31-32-00-A		C	1	0	May be inoperative provided no DFDR CAS message is displayed.	
31-32-00-B		A	1	0	May be inoperative provided DFDR is considered inoperative (item 31-31-32).	
31-41-00	Modular Avionic Unit (MAU)					
31-41-00-10	MAU Fan	A	8	7	One may be inoperative provided repairs are made within 2 consecutive calendar-days.	
31-50-01	Master Warning/Master Caution Light System	C	1	0	May be inoperative provided Aural Warning System is verified operative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 31-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
31-57-10 ***	Cabin Configuration Monitoring System – Cockpit Annunciation (A/C with M3557)					
31-57-10-10	“EXIT TABLE DEPLOYED” Light (A/C without M-OPT 55)	A	1	0	(O) May be inoperative provided: a) Table is verified stowed before each departure and approach, b) Table is placarded “DO NOT USE,” and c) Repairs are made within 10 consecutive calendar-days.	
31-57-10-21	“CABIN NOT READY” Indication (A/C with M-OPT 55 and without M-OPT 178)	A	1	0	(O) May be inoperative provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded “DO NOT USE,” and c) Repairs are made within 10 consecutive calendar-days.	
31-57-10-22	“CABIN NOT READY” Indication (A/C with M-OPT 55 and with M-OPT 178)	A	1	0	(O) May be inoperative provided: a) Console table is verified stowed before each departure and approach, b) Console table is placarded “DO NOT USE,” c) Affected Passenger Seats are considered inoperative (item 25-21-01), and d) Repairs are made within 10 consecutive calendar-days.	
31-60-02	Electronic Checklist (ECL) System	C	-	0	(O) One or more may be inoperative provided approved alternate procedures are established and used.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 31-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
31-60-05	Checklist Controller (CLC)	C	2	0	One or more may be inoperative.	
31-60-06	CCD Channel	B	4	3	(M) One Channel may be inoperative provided: a) Only Pilot Not Flying (PNF) CCD is affected, b) Associated MKB is operative, c) Approaches do not require its use, and d) Remaining CCD Channels are verified operative.	
31-60-09	Multifunction Keyboard (MKB)	B	2	1	One may be inoperative provided both Channels of the associated CCD are operative. NOTE: For CPDLC use, MKB on PNF side must be operative.	
31-60-13	Display Unit (DU)	A	4	3	(O) Lower DU may be inoperative provided: a) Affected DU is switched off, b) Jeppesen Electronic Terminal Charts are not used (item 34-00-02), except for aircraft with M3305, and c) Repairs are made within 3 consecutive calendar-days.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 31-5

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

31. Indicating/Recording Systems

Sequence No.	Item	1	2	3	4	Change Bar
31-60-17	Advanced Graphic Module (AGM)					
31-60-17-A		A	4	3	(O) AGM #1, AGM #2, or AGM #4 may be inoperative provided: <ul style="list-style-type: none"> a) Jeppesen Electronic Terminal Charts are not used (item 34-00-02), except for aircraft with M3305, b) Video System is not used (item 23-70-00), c) Associated DU knob on the reversion panel is set to REV, d) DUs are operative, e) It is verified that no DU with Mod M (M3077) and without Mod N (M3202) is installed, and f) Repairs are made within 3 consecutive calendar-days. NOTE: A red crossed DU should not be switched off.	
31-60-17-B		B	4	3	(O) AGM #3 may be inoperative provided: <ul style="list-style-type: none"> a) Jeppesen Electronic Terminal Charts are not used (item 34-00-02), except for aircraft with M3305, b) Video System is not used (item 23-70-00), c) Associated DU knob on the reversion panel is set to REV, d) DUs are operative, and e) It is verified that no DU with Mod M (M3077) and without Mod N (M3202) is installed. NOTE: A red crossed DU should not be switched off.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 32-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

32. Landing Gear

Sequence No.	Item	1	2	3	4	Change Bar
32-30-00	Landing Gear (L/G) Retraction System	A	1	0	(M)(O) May be inoperative provided: a) AFM Procedures, Limitations, and Performance are applied, b) Affected modes of the Enhanced Ground Proximity Warning System (E-GPWS)/Ground Proximity Warning System (GPWS) are considered inoperative (item 34-45-00), c) No untimely steady green L/G information was reported before L/G Retraction System failure, d) L/G Control Lever was not jammed in down position during the flight where the failure occurred, e) No Brake System Computer Unit (BSCU) fault code was logged before the L/G Retraction System failure, f) No BSCU fault code is displayed, except 315, 415, or both 333 and 433, g) L/G information are verified operative with L/G downlocked, h) Main L/G Doors are verified closed, i) L/G Control Lever is secured in down position, and j) Repairs are made within three flights or 2 consecutive calendar-days, whichever occurs first.	
32-31-10	L/G Handle Flashing Light	C	1	0	(O) May be inoperative provided: a) L/G position indications are operative, and b) "GEAR" aural warning is verified operative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 32-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

32. Landing Gear

Sequence No.	Item	1	2	3	4	Change Bar
32-41-00 ***	Autobrake System (Aircraft with M3177 and without M3605 and without M3718)	D	1	0	(M)(O) May be inoperative provided: a) Landing Performance is not predicated on its use, b) BSCU fault codes are read and considered before each departure, c) Autobrake switch light, if installed, is disregarded, d) BRAKE .. FAIL amber CAS messages are verified operative, and e) Associated C/Bs are pulled and collared.	
32-41-02	Brake System Computer Unit (BSCU)					
32-41-02-10	Gear Handle Function	C	2	1	One may be inoperative provided L/G Retraction System is operative.	
32-41-02-11	Main Gear Contact Function	A	4	3	(O) One may be inoperative provided: a) Landing distance is increased by 10%, b) Nose Gear Contact Functions are operative, c) Full-authority digital engine control (FADEC) WOW signals are verified operative, and d) Repairs are made within 2 consecutive calendar-days.	
32-41-02-12	Nose Gear Contact Function	A	2	1	(O) One may be inoperative provided: a) Landing distance is increased by 10%, b) Thrust Reverser System is considered inoperative (item 78-30-00), c) Main Gear Contact Functions are operative, d) FADEC WOW signals are verified operative, and e) Repairs are made within 2 consecutive calendar-days.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 32-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

32. Landing Gear

Sequence No.	Item	1	2	3	4	Change Bar
32-41-02-13	Nose Wheel Steering (NWS) Function	C	2	1	One may be inoperative.	
32-41-02-14	IRS Data Function	C	4	3	One may be inoperative provided landing distance is increased by 10%.	
32-41-02-15	Pressure Recorder Acquisition Function	C	6	0	One or more may be inoperative provided DFDR is considered inoperative (item 31-31-32).	
32-41-33	Brake Temperature Indication	D	4	0	(O) One or more may be inoperative provided minimum turnaround time is observed.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 33-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
33-10-01	Cockpit and Instrument Panel Light					
33-10-01-A		C	-	-	(O) Individual lights may be inoperative provided: a) Remaining lighting system lights are sufficient to clearly illuminate all required instruments, controls, and other devices for which they are provided, b) Remaining lighting system lights are positioned so that direct rays are shielded from flightcrew members' eyes, and c) Lighting configuration and intensity is acceptable to the flightcrew. NOTE: Individual button/switch lights and/or annunciations/indications are excluded from this relief.	
33-10-01-B		D	-	0	May be inoperative for other than night operations.	
33-10-20 ***	Chartholder Lighting (Aircraft with M1426)	D	2	0	One or more may be inoperative.	
33-20-00	Cabin Lighting					
33-20-00-A		C	-	0	One or more may be inoperative or missing provided: a) Cabin Lighting is sufficient for flightcrew to perform required duties, b) For night operations, inoperative lights do not exceed 50% of the total installed, and c) Flashlight is used, as required.	
33-20-00-B		D	-	0	One or more may be inoperative provided passengers are not carried.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 33-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
33-20-02	NO SMOKING and FASTEN BELT Signs	C	-	0	One or more signs or placards may be illegible or missing provided a legible sign or placard is visible from each occupied passenger seat.	
33-30-01	Servicing Compartment/ Nose Cone Light	C	3	0	One or more may be inoperative.	
33-30-02	Pressure Fueling Bay Light	C	2	0	One or more may be inoperative.	
33-30-10	Baggage Compartment Light	C	2	0	One or more may be inoperative.	
33-40-00	Anticollision Light					
33-40-00-10	Red ANTICOL Light					
33-40-00-10-A		C	2	1	One may be inoperative for all operations provided: a) Both wingtip strobe anticollision lights operate normally, and b) The white tail navigation light on lower vertical stabilizer operates normally.	
33-40-00-10-B		C	2	0	One or more may be inoperative for other than night operations provided both wingtip strobe anticollision lights operate normally.	
33-40-00-20	White ANTICOL Light	C	3	0	One or more may be inoperative provided all Red ANTICOL Lights installed are operative.	

REVISION NO. 7
DATE: 07/05/2018

PAGE NO. 33-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
33-40-01	Navigation Light					
33-40-01-10	RH/LH Navigation Light					
33-40-01-10-A		C	-	0	May be inoperative sunrise to sunset.	
33-40-01-10-B	Aircraft with M1401	C	4	2	One may be inoperative on each side.	
33-40-01-20	Rear Navigation Light	C	1	0	May be inoperative sunrise to sunset.	
33-40-33 ***	Logo Light (Aircraft with M1746 or M1932)	D	2	0	One or more may be inoperative.	
33-40-34	Pylon Light	C	-	0	May be inoperative.	
33-40-37	Landing Light					
33-40-37-A		C	2	1	One may be inoperative provided TAXI Light is operative.	
33-40-37-B		C	2	0	One or more may be inoperative for other than night operations.	
33-40-37-01	Pulse Light System	C	1	0	May be inoperative.	
33-40-41	Taxi Light					
33-40-41-A		C	1	0	May be inoperative provided both Landing Lights are operative.	
33-40-41-B		C	1	0	May be inoperative for other than night operations.	
33-40-70	Wing Ice Detection Light	C	2	0	(O) Both may be inoperative provided: a) Aircraft is not operated in known or forecast icing conditions at night, and b) Ground deicing procedures do not require their use.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 33-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
33-50-10	Interior Emergency Lighting					
33-50-10-04	Passenger Door – Exit Sign	C	2	0	One or more may be inoperative provided no passengers are carried.	
33-50-10-05	Passenger Door – Opening Instruction Sign	C	1	0	May be inoperative provided no passengers are carried.	
33-50-10-06	Passenger Door – Spotlight					
33-50-10-06-A		C	2	1	One may be inoperative.	
33-50-10-06-B		C	2	0	Both may be inoperative provided no passengers are carried.	
33-50-10-07	Overwing Emergency Exit – Exit Sign	C	2	0	One or more may be inoperative provided no passengers are carried.	
33-50-10-08	Overwing Emergency Exit – Handle Light	C	1	0	May be inoperative provided no passengers are carried.	
33-50-10-09	Overwing Emergency Exit – Opening Instruction Sign	C	1	0	May be inoperative provided no passengers are carried.	
33-50-10-10	Floor Emergency Escape Path Light					
33-50-10-10-A		A	-	-	(M) One may be inoperative provided: a) Emergency Escape Path Lights adjacent to Passenger Door and Overwing Emergency Exit are operative, b) All other Interior Emergency Lights are operative, c) Cabin Sliding Doors are secured in open position, and d) Repairs are made within 3 consecutive calendar-days.	

(Continued)

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 33-5

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

33. Lights

Sequence No.	Item	1	2	3	4	Change Bar
33-50-10	Interior Emergency Lighting (Cont'd)					
33-50-10-10	Floor Emergency Escape Path Light (Cont'd)					
33-50-10-10-B		C	-	0	May be inoperative provided no passengers are carried.	
33-50-10-20	Bulkhead Exit Sign	C	-	0	May be inoperative provided no seat behind the bulkhead is occupied.	
33-50-10-30	Pilot and Co-Pilot Emergency Dome Light Bulb	C	4	3	One bulb may be inoperative.	
33-50-10-40 ***	Passenger Dome Light (Aircraft with M3553)	D	2	0	One or more may be inoperative.	
33-50-11	Exterior Emergency Light	C	2	0	One or more may be inoperative for other than night operations.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-00-02 ***	Jeppesen Electronic Terminal Charts (Aircraft with M2519)	D	1	0	May be inoperative provided alternate charts required for the flight are available and used.	
34-15-02	Altitude Alerting System	A	1	0	(O) May be inoperative provided: a) Enroute operations (i.e., Reduced Vertical Separation Minimum (RVSM)) do not require its use, b) AP with altitude hold and altitude capture operates normally, c) Airplane does not depart from a designated airport (as listed in the operator's MEL) where repair or replacement can be made, and d) Repairs are made within 3 flight-days.	
34-15-02-01	Aural Alert	C	2	0	One or more may be inoperative provided: a) Visual Alert operates normally, and b) AP with altitude hold and altitude capture operates normally.	
34-15-02-02	Visual Alert	C	2	0	One or more may be inoperative provided: a) Aural Alert operates normally, and b) AP with altitude hold and altitude capture operates normally.	
34-21-00	Attitude and Heading System (AHS)	D	-	2	Any in excess of the two required to independently power the Captain and First Officer's system may be inoperative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-25-00	Standby Magnetic Compass	B	1	0	May be inoperative provided: a) Operations are conducted only in visual meteorological conditions (VMC), b) Operations are not conducted at night, and c) Two independent compass systems (IRS, Attitude and Heading Reference System (AHRS)) are operative.	
34-25-00-01	Compass Lighting					
34-25-00-01-A		B	1	0	May be inoperative provided the Standby Magnetic Compass is considered inoperative (item 34-25-00).	
34-25-00-01-B		C	1	0	May be inoperative for other than night operations.	
34-31-01 ***	Head-Up Display (HUD)	D	1	0	(O) May be inoperative provided: a) Approaches do not require its use, and b) The Combiner is stowed.	
34-31-01-10 ***	Synthetic Vision System (SVS) on HUD and MDU					
34-31-01-10-A ***	A/C with M-OPT0060 and without M-OPT0063	D	2	0	(O) One or more may be inoperative provided affected SVS image is not displayed. NOTE: SVS in HUD/MDU is independent from SVS in PDU. If SVS is neither available in PDU, it could be a Global Positioning System (GPS) reception issue.	
(Continued)						

REVISION NO. 8

PAGE NO. 34-3

DATE: 09/18/2020

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-31-01 ***	Head-Up Display (HUD) (Cont'd)					
34-31-01-10 ***	Synthetic Vision System (SVS) on HUD and MDU (Cont'd)					
34-31-01-10-B ***	A/C with M-OPT0063	D	2	0	(O) One or more may be inoperative provided: a) Affected SVS image is not displayed, and b) Approaches with EVS operational credit are not conducted. NOTE: SVS in HUD/MDU is independent from SVS in PDU. If SVS is neither available in PDU, it could be a GPS reception issue.	
34-31-01-20 ***	HUD BRIGHT Switch					
34-31-01-20-A ***	A/C with M-OPT0060 and without M-OPT0062	D	1	0	MAN position may be inoperative provided HUD is considered inoperative (see item 34-31-01).	
34-31-01-20-B ***	A/C with M-OPT0062	D	1	0	MAN position may be inoperative provided the AUTO position and setting are used.	
34-31-01-20-C ***	A/C with M-OPT0060 and without M-OPT0063	D	1	0	AUTO position may be inoperative provided MAN position and setting are used.	
34-31-01-20-D ***	A/C with M-OPT0063	D	1	0	(O) AUTO position may be inoperative provided: a) MAN position and setting are used, and b) Approaches with EVS operational credit are not conducted.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-32-00 ***	Enhanced Flight Vision System (EFVS)				NOTE: For SVS item, see item 34-31-01-10.	
34-32-00-10 ***	Enhanced Vision System (EVS)					
34-32-00-10-A ***	A/C with M2308 or (M-OPT0061 and without M-OPT0063)	D	1	0	(M) May be inoperative provided associated C/B is/are pulled and collared. NOTE: This item includes IRW heating and associated controls (except otherwise specified in the MMEL).	
34-32-00-10-B ***	A/C with M-OPT0061 and without M-OPT0063	D	1	0	(M) May be inoperative provided: a) Camera is removed and replaced with an approved blanking plate, and b) Associated C/B is pulled and collared. NOTE: This item includes IRW heating and associated controls (except otherwise specified in the MMEL).	
34-32-00-10-C ***	A/C with M-OPT0063	D	1	0	(M)(O) May be inoperative provided: a) Approaches with EVS operational credit are not conducted, and b) Associated C/B is pulled and collared. NOTE: This item includes IRW heating and associated controls (except otherwise specified in the MMEL).	
(Continued)						

REVISION NO. 8

PAGE NO. 34-5

DATE: 09/18/2020

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-32-00 ***	Enhanced Flight Vision System (EFVS) (Cont'd)					
34-32-00-10 ***	Enhanced Vision System (EVS) (Cont'd)					
34-32-00-10-D ***	A/C with M-OPT0063	D	1	0	(M)(O) May be inoperative provided: a) Approaches with EVS operational credit are not conducted, b) Camera is removed and replaced with an approved blanking plate, and c) Associated C/B is pulled and collared. NOTE: This item includes IRW heating and associated controls (except otherwise specified in the MMEL).	
34-32-00-20 ***	Combined Vision System (CVS) on HUD and MDU					
34-32-00-20-A ***	A/C with M-OPT0061 and without M-OPT0063	D	2	0	(O) One or more may be inoperative provided affected CVS image is not displayed.	
34-32-00-20-B ***	A/C with M-OPT0063	D	2	0	(O) One or more may be inoperative provided: a) Approaches with EVS operational credit are not conducted, and b) Affected CVS image is not displayed.	

REVISION NO. 8

PAGE NO. 34-6

DATE: 09/18/2020

AIRCRAFT:
Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-32-00-30 ***	XVS BRT/SBY Switch (on LH yoke)					
34-32-00-30-A ***	A/C with M-OPT0061 and without M-OPT0063	D	1	0	May be inoperative provided SVS/EVS image brightness is set to minimum.	
34-32-00-30-B ***	A/C with M-OPT0063	D	1	0	(O) May be inoperative provided: a) Approaches with EVS operational credit are not conducted, and b) SVS/EVS image brightness is set to minimum.	
34-41-00	Weather Radar (WX)	C	-	-	As required by 14 CFR.	
34-42-00	Radio Altimeter (RA)					
34-42-00-A		A	-	0	(O) May be inoperative provided: a) Approaches do not require its use, b) GPWS (basic modes) is considered inoperative (item 34-45-00), c) Traffic Alert and Collision Avoidance System (TCAS) is considered inoperative (item 34-44-00), d) No radio altitude is displayed, and e) Repairs are made within six flights or 2 consecutive calendar-days, whichever occurs first.	
34-42-00-B		D	2	1	(O) One may be inoperative provided: a) No radio altitude is displayed on affected RA, and b) Approaches do not require its use.	
34-43-00 ***	Lightning Sensor System (LSS)	D	1	0	May be inoperative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-7

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-44-00	Traffic Alert and Collision Avoidance System (TCAS)					
34-44-00-A		B	-	0	(M) May be inoperative provided: a) System is deactivated and secured, and b) Enroute or approach procedures do not require its use.	
34-44-00-B	A/C with M3688 or M3849	C	-	-	(M) May be inoperative provided: a) Not required by 14 CFR, b) System is deactivated and secured, and c) Enroute or approach procedures do not require its use.	
34-44-00-10	Combined Traffic Alert (TA) and RA Dual Display	C	2	1	May be inoperative on the non-flying pilot side provided: a) TA and Resolution Advisory (RA) visual display is operative on the flying pilot side, and b) TA and RA audio function is operative on flying pilot side.	
34-44-00-20	RA Display System					
34-44-00-20-A		C	2	1	One may be inoperative on the PNF side.	
34-44-00-20-B		C	-	0	(O) May be inoperative provided: a) TA visual display and audio functions are operative, b) TA only mode is selected by the crew, and c) Enroute or approach procedures do not require its use.	
(Continued)						

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-44-00	Traffic Alert and Collision Avoidance System (TCAS) (Cont'd)					
34-44-00-30	TA Display System	C	-	0	(O) May be inoperative provided: a) RA visual display and audio functions are operative, and b) Enroute or approach procedures do not require its use.	
34-44-00-40	Audio Functions	B	1	0	May be inoperative provided enroute or approach procedures do not require use of TCAS.	
34-44-00-50 ***	Airspace Selection Function	C	-	0	May be inoperative.	
34-45-00	Enhanced Ground Proximity Warning System (E-GPWS/GPWS)					
34-45-01-10	Class A Terrain Awareness and Warning System (TAWS) Equipment Required – GPWS					
34-45-01-10-A	A/C without M3688 and without M3849	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, b) Approaches are limited to instrument landing system (ILS), localizer performance with vertical guidance (LPV), or Visual approaches, and c) Repairs are made within 2 flight-days.	
34-45-01-10-B	A/C with M3688 or M3849	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
(Continued)						

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-45-00	Enhanced Ground Proximity Warning System (E-GPWS/GPWS) (Cont'd)					
34-45-01-10	Class A Terrain Awareness and Warning System (TAWS) Equipment Required – GPWS (Cont'd)					
34-45-01-11	Modes 1 to 4	A	4	0	(O) One or more mode may be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
34-45-01-12	Test Mode	A	1	0	May be inoperative provided: a) GPWS is considered inoperative, and b) Repairs are made within 2 flight-days.	
34-45-01-13	Glideslope Deviation (Mode 5)					
34-45-01-13-A		C	-	1	May be inoperative.	
34-45-01-13-B		B	-	0	May be inoperative.	
34-45-01-14	Advisory Callouts					
34-45-01-14-A		B	-	0	(O) May be inoperative provided alternate procedures are established and used.	
34-45-01-14-B		C	-	0	(O) May be inoperative provided: a) Advisory callout not required by 14 CFR, and b) Alternate procedures are established and used.	
(Continued)						

REVISION NO. 8

PAGE NO. 34-10

DATE: 09/18/2020

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-45-00	Enhanced Ground Proximity Warning System (E-GPWS/GPWS) (Cont'd)					
34-45-01-10	Class A Terrain Awareness and Warning System (TAWS) Equipment Required – GPWS (Cont'd)					
34-45-01-15 ***	Windshear Mode (Reactive)					
34-45-01-15-A		B	1	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Operator's alternate procedures should include reviewing windshear avoidance and windshear recovery procedures.	
34-45-01-15-B		C	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Windshear Detection and Avoidance System (Predictive) are operative.	
34-45-01-20	Terrain System – Forward Looking Terrain Avoidance (FLTA) and Premature Descent Alert (PDA) Functions	B	1	0	(O) May be inoperative provided alternate procedures are established and used.	
34-45-01-30	Terrain Displays					
34-45-01-30-A		C	-	1	May be inoperative.	
34-45-01-30-B		B	-	0	May be inoperative.	
34-45-01-40 ***	Runway Awareness and Advisory System (RAAS)	C	1	0	May be inoperative. (Continued)	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-11

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-45-00	Enhanced Ground Proximity Warning System (E-GPWS/GPWS) (Cont'd)					
34-45-02-10	Class B TAWS Equipment Required – GPWS					
34-45-02-10-A	A/C without M3688 and without M3849	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, b) Approaches are limited to ILS, LPV or Visual approaches, and c) Repairs are made within 2 flight-days.	
34-45-02-10-B	A/C with M3688 or M3849	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
34-45-02-11	Modes 1 and 3	A	2	0	(O) One or more may be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight-days.	
34-45-02-12	Test Mode	A	1	0	May be inoperative provided: a) GPWS is considered inoperative, and b) Repairs are made within 2 flight-days.	
34-45-02-13	Modes 2, 4, and 5	C	3	0	One or more may be inoperative.	
(Continued)						

REVISION NO. 8

PAGE NO. 34-12

DATE: 09/18/2020

AIRCRAFT:
 Falcon 2000EX EASy/DX/LX/S/LXS

TABLE KEY

1. REPAIR CATEGORY
2. NO. INSTALLED
3. NO. REQUIRED FOR DISPATCH
4. REMARKS OR EXCEPTIONS

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-45-00	Enhanced Ground Proximity Warning System (E-GPWS/GPWS) (Cont'd)					
34-45-02-10	Class B TAWS Equipment Required – GPWS (Cont'd)					
34-45-02-14	Advisory Callouts					
34-45-02-14-A		B	-	0	(O) May be inoperative provided alternate procedures are established and used.	
34-45-02-14-B		C	-	0	(O) May be inoperative provided: a) Advisory callout not required by 14 CFR, and b) Alternate procedures are established and used.	
34-45-02-15 ***	Windshear Mode (Reactive)	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
34-45-02-20	Terrain System – FLTA and PDA Functions	B	1	0	May be inoperative.	
34-45-02-30 ***	Terrain Displays	C	-	1	May be inoperative.	
34-45-02-40 ***	Runway Awareness and Advisory System (RAAS)	C	1	0	May be inoperative.	
34-45-03-10	Class C TAWS Equipment TAWS/GPWS	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
						NOTE: Any mode that is operative may be used.

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-13

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-45-10 ***	Synthetic Vision System (SVS) on PDU (A/C with M3303)	D	2	0	One or more may be inoperative provided: a) Affected SV Function is deselected, and b) AGM .. DATABASE OLD CAS message is not displayed.	
34-51-00	Very High Frequency Omni-Directional Range (VOR)/ILS Function	C	2	-	As required by 14 CFR.	
34-51-40	Marker Beacon	C	-	0	May be inoperative provided approach procedures do not require its use.	
34-51-60	Global Positioning System (GPS)	D	2	-	(O) As required by 14 CFR. NOTE: Automatic Dependent Surveillance-Broadcast (ADS-B OUT) function (aircraft with M3301) is not used when both GPS are inoperative.	
34-52-00	Distance Measuring Equipment (DME)	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	
34-53-00	Automatic Direction Finder (ADF)	D	2	-	Any in excess of those required by 14 CFR may be inoperative.	
34-54-00	ATC Transponder Function					
34-54-00-10	ATC Transponders and Automatic Altitude Reporting Systems					
34-54-00-10-A		B	-	0	May be inoperative provided: a) Operations do not require its use, and b) Prior to flight, approval is obtained from ATC facilities having jurisdiction over the planned route of flight.	
34-54-00-10-B		D	-	1	Any in excess of those required by 14 CFR may be inoperative.	

(Continued)

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-54-00	ATC Transponder Function (Cont'd)					
34-54-00-20	Elementary and Enhanced Downlink Aircraft Reportable Parameters Not Required by 14 CFR	A	-	0	May be inoperative provided: a) Operations do not require its use, and b) Repairs are made prior to completion of the next heavy maintenance visit.	
34-54-00-30	ADS-B Squitter Transmissions				Moved to item 34-55-00-10, Revision 7.	
34-55-00 ***	ADS-B System (A/C with M3301)					
34-55-00-A ***		C	-	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) It is not required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
34-55-00-B ***		D	-	0	May be inoperative provided: a) Enroute operations do not require its use, and b) It is not required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
34-55-00-C ***		C	-	1	One must be operative as required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-15

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-55-00 ***	ADS-B System (A/C with M3301) (Cont'd)					
34-55-00-10 ***	ADS-B Out Extended Squitter Transmissions					
34-55-00-10-A ***		C	-	0	(O) May be inoperative provided: a) Alternate procedures are established and used, b) Authorization is obtained from ATC facilities having jurisdiction over planned route of flight, and c) It is not required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
34-55-00-10-B ***		C	-	1	One must be operative as required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
34-55-00-20 ***	ADS-B Out Universal Access Transceiver (UAT) Transmissions					
34-55-00-20-A ***		C	-	0	(O) May be inoperative provided: a) Enroute operations do not require its use, b) Authorization is obtained from ATC facilities having jurisdiction over planned route of flight, and c) It is not required by 14 CFR. NOTE: Any ADS-B Out function that operates normally may be used.	

(Continued)

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-16

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-55-00 ***	ADS-B System (A/C with M3301) (Cont'd)					
34-55-00-20 ***	ADS-B Out Universal Access Transceiver (UAT) Transmissions (Cont'd)					
34-55-00-20-B ***		C	-	1	One must be operative as required by 14 CFR. NOTE: Any ADS-B function that operates normally may be used.	
34-55-00-30 ***	ADS-B In Transmissions					
34-55-00-30-A ***		C	-	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any ADS-B In function that operates normally may be used.	
34-55-00-30-B ***		D	-	0	May be inoperative provided operations do not require its use. NOTE: Any ADS-B function that operates normally may be used.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 34-17

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

34. Navigation

Sequence No.	Item	1	2	3	4	Change Bar
34-60-00 ***	Flight Management System (FMS) (Aircraft with M2504)	D	3	2	One may be inoperative.	
34-60-20	Navigation Database	A	-	0	May be inoperative provided: a) Operations do not require its use, b) It is not used in a primary navigation system required by 14 CFR, c) Alternate procedures are developed and used, d) The ICAO Flight Plan is updated (as required) to notify ATC of the navigation equipment status of the aircraft, and e) Is repaired within 10 flight-days. NOTE: An out-of-currency or out-of-date navigation database is not authorized MMEL relief per 14 CFR.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 35-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

35. Oxygen

Sequence No.	Item	1	2	3	4	Change Bar
35-20-00	Passenger Oxygen System					
35-20-00-A		D	1	0	May be inoperative provided: a) Only the pilot and co-pilot are on board, b) Passenger OXYGEN Selector is set to CLOSED, and c) Forward Observer Seat is not occupied.	
35-20-00-B		C	1	0	May be inoperative provided the flight altitude is limited to 10,000 ft or below.	
35-20-00-10	Mask Automatic Dropout Mode	C	1	0	(M)(O) May be inoperative provided: a) Flight level is limited to FL 250 or below, b) OVERRIDE and FIRST AID Oxygen Systems are verified operative, and c) CABIN Warning System (visual and aural) is verified operative.	
35-20-00-20	Mask Unit	C	-	-	(M)(O) May be inoperative provided: a) Affected seat is secured to prevent occupancy, and b) Mask Unit is verified operative for all operative passenger seats, toilet compartments, and flight attendant locations.	
35-21-20	First Aid Oxygen	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	
35-30-05	Portable Oxygen System	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 36-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

36. Pneumatic

Sequence No.	Item	1	2	3	4	Change Bar
36-00-01	Bleed Air System Computer (BASC)	B	1	0	(M)(O) May be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) Flight is conducted in an unpressurized configuration, c) APU is verified operative before each departure, and d) Both Engine Bleed Air Valves (HP) are secured in closed position.	
36-00-01-10	Anemometry Data Function	C	4	2	One or more may be inoperative provided only one ADC information side is affected.	
36-00-01-20	Computer Failure Warning Function	C	2	0	One or more may be inoperative.	
36-00-01-30	Cabin Pressure Control Monitoring Function	C	1	0	(O) May be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) COND: CKPT OVERPRESS test amber message is not displayed during light test operation, c) APU is verified operative before each departure, d) HP 1 and Engine Pressure Regulating Valve (PRV) 1 pushbuttons are set to OFF, and e) XBLEED pushbutton is set to OPEN.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 36-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

36. Pneumatic

Sequence No.	Item	1	2	3	4	Change Bar
36-00-01	Bleed Air System Computer (BASC) (Cont'd)					
36-00-01-40	Cockpit Pressure Control Monitoring Function	C	1	0	(O) May be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) COND: CABIN OVERPRESS test amber message is not displayed during light test operation, c) APU is verified operative before each departure, d) HP 2 and PRV 2 pushbuttons are set to OFF, and e) XBLEED Pushbutton is set to OPEN.	
36-10-02	Engine Bleed Air Valve (HP)	B	2	1	(M)(O) One may be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) APU is verified operative before each departure, c) Associated HP switch is set to OFF, d) CROSSBLEED selector switch is set to OPEN, and e) Associated Engine Bleed Air Valve (HP) is secured in closed position. NOTE: APU can pressurize the aircraft up to 35,000 ft but cannot anti-ice.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 36-3

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

36. Pneumatic

Sequence No.	Item	1	2	3	4	Change Bar
36-10-03	Engine Pressure Regulating Valve (PRV)	B	2	1	(O) One may be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) Opposite Engine Bleed Air Valve (HP) is operative, c) Affected PRV is verified in closed position before each departure, d) APU is verified operative before each departure, e) Associated PRV switch is set to OFF, and f) CROSSBLEED selector switch is set to OPEN. NOTE: APU can pressurize the aircraft up to 35,000 ft but cannot anti-ice.	
36-10-15	APU Bleed Air System					
36-10-15-A		C	1	0	(M)(O) May be inoperative and APU used for ground engine start provided: a) APU is not used in flight, b) APU is used on ground for electrical generation and engine start only, c) APU is shut down as soon as an engine runs, d) FADECs are operative, e) L/G Retraction System is operative, f) APU Bleed Valve is manually operated for APU-assisted ground engine start, and g) APU Bleed Valve is verified closed before each departure.	
36-10-15-B		C	1	0	(M) May be inoperative provided: a) APU is considered inoperative (item 49-10-01), and b) APU Bleed Valve is verified closed before each departure.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 36-4

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

36. Pneumatic

Sequence No.	Item	1	2	3	4	Change Bar
36-21-01	Cockpit Air Conditioning Temperature Sensor (Tcc)	C	1	0	May be inoperative provided both Bleed Air Temperature Sensors (T1 and T2) are operative.	
36-21-02	Wing Anti-Icing Temperature Sensor (Tv)	C	1	0	(O) May be inoperative provided airplane is not operated in known or forecast icing conditions.	
36-21-08	Cabin Air Conditioning Temperature Sensor (Tcp)	C	1	0	May be inoperative provided both Bleed Air Temperature Sensors (T1 and T2) are operative.	
36-21-09	Pressure Sensor (Pv and Pm)	B	2	0	(M)(O) One or more may be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) Flight is conducted in an unpressurized configuration, c) All DUs are operative, d) APU is verified operative before each departure, e) PRVs are verified in closed position, f) Engine Bleed Air Valves (HP) are secured in closed position, and g) PRV switches are set to OFF.	
36-21-13	Bleed Air Temperature Sensor (T1 or T2)	B	2	1	(O) One may be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) All other Bleed Air Temperature Sensors are operative, c) APU is verified operative before each departure, d) Associated HP switch is set to OFF, and e) CROSSBLEED selector switch is set to OPEN. NOTE: APU can pressurize the aircraft up to 35,000 ft but cannot anti-ice.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 38-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

38. Water/Waste

Sequence No.	Item	1	2	3	4	Change Bar
38-30-05	Lavatory Waste System	C	1	0	(M) Individual components may be inoperative provided: a) Associated components are deactivated or isolated, and b) Associated system components are verified not to have leaks. NOTE: Any portion of the system which is operative may be used.	
38-30-09	Toilet Drain Valve					
38-30-09-10 ***	Front Toilet Drain Valve					
38-30-09-10-A		A	1	0	May be inoperative in closed position provided repairs are made before next Toilet Drain pan-draining operation.	
38-30-09-10-B		A	1	0	(O) May be inoperative in open position provided: a) Flight is conducted in an unpressurized configuration, b) Front Toilet is not used, c) DUs are operative, d) Draining port cap is verified in locked position, e) Toilet door is placarded "DO NOT USE TOILET," and f) Repairs are made within 3 consecutive calendar-days.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 38-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

38. Water/Waste

Sequence No.	Item	1	2	3	4	Change Bar
38-30-09	Toilet Drain Valve (Cont'd)					
38-30-09-20	Rear Toilet Drain Valve					
38-30-09-20-A		A	1	0	May be inoperative in closed position provided repairs are made before next Toilet Drain pan-draining operation.	
38-30-09-20-B		A	1	0	(O) May be inoperative in open position provided: a) Flight is conducted in an unpressurized configuration, b) Rear Toilet is not used, c) DUs are operative, d) Draining port cap is verified in locked position, e) Toilet door is placarded "DO NOT USE TOILET," and f) Repairs are made within 3 consecutive calendar-days.	
38-30-09-20-C		A	1	0	(M) May be inoperative provided: a) After manually closing the Rear Toilet Drain Valve, it is verified not to have leaks, and b) Repairs are made within 3 consecutive calendar-days.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 45-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

45. Central Maintenance System

Sequence No.	Item	1	2	3	4	Change Bar
45-10-00	Central Maintenance Computer (CMC)	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
45-10-09 ***	Cockpit Printer (A/C with M2514)	D	1	0	May be inoperative provide alternate procedures, if required, are established and used.	
45-90-00	Navigation Database Loading System	D	1	0	May be inoperative provided: a) Alternate procedures are established and used when Navigation Databases become out-of-currency or out-of-date, and b) Repairs are made prior to operations that require up-to-date Navigation Databases.	
45-90-01	Data Management Unit (DMU)					
45-90-01-A ***	Aircraft with M2519	D	1	0	May be inoperative provided Jeppesen Electronic Terminal Charts (item 34-00-02) are considered inoperative.	
45-90-01-B ***	Aircraft without M2519	D	1	0	May be inoperative.	
45-90-01-C ***	Aircraft with M3305	D	1	0	May be inoperative.	
45-90-10	Database Module Aircraft without M3254	C	2	0	One or more may be inoperative.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 46-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

46. Information Systems

Sequence No.	Item	1	2	3	4	Change Bar
46-20-00 ***	Electronic Flight Bag (EFB) System				NOTE: Per FAA MMEL PL-121, portable EFB components are not installed equipment and are therefore not required for dispatch. Consequently, portable EFB components are not appropriate for MMEL relief and have been removed from the MMEL accordingly. However, if the EFB is the only means for the pilot to view digital documents required under 14 CFR (e.g., instrument procedures, performance, etc...), then the EFB is required unless alternate procedures are established and used.	
46-20-00-01 ***	EFB System (A/C with M2735)				DELETED Revision 8.	
46-20-00-02	EFB Device (Other Use)				DELETED Revision 8.	
(Continued)						

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 46-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

46. Information Systems

Sequence No.	Item	1	2	3	4	Change Bar
46-20-00 ***	Electronic Flight Bag (EFB) System (Cont'd)					
46-20-00-03 ***	Power Connection	C	-	0	One or more may be inoperative.	
46-20-00-04 ***	Mounting Device	C	-	0	(M) One or more may be inoperative provided inoperative Mounting Device is secured or removed from the aircraft.	
46-20-00-05 ***	Data Connectivity	C	-	0	One or more may be inoperative.	
46-50-01 ***	Airshow System					
46-50-01-A ***		D	-	0	May be inoperative provided passenger safety briefing does not require its use.	
46-50-01-B ***		C	-	0	May be inoperative provided alternate procedures for passenger safety briefing are established and used.	

REVISION NO. 6
DATE: 11/18/2016

PAGE NO. 49-1

<p>AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS</p>	<p>TABLE KEY</p> <ol style="list-style-type: none"> 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

49. Airborne Auxiliary Power

Sequence No.	Item	1	2	3	4	Change Bar
49-10-01	Auxiliary Power Unit (APU)	C	1	0	(O) May be inoperative provided: a) Both FADECs are operative, b) L/G Retraction System is operative, and c) MASTER APU is set to OFF.	
49-50-01	APU Inlet Door					
49-50-01-A		C	1	0	(M) May be inoperative closed provided: a) APU is considered inoperative (item 49-10-01), and b) APU Inlet Door is secured in closed position.	
49-50-01-B		C	1	0	(M)(O) May be jammed in other than closed position provided: a) APU is considered inoperative (item 49-10-01), b) AFM Limitations and Performance are applied, and c) APU Inlet Door is secured.	
49-50-05	APU Door Indication System					
49-50-05-A		C	1	0	May be inoperative provided APU Inlet Door operations are visually verified operative by performing an APU on/off cycle before each departure.	
49-50-05-B		C	1	0	May be inoperative provided APU is considered inoperative (item 49-10-01).	
49-70-00	APU Indications (N ₁ , EGT, OVSP, Oil)	C	4	0	(O) One or more may be inoperative provided: a) APU is only used for engine start, b) APU is verified operative before each flight, and c) APU FAULT amber CAS message is monitored during APU use.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 49-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

49. Airborne Auxiliary Power

Sequence No.	Item	1	2	3	4	Change Bar
49-91-10	APU Oil Test and Level Indication					
49-91-10-A		C	1	0	May be inoperative provided APU is considered inoperative (item 49-10-01).	
49-91-10-B		A	1	0	(M) May be inoperative provided: a) APU oil quantity is visually verified within the first three flights of the repair interval, and b) Repairs are made within 40 flight-hours.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 52-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

52. Doors

Sequence No.	Item	1	2	3	4	Change Bar
52-10-20	Passenger Door Electrical Maneuver System					
52-10-20-01	Electrical Lifting	B	1	0	(O) May be inoperative provided: a) The door is closed with an alternate procedure, and b) Door opening duration is verified adequate.	
52-10-20-02	DOOR LIFT Amber Light	B	1	0	(O) May be inoperative provided door opening duration is verified adequate.	
52-30-00	Baggage Compartment External Door					
52-30-00-01	Proximity Sensor	C	4	0	(O) One or more may be inoperative provided door is secured closed before each departure.	
52-40-10 ***	Pocket Sliding Door (Galley to Cabin)	D	1	0	(M) May be inoperative provided the door is secured open.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 73-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

73. Engine Fuel and Control

Sequence No.	Item	1	2	3	4	Change Bar
73-20-01	Full-Authority Digital Engine Control (FADEC)					
73-20-01-03	Channel	A	2	1	All FADEC Channels must be operative; however, aircraft may be dispatched with FADEC fault provided repairs are made in accordance with times established by Short Time/Long Time Dispatch Fault items, or by PWC Type Certificate Data Sheet (TCDS) No. E00065NE, note 13, whichever is more restrictive.	
73-20-01-04	Channel Monitoring Function	A	4	3	One may be inoperative provided: a) ENG...SHORT DISPATCH white CAS message of the associated engine is not displayed, and b) Repairs are made within 150 flight-hours.	
73-20-01-10	Short Time Dispatch Fault	A	-	-	Only one engine may be affected provided repairs are made within 125 flight-hours.	
73-20-01-11	Long Time Dispatch Fault	A	-	-	Only one engine may be affected provided repairs are made within 350 flight-hours.	
73-40-01	APR Automatic Mode	A	1	0	(O) May be inoperative provided: a) APR ORIDE operation is verified operative on both engines before departure, b) APR ORIDE Button is pressed before takeoff and landing, and c) Repairs are made within 2 consecutive calendar-days.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 74-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

74. Ignition

Sequence No.	Item	1	2	3	4	Change Bar
74-10-10	Igniter Channel	B	4	3	(O) One may be inoperative provided: a) Both FADECs are operative, b) Only one engine has a detected ground start light-off fault, and c) AFM procedure for starting engine in IGNITION mode is complied with.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 77-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

77. Engine Indicating

Sequence No.	Item	1	2	3	4	Change Bar
77-30-01	Engine Vibration Indication	C	2	1	One may be inoperative.	
77-30-10	Engine Vibration Monitor Computer (EVMC) Channel	C	2	1	One may be inoperative.	

REVISION NO. 7
 DATE: 07/05/2018

PAGE NO. 78-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

78. Engine Exhaust

Sequence No.	Item	1	2	3	4	Change Bar
78-30-00	Thrust Reverser System	A	2	0	(M)(O) One or more may be inoperative provided: a) Autobrake System is not used, b) Appropriate AFM Balanced Field Length (BFL) adjustments are applied, c) Takeoff and landing are not conducted on an icy runway, d) Both Thrust Reversers have sustained no damage, e) Both Thrust Reversers are secured in stowed position, f) Airbrakes are manually extended in case of RTO below V ₁ (Airbrake Handle on position 2), and g) Repairs are made within 100 consecutive calendar-days.	
78-30-06	TRANS Amber Label	A	2	0	One or more Labels may be inoperative provided: a) Thrust Reverser System is considered inoperative (item 78-30-00), and b) Repairs are made within 100 consecutive calendar-days.	
78-30-08	DEPLOY Green Label	A	2	0	One or more Labels may be inoperative provided: a) Thrust Reverser System is considered inoperative (item 78-30-00), and b) Repairs are made within 100 consecutive calendar-days.	

REVISION NO. 8
 DATE: 09/18/2020

PAGE NO. 79-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

79. Engine Oil

Sequence No.	Item	1	2	3	4	Change Bar
79-30-00	Engine Oil Level Indication System	C	1	0	(M) May be inoperative provided oil tank level of affected engine is verified adequate before each departure.	
79-30-02	Engine Oil Pressure Indication	A	2	1	(O) One may be inoperative provided: a) ENG...OIL PRESS FAIL white CAS message is not displayed, b) Associated Oil Temperature Indication is verified operative, and c) Repairs are made within 10 consecutive calendar-days.	
79-30-03	Engine Oil Chip Detector System	C	2	0	(M) One or more may be inoperative provided associated Engine Oil Chip Detector System is verified free of contaminant before each departure.	
79-30-05	Engine Oil Filter Clogging Indication	C	2	0	(M) One or more may be displayed provided associated Engine Oil Filter is verified free of contamination before each departure.	
79-30-10	Engine Oil Low Pressure Warning System	A	2	1	One may be inoperative provided: a) Associated Oil Pressure and Oil Temperature Indications are operative, b) Associated Oil Pressure and Oil Temperature Indications are monitored at least every 30 minutes in flight, and c) Repairs are made within 2 consecutive calendar-days.	

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 80-1

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

80. Starting

Sequence No.	Item	1	2	3	4	Change Bar
80-10-13	Engine Starting Valve					
80-10-13-10	Left Engine Starting Valve	A	1	0	(M)(O) May be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) Right Engine Starting Valve is operative, c) APU is verified operative before each departure, d) Bus Tie System is verified operative, e) Fuel Crossfeed System is verified operative, f) Wing tank pressurization is verified adequate, g) All Booster Pumps are verified operative, h) Affected valve is opened manually before engine start and secured in closed position after engine start, and i) Repairs are made within 2 consecutive calendar-days. NOTE: In flight, restart of associated engine is only possible using ENGINE-WINDMILLING AIRSTART procedure.	
(Continued)						

REVISION NO. 6
 DATE: 11/18/2016

PAGE NO. 80-2

AIRCRAFT: Falcon 2000EX EASy/DX/LX/S/LXS	TABLE KEY 1. REPAIR CATEGORY 2. NO. INSTALLED 3. NO. REQUIRED FOR DISPATCH 4. REMARKS OR EXCEPTIONS
---	--

80. Starting

Sequence No.	Item	1	2	3	4	Change Bar
80-10-13	Engine Starting Valve (Cont'd)					
80-10-13-20	Right Engine Starting Valve	A	1	0	(M)(O) May be inoperative provided: a) Airplane is not operated in known or forecast icing conditions, b) Left Engine Starting Valve is operative, c) APU is verified operative before each departure, d) Bus Tie System is verified operative, e) Fuel Crossfeed System is verified operative, f) Wing tank pressurization is verified adequate, g) All Booster Pumps are verified operative, h) Affected valve is opened manually before engine start and secured in closed position after engine start, and i) Repairs are made within 2 consecutive calendar-days.	