



U.S. Department
of Transportation

**Federal Aviation
Administration**

January 21, 2021

Learjet Inc.

Dear Learjet Inc.:

The Aircraft Evaluation Group (AEG) has reviewed your request for Supplemental Type Certificate (STC) relief that may be included in an operator's FAA approved MEL. The AEG finds your relief submission allowable as documented in the relief section of this letter. This relief is valid when an operator installs the listed STC on an aircraft that is listed in the Aircraft Model List (AML) below. No other application of this relief is allowed. The STC holder must contact the AEG when the STC is amended, revised or revoked.

Operators may use this relief letter to incorporate the relief listed below into their Minimum Equipment List (MEL) upon publication of this letter and in accordance with the MEL approval process in FAA Order 8900.1. The relief granted remains valid indefinitely with possession of this letter unless the relief is specifically revoked or revised by the Administrator.

STC Applicant	Learjet Inc.
STC Number	ST00360BO
STC Description	Installation of a cockpit speaker mute switch in accordance with Master Data List BAS63017018, Revision C, dated November 17, 2015 or later FAA-approved revision.
Aircraft Model List	CL-600-2B16(CL-601-3A-3R/604) CL-600-2B16(CL-604-DX/CL-605)

Sincerely,

Dusan Vukotic
FOEB Chair,
Aircraft Evaluation Group

Approved STC Relief

System	Item	Category	Installed	Required	Remarks-Exceptions
23	Cockpit Speaker Mute Pushbutton Annunciator Switch	C	1	0	May be inoperative in the mute state provided Flight Compartment Speakers (23-50-1) are considered inoperative.
23	Cockpit Speaker Mute Pushbutton Annunciator Switch	D	1	0	(O) May be inoperative provided the system is not failed in the mute state.
23	Cockpit Speaker Mute PBA Annunciator (light function only)	D	1	0	(O) May be inoperative provided Cockpit Speaker Mute Annunciator lights on the Glareshield are operative.
23	Cockpit Speaker Mute Annunciator lights on Glareshield	D	2	0	(O) May be inoperative provided Cockpit Speaker Mute PBA Switch is not in the muted state (not illuminated).