



U.S. Department of Transportation
Federal Aviation Administration
Washington, D.C.

Master Minimum Equipment List (MMEL)

Revision: 37
Date: 03/27/2015

BOEING 767

James P. Vogt
Flight Operations Evaluation Board (FOEB)

Federal Aviation Administration
Seattle Aircraft Evaluation Group
1601 Lind Ave SW
Renton, WA 98057

Telephone: (425) 917-6648
FAX: (425) 917-6638

(BOEING B-767)

Contents

SYSTEM	PAGES	REVISION	DATE
Title Page		37	03/27/2015
Contents	I	37	03/27/2015
Highlights of Change	II through VI	37	03/27/2015
Definitions	VII	37	03/27/2015
Preamble	VII	37	03/27/2015
21 Air Conditioning	21-1 through 21-32	37	03/27/2015
22 Auto Flight	22-1 through 22-13	37	03/27/2015
23 Communications	23-1 through 23-27	37	03/27/2015
24 Electrical Power	24-1 through 24-12	37	03/27/2015
25 Equipment/Furnishings	25-1 through 25-21	37	03/27/2015
26 Fire Protection	26-1 through 26-17	37	03/27/2015
27 Flight Controls	27-1 through 27-4	37	03/27/2015
28 Fuel	28-1 through 28-12	37	03/27/2015
29 Hydraulic Power	29-1 through 29-5	37	03/27/2015
30 Ice and Rain Protection	30-1 through 30-12	37	03/27/2015
31 Indicating/Recording Systems	31-1 through 31-12	37	03/27/2015
32 Landing Gear	32-1 through 32-10	37	03/27/2015
33 Lights	33-1 through 33-14	37	03/27/2015
34 Navigation	34-1 through 34-29	37	03/27/2015
35 Oxygen	35-1 through 35-7	37	03/27/2015
36 Pneumatic	36-1 through 36-30	37	03/27/2015
38 Water/Waste	38-1 through 38-2	37	03/27/2015
46 Information Systems	46-1 through 46-2	37	03/27/2015
47 Inert Gas System	47-1	37	03/27/2015
49 Airborne Auxiliary Power	49-1 through 49-4	37	03/27/2015
52 Doors	52-1 through 52-17	37	03/27/2015
56 Windows	56-1	37	03/27/2015
73 Engine Fuel & Control	73-1 through 73-7	37	03/27/2015
74 Ignition	74-1	37	03/27/2015
75 Bleed Air	75-1 through 75-4	37	03/27/2015
77 Engine Indicating	77-1 through 77-4	37	03/27/2015
78 Engine Exhaust	78-1 through 78-2	37	03/27/2015
79 Engine Oil	79-1 through 79-3	37	03/27/2015
80 Starting	80-1	37	03/27/2015

(BOEING B-767)

Highlights of Change

EFFECTIVE ABOVE DATE, the Boeing 767 Master Minimum Equipment List has been revised. The changes in this revision were made to align with FAA policy letters, apply restrictions, adjust format and nomenclature and increase dispatch flexibility. All changes are reflected in the highlights of change listed below and are indicated by revision bars in the associated ATA section. For any change affecting an ATA section, all pages in that associated ATA section are re-dated accordingly, with the exception of nomenclature changes for ATA chapter headings.

GENERAL

All item and sub-item designators are comprised of pairs of numerical digits. Sub-item options are designated by alpha characters. Use of the “/” symbol has been standardized in all titles.

767 model designations have been revised as follows in ATA 21, 23, 24, 25, 26, 32, 33, 35, 52, and 56:

- “-200SF ATC” indicates -200 Special Freighter Amended Type Certificate A1NM
- “-200SF STC” indicates -200 Special Freighter Supplemental Type Certificate ST01433SE

The Revision Number and Date have been revised for all chapters. Revised content is identified by change bars. The above items are not included in the ATA chapter list below.

ATA 21 AIR CONDITIONING

Item -20-01: Added asterisks. The item is not required by regulation but may have been installed on some models.

Item -51-01: Standardized configuration nomenclature in subtitle.

Item -52-03: Revised Remarks or Exceptions to include two separate provisos and require verification of the EICAS message.

Item -61-03: Revised valve name in accordance with AMM terminology, and standardized configuration nomenclature.

ATA 22 AUTO FLIGHT

Item -11-01: Added Category B relief in accordance with MMEL PL-93.

ATA 23 COMMUNICATIONS

Item -10-01: Added sub-item 1, Off-side Tuning Light.

Item -22-02: Revised title to include Interactive Display Unit (IDU).

Item -25-01: Revised title for cross-fleet standardization of wide-body fleet.

Item -40-01: Revised proviso to include the forward fuselage service interphone jack.

Item -51-03: Revised to clarify the relief applies only to interphone speakers. Relief for aural warning speakers has not been considered for the MMEL and is not included in this item.

ATA 24 ELECTRICAL POWER

Item -27-02: Revised structure to add sub-item 1 designation for -200/-300 models, with options -01A and -01B. Designated -400ER relief as sub-item 2 and revised proviso for clarification and standardization.

(BOEING B-767)

ATA 25 EQUIPMENT AND FURNISHINGS

- Item -11-01: Standardized terminology and added sub-item 25-11-01-02-05 in accordance with wide-body fleet MMELs.
- Item -11-02: Revised for cross-fleet standardization of wide-body fleet.
- Item -25-01: Added "USE" to proviso e; revised proviso b in accordance with MMEL PL-125; deleted "the" from proviso c; added asterisks to sub-item -03.
- Item -25-02: Revise sub-item title to plural "Armrests" and standardized terminology to state "airplane."
- Item -25-05: Added asterisks. The item is not required by regulation but may have been installed on some models.
- Item -41-01: Revised in accordance with MMEL PL-24.
- Item -50-01: Revised item title for cross-fleet standardization of wide-body fleet.
- Item -53-01: Revised item title for cross-fleet standardization of wide-body fleet.
- Item -54-01: Revised item title for cross-fleet standardization of wide-body fleet.
- Item -57-01: New MMEL item number for relief derived from previous Item 25-53-01, for cross-fleet standardization of wide-body fleet.
- Item -58-01: New MMEL item number for relief derived from previous Item 25-54-01, for cross-fleet standardization of wide-body fleet.
- Item -63-01: Revised proviso in accordance with MMEL PL-125.
- Item -63-04: Revised for cross-fleet standardization of wide-body fleet. Revised proviso in accordance with MMEL PL-125.

ATA 26 FIRE PROTECTION

- Item -26-03: Added asterisks to sub-item -01-01. The item is not required by regulation but may have been installed on some models.

ATA 27 FLIGHT CONTROLS

- Item -41-02: Revised proviso to require verification of stabilizer trim.

ATA 28 FUEL

- Item -21-02: Revised to indicate a variable Number Installed. Some configurations have two fueling stations.
- Item -22-02: Revised proviso "e" to require the center tank and both main tank quantity indications operate normally, to avoid a conflict between requirements and recommended procedures regarding the crossfeed valve.
- Item -22-03: Revised proviso b to require verification of the remaining valve.
- Item -41-06: Revised title for cross-fleet standardization. Revised to indicate a variable Number Installed. Some configurations have two fueling stations.

(BOEING B-767)

ATA 29 HYDRAULIC POWER

Item -33-01: Revised proviso to require verification of normal operation. The MMEL requirement of an (M) procedure is intended for confirmation of normal operation and hydraulic quantity.

ATA 30 ICE AND RAIN PROTECTION

Item -21-01: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.

Item -33-01: Revised sub-item title to include ADIRS-equipped airplanes with air data system functionality.

Item -41-01: Revised proviso to state "affected."

Item -42-01: Revised for cross-fleet standardization of wide-body fleet.

ATA 31 INDICATING/RECORDING SYSTEMS

Item -61-12: Added new item Head-Up Display (HUD)/Enhanced Flight Vision System (EFVS) (STC ST04174AT).

ATA 32 LANDING GEAR

Item -30-01: Revised title for cross-fleet standardization of wide-body fleet. There is one actuation system for the landing gear. The system provides extend and retract functions, as described in AMM 32-30-00/1.

ATA 33 LIGHTS

Item -11-01: Standardized terminology of system in proviso b.

Item -14-01: Added asterisks. The item is not required by regulation but may have been installed on some models.

Item -21-01: Revised 33-21-01-01 title to state "Non-Photoluminescent," to be inclusive of light technologies other than incandescent, such as electroluminescent. Revised provisos for cross-fleet standardization of wide-body fleet.

Item -24-01: Revised proviso in accordance with MMEL PL-125. Sub-item relief for All-Cargo configuration moved to Item 33-24-02. Subsequent sub-items re-numbered; no change to content.

Item -24-02: Relief for All-Cargo configuration moved to Item 33-24-02 with revised title. Previous content for STC relief moved from this item to new Item 33-24-03; no change to content.

Item -24-03: Relief for STC ST01994SE and ST02137SE moved from 33-24-02 to new Item 33-24-03, to accommodate similar movement of relief from Item 33-24-01-01 into Item 33-24-02.

Item -31-01: Revised title for cross-fleet standardization of wide-body fleet.

Item -51-01: Revised proviso "b" in accordance with MMEL PL-125.

Item -51-03: Revised 33-51-03B proviso "b" in accordance with MMEL PL-125. Revised 33 51-03-01 title to state "Non-Photoluminescent," to be inclusive of light technologies other than incandescent, such as electroluminescent.

FEDERAL AVIATION ADMINISTRATION
MASTER MINIMUM EQUIPMENT LIST
(BOEING B-767)

Page: V
Revision: 37
Date: 03/27/2015

ATA 34 NAVIGATION

- Item -21-01: Standardized subtitle format of 34 -21-01-01-02. Deleted redundant proviso d) from sub-item 34-21-01-01-02B; only the right IRS may be inoperative, therefore left and center IRS must operate normally.
- Item -26-01: Revised title, added asterisks and deleted model designator. The item is not installed on all models. The item is also applicable to 767-300F L/N 1070 and on.
- Item -51-01: Revised Repair Interval to standardize with wide-body fleet MMELs.
- Item -53-01: Revised sub-item in accordance with MMEL PL-76 Rev. 6, and for cross-fleet standardization of wide-body fleet.
- Item -60-03: Revised for cross-fleet standardization of wide-body fleet.

ATA 35 OXYGEN

- Item -21-01: Revised in accordance with AD 2012-11-09.

ATA 36 PNEUMATIC

- Item -00-01: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -11-02: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -11-03: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -11-08: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -12-01: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -21-03: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -22-01: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -22-03: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.

ATA 47 INERT GAS SYSTEM

- Item -11-01: Revised title in accordance with ATA Master List 47-11.

ATA 49 AIRBORNE AUXILIARY POWER

- Item -11-01: Added proviso to second set of relief to address configurations impacted by an inoperative APU.
- Item -15-01: Revised format to consolidate relief according to model; added relief for -200/-300 door in any position.

ATA 52 DOORS

- Item -11-04: Revised proviso in accordance with MMEL PL-125.

(BOEING B-767)

ATA 73 ENGINE FUEL & CONTROL

- Item -21-01: Standardized nomenclature of Supervisory system controls to use PMC (Power Management Control) in accordance with AMM 73-21-1.
- Item -21-02: Standardized nomenclature of Supervisory system controls to use PMC (Power Management Control) in accordance with AMM 73-21-1.
- Item -21-08: Standardized nomenclature of Supervisory system controls to use PMC (Power Management Control) in accordance with AMM 73-21-1.

ATA 78 ENGINE EXHAUST

- Item -34-01: Revised proviso to state "are verified to operate normally," in accordance with (M) requirement.
- Item -34-03: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -36-01: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.
- Item -36-03: Revised provisos to state "Associated thrust reverser is considered inoperative" in accordance with FAA MMEL Definitions.

ATA 79 ENGINE OIL

- Item -34-02: Deleted parentheses from PMC in title.

FEDERAL AVIATION ADMINISTRATION

Page: VII

MASTER MINIMUM EQUIPMENT LIST

Revision: 37

Date: 03/27/2015

(BOEING B-767)

Definitions

The Definitions are as published in FAA Policy Letter 25.

Preamble

The Preamble is as published in FAA Policy Letter 34.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
21 AIR CONDITIONING					
-20-01 ***	A/C Ozone Converters	C	2	0	As required by 14 CFR.
-22-01 ***	Flight Deck Supply Boost Fan	D	1	0	(M) May be inoperative deactivated.
-24-01 ***	Gasper Fan	D	1	0	
-25-01 ***	Recirculation Fans				
-25-01-01	-200/-300				
-25-01-01A		C	2	1	
-25-01-01B		C	2	0	May be inoperative provided both packs operate normally.
-25-01-02	-400ER				
-25-01-02A		C	2	1	
-25-01-02B		C	2	0	(O) May be inoperative provided: a) Both packs operate normally, and b) Appropriate performance adjustments are applied.
-25-02 ***	Recirculation Fan INOP Lights	C	2	0	(M) May be inoperative provided associated EICAS message is verified to operate normally.
-28-01 ***	Forward Cargo Air Conditioning System	D	1	0	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-29-01	Crew Rest Area Air Distribution System (STC ST00973WI-D)				
-29-01-01	Air Supply Shutoff Valves	C	2	0	(M) May be inoperative closed provided associated crew rest area is locked closed and placarded DO NOT USE. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-29-01-02	Boost Fans	C	2	0	(M) May be inoperative deactivated provided associated heater is deactivated.
-29-02	Lower Lobe Crew Rest Air Distribution System (STCs ST01994SE and ST02137SE)	C	1	0	(M) May be inoperative provided: a) Lower lobe crew rest module is not used and personal items are removed, and b) Lower lobe crew rest door is closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest inspections by crewmembers
-29-02-01	Air Flow Sensor	C	1	0	(O) May be inoperative provided no hazardous goods are carried in associated cargo compartment.
-31-01	Auto Cabin Pressure Control Systems				
-31-01A		C	2	1	One may be inoperative provided manual mode and one autopilot operate normally. (Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-3

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2.	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING					
-31-01 Auto Cabin Pressure Control Systems (Cont'd)					
-31-01B	C	2	0		<p>(M) (O) May be inoperative provided:</p> <ul style="list-style-type: none"> a) Flight is conducted in an unpressurized configuration, b) Manual cabin pressure control system operates normally, c) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, e) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and f) For -400ER, appropriate performance adjustments are applied. <p>NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.</p> <p>(Continued)</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 21-4
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING						
-31-01	Auto Cabin Pressure Control Systems (Cont'd)					
-31-01C		C	2	0		(M) (O) May be inoperative provided: <ul style="list-style-type: none"> a) Flight is conducted in an unpressurized configuration, b) Extended overwater flight is prohibited, c) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, e) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and f) For -400ER, appropriate performance adjustments are applied. <p>NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 21-5
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING						
-31-02	Manual Cabin Pressure Control System	C	1	0	(M)(O)	<p>May be inoperative provided:</p> <ul style="list-style-type: none"> a) Flight is conducted in an unpressurized configuration, b) Extended overwater flight is prohibited, c) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, e) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and f) For -400ER, appropriate performance adjustments are applied. <p>NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	21-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING						
-31-03	Outflow Valve	C	1	0		(M)(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, b) Extended overwater flight is prohibited, c) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, e) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and f) For -400ER, appropriate performance adjustments are applied. g) NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.
-32-01	Positive Pressure Relief Valves					
-32-01A		C	-	-		(M) One may be inoperative closed.
(Continued)						

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-32-01	Positive Pressure Relief Valves (Cont'd)				
-32-01B		C	-	0	<p>(M)(O) May be inoperative provided:</p> <ul style="list-style-type: none"> a) Flight is conducted in an unpressurized configuration, b) Manual cabin pressure control system operates normally, c) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, e) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and f) For -400ER, appropriate performance adjustments are applied. <p>NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.</p> <p>(Continued)</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 21-8
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING						
-32-01	Positive Pressure Relief Valves (Cont'd)					
-32-01C		C	-	0	(M)(O) May be inoperative provided:	
						<ul style="list-style-type: none"> a) Flight is conducted in an unpressurized configuration, b) Extended overwater flight is prohibited c) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, e) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and f) For -400ER, appropriate performance adjustments are applied. <p>NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.</p>

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-33-01	CABIN RATE of Climb Indicator				
-33-01A		C	1	0	May be inoperative provided both automatic pressure control systems operate normally.
-33-01B		C	1	0	(M)(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, b) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, c) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and e) For -400ER, appropriate performance adjustments are applied.
NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	21-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
21 AIR CONDITIONING						
-33-02	CABIN DIFF Pressure Indicator					
-33-02A		C	1	0		(O) May be inoperative provided: a) CABIN ALT indicator operates normally, and b) A chart is provided to convert cabin altitude to cabin differential pressure altitude.
-33-02B		C	1	0		(M)(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, b) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, c) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, d) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and e) For -400ER, appropriate performance adjustments are applied.
						NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 21-11
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING						
-33-03	CABIN ALT Indicator					
-33-03A		C	1	0	(O)	May be inoperative provided: c) CABIN DIFF indicator operates normally, and d) A chart is provided to convert cabin differential pressure to cabin altitude.
-33-03B		C	1	0	(M)(O)	May be inoperative provided: f) Flight is conducted in an unpressurized configuration, g) For cargo compartments with Class C fire suppression, procedures are established and used to ensure lower compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, h) For forward lower lobe cargo compartments with Class E fire suppression, procedures are established and used to ensure forward lower lobe compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, i) For -200SF ATC and -300BCF with Class E fire suppression, procedures are established and used to ensure all compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits, and j) For -400ER, appropriate performance adjustments are applied.
						NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-33-04	Outflow VALVE Position Indicator	C	1	0		
-33-05	AUTO INOP Light (Cabin Altitude Control)	C	1	0	(O) May be inoperative provided: a) Both automatic pressure control systems operate normally, and b) CABIN ALT or CABIN RATE of climb indicator operates normally.	
-33-06	Cabin Altitude Warning System	C	1	0	May be inoperative provided flight remains at or below 10,000 feet MSL.	
-40-01	Cargo Heating Systems					
-40-01-01	Fwd and Aft	C	2	0	(M) May be inoperative deactivated.	
-40-01-02	*** Bulk	C	1	0	(M) May be inoperative deactivated.	
-40-01-02-01	Bulk Cargo Vent Fan	C	1	0	(O) May be inoperative provided BULK CARGO HEAT selector remains in NORM position.	
-40-02	Cargo Heat Indicating Systems (OVHT and/or ON Light)					
-40-02-01	Fwd and Aft					
-40-02-01-01	-200/-300					
-40-02-01-01A		C	-	0	(M) May be inoperative provided overheat protective system(s) is verified to operate normally.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	21-13

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-40-02	Cargo Heat Indicating Systems (OVHT and/or ON Light) (Cont'd)				
-40-02-01	Fwd and Aft (Cont'd)				
-40-02-01-01	-200/-300 (Cont'd)				
-40-02-01-01B		C	-	0	May be inoperative provided associated cargo heat system is selected OFF.
-40-02-01-02	-400ER	C	2	0	
-40-02-02	*** Bulk				
-40-02-02-01	-200/-300				
-40-02-02-01A		C	1	0	(M) May be inoperative provided overheat protective system(s) is verified to operate normally.
-40-02-02-01B		C	1	0	May be inoperative provided bulk cargo heat system is selected OFF.
-40-02-02-02	-400ER	C	1	0	

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 21-14
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING						
-45-01	Flight Crew Auxiliary Heat Systems					
-45-01A		C	4	0		May be inoperative OFF. NOTE: Any portion that operates normally may be used.
-45-01B		C	4	0		(M) May be inoperative provided affected system is deactivated. NOTE: Any portion that operates normally may be used.
-45-02	Forward Door Area Heater System (-200SF ATC/-300BCF/-300F/-300BDSF)	C	1	0		(M) May be inoperative deactivated.
-45-03	Door Heater Systems (Type A, I, III Doors)	C	-	0		(M) May be inoperative deactivated.
-51-01	Air Conditioning Packs					
-51-01-01	-200/-300	C	2	1		(O) One may be inoperative provided: a) Airplane remains at or below FL 350, b) Remaining (opposite) pack operates normally, and c) Flight remains within 60 minutes of landing at a suitable airport.
-51-01-02	-400ER	C	2	1		(O) One may be inoperative provided: a) Airplane remains at or below FL 350, b) Remaining (opposite) pack operates normally,
(Continued)						

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 21-15
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING						
-51-01	Air Conditioning Packs (Cont'd)					
-51-01-02	-400ER (Cont'd)	C	2	1		c) Flight remains within 60 minutes of landing at a suitable airport, and d) Appropriate performance adjustments are applied.
-51-01-03	-200/-300 Passenger Configuration with Classic Interior	C	2	0		(M)(O) May be inoperative provided: a) Flight is conducted in an unpressurized configuration, b) Both recirculation fans operate normally, and c) Procedures are established and used to ensure lower cargo compartments remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE 1: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast. NOTE 2: Classic Interior is on most -200/-300 passenger airplanes. All 767 passenger airplanes built prior to March 2000 and some built since then have classic interior. NOTE 3: 767 New Look Interior (NLI) looks similar to 777 interior. NLI, also referred to as Signature Series Interior, was first installed in 767 in March 2000.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-16

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH		4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING							
-51-02	Pack Flow Control/Shutoff Valves	C	2	-			(M)(O) May be inoperative closed for an associated inoperative pack.
-51-02-01	Hi Flow Mode (-200/-300 Passenger)	C	2	1			Except for ER operations, one may be inoperative provided remaining (opposite) pack operates normally.
-51-02-02	Hi Flow Mode (All Cargo Configuration)	C	2	0			
-51-03	Pack Temperature Control Systems (-200/-300)	C	2	-			May be inoperative OFF for an associated inoperative pack.
-51-03-01	Auto Mode	C	2	0			May be inoperative provided associated standby mode operates normally.
-51-03-02	Standby Mode	C	2	0			May be inoperative provided associated auto mode operates normally.
-51-04	Pack Temperature Control Valves (-200/-300)						
-51-04A		C	2	1			(M)(O) One valve may be inoperative deactivated in mid position provided: a) Associated pack is operated in STBY, and b) Remaining (opposite) pack operates normally in AUTO.
-51-04B		C	2	1			(M) One may be inoperative closed in STBY provided remaining (opposite) pack operates normally in AUTO.
(Continued)							

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-17

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-51-04	Pack Temperature Control Valves (-200/-300) (Cont'd)					
-51-04C		C	2	-	May be inoperative for an associated inoperative pack.	
-51-05	Pack Altitude Switch (-200/-300)	C	1	0		
-51-06	Main Cargo Air Distribution Riser Shutoff Valves					
-51-06-01						
-200SF ATC/ -300BCF/-300F		C	-	1	(M) May be inoperative closed provided: a) Corresponding zone trim air modulating valve is deactivated closed, and b) Operation is limited to one pack.	
					NOTE: In event of operating pack failure, turn on remaining pack.	
-51-06-02						
-200PC/-200SF STC/ -300BDSF		C	-	1	(M) May be inoperative closed provided: a) Corresponding zone trim air modulating valve is deactivated closed, b) Operation is limited to one pack, and c) Operations are limited to FL 350 and below.	
					NOTE: In event of operating pack failure, turn on remaining pack.	

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-18

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
21 AIR CONDITIONING					
-51-07	Air Cycle Machine				
-51-07-01					
	-200/-300	C	2	1	(M)(O) Except for ER operations, one may be inoperative provided: <ul style="list-style-type: none"> a) Associated pack is operated in STBY WARM, b) Flow control valve in associated pack is verified to operate normally, c) Remaining (opposite) pack operates normally, and d) Associated pack is turned OFF at TAT above 0 degrees C.
-51-07-02					
	-400ER	C	2	1	(M)(O) One may be inoperative with associated pack selected on provided: <ul style="list-style-type: none"> a) Remaining (opposite) pack operates normally, b) Remaining (opposite) engine bleed system operates normally, c) Associated turbine bypass valve is secured open, and d) Appropriate performance adjustments are applied.
-52-01	PACK RESET Switches				
-52-01A		C	2	1	One may be inoperative provided both packs operate normally.
-52-01B		C	2	-	May be inoperative for an associated inoperative pack(s).
-52-02	Pack INOP Lights	C	2	1	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-19

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
				3. NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-52-03	Air Conditioning PACK OFF Lights	C	2	1	(M) One may be inoperative OFF provided: a) Associated EICAS message is verified to operate normally, and b) All other pack indications operate normally.
-52-05	Secondary Heat Exchanger Outlet Temperature Sensor Systems (-400ER)				
-52-05A		C	2	0	May be inoperative provided: c) Associated condenser low limit control system operates normally, and d) Associated ram air inlet door operates normally.
-52-05B		C	2	1	One may be inoperative for an associated inoperative pack.
-52-06	ASCTU Pack Outlet Temperature Sensors (-400ER)				
-52-06A		C	2	0	(M) May be inoperative provided: a) CTC sensor for associated pack is verified to operate normally, b) Associated CTC operates normally, and c) Associated secondary heat exchanger outlet temperature sensor system operates normally.
-52-06B		C	2	1	One may be inoperative for an associated inoperative pack.

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 21-20
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-52-07	Compressor Discharge Temperature Sensors (-400ER)				
-52-07A		C	6	2	May be inoperative provided at least one sensor per pack operates normally.
-52-07B		C	6	2	(M) May be inoperative for an associated inoperative pack provided at least two sensors are verified to operate normally on remaining (opposite) pack.
-52-08	Condenser Low Limit Control Systems (-400ER)				
-52-08A		C	2	1	(M)(O) One may be inoperative provided: a) Associated condenser low limit valve is secured open, b) Remaining (opposite) pack operates normally, c) Remaining (opposite) engine bleed system operates normally, and d) Appropriate performance adjustments are applied.
-52-08B		C	2	1	One may be inoperative for an associated inoperative pack.
-53-01	Ram Air Inlet/Exhaust Door Systems				
-53-01A		C	2	0	(M)(O) May be inoperative provided doors are secured open with pack(s) operating.
-53-01B		C	2	-	(M) May be inoperative in any position provided associated pack is considered inoperative.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	21-21

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
21 AIR CONDITIONING					
-58-01	Forward Equipment Cooling AUTO System				
-58-01-01	-200/-300	C	1	0	May be inoperative provided STBY control system is used.
-58-01-02	-400ER	C	1	0	May be inoperative provided: a) STBY control system is used, and b) Both packs operate normally.
-58-02	Forward Equipment Cooling Temperature Control System (Two Supply Fan Installation)	C	1	0	(M) May be inoperative provided: a) STBY control system is used, and b) Heat exchanger bypass valve is deactivated CLOSED.
-58-03	Forward Equipment Cooling Supply Fans				
-58-03-01	Two Supply Fan Installation	C	2	1	One may be inoperative provided: a) Forward equipment cooling exhaust fan operates normally, and b) Automatic control system operates normally.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	21-22

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-58-03	Forward Equipment Cooling Supply Fans (Cont'd)					
-58-03-02	One Supply Fan Installation					
-58-03-02-01	-200/-300	C	1	0	May be inoperative provided: a) Forward equipment cooling exhaust fan operates normally, b) STBY control system is used, and c) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air.	
-58-03-02-02	-400ER	C	2	1	(O) May be inoperative provided: a) Forward equipment cooling exhaust fan operates normally, b) STBY control system is used, c) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air, d) Both packs operate normally, and e) SMOKE/OVRD valve is verified to operate normally.	
-58-04	Forward Equipment Cooling Exhaust Fan					
-58-04-01	Two Supply Fan Installation	C	1	0	May be inoperative provided both forward equipment cooling supply fans operate normally. (Continued)	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-23

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-58-04	Forward Equipment Cooling Exhaust Fan (Cont'd)				
-58-04-02	One Supply Fan Installation				
-58-04-02-01	-200/-300	C	1	0	May be inoperative provided: a) Forward equipment cooling supply fan operates normally, b) STBY control system is used, and c) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air.
-58-04-02-02	-400ER	C	1	0	(O) May be inoperative provided: a) Forward equipment cooling supply fan operates normally, b) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air, c) Both packs operate normally, and d) SMOKE/OVRD valve is verified to operate normally.
-58-05	Aft Equipment/ Lav/Galley Exhaust (Vent) Fans	C	2	1	
-58-06 ***	Forward Equipment Cooling Ground Supply Valve	D	1	0	(M) May be inoperative secured closed.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-24

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-58-07	Forward Equipment Cooling Overboard Exhaust Valve					
-58-07-01	Two Supply Fan Installation	C	1	0	(M)(O) May be inoperative secured closed.	
-58-07-02	One Supply Fan Installation					
-58-07-02-01	-200/-300	C	1	0	(M) May be inoperative secured closed provided: a) STBY control system is used, and b) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air.	
-58-07-02-02	-400ER	C	1	0	(M)(O) May be inoperative secured closed provided: a) STBY control system is used, b) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air, and c) Both packs operate normally.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-25

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-58-08	Forward Equipment Cooling Inboard Supply Valve					
-58-08-01	One Supply Valve Installation					
-58-08-01-01	-200/-300	C	1	0	(M) May be inoperative secured closed provided: a) STBY control system is used, and b) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air.	
-58-08-01-02	-400ER	C	1	0	(M) May be inoperative secured closed provided: a) STBY control system is used, b) For ground operation above 29 degrees C OAT, main cabin is supplied with conditioned air, and c) Both packs operate normally.	
-58-09 ***	Avionics Cooling Refrigeration Unit (ACRU)	D	1	0		
-58-10 ***	ACRU Supply Valve	D	1	0	(M) May be inoperative secured closed.	
-58-11 ***	ACRU Isolation Valve	D	1	0	(M) May be inoperative secured open.	
-58-12 ***	Instrument Cooling Monitor System					
-58-12A		C	1	0	(M) May be inoperative provided availability of adequate air flow is verified before each departure.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-26

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-58-12 ***	Instrument Cooling Monitor System (Cont'd)					
-58-12B		D	1	0	Except for ER operations, may be inoperative.	
-58-13 ***	In-Flight Entertainment (IFE) Cooling Systems	D	-	0	(M) May be inoperative provided associated IFE system is deactivated.	
-58-14	AVS/IFE Inboard/Overboard Exhaust Valves					
-58-14-01	Alternate Ventilation System (AVS) Inboard Exhaust Valve (-400ER)	C	1	0	(M) May be inoperative secured closed provided both packs operate normally.	
-58-14-02 ***	IFE Inboard/Overboard Exhaust Valves					
-58-14-02A		C	2	1	(M) One may be inoperative secured open.	
-58-14-02B		C	2	0	(M) May be inoperative provided: a) One valve is secured closed, and b) Both packs operate normally.	
-58-15	Flight Deck Air Relief System Valve (-300F)	C	1	0	(M) May be inoperative secured closed.	
-58-16 ***	F1 Forward Galley Chiller Smoke Detector	C	1	0	(M) May be inoperative deactivated provided associated chiller is deactivated.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-27

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-58-17 ***	Flight Deck Panel Cooling Air Shutoff Valve	D	1	0	(M) May be inoperative deactivated open.	
-61-01	Cabin COMPT TEMP Control Systems					
-61-01-01	Passenger					
-61-01-01-01	-200/-300/-400ER	C	-	0	(M) May be inoperative provided associated zone trim air modulating valve(s) or trim air regulating/shutoff valve(s) remains closed.	
-60-01-01-02	-400ER Control Panel Functions	C	3	0	(M) May be inoperative for unannunciated faults that do not affect zone temperature control availability.	
-61-01-02	All Cargo Configuration	C	2	0	(M) May be inoperative provided associated zone trim air modulating valve remains closed.	
-61-02	Flight Deck COMPT TEMP Control System					
-61-02-01	Passenger	C	1	0	(M) Both auto and manual modes may be inoperative provided associated zone trim air modulating valve or trim air regulating/shutoff valve remains closed.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 21-28
----------------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
21 AIR CONDITIONING							
-61-02	Flight Deck COMPT TEMP Control System (Cont'd)						
-61-02-02	-400ER Control Panel Functions	C	1	0		(M) May be inoperative for unannunciated faults that do not affect zone temperature control availability.	
-61-02-03	AUTO Mode	C	1	0		May be inoperative provided MAN mode operates normally.	
-61-02-04	MAN Mode	C	1	0		May be inoperative provided AUTO mode operates normally.	
-61-03	Trim Air Pressure Regulating/Shutoff Valve System(s) (Passenger Configuration)	C	-	0		(M) May be inoperative provided associated trim air pressure regulating/shutoff valve is secured closed.	
-61-04	Zone Trim Air Modulating Valves						
-61-04-01	Passenger						
-61-04-01A		C	-	0		(M) May be inoperative provided affected valve is closed.	
-61-04-01B		C	-	0		May be inoperative in any position provided trim air switch remains OFF.	
-61-04-02	All Cargo Configuration	C	3	1		(M) Main cargo compartment valves may be inoperative closed.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

21-29

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-61-05	Trim Air OFF Light(s)	C	-	0		
-61-06	COMPT TEMP INOP Lights					
-61-06-01	Passenger					
-61-06-01-01	-200/-300					
-61-06-01-01A		C	-	0	(M) May be inoperative provided associated trim air modulating valve remains closed.	
-61-06-01-01B		C	-	0	(M) May be inoperative provided associated trim air regulating/shutoff valve remains closed.	
-61-06-01-02	-400ER	C	4	0	(O) May be inoperative.	
-61-06-02	All Cargo Configuration	C	3	1	(M) FWD and/or AFT light(s) may be inoperative provided associated trim air modulation valve(s) remains closed.	
-61-07	Trim Air Check Valves (-200/-300)					
-61-07-01	Passenger	C	2	0	(M) May be inoperative provided one failed check valve is secured closed	
-61-07-02	All Cargo Configuration	C	2	1	(M)(O) May be inoperative provided: a) Failed check valve is secured closed, and b) Trim air is available from side opposite to valve that is secured closed.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-30

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
21 AIR CONDITIONING					
-61-08	Cabin Temperature Controllers (CTC) (-400ER)				
-61-08A		C	2	1	(M)(O) One may be inoperative provided: a) Associated pack flow control valve is secured closed, b) Remaining (opposite) pack operates normally, c) Remaining (opposite) engine bleed system operates normally, and d) Appropriate performance adjustments are applied.
-61-08B		C	2	1	(O) One may be inoperative for associated inoperative pack provided associated trim air system remains off.
-64-01	Trim Air Valve Position Indicator	C	1	0	
-64-02	Forward Overboard Valve (-300/-400ER)	C	1	0	(M) May be inoperative provided valve is deactivated closed.
-65-01	COMPT TEMP Indications	C	3	0	
-66-01	Crew Rest Area Temperature Control System (STC ST00973WI-D)				
-66-01-01	Pre-Heater System	C	1	0	(M) May be inoperative deactivated.
-66-01-02	Heaters	C	2	0	(M) May be inoperative deactivated.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-31

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-66-01	Crew Rest Area Temperature Control System (STC ST00973WI-D) (Cont'd)					
-66-01-03	Heat Select Switches	C	2	0	(M) May be inoperative deactivated provided associated heater and boost fan are deactivated.	
-66-02	Lower Lobe Crew Rest Bunk Heater System (STCs ST01994SE and ST02137SE)					
-66-02A		C	1	0	(M) May be inoperative provided: a) Heater System is deactivated b) Lower lobe crew rest module is not used and personal items are removed, and c) Lower lobe crew rest door is closed and placarded INOPERATIVE - DO NOT ENTER.	
-66-02B		C	1	0	(M)(O) May be inoperative provided: a) Associated Crew Rest Air Distribution System operates normally, and b) Heater system is deactivated.	
-71-01	CTT Systems Zonal Comfort System (STC ST00436SE)					
-71-01-01	Zonal Humidifier System	D	1	0	(M) May be inoperative provided humidifier system is deactivated.	
-71-01-01-01	Humidifiers	D	7	0	(M) May be inoperative deactivated.	
(Continued)						

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	21-32

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
21 AIR CONDITIONING						
-71-01	CTT Systems Zonal Comfort System (STC ST00436SE) (Cont'd)					
-71-01-02	Zonal Drying System	D	1	0	(M) May be inoperative provided: a) Zonal drying system is deactivated, and b) Humidifier system is deactivated.	
-71-01-02-01	Zonal Dryers	D	3	0	(M) May be inoperative provided: a) Affected zonal dryer is deactivated, and b) Associated humidifier is deactivated.	

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

22-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
22 AUTOFLIGHT					
-10-01	Autopilot Systems				
-10-01A		C	3	2	(M) One may be inoperative provided: a) Associated FCC SERVO circuit breaker is pulled and collared, b) If FCC single source option is installed, autopilot flight director system is verified not in a single source configuration prior to each departure, and c) Approach minimums do not require its use.
-10-01B		C	3	1	(M) Two may be inoperative provided: a) At least two FCC power circuit breakers remain in, b) Associated FCC SERVO circuit breakers are pulled and collared, c) If FCC single source option is installed, autopilot flight director system is verified not in a single source configuration prior to each departure, and d) Approach minimums do not require their use.
-10-01C		B	3	0	(M) Except for ER operations, all may be inoperative provided: a) At least one FCC power circuit breaker remains in, b) All three FCC SERVO circuit breakers are pulled and collared, c) Enroute operations and approach minimums do not require their use, and d) Number of flight segments and segment duration is acceptable to flight crew.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

22-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
22 AUTOFLIGHT						
-11-01	Control Wheel Disengage Switches					
-11-01A		C	2	1	One may be inoperative provided: a) Autopilots are not used below 1,500 feet AGL, and b) Approach minimums do not require use of autopilot.	
-11-01B		B	2	0	May be inoperative provided: a) Autopilots are not used, b) Enroute operations and approach minimums do not require use of autopilot, and c) Number of flight segments and segment duration is acceptable to flight crew.	
-11-02	A/P DISC Light (-200/-300)	C	2	1	May be inoperative provided: a) Autopilots are not used below 1,500 feet AGL, and b) All other A/P disengagement alerts operate normally.	
-11-03	Mode Control Panel Selectors					
-11-03-01	VERT SPD Selector (DN & UP)	C	1	0	(O) May be inoperative provided FL CH mode operates normally.	
-11-03-02	BANK LIMIT Selector	C	1	0	(O) May be inoperative.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	22-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
22 AUTOFLIGHT					
-11-03	Mode Control Panel Selectors (Cont'd)				
-11-03-03	Selector Push Functions				
-11-03-03-01	IAS/MACH	C	1	0	(O) May be inoperative. NOTE: Rotational function must operate normally.
-11-03-03-02	*** ALT	C	1	0	(O) May be inoperative. NOTE: Rotational function must operate normally.
-11-03-03-03	HDG SEL	B	1	0	(O) May be inoperative. NOTE: Rotational function must operate normally.
-11-04	Mode Control Panel Switches				
-11-04-01	A/P Engage Switches/Paddles (L CMD/C CMD/ R CMD)				
-11-04-01A		C	3	1	(O) May be inoperative. NOTE: All operative autopilots may be used during autoland operations.
(Continued)					

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	22-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
22 AUTOFLIGHT						
-11-04	Mode Control Panel Switches (Cont'd)					
-11-04-01	A/P Engage Switches/Paddles (L CMD/C CMD/ R CMD) (Cont'd)					
-11-04-01B		B	3	0	Except for ER operations, may be inoperative provided: a) Enroute operations and approach minimums do not require their use, and b) Number of flight segments and segment duration is acceptable to flight crew.	
-11-04-02	A/P CWS Engage Switches	C	3	0		
-11-04-03	A/T ARM Switch	C	1	0	May be inoperative OFF provided approach minimums do not require use of autothrottle system.	
-11-04-04	A/T SPD Mode Engage Switch	C	1	0	(O) May be inoperative provided procedures and approach minimums do not require its use.	
-11-04-05	F/D Switches	C	2	0	May be inoperative OFF provided approach minimums do not require use of flight director displays.	
-11-04-06	IAS/MACH SEL Switch	C	1	0	May be inoperative provided IAS is displayed in associated window.	
(Continued)						

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	22-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
22 AUTOFLIGHT						
-11-04	Mode Control Panel Switches (Cont'd)					
-11-04-07	APP Switch	C	1	0	May be inoperative provided approach minimums do not require use of autopilot or flight director.	
-11-04-08	LOC Switch	C	1	0	(O) May be inoperative.	
-11-04-09	*** B/CRS Switch	C	1	0	(O) May be inoperative.	
-11-04-10	V NAV/FL CH/ V/S / ALT HOLD Switches	C	4	3	(O) One may be inoperative provided procedures or enroute operations do not require its use.	
-11-04-11	L NAV/HDG HOLD Switches	C	2	1	(O) One may be inoperative provided: a) HDG SEL operates normally, and b) Procedures or enroute operations do not require its use.	
-11-04-12	EPR/N1/THR Switch	C	1	0	May be inoperative provided both thrust levers are operated manually for takeoff.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

22-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
22 AUTOFLIGHT					
-11-05	Mode Control Panel Windows				
-11-05-01	Airspeed (IAS/MACH)				
-11-05-01-01	-200/-300	C	1	0	(O) May be inoperative provided command airspeed bug on airspeed indicator (and ADI speed tape, if installed) operates normally on both sides.
-11-05-01-02	-400ER	C	1	0	(O) May be inoperative provided selected airspeed indications on both PFD operate normally.
-11-05-01-03	-200/-300 (STC ST02165NY)	C	1	0	(O) May be inoperative provided selected airspeed indications on both PFD operate normally.
-11-05-01-04	-300F (STC ST01750WI)	C	1	0	(O) May be inoperative provided selected airspeed indications on both PFD operate normally.
-11-05-02	Heading (HDG)				
-11-05-02-01	-200/-300	C	1	0	(O) May be inoperative provided selected heading indications on both HSI operate normally.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

22-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
22 AUTOFLIGHT						
-11-05	Mode Control Panel Windows (Cont'd)					
-11-05-02	Heading (HDG) (Cont'd)					
-11-05-02-02	-400ER	C	1	0	(O) May be inoperative provided selected heading indications on both PFD operate normally.	
-11-05-02-03	-200/-300 (STC ST02165NY)	C	1	0	(O) May be inoperative provided selected heading indications on both PFD operate normally.	
-11-05-02-04	-300F (STC ST01750WI)	C	1	0	(O) May be inoperative provided selected heading indications on both PFD operate normally.	
-11-05-03	Vertical Speed (VERT SPD)	C	1	0	(O) May be inoperative provided vertical speed mode is not selected.	
-11-05-03-01	-400ER	C	1	0	(O) May be inoperative provided selected vertical speed indications on both PFD operate normally.	
-11-05-03-02	-200/-300 (STC ST02165NY)	C	1	0	(O) May be inoperative provided selected vertical speed indications on both PFD operate normally.	
(Continued)						

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

22-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
22 AUTOFLIGHT					
-11-05	Mode Control Panel Windows (Cont'd)				
-11-05-03	Vertical Speed (VERT SPD) (Cont'd)				
-11-05-03-03	-300F (STC ST01750WI)	C	1	0	(O) May be inoperative provided selected vertical speed indications on both PFD operate normally.
-11-05-04	Altitude (ALT)				
-11-05-04-01	-400ER	C	1	0	(O) May be inoperative provided selected altitude indications on both PFD operate normally.
-11-05-04-02	-300F (STC ST01750WI)	C	1	0	(O) May be inoperative provided selected altitude indications on both PFD operate normally.
-11-06	Mode Control Panel Switch Lights				
-11-06-01	Autopilot Engage Switch Lights (CMD)	C	3	2	NOTE: A switch with one lamp operational is considered to be operating normally.
-11-06-02	Mode Selector Switch Lights				
-11-06-02A		C	-	-	Lights for any two switches may be inoperative. NOTE: A switch with one lamp operational is considered to be operating normally.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

22-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
22 AUTOFLIGHT					
-11-06	Mode Control Panel Switch Lights (Cont'd)				
-11-06-02	Mode Selector Switch Lights (Cont'd)				
-11-06-02B		B	-	0	NOTE: A switch with one lamp operational is considered to be operating normally.
-14-01	Autoland Status Annunciators (-200/-300)	C	2	0	May be inoperative provided approach minimums do not require their use.
-14-02	Automatic Landing System (AUTOLAND)	C	1	0	May be inoperative provided approach minimums do not require its use.
-14-02-01	Triple Channel Autoland (LAND 3)	C	1	0	May be inoperative provided approach minimums do not require its use.
-21-01	Yaw Dampers	C	2	1	(M) One may be inoperative provided remaining yaw damper is verified to operate normally. NOTE: Airplanes without SB 767-22-7 or production equivalent installed, see AFM Limitations.
-30-01	Thrust Management System (Including Autothrottle System)	C	1	0	(M) May be inoperative provided approach minimums do not require its use.
-30-01-01	Autothrottle Servo	C	1	0	(M) May be inoperative provided: a) Autothrottles are deactivated, and b) Approach minimums do not require use of autothrottle.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	22-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
22 AUTOFLIGHT					
-30-01	Thrust Management System (Including Autothrottle System) (Cont'd)				
-30-01-02	Autothrottle Disconnect Switches				
-30-01-02A		C	2	1	
-30-01-02B		C	2	0	(M) May be inoperative provided: a) Autothrottles are deactivated, and b) Approach minimums do not require use of autothrottle.
-30-01-03	Thrust Mode Select Panel (-200/-300)				
-30-01-03-01	Derate Switches	C	2	0	
-30-01-03-02	TEMP SEL Selector	C	1	0	
-30-01-03-03	TO/GA Switch	C	1	0	
-30-01-03-04	CLB Switch	C	1	0	(O) May be inoperative provided automatic climb thrust select option is installed and operates normally.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

22-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
22 AUTOFLIGHT					
-30-01	Thrust Management System (Including Autothrottle System) (Cont'd)				
-30-01-03	Thrust Mode Select Panel (-200/-300) (Cont'd)				
-30-01-03-05	CON Switch	C	1	0	(O) May be inoperative provided max continuous thrust is set manually if required.
-30-01-03-06	CRZ Switch	C	1	0	
-30-02	Go-Around and Takeoff/Go-Around Switches				
-30-02-01	Go-Around Switches (-200/-300)				
-30-02-01A		C	2	1	(M) One may be inoperative provided: a) Approach minimums do not require its use, and b) Remaining go-around switch is verified to operate normally.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 22-12
----------------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
22 AUTOFLIGHT						
-30-02	Go-Around and Takeoff/Go-Around Switches (Cont'd)					
-30-02-01	Go-Around Switches (-200/-300) (Cont'd)					
-30-02-01B		C	2	0		May be inoperative provided: <ul style="list-style-type: none"> a) Both thrust levers are operated manually for go-around, and b) Autopilot and flight director are not used below 500 feet AGL or applicable approach minimum, whichever is higher. NOTE: Flight director go-around and windshear guidance are not available with both go-around switches inoperative.
-30-02-02	Takeoff/Go-Around (TO/GA) Switches (-400ER)					
-30-02-02A		C	2	1		(M) One may be inoperative provided: <ul style="list-style-type: none"> a) Approach minimums do not require its use, and b) Remaining TO/GA switch is verified to operate normally.
-30-02-02B		C	2	0		May be inoperative provided: <ul style="list-style-type: none"> a) Both thrust levers are operated manually for takeoff and go-around, and b) Autopilot and flight director are not used below 500 feet AGL or applicable approach minimum, whichever is higher. NOTE: Flight director go-around and windshear guidance are not available with both go-around switches inoperative.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 22-13
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
22 AUTOFLIGHT						
-34-01	Autothrottle Disconnect (A/T DISC) Light (-200/-300)					
-34-01A		C	1	0		May be inoperative provided: a) Associated EICAS annunciation operates normally, and b) Associated aural alert operates normally.
-34-01B		C	1	0		May be inoperative provided: a) A/T ARM switch remains OFF, and b) Approach minimums do not require its use.
-41-01	Maintenance Control Display Panel (MCDP)	D	1	0		

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
23 COMMUNICATIONS						
-10-01 ***	Radio Tuning Panels (Digital RTP)	C	3	2	One may be inoperative provided left radio tuning panel operates normally.	
-10-01-01	Off-side Tuning Light	C	-	0		
-11-01	Communications Systems (VHF/HF/UHF)	D	-	-	Any in excess of those required by 14 CFR, and not powered by a standby bus, may be inoperative.	
-11-01-01	VHF Comm					
-11-01-01-01	Frequency In Use Light	C	-	0		
-11-01-01-02	Frequency Transfer Switch					
-11-01-01-02A		C	-	0	May be inoperative provided associated VHF active frequency can be selected.	
-11-01-01-02B		D	-	-	Any in excess of those required by 14 CFR, and not powered by a standby bus, may be inoperative.	
-11-01-01-03	Frequency Selector Knob	C	-	2		
-11-01-01-04	Frequency Indication	C	-	2		
(Continued)						

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	23-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-11-01	Communications Systems (VHF/HF/UHF) (Cont'd)				
-11-01-02	High Frequency (HF) Communication System				
-11-01-02A		D	-	-	Any in excess of those required by 14 CFR may be inoperative.
-11-01-02B		C	-	1	(O) May be inoperative while conducting operations that require two LRCS provided: a) SATCOM voice or data link operates normally, b) Alternate procedures are established and used, c) SATCOM voice coverage is available over intended route of flight, and d) If SATCOM voice is to be used over intended route of flight, SATCOM voice short codes (INMARSAT) or direct dial commercial numbers (IRIDIUM) must be available. If not available, prior coordination with appropriate ATS (FIR) facility is required.
					NOTE: SATCOM is to be used only as a backup to normal HF communications unless otherwise authorized by appropriate ATS facilities.
-11-02	Flight Deck Communications Systems (Datalink)				

-11-02A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.
-11-02B		D	1	0	May be inoperative provided procedures do not require its use.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-21-01 ***	Selective Call System (SELCAL)				
-21-01A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.
-21-01B		D	1	0	May be inoperative provided procedures do not require its use.
-21-01-01	Channels				
-21-01-01A		C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-21-01-01B		D	-	0	May be inoperative provided procedures do not require its use.
-22-01 ***	ACARS System				
-22-01A		C	1	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any mode that operates normally may be used.
-22-01B		D	1	0	May be inoperative provided procedures do not require its use. NOTE: Any mode that operates normally may be used. (Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
23 COMMUNICATIONS					
-22-01 ***	ACARS System (Cont'd)				
-22-01-01 ***	ACARS Printer				
-22-01-01A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.
-22-01-01B		D	1	0	May be inoperative provided procedures do not require its use.
-22-02 ***	Multipurpose Interactive Display Unit (MIDU) (Includes Interactive Display Unit (IDU))				
-22-02A		C	1	0	(O) May be inoperative provided alternate procedures are established and used for subsystems.
-22-02B		D	1	0	May be inoperative provided procedures do not require its use.
-25-01 ***	Satellite Communication (SATCOM) Systems				
-25-01A		C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-25-01B		D	-	0	May be inoperative provided procedures do not require its use.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
23 COMMUNICATIONS					
-25-01 ***	Satellite Communication (SATCOM) Systems (Cont'd)				
-25-01-01	SATCOM Voice				
-25-01-01A		C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-25-01-01B		D	-	0	May be inoperative provided procedures do not require its use.
-25-01-02 ***	HF/SAT XFER Switches (P5 Panel)				
-25-01-02A		C	2	0	(M)(O) May be inoperative provided alternate procedures are established and used.
-25-01-02B		D	2	0	(M) May be inoperative provided procedures do not require its use.
-25-01-03 ***	SATCOM Lights				
-25-01-03A		C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-25-01-03B		D	2	0	May be inoperative provided procedures do not require its use.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
23 COMMUNICATIONS						
-25-01 ***	Satellite Communication (SATCOM) Systems (Cont'd)					
-25-01-04	SCS Aircraft Communication Unit Wingspeed SCS (STC ST02534CH)	C	1	0	(O) May be inoperative provided all messaging data transfers are via SCS voice (handset).	
-25-01-05	Cockpit Display Device (CDD) Wingspeed SCS (STC ST02534CH)					
-25-01-05A		C	2	1	(M) May be inoperative provided master position operates normally.	
-25-01-05B		D	2	0	(O) May be inoperative provided SCS voice (handset) operates normally.	
-25-01-06	Remote Processor Unit (RPU) Wingspeed SCS (STC ST02534CH)					
-25-01-06A		C	2	1	(M) May be inoperative provided master position operates normally.	
-25-01-06B		C	2	1	(O) May be inoperative provided SCS voice (handset) operates normally.	
-25-01-07	SCS Printer Wingspeed SCS (STC ST02534CH)	C	1	0	NOTE: Any function of system that operates normally may be used.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-25-02	Automated Flight Information Reporting System (AFIRS) (STC ST02523NY)				
-25-02A		C	1	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any portion of system that operates normally may be used.
-25-02B		D	1	0	May be inoperative provided procedures do not require its use. NOTE: Any portion of system that operates normally may be used.
-25-02-01	Global Voice SATCOM				
-25-02-01A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.
-25-02-01B		D	1	0	May be inoperative provided procedures do not require its use.
-25-02-01-01	Cockpit Dialer Pad				
-25-02-01-01A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.
-25-02-01-01B		D	1	0	May be inoperative provided procedures do not require its use.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-8

SYSTEM & SEQUENCE NUMBERS	1. ITEM		2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
23 COMMUNICATIONS					
-25-02 Automated Flight Information Reporting System (AFIRS) (STC ST02523NY) (Cont'd)					
-25-02-01 Global Voice SATCOM (Cont'd)					
-25-02-01-02 Handset					
-25-02-01-02A	C	1	0		(O) May be inoperative provided alternate procedures are established and used.
-25-02-01-02B	D	1	0		May be inoperative provided procedures do not require its use.
-25-02-02 Global Messaging					
-25-02-02A	C	1	0		(O) May be inoperative provided alternate procedures are established and used.
-25-02-02B	D	1	0		May be inoperative provided procedures do not require its use.
					NOTE: Any portion of system that operates normally may be used.
					NOTE: Any portion of system that operates normally may be used.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-31-01	Passenger Address System (PA)				
-31-01-01	Passenger Configuration				
-31-01-01A		B	1	0	(O) May be inoperative provided: a) Alternate, normal and emergency procedures, and/or operating restrictions are established and used, and b) Flight attendant alerting system (audio and visual) operates normally. NOTE: Any station function(s) that operate normally may be used.
-31-01-01B		C	1	0	(O) May be inoperative provided: a) PA not required by 14 CFR, and b) Alternate, normal and emergency procedures, and/or operating restrictions are established and used. NOTE: Any station function(s) that operate normally may be used.
-31-01-01-01	Lavatory Speakers	C	-	0	(O) May be inoperative provided alternate procedures are established and used.
-31-01-01-02	Cabin Speakers				
-31-01-01-02A		C	-	-	May be inoperative provided inoperative speakers are not adjacent to each other.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	23-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
23 COMMUNICATIONS					
-31-01	Passenger Address System (PA) (Cont'd)				
-31-01-01	Passenger Configuration (Cont'd)				
-31-01-01-02	Cabin Speakers (Cont'd)				
-31-01-01-02B		C	-	-	(M) No passenger seat, cabin attendant seat or crew rest area bunk may be occupied from which Passenger Address System is not audible and intelligible; seat must be blocked and placarded DO NOT OCCUPY.
-31-01-01-03	Zone Selection Rotary Switch Positions, FWD Attendant Panel	D	4	3	May be inoperative provided: a) Procedures do not require their use, and b) ALL position operates normally.
-31-01-02	All Cargo Configuration (Courier/Supernumerary Address System)				
-31-01-02A		C	1	0	(O) May be inoperative provided alternate, normal and emergency procedures and/or operating restrictions are established and used.
-31-01-02B		D	1	0	May be inoperative provided procedures do not require its use.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
23 COMMUNICATIONS							
-31-01	Passenger Address System (PA) (Cont'd)						
-31-01-02	*** All Cargo Configuration (Courier/Supernumerary Address System) (Cont'd)						
-31-01-02-01	*** Lavatory Speakers						
-31-01-02-01A		C	-	0	(O) May be inoperative provided alternate procedures are established and used.		
-31-01-02-01B		D	-	0	May be inoperative provided procedures do not require its use.		
-31-02	*** Pre-recorded Passenger Announcement System						
-31-02A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.		
-31-02B		D	1	0	May be inoperative provided procedures do not require its use.		

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	23-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-40-01	Crewmember Interphone Systems				
-40-01-01	Passenger Configuration				
-40-01-01-01	Flight Deck to Cabin, Cabin to Flight Deck Functions	B	-	-	(O) May be inoperative provided: <ul style="list-style-type: none"> a) Flight deck to cabin and cabin to flight deck interphone functions operate normally on at least fifty percent of cabin handsets, b) Flight deck to cabin and cabin to flight deck interphone function operates normally at one door for each pair of exit doors, and c) Alternate communication procedures between affected flight attendant stations are established and used. NOTE: Any station function(s) that operate normally may be used.
-40-01-01-02	Cabin to Cabin Function	B	-	-	(O) May be inoperative provided: <ul style="list-style-type: none"> a) Cabin to cabin interphone functions operate normally on at least fifty percent of cabin handsets, b) Cabin to cabin interphone function operates normally at one door for each pair of exit doors, and c) Alternate communications procedures between affected flight attendant stations are established and used. NOTE: Any station function(s) that operate normally may be used.
(Continued)					

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	23-13

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
23 COMMUNICATIONS						
-40-01	Crewmember Interphone Systems (Cont'd)					
-40-01-01	Passenger Configuration (Cont'd)					
-40-01-01-03	Flight Deck to Ground Function					
-40-01-01-03A		C	1	0	(O) Flight interphone flight deck to ground/ground to flight deck function may be inoperative provided: a) Alternate procedures are established and used, b) Nose gear/forward fuselage service interphone jack operates normally.	
-40-01-01-03B		C	1	0	(O) Service interphone flight deck to ground/ground to flight deck function may be inoperative provided: a) Alternate procedures are established and used, and b) Nose gear flight interphone jack operates normally.	
-40-01-01-03C		B	2	0	(O) May be inoperative provided alternate procedures are established and used. (Continued)	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	23-14

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-40-01	Crewmember Interphone Systems (Cont'd)				
-40-01-02	All Cargo Configuration				
-40-01-02-01	Flight Deck to Cabin, Cabin to Flight Deck Functions				
-40-01-02-01A		C	1	0	(O) May be inoperative provided alternate, normal and emergency procedures, and/or operating restrictions are established and used.
-40-01-02-01B		D	1	0	May be inoperative provided procedures do not require its use.
-40-01-02-02	Cabin to Cabin Function	D	1	0	
-40-01-02-03	Flight Deck to Ground Function				
-40-01-02-03A		C	1	0	(O) Flight interphone flight deck to ground/ground to flight deck function may be inoperative provided: a) Alternate procedures are established and used, and b) Nose gear/forward fuselage service interphone jack operates normally.
(Continued)					

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	23-15

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-40-01	Crewmember Interphone Systems (Cont'd)				
-40-01-02	All Cargo Configuration (Cont'd)				
-40-01-02-03	Flight Deck to Ground Function (Cont'd)				
-40-01-02-03B		C	1	0	(O) Service interphone flight deck to ground/ground to flight deck function may be inoperative provided: a) Alternate procedures are established and used, and b) Nose gear flight interphone jack operates normally.
-40-01-02-03C		B	2	0	(O) May be inoperative provided alternate procedures are established and used.
-40-02	Crew Rest Interphone System and PA Announcement (STCs ST00973WI-D and ST01994SE)	D	2	0	(M) May be inoperative provided: a) Associated crew rest is not used by personnel, and b) Associated crew rest door is locked closed and placarded DO NOT USE - COMM INOP. NOTE: These provisos are not intended to prohibit crew rest inspections by crewmembers.
-40-02-01	Pilot Crew Rest (ST00973WI-D)	C	2	1	(O) Either PA or Interphone may be inoperative provided remaining system is verified to operate normally. (Continued)

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	23-16

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-40-02	Crew Rest Interphone System and PA Announcement (STCs ST00973WI-D and ST01994SE) (Cont'd)				
-40-02-02	Attendant Crew Rest (ST00973WI-D)	C	2	1	(O) Either PA or Interphone may be inoperative provided remaining system is verified to operate normally.
-40-03	Lower Lobe Crew Rest Interphone System (STCs ST01994SE and ST02137SE)	C	1	0	(M) May be inoperative provided: a) Lower lobe crew rest module is not used and personal items are removed, and b) Lower lobe crew rest door is closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest inspections by crewmembers.
-41-01	Alerting System (Audio/Visual)				
-41-01-01	Passenger Configuration				
-41-01-01-01	Flight Deck Call Visual Alerting System	B	1	0	May be inoperative provided flight deck audio alerting system operates normally. NOTE: Flight deck audio alerting system must always be operative.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 23-17
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
23 COMMUNICATIONS						
-41-01	Alerting System (Audio/Visual) (Cont'd)					
-41-01-01	Passenger Configuration (Cont'd)					
-41-01-01-02	Flight Attendant Visual Alerting System	B	1	0		(O) May be inoperative provided: <ul style="list-style-type: none"> a) PA system operates normally, b) If affected visual alerting system is used for lavatory smoke detector alerting, an alternate lavatory smoke detector alert (audio or visual) is installed and operates normally, and c) Alternate procedures for contacting flight attendants are established and used. NOTE 1: Passenger to attendant call system is considered a Nonessential Equipment and Furnishings (NEF) item. NOTE 2: Any visual alerting system function(s) that operates normally may be used.
-41-01-01-03	Flight Attendant Audio Alerting System	B	-	0		(O) May be inoperative provided: <ul style="list-style-type: none"> a) PA system operates normally, b) If affected audio alerting system is used for lavatory smoke detector alerting, an alternate lavatory smoke detector alert (audio or visual) is installed and operates normally, and c) Alternate procedures for contacting flight attendants are established and used. NOTE 1: Passenger to attendant call system is considered a Nonessential Equipment and Furnishings (NEF) item.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	23-18

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
23 COMMUNICATIONS					
-41-01	Alerting System (Audio/Visual) (Cont'd)				
-41-01-01	Passenger Configuration (Cont'd)				
-41-01-01-03	Flight Attendant Audio Alerting System (Cont'd)				NOTE 2: Any audio alerting system function(s) that operates normally may be used.
-41-01-02	All Cargo Configuration				
-41-01-02-01	Flight Deck Call Visual Alerting System	B	1	0	May be inoperative provided flight deck audio alerting system operates normally.
-41-01-02-02	Flight Deck Call System	D	1	0	May be inoperative provided courier/supernumerary compartment remains unoccupied.
-41-01-02-03	Courier/Supernumerary Visual Alerting System				
-41-01-02-03A		B	1	0	(O) May be inoperative provided: a) Courier/supernumerary address system operates normally, and b) Alternate procedures are established and used.
					NOTE: Any visual alerting system function(s) that operates normally may be used. (Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	23-19

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-41-01	Alerting System (Audio/Visual) (Cont'd)				
-41-01-02	All Cargo Configuration (Cont'd)				
-41-01-02-03	Courier/Supernumerary Visual Alerting System (Cont'd)				
-41-01-02-03B		D	1	0	May be inoperative provided courier/supernumerary compartment remains unoccupied. NOTE: Any visual alerting system function(s) that operates normally may be used.
-41-01-02-04	Courier/Supernumerary Audio Alerting System				
-41-01-02-04A		B	1	0	(O) May be inoperative provided: a) Courier/supernumerary address system operates normally, and b) Alternate procedures are established and used. NOTE: Any audio alerting system function(s) that operates normally may be used.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	23-20

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-41-01	Alerting System (Audio/Visual) (Cont'd)				
-41-01-02	All Cargo Configuration (Cont'd)				
-41-01-02-04	Courier/Supernumerary Audio Alerting System (Cont'd)				
-41-01-02-04B		D	1	0	May be inoperative provided courier/ supernumerary compartment remains unoccupied. NOTE: Any audio alerting system function(s) that operates normally may be used.
-41-01-02-05	Main Cargo Deck Crew Aural Warning System	B	1	0	May be inoperative provided access to main cargo compartment is prohibited in flight.
-41-02	Crew Rest Module Call System (STC ST02372AT)				
-41-02-01	Flight Deck to Crew Rest Module/Crew Rest Module to Flight Deck Call Functions	C	2	0	(M) May be inoperative provided: a) Crew rest module is not used, and b) Crew rest door is closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-21

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
23 COMMUNICATIONS						
-41-02	Crew Rest Module Call System (STC ST02372AT) (Cont'd)					
-41-02-02	Flight Deck Visual Alert	B	1	0	May be inoperative provided flight deck audio alerting system operates normally.	
-42-01	Handset Systems					
-42-01-01	Passenger Configuration					
-42-01-01-01	*** Flight Deck					
-42-01-01-01A		C	1	0	(O) May be inoperative provided: a) Flight deck to cabin communication operates normally, and b) Alternate procedures are established and used.	
-42-01-01-01B		D	1	0	May be inoperative provided procedures do not require its use.	
-42-01-01-02	Cabin	B	-	-	(O) May be inoperative provided: a) Fifty percent of cabin handsets operate normally, b) One handset must operate normally at each pair of exit doors, and c) Alternate communication procedures between affected flight attendant stations are established and used.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-22

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
23 COMMUNICATIONS						
-42-01	Handset Systems (Cont'd)					
-42-01-01	Passenger Configuration (Cont'd)					
-42-01-01-02	Cabin (Cont'd)					NOTE 1: An operative handset at an inoperative flight attendant seat shall not be counted to satisfy fifty percent requirement.
-42-01-02	All Cargo Configuration					NOTE 2: Any handset function that operates normally may be used.
-42-01-02-01	*** Flight Deck					
-42-01-02-01A		C	1	0	May be inoperative provided flight deck to courier/supernumerary communication operates normally.	
-42-01-02-01B		D	1	0	May be inoperative provided procedures do not require its use.	
-42-01-02-02	*** Courier/ Supernumerary					
-42-01-02-02A		D	-	1		
-42-01-02-02B		D	-	0	May be inoperative provided courier/supernumerary compartment remains unoccupied.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-23

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
23 COMMUNICATIONS						
-43-01	Ground Crew Call System	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-43-01-01	Ground Crew Call Horn	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-51-03	Flight Deck Interphone Speakers	C	2	0	May be inoperative provided: a) Procedures do not require their use, and b) TSO headset earphones/headphones (or equivalent) are installed and operate normally.	
-51-04	Push-To-Talk (PTT) Switches					
-51-04-01	Control Wheel PTT Switches	C	2	1	(M) One may be inoperative provided: a) Associated audio selector panel or glareshield PTT switch operates normally, and b) Affected switch is deactivated.	
-51-04-02	Flightcrew Audio Selector Panel PTT Switches	C	2	1	(M) One may be inoperative provided: a) Associated control wheel or glareshield PTT switch operates normally, and b) Affected switch is verified failed open.	
-51-04-03	*** Glareshield PTT Switches	C	2	1	(M) One may be inoperative provided: a) Associated audio selector panel or control wheel PTT switch operates normally, and b) Affected switch is deactivated.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-24

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
23 COMMUNICATIONS						
-51-05	Flight Crew Communication Equipment	D	-	-	Any boom and/or hand microphones in excess of those required by 14 CFR for flight deck crewmembers may be inoperative or missing.	
-51-05-01	Boom Microphones	A	-	0	May be inoperative or missing provided: a) Associated hand microphone is installed and operates normally, b) Flight data recorder (FDR) operates normally, and c) Repairs are made within 3 flight days.	
-51-05-02	Hand Microphones					
-51-05-02A		C	-	0	May be inoperative or missing provided associated boom microphone operates normally.	
-51-05-02B		D	-	0	May be inoperative or missing provided procedures do not require its use.	
-51-05-02-01	*** Dual Tone Multi-Frequency (DTMF) (Telephone Dialing Feature)					
-51-05-02-01A		C	1	0	(O) May be inoperative provided: a) Voice mode operates normally, and b) Alternate procedures are established and used.	
-51-05-02-01B		D	1	0	May be inoperative provided procedures do not require its use.	
-51-05-03	TSO Headset Earphones/Headphones	C	-	1	Either captain's or first officer's earphone/headphone may be inoperative or missing provided associated flight deck speaker operates normally.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-25

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-70-01	Flight Deck Door Visual Surveillance Systems				
-70-01-01	*** Electronic System				
-70-01-01A		A	1	0	(O) May be inoperative and components may be missing provided: a) Alternate procedures are established and used, and b) Repairs are made within 3 flight days. NOTE: Any portion of system that operates normally may be used.
-70-01-01B		C	1	0	(O) May be inoperative and components may be missing provided: a) Flight deck door viewing port operates normally, and b) Alternate procedures are established and used. NOTE: Any portion of system that operates normally may be used.
-70-01-01C		D	1	0	May be inoperative and components may be missing provided procedures do not require its use.
-70-01-01-01	All Cargo Configuration				
-70-01-01-01A		C	1	0	May be inoperative and components may be missing provided aircraft aft of flight deck door is occupied only by those personnel authorized by 14 CFR. NOTE: Any portion of system that operates normally may be used.

(Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	23-26

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
23 COMMUNICATIONS					
-70-01	Flight Deck Door Visual Surveillance Systems (Cont'd)				
-70-01-01	*** Electronic System (Cont'd)				
-70-01-01-01	All Cargo Configuration (Cont'd)				
-70-01-01-01B		D	1	0	May be inoperative and components may be missing provided procedures do not require its use.
-70-01-02	*** Viewing Ports				
-70-01-02A		A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 3 flight days.
-70-01-02B		C	1	0	(O) May be inoperative provided: a) Electronic flight deck door visual surveillance system operates normally, and b) Alternate procedures are established and used.
-70-01-02C		D	1	0	May be inoperative provided procedures do not require its use.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

23-27

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
23 COMMUNICATIONS						
-70-01	Flight Deck Door Visual Surveillance Systems (Cont'd)					
-70-01-02	*** Viewing Ports (Cont'd)					
-70-01-02-01	All Cargo Configuration					
-70-01-02-01A		C	1	0	May be inoperative and components may be missing provided aircraft aft of flight deck door is occupied only by those personnel authorized by 14 CFR.	
-70-01-02-01B		D	1	0	May be inoperative provided procedures do not require its use.	
-71-01	Cockpit Voice Recorder (CVR) System	A	1	0	May be inoperative provided: a) Flight data recorder (FDR) operates normally, and b) Repairs are made within 3 flight days.	
-71-01-01	*** Independent Power Source	C	1	0		

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	24-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
24 ELECTRICAL POWER					
-00-01	Engine Generator Systems (IDG/GCB)				
-00-01-01	CF6/RB211	B	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: a) APU generator operates normally and is used to supply busses of inoperative channel throughout flight, b) All generator control units, including APU, operate normally, c) For ER operations, at least one Hydraulic Motor Generator (HMG) is verified to operate normally, and d) If APU has been operating for an extended period of time in heavy falling or blowing snow, inspect inlet plenum before departure to verify that accumulations of snow or ice are not present.
-00-01-02	PW4000	B	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: a) APU generator operates normally and is used to supply busses of inoperative channel throughout flight, b) All generator control units, including APU, operate normally, c) For ER operations, at least one Hydraulic Motor Generator (HMG) is verified to operate normally, d) If APU has been operating for an extended period of time in heavy falling or blowing snow, inspect inlet plenum before departure to verify that accumulations of snow or ice are not present, e) FUEL TEMP indicating system operates normally,
(Continued)					

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

24-2

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
24 ELECTRICAL POWER				
-00-01	Engine Generator Systems (IDG/GCB) (Cont'd)			
-00-01-02	PW4000 (Cont'd)			<ul style="list-style-type: none"> f) For engine air oil cooler operating normally, fuel tank temperature remains at or above -37 degrees C, g) For engine air oil cooler open, fuel tank temperature remains at or above -30 degrees C, and h) For either f) or g) configuration, fuel tank temperature must remain above specified minimum throughout entire flight.
-00-01-03	JT9D	B	2	1
				<p>(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided:</p> <ul style="list-style-type: none"> a) APU generator operates normally and is used to supply busses of inoperative channel throughout flight, b) All generator control units, including APU, operate normally, c) For ER operations, at least one Hydraulic Motor Generator (HMG) is verified to operate normally, d) If APU has been operating for an extended period of time in heavy falling or blowing snow, inspect inlet plenum before departure to verify that accumulations of snow or ice are not present, and e) If IDG is disconnected, manual fuel heat cycle must be completed before takeoff when fuel temperature is below 0 degrees C.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

24-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
24 ELECTRICAL POWER					
-00-02	APU Generator				
-00-02A		C	1	0	Except for ER operations, may be inoperative provided both engine generators operate normally.
-00-02B		B	1	0	(M) Except for ER operations beyond 120 minutes, may be inoperative provided: a) Both engine generators operate normally, and b) At least one Hydraulic Motor Generator (HMG) is verified to operate normally.
-11-01	Generator DRIVE Lights				
-11-01-01	-200/-300				
-11-01-01A		B	2	1	(M) One may be inoperative off provided associated EICAS message is verified to operate normally.
-11-01-01B		B	2	1	(M) One may be inoperative off provided associated IDG is disconnected.
-11-01-02	-400ER	C	2	0	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	24-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
24 ELECTRICAL POWER					
-25-01 ***	Hydraulic Motor Generators (HMG)				
-25-01-01	Air Data Computer (ADC) Equipped Airplanes				
-25-01-01A		C	-	0	(O) Except for ER operations, may be inoperative provided: a) Center IRS operates normally, and b) First officer's IRS instrument source select switch operates normally.
-25-01-01B		C	-	0	Except for ER operations, may be inoperative for day VMC flight.
-25-01-01C		C	-	0	(M)(O) Except for ER operations beyond 120 minutes, may be inoperative provided: a) Both engine generators and APU generator operate normally, b) Center IRS operates normally, and c) First officer's IRS instrument source select switch operates normally.
-25-01-01D		A	-	0	(M)(O) For ER operations beyond 120 minutes, may be inoperative provided: a) Both engine generators and APU generator operate normally, b) APU is started before reaching ETOPS segment, then operated continuously until within 60 minutes of a suitable airport, c) Center IRS operates normally, d) First officer's IRS instrument source select switch operates normally, and e) Operations are limited to not more than 3 flight days before repair is made.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

24-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
24 ELECTRICAL POWER						
-25-01 *** Hydraulic Motor Generators (HMG) (Cont'd)						
-25-01-01 Air Data Computer (ADC) Equipped Airplanes (Cont'd)						
-25-01-01E	A	3	1	(M) Except for ER operations beyond 120 minutes, may be inoperative provided: a) At least one Hydraulic Motor Generator (HMG) is verified to operate normally, and b) Operations are limited to not more than 3 flight days before repair is made.		
-25-01-01F	C	3	1	(M) May be inoperative provided: a) Both engine generators and APU generator operate normally, and b) At least one Hydraulic Motor Generator (HMG) is verified to operate normally.		
-25-01-02 Air Data Inertial Reference System (ADIRS) Equipped Airplanes						
-25-01-02A	C	1	0	Except for ER operations, may be inoperative.		
-25-01-02B	C	1	0	(M) Except for ER operations beyond 120 minutes, may be inoperative provided both engine generators and APU generator operate normally.		
				(Continued)		

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 24-6
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
24 ELECTRICAL POWER						
-25-01 ***	Hydraulic Motor Generators (HMG) (Cont'd)					
-25-01-02	Air Data Inertial Reference System (ADIRS) Equipped Airplanes (Cont'd)					
-25-01-02C		A	1	0		(M)(O) For ER operations beyond 120 minutes, may be inoperative provided: a) Both engine generators and APU generator operate normally, b) APU is started before reaching ETOPS segment, then operated continuously until within 60 minutes of a suitable airport, and c) Operations are limited to not more than 3 flight days before repair is made.
-25-02 ***	Hydraulic Motor Generator Valves					
-25-02-01	Air Data Computer (ADC) Equipped Airplanes					
-25-02-01A		C	-	0		(M)(O) Except for ER operations, may be inoperative closed provided: a) Center IRS operates normally, and b) First officer's IRS instrument source select switch operates normally.
-25-02-01B		C	-	0		(M) Except for ER operations, may be inoperative closed for day VMC flight.
(Continued)						

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

24-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
24 ELECTRICAL POWER					
-25-02 ***	Hydraulic Motor Generator Valves (Cont'd)				
-25-02-01	Air Data Computer (ADC) Equipped Airplanes (Cont'd)				
-25-02-01C		C	-	0	(M)(O) Except for ER operations beyond 120 minutes, may be inoperative closed provided: a) Both engine generators and APU generator operate normally, b) Center IRS operates normally, and c) First officer's IRS instrument source select switch operates normally.
-25-02-01D		A	-	0	(M)(O) For ER operations beyond 120 minutes, may be inoperative closed provided: a) Both engine generators and APU generator operate normally, b) APU is started before reaching ETOPS segment, then operated continuously until within 60 minutes of a suitable airport, c) Center IRS operates normally, d) First officer's IRS instrument source select switch operates normally, and e) Operations are limited to not more than 3 flight days before repair is made.
-25-02-01E		A	3	1	(M) Except for ER operations beyond 120 minutes, may be inoperative closed provided: a) At least one Hydraulic Motor Generator (HMG) is verified to operate normally, and b) Operations are limited to not more than 3 flight days before repair is made.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	24-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
24	ELECTRICAL POWER				
-25-02 ***	Hydraulic Motor Generator Valves (Cont'd)				
-25-02-01	Air Data Computer (ADC) Equipped Airplanes (Cont'd)				
-25-02-01F		C	3	1	(M) May be inoperative closed provided: a) Both engine generators and APU generator operate normally, and b) At least one Hydraulic Motor Generator (HMG) is verified to operate normally.
-25-02-02	Air Data Inertial Reference System (ADIRS) Equipped Airplanes				
-25-02-02A		C	1	0	(M) Except for ER operations, may be inoperative closed.
-25-02-02B		C	1	0	(M) Except for ER operations beyond 120 minutes, may be inoperative closed provided both engine generators and APU generator operate normally.
-25-02-02C		A	1	0	(M)(O) For ER operations beyond 120 minutes, may be inoperative closed provided: a) Both engine generators and APU generator operate normally, b) APU is started before reaching ETOPS segment, then operated continuously until within 60 minutes of a suitable airport, and c) Operations are limited to not more than 3 flight days before repair is made.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	REVISION NO: 37	PAGE:
BOEING B-767	DATE: 03/27/2015	24-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
24 ELECTRICAL POWER						
-25-03 ***	Flight Instrument Power Bus Switch	C	1	0		Except for ER operations, may be inoperative provided HMG is not required.
-27-01	BUS OFF Lights	C	2	1		(O) One may be inoperative provided BUS TIE ISLN lights and associated GEN CONT OFF light operate normally.
-27-02	GEN CONT OFF Lights					
-27-02-01						
	-200/-300					
-27-02-01A		C	2	1		(M)(O) One may be inoperative provided associated EICAS message L(R) GEN OFF is verified to operate normally.
-27-02-01B		B	2	1		One may be inoperative for an associated inoperative generator.
-27-02-02						
	-400ER	C	2	0		(O) May be inoperative provided alternate procedures are established and used.
-27-03	APU GEN OFF Light					
-27-03A		C	1	0		(M) May be inoperative provided EICAS message APU GEN OFF is verified to operate normally.
-27-03B		C	1	0		May be inoperative provided APU generator is not required for flight.
-27-04	BUS TIE ISLN Lights	C	2	0		May be inoperative provided associated BUS OFF light operates normally.
-27-05	UTILITY BUS OFF Lights	C	2	0		

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 24-10
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
24 ELECTRICAL POWER						
-27-06 ***	Generator FIELD OFF Lights	D	3	0		
-30-01	Standby Power Bus OFF Light					
-30-01-01 -200/300		C	1	0	(M)(O) May be inoperative provided: a) Both EICAS systems operate normally, and b) All other standby bus indications are verified to operate normally.	
-30-01-02 -400ER		C	1	0	(O) May be inoperative.	
-31-01	APU Battery					
-31-01-01	Without Main/APU Battery Tie System Installed	C	1	0	(M)(O) May be inoperative provided: a) APU battery is deactivated or removed, and b) APU is considered inoperative.	
-31-01-02 ***	With Main/APU Battery Tie System Installed	C	1	0	(M)(O) May be inoperative provided: a) APU battery is deactivated or removed, b) APU is considered inoperative, and c) Operations do not require paralleling of Main and APU batteries.	
-31-02	APU Battery Charger					
-31-02-01	Without Main/APU Battery Tie System Installed	C	1	0	(M) May be inoperative provided: a) APU battery charger is deactivated or removed, and b) APU is not required.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

24-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
24 ELECTRICAL POWER						
-31-02	APU Battery Charger (Cont'd)					
-31-02-02						
***	With Main/APU Battery Tie System Installed	C	1	0	(M) May be inoperative provided: a) APU battery charger is deactivated or removed, b) APU is not required, and c) Operations do not require paralleling of Main and APU batteries.	
-31-03	Standby Power Main/APU Battery Tie System	C	1	0	May be inoperative provided: a) Operations do not require paralleling of Main and APU batteries, b) Both engine generators operate normally, and c) APU generator operates normally.	

-32-01	APU Start Transformer Rectifier Unit					

-32-01A		C	1	0	May be inoperative provided APU is considered inoperative.	
-32-01B		D	1	0	(M) May be inoperative provided APU TRU is deactivated.	
-32-02	First Officer's Display Transformer Rectifier Unit (-400ER)					

-32-02A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-32-02B		D	1	0	May be inoperative provided procedures do not require its use.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	24-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
24	ELECTRICAL POWER					
-41-01	External Power System(s)	C	-	0		
-41-01-01	EXT PWR AVAIL Light (Flight Deck)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-41-01-02	EXT PWR ON Light (Flight Deck)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-41-01-03	EXTERNAL POWER CONNECTED Light (External Power Panel)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-41-01-04	EXTERNAL POWER NOT IN USE Light (External Power Panel)	C	-	0	(O) May be inoperative provided alternate procedures are established and used.	
-51-01	Utility Bus Systems (All Cargo Configuration)	C	2	0	(M) May be inoperative provided bus is deactivated.	
-51-02	Voltage Harmonic Filters					
-51-02A		D	-	0	(M) May be inoperative provided associated individual video system (IVS) zone is deactivated.	
-51-02B		D	-	0	May be inoperative provided associated video system remains off.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
25 EQUIPMENT/FURNISHINGS						
-00-01	Crewmember Shoulder Harness (Flight Deck)	D	-	-	Any in excess of those required for flight deck crewmembers (including official observer in observer's seat) may be inoperative.	
-11-01	Flight Crew Seats					
-11-01-01	Power Adjustment Systems	D	2	0	May be inoperative provided fwd/aft and vertical manual adjustment modes operate normally.	
-11-01-02	Manual Adjustment Systems					
-11-01-02-01	Recline Systems	A	2	0	(M) May be inoperative provided: a) Seat is secured in upright position and is acceptable to affected crewmember, b) Fwd/aft and vertical manual adjustment modes operate normally, and c) Repairs are made within 2 flight days	
-11-01-02-02	Vertical Adjustments	A	2	0	May be inoperative provided: a) Seat is acceptable to affected crewmember, and b) Repairs are made within 2 flight days.	
-11-01-02-03	Armrests	B	4	0	May be inoperative provided: a) Affected armrest is in up position or removed, and b) Seat is acceptable to affected crewmember.	
-11-01-02-04	Lumbar/Thigh Supports	C	2	0	May be inoperative provided seat is acceptable to the affected crewmember.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-11-01	Flight Crew Seats (Cont'd)				
-11-01-02	Manual Adjustment Systems (Cont'd)				
-11-01-02-05	Headrests	C	2	0	May be inoperative provided seat is acceptable to the affected crewmember.
-11-02	Observer Seat(s)				
-11-02-01	First Observer Seat (Including Associated Equipment)				
-11-02-01A		A	-	-	May be inoperative provided: a) A supernumerary/passenger seat is made available to an FAA inspector for performance of official duties, and b) Repairs are made within 2 flight days.
-11-02-01B		A	-	-	May be inoperative provided: a) Second observer seat is available to an FAA inspector for performance of official duties, and b) Repairs are made within 2 flight days.
-11-02-01C		A	-	-	May be inoperative provided: a) Required minimum safety equipment (safety belt and oxygen) is available, b) Seat is acceptable to an FAA inspector for performance of official duties, and c) Repairs are made within 2 flight days.

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-3
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS						
-11-02	Observer Seat(s) (Cont'd)					
-11-02-01	First Observer Seat (Including Associated Equipment) (Cont'd)					
-11-02-01C (Cont'd)						NOTE 1: These provisos are intended to provide for occupancy of above seats by an FAA inspector when minimum safety equipment (oxygen and safety belt) is functional and inspector determines conditions to be acceptable. NOTE 2: Pilot-in-Command will determine if minimum safety equipment is functional for other persons authorized to occupy observer seat(s).
-11-02-02 ***	Second Observer Seat (Including Associated Equipment)	D	-	0		NOTE: Pilot-in-Command will determine if minimum safety equipment is functional for other persons authorized to occupy additional observer seat(s).
-20-01	Non-Essential Equipment and Furnishings (NEF)		-	0		May be inoperative, damaged, or missing provided that item(s) is deferred in accordance with operator's NEF deferral program. NEF program, procedures, and processes are outlined in operator's (insert name) Manual. (M) and (O) procedures, if required, must be available to flight crew and included in operator's appropriate document. NOTE: Exterior lavatory door ash trays are not considered NEF items.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 25-4
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS					
-25-01	Flight Attendant Seat Assembly (Single or Dual Position)				
-25-01-01	Required Flight Attendant Seats				
-25-01-01A		B	-	-	<p>(M)(O) One seat position or assembly (dual position) may be inoperative provided:</p> <ul style="list-style-type: none"> a) Affected seat position or seat assembly is not occupied, b) Flight attendant(s) displaced by inoperative seat(s) occupies either an adjacent flight attendant seat or passenger seat which is most accessible to inoperative seat(s), so as to most effectively perform assigned duties, c) Alternate procedures are established and used as published in crewmember manuals, d) Folding type seat stows automatically or is secured in retracted position, and e) Passenger seat assigned to flight attendant is placarded FOR FLIGHT ATTENDANT USE ONLY. <p>NOTE 1: An automatic folding seat that will not stow automatically is considered inoperative.</p> <p>NOTE 2: A seat position with an inoperative or missing restraint system is considered inoperative.</p> <p>(Continued)</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-5
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS					
-25-01	Flight Attendant Seat Assembly (Single or Dual Position) (Cont'd)				
-25-01-01	Required Flight Attendant Seats (Cont'd)				
-25-01-01A	(Cont'd)				
-25-01-01B		C	-	0	<p>(M)(O) May be inoperative provided:</p> <ul style="list-style-type: none"> a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, c) Folding type seat stows automatically or is secured in retracted position, d) Affected seat position or seat assembly is not occupied, and e) Alternate procedures are established and used. <p>NOTE 1: An automatic folding seat that will not stow automatically is considered inoperative.</p> <p>NOTE 2: A seat position with an inoperative or missing restraint system is considered inoperative.</p> <p>(Continued)</p>

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-25-01	Flight Attendant Seat Assembly (Single or Dual Position) (Cont'd)				
-25-01-02	Excess Flight Attendant Seats	C	-	-	(M) May be inoperative provided: a) Affected seat position or seat assembly is not occupied, and b) Folding type seat stows automatically or is secured in retracted position. NOTE 1: An automatic folding seat that will not stow automatically is considered inoperative. NOTE 2: A seat position with an inoperative or missing restraint system is considered inoperative.
-25-01-03	*** All Cargo Configuration	D	-	-	May be inoperative provided affected seat or seat assembly is not occupied.
-25-02	Passenger Seats	D	-	-	(M) May be inoperative provided: a) Seat does not block an emergency exit, b) Seat does not restrict any passenger from access to the main airplane aisle, and c) Affected seat(s) is blocked and placarded DO NOT OCCUPY. NOTE 1: A seat with an inoperative seat belt is considered inoperative. NOTE 2: Inoperative seats do not affect required number of flight attendants. NOTE 3: Affected seat(s) may include the seat(s) behind and/or adjacent outboard seats.
(Continued)					

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-7

SYSTEM & SEQUENCE NUMBERS	1. ITEM			2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS						
-25-02	Passenger Seats (Cont'd)					
-25-02-01	Recline Mechanism					
-25-02-01A		D	-	-		(M) May be inoperative and seat occupied provided seat back is secured in full up-right position.
-25-02-01B		D	-	-		May be inoperative and seat occupied provided seat back is immovable in full up-right position.
-25-02-02	Underseat Baggage Restraining Bars	C	-	-		(O) May be inoperative provided: a) Baggage is not stowed under seat with inoperative restraining bar, b) Associated seat is placarded DO NOT STOW BAGGAGE UNDER THIS SEAT, and c) Procedures are established to alert cabin crew of inoperative restraining bar.
-25-02-03	Armrests					
-25-02-03-01	Armrest with Recline Mechanism	D	-	-		(M) May be inoperative or missing and seat occupied provided: a) Armrest does not block an Emergency Exit, b) Armrest does not restrict any passenger from access to main airplane aisle, and c) If armrest is missing, seat is secured in full upright position.

(Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-8
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-25-02	Passenger Seats (Cont'd)				
-25-02-03	Armrests (Cont'd)				
-25-02-03-02	Armrest without Recline Mechanism	D	-	-	May be inoperative or missing and seat occupied provided: a) Armrest does not block an Emergency Exit, and b) Armrest does not restrict any passenger from access to main airplane aisle.
-25-02-04	Seat Belt Air Bag Restraint Systems				

-25-02-04-01	Seat Belt Air Bags Required by 14 CFR	D	-	-	May be inoperative provided affected seat is blocked and placarded DO NOT OCCUPY.
-25-02-04-02	Seat Belt Air Bags Not Required by 14 CFR	D	-	-	May be inoperative or disconnected provided seat belt operates normally.
-25-03	Supernumerary Seats (All Cargo Configuration)	D	-	0	(M) May be inoperative provided: a) Seat is not occupied, and b) Seat is stowed or secured.

-25-03-01	Armrests	D	-	0	(M) May be inoperative provided armrest is stowed in retracted position or removed.
-25-03-02	Recline Mechanism	D	-	0	(M) May be inoperative and seat occupied provided seat is secured in upright position.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	25-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS			3. NUMBER REQUIRED FOR DISPATCH		
-25-05 ***	Crew Rest Bunk Restraints	C	-	0	(M) May be inoperative provided associated bunk is blocked and placarded INOPERATIVE – DO NOT USE.
-25-06	Crew Rest Module (STC ST02372AT)	C	1	0	(M) May be inoperative provided: a) Crew rest module is not used and personal items are removed, and b) Crew rest door is closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-25-07	Lower Lobe Crew Rest Module (STCs ST01994SE and ST02137SE)	C	1	0	(M) May be inoperative provided: a) Lower lobe crew rest module is not used and personal items are removed, and b) Lower lobe crew rest door is closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-25-07-01	Crew Rest Seats	C	-	0	(M) May be inoperative provided seat is placarded INOPERATIVE - DO NOT USE.

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-10
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS						
-28-01	Storage Bins/Cabin, Galley and Lavatory Storage Compartments/ Closets					
-28-01A		C	-	-		(M) May be inoperative provided: <ul style="list-style-type: none"> a) Procedures are established to secure affected bin, compartment or closet in closed position, b) Affected bin, compartment or closet is prominently placarded DO NOT USE, c) Any emergency equipment located in affected compartment is considered inoperative, and d) Affected bin, compartment or closet is not used for storage of any items except for those permanently affixed. NOTE: For overhead bins, if no partitions are installed, entire overhead bin is considered inoperative.
-28-01B		C	-	-		(M)(O) May be inoperative provided: <ul style="list-style-type: none"> a) For non-retractable doors, affected door is removed, b) For retractable doors, affected door is removed or secured in retracted (fully open) position, c) Affected bin, compartment or closet is not used for storage of any items except for those permanently affixed, d) Affected bin, compartment or closet is prominently placarded DO NOT USE, e) Procedures are established and used to alert crewmembers and supernumeraries/passengers of inoperative bins, compartments or closets, and f) Supernumeraries/passengers are briefed that affected bin, compartment or closet is not used. (Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	25-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-28-01	Storage Bins/Cabin, Galley and Lavatory Storage Compartments/ Closets (Cont'd)				
-28-01B (Cont'd)					NOTE 1: For overhead bins, if no partitions are installed, entire overhead bin is considered inoperative. NOTE 2: Any emergency equipment located in affected bin, compartment or closet (permanently affixed) is available for use.
-28-01-01	Multi Latch/Quarter Turn Lug Installations	C	-	-	One latch/lug per compartment may be inoperative provided: a) Remaining latch(es)/lug(s) on affected compartments operate normally, and b) If affected compartment is used for a galley cart, cart remains empty.
-28-01-02	Storage Compartment Key Locks	D	-	0	(M) May be inoperative in unlocked position provided doors can be secured by other means.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-38-01	Exterior Lavatory Door Ashtrays				
-38-01-01	Airplanes with Multiple Exterior Lavatory Door Ashtrays Installed				
-38-01-01A		A	-	-	Up to and including 50 percent may be missing or inoperative for 10 calendar days. NOTE: Crew lavatories are included in total aircraft exterior lavatory door ashtray count.
-38-01-01B		A	-	-	More than 50 percent may be missing or inoperative for 3 calendar days. NOTE: Crew lavatories are included in total aircraft exterior lavatory door ashtray count.
-38-01-02	Airplanes with Only One Exterior Lavatory Door Ashtray Installed	A	1	0	May be missing or inoperative for 10 calendar days.
-38-02	Galley/Cabin Waste Receptacles Access Door/Covers	C	-	-	(M)(O) May be inoperative provided: a) Container is empty and access is secured to prevent waste introduction into compartment, and b) Procedures are established to ensure that sufficient galley/cabin waste receptacles are available to accommodate all waste that may be generated on flight.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-13

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-41-01	Lavatory Waste Container Flapper/Access Doors	C	-	-	(M) May be inoperative provided: a) Associated lavatory waste container is empty and access is secured to prevent waste introduction into waste container, b) Lavatory is only used by crewmembers, and c) Associated lavatory entrance door is locked closed and placarded INOPERATIVE – DO NOT ENTER.
-50-01	Lower Cargo Compartment Lining Panels, Floor Panels, and Walkways (Forward and Aft)				
-50-01-01	Lining Panels	C	-	-	(O) May be damaged or missing provided procedures are established and used to ensure associated compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE: Operator MELs must define which items are approved for inclusion in fly away kits, and which materials can be used as ballast.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-14
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS						
-50-01	Lower Cargo Compartment Lining Panels, Floor Panels, and Walkways (Forward and Aft) (Cont'd)					
-50-01-02	Floor Panels and Walkways					
-50-01-02-01	Full Floor Configuration	C	-	-		(O) May be damaged or missing provided procedures are established and used to ensure associated compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE: Operator MELs must define which items are approved for inclusion in fly away kits, and which materials can be used as ballast.
-50-01-02-02	Partial Floor Configuration	C	-	-		May be damaged or missing.
-53-01 ***	Lower Cargo Handling Systems	D	-	0		NOTE: Any portion of system that operates normally may be used.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-15

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-54-01	Lower Cargo Restraint Systems				
-54-01A		A	-	-	(M) May be inoperative or missing provided: a) Acceptable cargo loading limits from an approved source, i.e., an approved cargo loading manual, cargo handling manual, or weight and balance document are observed, and b) Repairs are made prior to completion of next heavy maintenance visit.
-54-01B		C	-	-	May be inoperative or missing provided associated cargo compartment remains empty.
-57-01	Main Deck Cargo Handling Systems	D	-	0	NOTE: Any portion of system that operates normally may be used.
-58-01	Main Deck Cargo Restraint Systems				
-58-01A		A	-	-	(M) May be inoperative or missing provided: a) Acceptable cargo loading limits from an approved source, i.e., an approved cargo loading manual, cargo handling manual, or weight and balance document are observed, and b) Repairs are made prior to completion of next heavy maintenance visit.
-58-01B		C	-	-	May be inoperative or missing provided main deck cargo compartment remains empty.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	25-16

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-61-01	Flight Crew/Supernumerary Escape Devices (All Cargo Configuration)				
-61-01-01	Inertial Escape Reels	C	-	-	(M) May be inoperative provided: a) Occupants are limited to number of operative escape reels, and b) Inoperative escape reel(s) is removed from installed location.
-61-01-02	Escape Harnesses	C	-	-	(M) May be inoperative provided: a) Occupants are limited to number of operative escape harness(es), and b) Inoperative escape harness(es) is removed from installed location.
-61-02	Lower Lobe Crew Rest Escape Harness (STCs ST01994SE and ST02137SE)	C	1	0	(M) May be inoperative provided: a) Lower lobe crew rest module is not used and personal items are removed, and b) Lower lobe crew rest door is closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-62-01	Flotation Equipment (Crew and Passengers)	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing provided required distribution is maintained.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-17

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-63-01	Megaphones				
-63-01-01	Passenger Configuration				
-63-01-01A		D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing provided: a) Inoperative megaphone is removed from passenger cabin, b) Associated placard is removed or obscured, and c) Required distribution is maintained.
-63-01-01B		C	-	0	(O) May be inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used.
-63-01-02	All Cargo Configuration	D	-	0	
-63-02	Emergency Evacuation Signal System				
-63-02A		C	1	0	(O) May be inoperative provided alternate procedures for initiating an emergency evacuation are established and used.
-63-02B		D	1	0	May be inoperative provided procedures do not require its use.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-18
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-63-03	FASTEN SEAT BELT WHILE SEATED Signs or Placards	C	-	-	One or more signs or placards may be illegible or missing provided a legible sign or placard is visible from each occupied passenger seat.
-63-04	Flashlight Holder Assemblies (Including Flashlight)				
-63-04A		C	-	-	May be inoperative or missing provided crewmember has a flashlight of equivalent characteristics readily available.
-63-04B		C	-	0	(O) May be inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used.
-63-05 ***	Onboard Weight and Balance System (All Cargo Configuration)	D	-	0	(O) May be inoperative provided alternate procedures are established and used.
-63-06	Cockpit Smoke Vision System (CSVs) (STC ST00731LA)	D	-	0	May be inoperative or missing.
-63-10 ***	Emergency Locator Transmitter (ELT)				
-63-10-01	Survival Type ELTs	D	-	-	Any in excess of those required by 14 CFR may be inoperative or missing.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

25-19

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-63-10 ***	Emergency Locator Transmitter (ELT) (Cont'd)				
-63-10-02	Fixed ELTs				
-63-10-02A		A	-	0	(M) May be inoperative provided: a) System is deactivated, and b) Repairs are made within 90 days.
-63-10-02B		A	-	0	May be missing provided repairs are made within 90 days.
-63-10-02C		D	-	-	(M) Any in excess of those required by 14 CFR may be inoperative provided system is deactivated.
-63-10-02D		D	-	-	Any in excess of those required by 14 CFR may be missing.
-64-01	Emergency Medical Equipment				
-64-01-01	First Aid Kit (FAK) and/or Associated Equipment				
-64-01-01A		A	-	-	(O) If more than one is required by 14 CFR, only one of required first aid kits may be incomplete, missing or inoperative provided: a) FAK is resealed in a manner that will identify it as a unit that can not be mistaken for a fully serviceable unit, and b) Repairs or replacements are made within 1 flight.

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-20
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
25 EQUIPMENT/FURNISHINGS						
-64-01	Emergency Medical Equipment (Cont'd)					
-64-01-01	First Aid Kit (FAK) and/or Associated Equipment (Cont'd)					
-64-01-01B		D	-	-		Any in excess of those required by 14 CFR may be incomplete, missing or inoperative.
-64-01-02	Emergency Medical Kit (EMK) and/or Associated Equipment					
-64-01-02A		A	-	0		(O) May be incomplete, missing or inoperative provided: a) EMK is resealed in a manner that will identify it as a unit that can not be mistaken for a fully serviceable unit, and b) Repairs or replacements are made within 1 flight.
-64-01-02B		D	-	-		Any in excess of those required by 14 CFR may be incomplete, missing or inoperative.
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 25-21
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
25 EQUIPMENT/FURNISHINGS					
-64-01	Emergency Medical Equipment (Cont'd)				
-64-01-03	Automated External Defibrillators (AED) and/or Associated Equipment				
-64-01-03A		A	-	0	(O) May be incomplete, missing or inoperative provided: a) AED is resealed in a manner that will identify it as a unit that can not be mistaken for a fully serviceable unit, and b) Repairs or replacements are made within 1 flight.
-64-01-03B		D	-	-	Any in excess of those required by 14 CFR may be incomplete, missing or inoperative.
-66-03	Overwing Escape Squib Test System	A	1	0	(M) May be inoperative provided: a) Overwing escape system is verified to operate normally, and b) Operations are limited to not more than 50 flight hours before repairs are made.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-10-01	Crew Rest Smoke Detection Systems (STC ST00973WI-D)	C	2	0	(M) May be inoperative provided: a) Associated crew rest area is not used and personal items are removed, and b) Associated crew rest door is locked closed and placarded INOPERATIVE - DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-10-02	Crew Rest Module Smoke Detection Systems (STC ST02372AT)	C	1	0	(M) May be inoperative provided: a) Crew rest module is not used and personal items are removed, and b) Crew rest door is closed and placarded INOPERATIVE - DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-10-03	Lower Lobe Crew Rest Smoke Detection Systems (STCs ST01994SE and ST02137SE)	C	-	0	(M) May be inoperative provided: a) Heater system is deactivated. b) Crew rest module is not used and personal items are removed, and c) Crew rest door is closed and placarded INOPERATIVE - DO NOT ENTER NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-11-01	Engine Fire Detection Systems				
-11-01-01	Detection Loops	C	4	2	Except for ER operations beyond 120 minutes, one loop per engine may be inoperative.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
26 FIRE PROTECTION						
-11-02	Engine Overheat Detection Systems					
-11-02-01	Detection Loops	C	4	2	Except for ER operations beyond 120 minutes, one loop per engine may be inoperative.	
-12-01	Engine Strut Overheat Detection Systems (RB211)					
-12-01-01	Detection Loops	C	4	2	Except for ER operations beyond 120 minutes, one loop per engine may be inoperative.	
-14-01	CARGO DET AIR Indicating System	C	1	0	(M) Indication may be inoperative provided smoke sampling system integrity is verified before each departure.	
-15-01	APU Fire Detection System					
-15-01A		C	1	0	May be inoperative provided APU is considered inoperative.	
-15-01B		C	1	0	(M)(O) May be inoperative provided: a) Other procedures do not require use of APU, b) APU is used for ground operations only, c) APU is continuously monitored by ground personnel when operating, d) APU external control system operates normally, and e) APU is not used during taxi.	
-15-01-01	Detection Loops	C	2	1	Except for ER operations beyond 120 minutes, one loop may be inoperative.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	26-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
26 FIRE PROTECTION					
-16-01	Lower Cargo Compartment Smoke Detection Systems (Fwd and Aft)	C	2	0	(O) May be inoperative provided procedures are established and used to ensure associated compartment or zone remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.
-16-01-01	Detectors				
-16-01-01-01	-200/-300	C	4	2	(O) One in each compartment or zone may be inoperative provided remaining detector is verified to operate normally before each departure.
-16-01-01-02	-400ER	C	8	4	One in each compartment zone may be inoperative.
-16-01-02	Detector Loops (-200SF ATC/ -300BCF)	C	4	2	(O) One in each compartment may be inoperative provided remaining detector loop is verified to operate normally before each departure.
-16-01-03	Detector Fans				
-16-01-03-01	-200/-300	C	4	2	One in each compartment may be inoperative.
-16-01-03-02	-400ER	C	8	4	One in each compartment zone may be inoperative.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-16-02	Main Deck Cargo Compartment Smoke Detection System (All Cargo Configuration)	C	1	0	(O) May be inoperative provided procedures are established and used to ensure associated compartment or zone remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.
-16-02-01	Loops	C	2	1	(M) One detector loop may be inoperative provided remaining detector loop is verified to operate normally before each departure.
-16-02-02	Detectors (-300BDSF)	C	16	8	(O) One detector in each zone may be inoperative provided remaining detector in that zone is verified to operate normally before each departure.
-17-01	Wheel Well Fire Detection System				
-17-01A		C	1	0	(M) May be inoperative provided BTMS operates normally. NOTE: Avoid possibility of retracting an overheated wheel by monitoring brake temperature indications.
(Continued)					

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-17-01	Wheel Well Fire Detection System (Cont'd)				
-17-01B		C	1	0	(M) May be inoperative provided an accepted procedure is used to ensure brakes are cool before engine start. NOTE 1: Avoid possibility of retracting an overheated wheel by leaving landing gear extended for 10 minutes after takeoff. NOTE 2: In case of engine failure after V1, landing gear should be retracted until takeoff obstacles are cleared.
-18-01	DUCT LEAK Detection Systems				
-18-01-01	L and R Loops				
-18-01-01-01	Dual Loop Configuration	C	4	2	One loop in each system may be inoperative.
-18-01-01-02	CF6-80A/A2 and JT9D				
-18-01-01-02A		A	-	1	(O) May be inoperative provided: a) Associated ENG bleed air switch remains OFF, b) Associated bleed ISLN valve remains closed except for engine start, c) Airplane is not operated in known or forecast icing conditions, d) Airplane remains at or below FL 270,
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-7

SYSTEM & SEQUENCE NUMBERS	1. ITEM		2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
26 FIRE PROTECTION					
-18-01 DUCT LEAK Detection Systems (Cont'd)					
-18-01-01 L and R Loops (Cont'd)					
-18-01-01-03 CF6-80C2 and PW4000					
-18-01-01-03A	A	-	1		(M)(O) May be inoperative provided: <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated bleed ISLN valve remains closed except for engine start, c) Airplane is not operated in known or forecast icing conditions, d) Airplane remains at or below FL 270, e) APU is used as air source for ADP for takeoff and landing, f) One body loop operates normally, g) Associated fan air modulation valve is secured in intermediate position, h) Appropriate performance adjustments are applied, and i) Operation is limited to 1 flight day before repairs are made.
-18-01-01-03B	A	-	1		(M)(O) May be inoperative provided: <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated bleed ISLN valve remains closed except for engine start, c) Airplane is not operated in known or forecast icing conditions, d) Airplane remains at or below FL 270, e) ADP inoperative penalties are applied, (Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	26-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26	FIRE PROTECTION				
-18-01	DUCT LEAK Detection Systems (Cont'd)				
-18-01-01	L and R Loops (Cont'd)				
-18-01-01-03	CF6-80C2 and PW4000 (Cont'd)				
-18-01-01-03B	(Cont'd)				<ul style="list-style-type: none"> f) Center Hydraulic Motor Generator (HMG) is considered inoperative, g) One body loop operates normally, h) Associated fan air modulation valve is secured in intermediate position, i) Appropriate performance adjustments are applied, and j) Operation is limited to 1 flight day before repairs are made.
-18-01-01-03C		A	-	1	<ul style="list-style-type: none"> (O) May be inoperative provided: <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated bleed ISLN valve remains closed except for engine start, c) Airplane is not operated in known or forecast icing conditions, d) Airplane remains at or below FL 270, e) APU is used as air source for ADP for takeoff and landing, f) One body loop operates normally, g) Appropriate performance adjustments are applied for an open fan air modulation valve, and h) Operation is limited to 1 flight day before repairs are made. <p>(Continued)</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 26-9
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
26 FIRE PROTECTION					
-18-01	DUCT LEAK Detection Systems (Cont'd)				
-18-01-01	L and R Loops (Cont'd)				
-18-01-01-03	CF6-80C2 and PW4000 (Cont'd)				
-18-01-01-03D		A	-	1	(O) May be inoperative provided: a) Associated ENG bleed air switch remains OFF, b) Associated bleed ISLN valve remains closed except for engine start, c) Airplane is not operated in known or forecast icing conditions, d) Airplane remains at or below FL 270, e) ADP inoperative penalties are applied, f) Center Hydraulic Motor Generator (HMG) is considered inoperative, g) One body loop operates normally, h) Appropriate performance adjustments are applied for an open fan air modulation valve, and i) Operation is limited to 1 flight day before repairs are made.
-18-01-01-04	RB211				
-18-01-01-04A		A	-	1	(O) May be inoperative provided: a) Associated ENG bleed air switch remains OFF, b) Associated bleed ISLN valve remains closed except for engine start, c) Airplane is not operated in known or forecast icing conditions,
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	26-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
26 FIRE PROTECTION					
-18-01	DUCT LEAK Detection Systems (Cont'd)				
-18-01-01	L and R Loops (Cont'd)				
-18-01-01-04	RB211 (Cont'd)				
-18-01-01-04A	(Cont'd)				<ul style="list-style-type: none"> d) Airplane remains at or below FL 270, e) APU is used as air source for ADP for takeoff and landing, f) One body loop operates normally, and g) Operation is limited to 1 flight day before repairs are made.
-18-01-01-04B		A	-	1	<ul style="list-style-type: none"> (O) May be inoperative provided: <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated bleed ISLN valve remains closed except for engine start, c) Airplane is not operated in known or forecast icing conditions, d) Airplane remains at or below FL 270, e) ADP inoperative penalties are applied, f) Center Hydraulic Motor Generator (HMG) is considered inoperative, g) One body loop operates normally, and h) Operation is limited to 1 flight day before repairs are made. <p>(Continued)</p>

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-18-01	DUCT LEAK Detection Systems (Cont'd)				
-18-01-02	Body Loop				
-18-01-02A		C	2	1	
-18-01-02B		C	-	0	(O) May be inoperative provided: a) APU is not used as a pneumatic source except as required for engine start, b) APU bleed air switch remains off except as required for engine start, c) Center bleed ISLN valve remains closed except as required for engine start, d) ADP inoperative performance penalties are applied, e) Both center electric pumps operate normally, f) Airplane remains at or below FL 270, g) Center Hydraulic Motor Generator (HMG) is considered inoperative, and h) One L and one R loop operate normally.
-18-01-03	Test Function	C	1	0	(M) May be inoperative provided detection system is verified to operate normally once each flight day.
-18-01-04	DUCT LEAK Lights (-400ER)	C	3	0	(O) May be inoperative.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	26-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
26 FIRE PROTECTION						
-20-01	Engine Fire Extinguisher Bottle Pressure Indicating System	C	2	0	(M) May be inoperative provided an acceptable test procedure is used once each flight day to verify that associated bottle is properly charged.	
-20-02	Fire Extinguisher SQUIB TEST System	C	1	0	(M) May be inoperative or individual test functions may be inoperative provided each squib circuit associated with an inoperative test function is verified to operate normally once each flight day.	
-20-02-01	APU Squib Test Functions	C	-	0	May be inoperative provided APU is considered inoperative.	
-20-02-02	Cargo Squib Test Functions					
-20-02-02A		C	-	0	May be inoperative provided extinguisher system is inoperative.	
-20-02-02B		C	-	0	(O) May be inoperative provided procedures are established and used to ensure associated compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.	
-22-01	APU Fire Extinguisher System					
-22-01A		C	1	0	Except for ER operations, may be inoperative provided APU is considered inoperative.	
(Continued)						

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	26-13

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-22-01	APU Fire Extinguisher System (Cont'd)				
-22-01B		B	1	0	Except for ER operations beyond 120 minutes, may be inoperative provided APU is considered inoperative.
-22-01-01	*** Fire Extinguisher Bottle (Two Bottle System)	C	2	1	
-22-01-02	Fire Extinguisher Bottle Pressure Indicating System				
-22-01-02A		C	2	1	
-22-01-02B		C	-	0	(M) May be inoperative provided an acceptable test procedure is used once each flight day to verify that associated bottle(s) is properly charged.
-23-01	Lower Cargo Compartment Fire Extinguisher System (Metered or Non-Metered)	C	1	0	(O) May be inoperative provided procedures are established and used to ensure lower cargo compartments or zones remain empty, or are verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.
(Continued)					

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	26-14

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-23-01	Lower Cargo Compartment Fire Extinguisher System (Metered or Non-Metered) (Cont'd)				
-23-01-01	Fire Extinguisher Bottles (Two and Three Bottle Systems) (-200/-300)	C	-	-	(O) Extinguisher bottle No. 2 or 2A may be inoperative with cargo carried in compartments provided: a) Airplane is operated pressurized, and b) A chart is provided to determine time airplane must remain in proximity to a suitable airport.
-23-01-02	Fire Extinguisher Bottles (Four Bottle System) (-400ER)	C	4	2	(M)(O) Extinguisher bottle No. 2, 2A or 2B may be inoperative deactivated with cargo carried in compartments provided: a) Airplane is operated pressurized, and b) A chart is provided to determine time airplane must remain in proximity to a suitable airport.
-23-01-03	Fire Extinguisher Bottle Pressure Indicating System				
-23-01-03A		C	-	0	(M) May be inoperative provided an acceptable test procedure is used once each flight day to verify that associated bottle(s) is properly charged.
-23-01-03B		C	-	0	May be inoperative provided associated fire bottle(s) is considered inoperative.
(Continued)					

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	26-15

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-23-01	Lower Cargo Compartment Fire Extinguisher System (Metered or Non-Metered) (Cont'd)				
-23-01-04	Bottle Pressure Switches (-400ER)	C	4	0	(M) May be inoperative provided: a) Associated bottle is verified full, and b) Associated bottle squib is verified to operate normally before each departure.
-23-02	Lower Cargo Compartment Fire Extinguisher Flow Valves (Forward or Aft) (-400ER)	C	2	0	(M)(O) May be inoperative deactivated provided procedures are established and used to ensure associated compartment remains empty, or is verified to contain only empty cargo handling equipment, ballast (ballast may be loaded in ULDs), and/or fly away kits. NOTE: Operator MELs must define which items are approved for inclusion in fly away kits and which materials can be used as ballast.
26-01	Portable Fire Extinguishers	D	-	-	(M) Any in excess of those required by 14 CFR may be inoperative or missing provided: a) Inoperative fire extinguisher is tagged inoperative, removed from installed location, and placed out of sight so it can not be mistaken for a functional unit, and b) Required distribution is maintained.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-16

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
26 FIRE PROTECTION					
-26-02	Lavatory Fire Extinguisher Systems				
-26-02-01	Passenger Configuration				
-26-02-01A		C	-	0	For each lavatory, lavatory fire extinguisher system may be inoperative provided associated lavatory smoke detection system operates normally.
-26-02-01B		C	-	0	(M)(O) For each lavatory, lavatory fire extinguisher system may be inoperative provided: a) Lavatory waste receptacle is empty, b) Associated lavatory door is locked closed and placarded INOPERATIVE – DO NOT ENTER, and c) Lavatory is used only by crewmembers. NOTE: These provisos are not intended to prohibit lavatory use or inspections by crewmembers.
-26-02-02	All Cargo Configuration	D	-	0	
-26-03	Lavatory Smoke Detection Systems				
-26-03-01	Passenger Configuration	C	-	-	(M)(O) For each lavatory, lavatory smoke detection system may be inoperative provided: a) Lavatory waste receptacle is empty, b) Associated lavatory door is locked closed and placarded INOPERATIVE – DO NOT ENTER, and c) Lavatory is used only by crewmembers.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

26-17

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
26	FIRE PROTECTION			
	-26-03			(Continued)
	Lavatory Smoke Detection Systems (Cont'd)			
	-26-03-01			NOTE: These provisos are not intended to prohibit lavatory use or inspections by crewmembers.
	Passenger Configuration (Cont'd)			
	-26-03-01-01 ***	C	-	0
	Lavatory Call Light Smoke Detected Function			NOTE: Attendant call and occupancy indications are considered NEF.
	-26-03-02	D	-	0
	All Cargo Configuration			

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

27-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
27 FLIGHT CONTROLS					
-03-01	FLT CONTROL SHUTOFF Valves	C	6	0	(M) May be inoperative open.
-03-02	FLT CONTROL SHUTOFF OFF Lights	C	6	0	(M) May be inoperative provided associated valve is verified open before each departure.
-08-01	Control Surface Position Indicating System	C	1	0	(M) May be inoperative provided a visual flight control check is accomplished before each departure.
-08-02	Flap Position Indicator System				
-08-02-01	Position Needles (-200/-300)	C	2	1	
-08-02-02	Position Sensors (-400ER)	C	2	1	
-09-01	Yaw Damper Stabilizer Trim Module (YSM)	B	2	1	(M)(O) One may be inoperative. NOTE: Associated autopilot will not engage until Approach Mode engages.
-11-01	Aileron Trim System	C	1	0	(M) May be inoperative provided: a) One autopilot operates normally, and b) Aileron trim system is verified centered.
-11-02	Outboard Aileron Lockout System	C	1	0	(M)(O) May be inoperative unlocked provided maximum airspeed is limited to 270 KIAS or 0.73 Mach, whichever is less.
-11-02-01	Indication System	C	1	0	(M)(O) May be inoperative provided aileron lockout system is verified to operate normally before each departure.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

27-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
27 FLIGHT CONTROLS					
-21-01	Rudder Ratio Light	C	1	0	(M) May be inoperative off provided: a) RUDDER RATIO message on EICAS is verified to operate normally, and b) Both control channels operate normally.
-21-03	Rudder Trim Indication System	C	1	0	(M) May be inoperative provided: a) Rudder trim actuator operates normally, b) Rudder control surface position indicating system operates normally, and c) Rudder trim is verified to be centered before each departure.
-31-01	Elevator Feel Pressure Takeoff Limit Function (-400ER)	C	1	0	(O) May be inoperative provided: a) Appropriate takeoff center of gravity restrictions are observed, and b) Improved Climb takeoffs are not conducted.
-32-01	Stall Warning Test Systems	C	2	0	(M) May be inoperative provided operation of associated system is verified once each flight day.
-32-02	Stall Warning Systems (-400ER)	A	2	1	(M) One may be inoperative provided: a) Remaining system is verified to operate normally before each departure, and b) Operations are limited to not more than 3 flight days before repair is made.
-41-01	Control Wheel Trim Switch Systems	B	2	1	(M) One may be inoperative on non-flying pilot's side provided stabilizer trim system is verified to operate normally.
-41-02	Horizontal Stabilizer Primary Trim Channels	C	2	1	(M)(O) One may be inoperative provided: a) Horizontal stabilizer trim is verified to operate normally using stabilizer trim levers (alternate stabilizer trim switches), b) Approach minimums do not require use of three autopilots, c) No arm or control valves are failed in energized position, and d) Associated autopilot is not used.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	27-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
27 FLIGHT CONTROLS						
-48-01	STAB TRIM Indicators	C	2	1	One may be inoperative provided faulty indicator is not visible.	
-51-01	Automatic Flap Load Relief Retraction System (Trailing Edge)					
-51-01-01	-200/-300 (Actuator Rod End Down)	C	1	0	(M) May be inoperative in normal (actuator extended) position provided flaps 30 are not used. NOTE: Flaps 25 may be used to AFM limit maximum landing weight.	
-51-01-02	-300 (Actuator Rod End Up)	C	1	0	(M)(O) May be inoperative in normal (actuator retracted) position provided flaps 25 and flaps 30 adjusted maximum landing weights are observed.	
-51-01-03	-400ER (Actuator Rod End Up)	C	1	0	(M)(O) May be inoperative in normal (actuator retracted) position provided flaps 20, flaps 25 and flaps 30 adjusted maximum landing weights are observed.	
-61-01	Speed Brake Load Alleviation System (-300/-300F with Blended Winglets STC ST01920SE)	C	1	0	(M)(O) May be inoperative provided: a) Speedbrake handle forces are verified normal from full down to full up position, and b) Airspeed does not exceed 290 KIAS, or .84 Mach, whichever is lower, when inflight gross weight is in excess of 340,000 pounds (154,545 kg).	

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

27-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
27 FLIGHT CONTROLS						
-62-01	Auto Speed Brake System					
-62-01-01	Without Speed Brake Load Alleviation System Installed	C	1	0	(M)(O) May be inoperative provided: a) System is deactivated, and b) AFM decrements are applied if landing performance requires use of auto speed brakes.	
-62-01-02	With Speed Brake Load Alleviation System Installed	C	1	0	(M)(O) May be inoperative provided: a) System is deactivated, b) Speedbrake handle forces are verified normal from full down to full up position, c) AFM decrements are applied if landing performance requires use of auto speed brakes, and d) Airspeed does not exceed 290 KIAS, or 84 Mach, whichever is lower, when inflight gross weight is in excess of 340,000 pounds (154,545kg).	
-62-02	Speedbrake Caution Indication System	C	1	0	(O) May be inoperative provided speedbrake lever is not positioned beyond ARMED position inflight below 800 feet radio altitude or when landing flaps are extended.	
-63-01	AUTO SPDBRK/ SPOILERS/STAB TRIM Lights	C	3	0	(M) May be inoperative provided associated EICAS message is verified to operate once each flight day.	
-81-01 ***	Leading Edge Slat Skew/Loss Detection System	C	1	0	(M) May be inoperative deactivated provided leading edge slat system is verified to operate normally.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	28-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
28 FUEL					
-11-01	Sump Drain Valves	C	-	-	(M) One may be inoperative closed.
-21-01	Pressure Fueling System	C	1	0	(M) May be inoperative provided alternate procedures are established and used.
-21-01-01	Fuel Shutoff Valves				
-21-01-01A		C	6	0	(M) May be inoperative closed.
-21-01-01B		C	6	0	(M) May be inoperative open if fuel jettison system is deactivated or not installed.
-21-02 ***	Fueling Receptacle Caps	C	-	0	May be inoperative or missing provided no leakage can be detected after refueling is complete.
-22-01	Main Tank Fuel Pumps	C	4	3	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: <ul style="list-style-type: none"> a) Inoperative pump is deactivated, b) Both main tank quantity indications operate normally, and c) Following minimum fuel quantities are retained in affected tank for flight condition shown: With fuel tank dams installed – (SB 767-28-11 or production equivalent): TAKEOFF - 10,000 lb. (4,540 kg) LANDING - 5,000 lb. (2,270 kg) Without fuel tank dams: TAKEOFF - 25,000 lb. (11,340 kg) LANDING - 7,000 lb. (3,175 kg)
-22-01-01	Automatic Function of Left FWD Pump	C	1	0	(O) May be inoperative provided alternate procedures are established and used.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	28-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
28 FUEL					
-22-02	Center Tank Fuel Pumps				
-22-02A		C	2	1	(M)(O) One may be inoperative with center tank fueled provided: a) Fuel quantity in main tanks is adequate to reach a suitable airport if remaining pump fails at any time, b) Zero fuel weight calculations are adjusted by weight of center tank fuel, c) Effect on airplane balance, in event fuel cannot be used, is accounted for, d) For -200/-300, low PRESS light operates normally on remaining pump, e) Center tank and both main tank quantity indications operate normally, f) One crossfeed valve is open prior to takeoff and remains open until center tank pump is selected OFF, and g) Affected pump is deactivated.
-22-02B		C	2	0	(M) May be inoperative provided: a) Center tank remains empty, b) Center tank is verified to be empty before each refueling, and c) Affected pumps are deactivated.
-22-02-01	Service Bulletin 767-28-0062 or Production Equivalent Installed	C	2	0	(M) May be inoperative provided: a) Center tank remains empty, b) Center tank scavenge system is installed and operates normally, and c) Center tank fuel pumps are deactivated.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	28-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
28 FUEL						
-22-02	Center Tank Fuel Pumps (Cont'd)					
-22-02-02	Subject to Airworthiness Directive 2001-15-08 and without Automatic Shut Off System Installed	C	2	0	(M) May be inoperative provided: a) Boeing Alternative Method of Compliance to Airworthiness Directive 2001-15-08 (Operations Manual Bulletin Center Tank Fuel Pumps) is in effect, b) Center tank is verified to contain less than 5,000 pounds (2,300 kg) of fuel, c) Center tank fuel is not used, and d) Affected pumps are deactivated.	
-22-03 ***	Dual Fuel Crossfeed Valves					
-22-03A		C	2	1	(M) Except for ER operations, one may be inoperative provided: a) Affected valve is secured closed, b) Remaining valve is verified to operate normally.	
-22-03B		C	2	1	(M)(O) One may be inoperative provided: a) Affected valve is secured closed, b) Remaining valve is verified to operate normally, and c) Remaining valve is exercised during last hour of flight.	
-22-04	Center Tank Float Operated Shutoff Valves	C	2	0	May be inoperative provided center tank remains empty	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

28-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
28 FUEL					
-22-05	Automatic Shut Off System (Service Bulletins 767-28A0083, 767-28A0084, or Production Equivalent Installed)				
-22-05A		C	2	0	May be inoperative provided associated center tank fuel pump is considered inoperative.
-22-05B		C	2	0	May be inoperative provided center tank remains empty.
-22-05-01	Not Subject to Airworthiness Directive 2001-15-08	C	2	0	May be inoperative.
-22-05-02	Subject to Airworthiness Directive 2001-15-08	C	2	0	(O) May be inoperative with center tank fueled provided: a) Center tank fuel pump low PRESS lights operate normally, b) Center tank quantity indication operates normally, c) Center tank pumps are OFF for takeoff if center tank fuel is less than 5,000 pounds (2,300 kg) with airplane readied for initial taxi, d) Center tank fuel pumps are repositioned ON above 10,000 feet or after pitch attitude has been reduced to begin acceleration to climb speed, if more than 1,000 pounds (500 kg) remain in center tank,
(Continued)					

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

28-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
28 FUEL					
-22-05	Automatic Shut Off System (Service Bulletins 767-28A0083, 767-28A0084, or Production Equivalent Installed) (Cont'd)				
-22-05-02	Subject to Airworthiness Directive 2001-15-08 (Cont'd)				<ul style="list-style-type: none"> e) Both center tank fuel pumps are positioned OFF at first indication of fuel pump low pressure, f) Both center tank pumps are selected OFF when center tank fuel quantity reaches 1,000 pounds (500 kg) of fuel during climb, cruise or descent, g) In cruise and only when required to extinguish the FUEL CONFIG light and EICAS FUEL CONFIG message, both center tank pumps are selected OFF when center tank fuel quantity reaches 800 pounds (400 kg) of fuel, and h) For airplanes not equipped with a scavenge system, 1,000 pounds (500 kg) of center tank fuel is considered unusable.
-22-06	Universal Fault Interrupter (UFI) (STC ST02285LA)	C	2	0	May be inoperative provided associated center tank boost pump is considered inoperative.
-25-01	APU (DC) Fuel Pump	C	1	0	(M) May be inoperative deactivated provided both left fuel tank boost pumps operate normally when APU is required for dispatch.
-25-02	APU Fuel Shutoff Valve	C	1	0	(M) May be inoperative provided: <ul style="list-style-type: none"> a) APU is considered inoperative, and b) Valve is secured closed.
-25-03 ***	APU Fuel Isolation Valve	C	1	0	(M) May be inoperative provided valve is secured closed.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

28-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
28 FUEL						
-26-01	Defuel Valves	C	-	0	(M) May be inoperative closed.	
-31-03 ***	Fuel Jettison System	C	1	0	(M)(O) May be inoperative provided a) Jettison nozzle valves are secured closed, and b) Jettison transfer valves are secured closed.	
-31-03-01	Center Tank Jettison Pumps	C	2	0	(M)(O) May be inoperative provided both center tank fuel pumps operate normally if center tank is used.	
-40-01	Crossfeed VALVE Light(s)					
-40-01-01	Single VALVE Installation	C	1	0	(M) Except for ER operations, may be inoperative provided: a) Crossfeed valve is verified to operate normally, and b) Both main fuel quantity indications operate normally.	
-40-01-02	Dual Valve Installation					
-40-01-02-01 -200/-300						
-40-01-02-01A		C	2	1	(M) May be inoperative provided: a) One crossfeed valve is verified to operate normally, and b) Both main fuel quantity indications operate normally.	
(Continued)						

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	28-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
28 FUEL					
-40-01	Crossfeed VALVE Light(s) (Cont'd)				
-40-01-02	Dual VALVE Installation (Cont'd)				
-40-01-02-01	-200/-300 (Cont'd)				
-40-01-02-01B		C	2	0	(M) Except for ER operations, may be inoperative provided: a) Both crossfeed valves are verified to operate normally, and b) Both main fuel quantity indications operate normally.
-40-01-02-02	-400ER				
-40-01-02-02A		C	2	1	May be inoperative provided: a) One crossfeed valve operates normally, and b) Both main fuel quantity indications operate normally.
-40-01-02-02B		C	2	0	Except for ER operations, may be inoperative provided: a) Both crossfeed valves operate normally, and b) Both main fuel quantity indications operate normally.
-40-02	SPAR VALVE Lights (-200/-300)	C	2	0	(M) May be inoperative provided spar valve is verified to operate normally once each flight day.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

28-8

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
28 FUEL				
-41-01 Fuel Tank Quantity Indication Systems (Flight Deck)				
-41-01-01 Main Tank Indicators	C	2	1	<p>(M)(O) Except for ER operations, one may be inoperative provided:</p> <ul style="list-style-type: none"> a) Fuel quantity in associated tank is verified by an alternate procedure, b) For non-PIP and non-Pegasus FMCs, both EICAS computers operate normally, c) Fuel flow indications operate normally, d) FMC FUEL is initialized with known total fuel quantity, e) Procedures to identify and contain an inflight engine fuel leak are used, f) All main tank boost pumps operate normally, g) For -200/-300, fuel pump low PRESS lights for associated tank operate normally, h) For Pegasus FMCs with Operational Program Software part number 3418-HNP-02C-08 or earlier, Thrust Management System operates normally, and i) For airplanes with Service Bulletin 767-28-0062, or production equivalent, center tank remains empty. <p>NOTE: FUEL CONFIG advisory message for lateral imbalance may be inhibited.</p> <p>(Continued)</p>

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

28-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
28 FUEL						
-41-01	Fuel Tank Quantity Indication Systems (Flight Deck) (Cont'd)					
-41-01-02	Center Tank Indicator	C	1	0	(M) May be inoperative provided: a) Center tank remains empty, b) Center tank scavenge system is installed and operates normally, and c) Center tank fuel pumps are deactivated.	
-41-01-02-01	With Automatic Shut Off System (Service Bulletin 767-28A0083, 767-28A0084, STC ST02285LA, or Production Equivalent Installed)	C	1	0	(M)(O) Except for ER operations, may be inoperative provided: a) Fuel quantity in center tank is verified by an alternate procedure, b) Fuel flow indications operate normally, c) FMC FUEL is initialized with known total fuel quantity, d) Both main tank indicators operate normally, e) Procedures to identify and contain an inflight engine fuel leak are used, f) Both center tank boost pumps operate normally, and g) Center tank fuel pump low PRESS lights operate normally.	
-41-01-02-02	Subject to AD 2001-15-08 and without Automatic Shut Off System Installed	C	1	0	(M) May be inoperative provided: a) Boeing Alternative Method of Compliance to Airworthiness Directives 2001-15-08 (Operations Manual Bulletin Center Tank Fuel Pumps) is in effect, b) Center tank is verified to contain less than 5,000 pounds (2,300 kg) of fuel, and c) Center tank fuel is not used.	

(Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

28-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
28 FUEL					
-41-01	Fuel Tank Quantity Indication Systems (Flight Deck) (Cont'd)				
-41-01-03	Fuel Quantity Densitometers				
-41-01-03-01	Honeywell	C	3	0	(M) May be inoperative provided affected densitometer(s) is deactivated.
-41-01-03-02	B.F. Goodrich (Simmonds)	C	3	0	
-41-02	Fuel Quantity Processor Channels				
-41-02-01	Honeywell FQIS	B	2	1	(M)(O) Except for ER operations, one channel may be inoperative provided: <ul style="list-style-type: none"> a) Total fuel quantity is determined by measuring sticks or other acceptable means after each refueling, and agrees with fuel quantity indications, b) Inoperative channel is deactivated by an acceptable procedure, c) All flight deck fuel indications operate normally, d) For non-PIP and non-Pegasus FMCs, both EICAS computers operate normally, e) Fuel flow indications operate normally, f) FMC TOTALIZER FUEL quantity agrees with fuel quantity indications, and g) For Pegasus FMCs with Operational Program Software part number 3418-HNP-02C-08 or earlier, thrust management system operates normally. (Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	28-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
28 FUEL					
-41-02	Fuel Quantity Processor Channels (Cont'd)				
-41-02-02	B.F. Goodrich (Simmonds) FQIS	B	2	1	(O) Except for ER operations, one channel may be inoperative provided: a) All flight deck fuel indications operate normally, b) For non-PIP and non-Pegasus FMCs, both EICAS computers operate normally, c) Fuel flow indications operate normally, d) FMC TOTALIZER FUEL quantity agrees with fuel quantity indications, and e) For Pegasus FMCs with Operational Program Software part number 3418-HNP-02C-08 or earlier, thrust management system operates normally.
-41-06	Wing Fueling Station Quantity Indications	C	-	0	(M) May be inoperative provided alternate fueling procedures are established and used.
-41-07	Total Fuel Quantity Indication				
-41-07A		C	1	0	(O) May be inoperative provided: a) FMC is initialized with known total fuel quantity, b) For non-PIP and non-Pegasus FMCs, both EICAS computers operate normally, c) Fuel flow indications operate normally, d) Both FMCs operate normally, and e) For Pegasus FMCs with Operational Program Software part number 3418-HNP-02C-08 or earlier, thrust management system operates normally.

(Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

28-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
28 FUEL						
-41-07	Total Fuel Quantity Indication (Cont'd)					
-41-07B		C	1	0	(O) May be inoperative provided: a) Main tank fuel quantity indicators operate normally, and b) Center tank fuel quantity indicator is considered inoperative.	
-42-01	Fuel Pump Low PRESS Lights	C	6	3	May be inoperative for an associated inoperative pump.	
-42-01-01						
-200/-300		C	6	3	(M) May be inoperative provided associated EICAS message is verified to operate normally once each flight day.	
-42-01-02						
-400ER		C	6	0		
-43-01	FUEL TEMP Indicating System	C	1	0	(O) May be inoperative provided total air temperature (TAT) is used as an indication of fuel temperature. NOTE: Static air temperature may be used provided appropriate ram rise factor is applied.	
-44-01	Measuring Sticks	C	16	0	May be inoperative provided fuel quantity is determined by other approved means.	

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

29-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
29 HYDRAULICS						
-11-01	Engine Driven Hydraulic Pumps					
-11-11-01	Depressurization Function	C	2	0		
-11-02	Center System (Electric) Hydraulic Pumps	C	2	1	Pump No. 2 may be inoperative provided air driven pump operates normally.	
-11-03	Air Driven Pump (ADP)	C	1	0	(M)(O) May be inoperative provided: a) Center Hydraulic Motor Generator (HMG) is not required, b) Both center system electric pumps operate normally, and c) Appropriate performance adjustments are applied.	
-11-04	ADP Controller					
-11-04-01	AUTO Function	C	1	0	(O) May be inoperative provided: a) Control is ON for takeoff and landing, b) Center Hydraulic Motor Generator (HMG) is not required, or control is ON continuously when HMG is required, c) OFF position operates normally, and d) Appropriate performance adjustments are applied.	
-11-04-02	ON Function	C	1	0	May be inoperative provided: a) AUTO and OFF functions of ADP operate normally, and b) Center HMG is not required.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	29-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
29 HYDRAULICS						
-11-05	Electric Demand Pump (ACMP)					
-11-05-01	AUTO Function	C	2	1	One may be inoperative provided: a) Pump operates normally, and b) Associated pump is selected ON and remains on.	
-18-01	Remote Quantity Indicator	C	1	0		
-31-01	Hydraulic Low SYS PRESS Lights					
-31-01-01	Non-PTU Equipped Airplanes	C	3	0	(M) May be inoperative provided: a) Associated pump low PRESS lights operate normally, and b) Associated HYD SYS PRESS EICAS indication is verified to operate normally.	
-31-01-02	PTU Equipped Airplanes					
-31-01-02-01	Left Low SYS PRESS Light	C	1	0	(M) May be inoperative provided: a) Associated pump low PRESS lights operate normally, b) Associated HYD SYS PRESS EICAS indication is verified to operate normally, and c) Left low pressure signal wire of PTU system is capped and stowed.	
(Continued)						

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	29-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
29 HYDRAULICS					
-31-01	Hydraulic Low SYS PRESS Lights (Cont'd)				
-31-01-02	PTU Equipped Airplanes (Cont'd)				
-31-01-02-02	Right Low SYS PRESS Light	C	1	0	(M) May be inoperative provided: a) Associated pump low PRESS lights operate normally, and b) Associated HYD SYS PRESS EICAS indication is verified to operate normally.
-31-02	Pump Low PRESS Indication Systems				
-31-02-01	Left/Center/Right/Air Driven Pump PRESS Lights	C	7	4	(O) One in each hydraulic system may be inoperative provided: a) Associated low SYS PRESS light operates normally, and b) Associated pump is verified to operate normally before each departure.
-31-02-02	Engine Driven Pump Indication Systems	C	2	1	(O) One may be inoperative provided: a) Associated demand pump AUTO function is considered inoperative, b) Associated low SYS PRESS light operates normally, and c) Associated pump is verified to operate normally before each departure.
(Continued)					

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

29-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
29 HYDRAULICS						
-31-02	Pump Low PRESS Indication Systems (Cont'd)					
-31-02-03	Center System No. 2 Electric Pump Indication System	C	1	0	May be inoperative provided: a) Air driven pump operates normally, and b) Associated pump is selected OFF.	
-31-02-04	Air Driven Pump (ADP) Indication System	C	1	0	(O) May be inoperative provided: a) Both center system electric pumps operate normally, b) ADP is selected OFF, c) Center Hydraulic Motor Generator (HMG) is not required, and d) Appropriate performance adjustments are applied	
-31-03 ***	HYD PRESS Indications (EICAS)	D	3	0		
-32-01	Pump OVHT Indication Systems					
-32-01-01	Left/Center/Right/Air Driven Pump OVHT Lights	C	7	4	(O) One in each hydraulic system may be inoperative provided: a) Associated low SYS PRESS light or pump low PRESS light operates normally, and b) Associated pump is verified to operate normally before each departure.	
-32-01-02	Center System No. 2 Electric Pump Indication System	C	1	0	May be inoperative provided: a) Air driven pump operates normally, and b) Associated pump is selected OFF.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

29-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
29 HYDRAULICS					
-32-01	Pump OVHT Indication Systems (Cont'd)				
-32-01-03	Air Driven Pump (ADP) Indication System	C	1	0	(O) May be inoperative provided: a) Both center system electric pumps operate normally, b) ADP is selected OFF, c) Center Hydraulic Motor Generator (HMG) is not required, and d) Appropriate performance adjustments are applied.
-33-01	Hydraulic System Low QTY or RSVR Lights				
-33-01A		C	3	0	(M) May be inoperative provided associated HYD QTY indication is verified to operate normally.
-33-01B		C	3	0	(M) May be inoperative provided: a) Associated reservoir level(s) is verified normal before each departure, b) Associated SYS PRESS lights operate normally, and c) On PTU equipped airplanes, with left hydraulic system low QTY or RSVR light inoperative, left low quantity signal wire of PTU system is capped and stowed.
-33-02	HYD QTY Indications	C	3	0	(M) May be inoperative provided: a) Associated reservoir level(s) is verified normal before each departure, b) Associated SYS PRESS lights operate normally, and c) On PTU equipped airplanes, with left hydraulic system low QTY or RSVR light inoperative, left low quantity signal wire of PTU system is capped and stowed.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
30 ICE AND RAIN PROTECTION					
-11-01	Wing Anti-Ice Valves	C	2	0	(M) Except for ER operations beyond 120 minutes, may be inoperative closed provided airplane is not operated in known or forecast icing conditions.
-11-02	Wing Anti-Ice VALVE Lights				
-11-02A		C	2	0	(O) May be inoperative provided associated valve operates normally.
-11-02B		C	2	0	May be inoperative provided associated valve is inoperative.
-11-02C		C	2	0	May be inoperative provided associated EICAS Advisory message L/R WING ANTI-ICE operates normally.
-11-03	Wing Anti-Ice Ground Test	C	1	0	
-21-01	Engine Anti-Ice Valves				
-21-01-01	Cowl Valves	C	2	1	(M) Except for ER operations beyond 120 minutes, one may be inoperative closed provided airplane is not operated in known or forecast icing conditions.
(Continued)					

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	30-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
30 ICE AND RAIN PROTECTION					
-21-01	Engine Anti-Ice Valves (Cont'd)				
-21-01-02	Cowl Valves (JT9D-7R4)	C	2	1	(M)(O) One may be inoperative locked open provided: a) Fan air modulation valve is locked in intermediate position, b) High pressure shutoff valve is secured closed, c) Remaining (opposite) engine bleed system operates normally, d) Ambient temperature is below 38 degrees C, e) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained in icing conditions, f) Center Hydraulic Motor Generator (HMG) is considered inoperative, and g) Appropriate EPR limit and performance adjustments are applied.
-21-01-03	Stator Vane Valves (JT9D-7R4)				
-21-01-03A		C	2	1	(M)(O) One may be inoperative open provided appropriate EPR limit and performance adjustments are applied.
-21-01-03B		C	2	0	(M) May be inoperative closed.
(Continued)					

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-3

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
30 ICE AND RAIN PROTECTION				
-21-01 Engine Anti-Ice Valves (Cont'd)				
-21-01-04 Cowl Valves				
-21-01-04-01 PW4000	C	2	1	<p>(M)(O) One may be inoperative open provided:</p> <ul style="list-style-type: none"> a) High pressure shutoff valve is secured closed, b) Bleed air switch for associated engine remains OFF except when TAT is 10 degrees C or below, c) For operations with associated bleed air switch OFF, <ul style="list-style-type: none"> 1) APU is used as air source for ADP for takeoff or ADP inoperative penalties are applied, 2) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, 3) Airplane is not operated in known or forecast icing conditions, and 4) Airplane remains at or below FL 350, d) For operations with associated bleed air switch ON, a minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, e) Remaining (opposite) engine bleed system operates normally, f) Associated PRV operates normally, g) Center Hydraulic Motor Generator (HMG) is considered inoperative, and h) Appropriate performance adjustments are applied. <p>NOTE: Bleed air switch for associated engine may be selected ON when TAT is 10 degrees C or below.</p> <p>(Continued)</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	30-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
30 ICE AND RAIN PROTECTION					
-21-01	Engine Anti-Ice Valves (Cont'd)				
-21-01-04	Cowl Valves (Cont'd)				
-21-01-04-02	CF6-80C2	C	2	1	(M)(O) One may be inoperative open provided: a) High pressure shutoff valve is secured closed, b) Bleed air switch for associated engine remains OFF except when TAT is 10 degrees C or below, c) For operations with associated bleed air switch OFF, 1) APU is used as air source for ADP for takeoff or ADP inoperative penalties are applied, 2) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, 3) Airplane is not operated in known or forecast icing conditions, and 4) Airplane remains at or below FL 350, d) For operations with associated bleed air switch ON, a minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, e) Remaining (opposite) engine bleed system operates normally, f) Associated PRV operates normally, g) Center Hydraulic Motor Generator (HMG) is considered inoperative, h) Associated thrust reverser is considered inoperative.
(Continued)					

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-5

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
30 ICE AND RAIN PROTECTION				
-21-01	Engine Anti-Ice Valves (Cont'd)			
-21-01-04	Cowl Valves (Cont'd)			
-21-01-04-02	CF6-80C2 (Cont'd)			NOTE: Bleed air switch for associated engine may be selected ON when TAT is 10 degrees C or below.
-21-01-04-03 RB211	C	2	1	(M)(O) One may be inoperative open provided: a) High pressure shutoff valve is secured closed, b) Bleed air switch for associated engine remains OFF except for engine start or when TAT is 10 degrees C or below, c) For operations with associated bleed air switch OFF, 1) APU is used as air source for ADP for takeoff or ADP inoperative penalties are applied, 2) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, 3) Airplane is not operated in known or forecast icing conditions, and 4) Airplane remains at or below FL 350, d) For operations with associated bleed air switch ON, a minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, e) Remaining (opposite) engine bleed system operates normally, f) Associated FWSOV operates normally, g) Center Hydraulic Motor Generator (HMG) is considered inoperative, and h) Appropriate performance adjustments are applied. (Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
30 ICE AND RAIN PROTECTION					
-21-01	Engine Anti-Ice Valves (Cont'd)				
-21-01-04	Cowl Valves (Cont'd)				
-21-01-04-03	RB211 (Cont'd)				
-21-02	Engine Anti-Ice VALVE Lights				
-21-02-01	-200/-300				
-21-02-01A		C	2	1	(M) One may be inoperative provided associated valve is verified to operate normally before operating in known or forecast icing conditions.
-21-02-01B		C	2	1	One may be inoperative provided associated valve is inoperative.
-21-02-01-01	JT9D	C	2	1	One may be inoperative provided associated EICAS Advisory message L/R ENG ANTI-ICE operates normally.
-21-02-01-02	CF6-80A/A2	C	2	1	One may be inoperative provided associated EICAS Advisory message L/R ENG ANTI-ICE operates normally.
-21-02-01-03	RB211	C	2	1	One may be inoperative provided associated EICAS Advisory message L/R ENG ANTI-ICE operates normally.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 30-7
-------------------------------	---	-------------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
30 ICE AND RAIN PROTECTION						
-21-02	Engine Anti-Ice VALVE Lights (Cont'd)					
-21-02-01	-200/-300 (Cont'd)					
-21-02-01-04	CF6-80C2	C	2	1		(O) One may be inoperative provided associated EICAS Advisory message L/R ENG ANTI-ICE operates normally.
-21-02-01-05	PW4000	C	2	1		(O) One may be inoperative provided associated EICAS Advisory message L/R ENG ANTI-ICE operates normally.
-21-02-02	-400ER	C	2	0		(O) May be inoperative.
-21-03	Engine Cowl Overheat Indications (RB211)	C	2	1		(M)(O) One may be inoperative provided: a) Associated HPSOV is secured in closed position, b) Associated nacelle anti-ice valve operates normally, c) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, d) Remaining (opposite) engine bleed system operates normally, and e) Associated ENG COWL OVHT card is deactivated (removed) from fire detection card file.
-31-01	Pitot-Static Probe Heater Systems	B	4	3		Except for ER operations beyond 120 minutes, one probe heater may be inoperative provided airplane is not operated in visible moisture, or in known or forecast icing conditions.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
30 ICE AND RAIN PROTECTION						
-31-02	Probe Heat Lights (Except CAPT and F/O PITOT)	B	-	0	(M) May be inoperative provided: a) Associated EICAS Advisory message is verified to operate normally, and b) Probe heater systems operate normally.	
-31-02-01	Pitot Probe Heat Lights	B	2	1	May be inoperative provided associated probe heater is considered inoperative.	
-31-02-02	Angle of Attack (AOA) and Temperature (TAT) Probe Heat Lights	C	-	1	May be inoperative provided associated probe heater is considered inoperative.	
-31-03	ENG EEC PROBE Light (JT9D)	B	1	0	(M) May be inoperative provided both probe heater functions are verified to operate normally before operating in known or forecast icing conditions.	
-31-04	MACH PROBES Light (JT9D)	B	1	0	(O) May be inoperative provided a minimum of 50% N1 above 10,000 feet MSL, or 45% N1 at or below 10,000 feet MSL is maintained while in icing conditions.	
-31-05	CAPT PITOT and F/O PITOT Heat Indicating Systems (Heater OFF Monitor)	B	2	0	Except for ER operations beyond 120 minutes, may be inoperative provided: a) Pitot heater systems operate normally, b) Remaining probe heater indicating systems for operative probe heaters operate normally, and c) Airplane is not operated in known or forecast icing conditions.	
-32-01	Angle of Attack Sensor Heater Systems	C	2	1	(M) May be inoperative provided: a) Associated AOA vane is verified intact, b) Remaining probe heater indicating systems for operative probe heaters operate normally, and c) Airplane is not operated in known or forecast icing conditions.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	30-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
30 ICE AND RAIN PROTECTION						
-33-01	Temperature (TAT) Probe Heater Systems	C	-	0	(O) Except for ER operations beyond 120 minutes, may be inoperative provided: a) Remaining probe heater indicating systems for operative probe heaters operate normally, and b) Airplane is not operated in known or forecast icing conditions.	
-33-01-01	ADIRS Equipped Airplanes with Air Data System Functionality	C	2	1	(M)(O) May be inoperative provided: a) Associated air data system is considered inoperative, and b) Remaining probe heater indicating systems for operative probe heaters operate normally.	
-34-01	Engine PT2/TT2 Probe Heater Systems					
-34-01-01	JT9D	C	2	1	One may be inoperative provided associated engine EPR indication is considered inoperative.	
-34-01-02	PW4000	C	2	1	(O) One may be inoperative provided: a) Both EECs are switched to ALTN mode, b) N1, N2, and fuel flow systems on associated engine operate normally, and c) Appropriate procedures, AFM limitations and performance decrements are applied.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
30 ICE AND RAIN PROTECTION						
-34-02	Engine Mach Probe Heaters (JT9D)					
-34-02A		C	4	2	One per engine may be inoperative.	
-34-02B		C	4	0	(O) May be inoperative provided at least 50% N1 above 10,000 feet MSL, or 45% N1 at or below 10,000 feet MSL is maintained while in icing conditions.	
-41-01	Flight Deck Window Heat Systems					
-41-01-01	No. 1 (fwd) Windows	C	2	1	(M) Except for ER operations beyond 120 minutes, one may be inoperative provided: <ul style="list-style-type: none"> a) Airplane is not operated in known or forecast icing conditions, b) Both No. 2 (side) window heaters operate normally, c) Associated windshield pneumatic anti-fog system operates normally, and d) Affected window heat is deactivated. 	
-41-01-02	No. 2 (side) Windows	C	2	1	(M) One may be inoperative provided: <ul style="list-style-type: none"> a) Both No. 1 (fwd) window heaters operate normally, and b) Affected window heat is deactivated. 	
-41-01-03	No. 3 (side) Windows	C	2	0	(M) May be inoperative provided affected window heat is deactivated.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
30 ICE AND RAIN PROTECTION					
-41-02	Window Heat INOP Lights				
-41-02A		C	4	0	(M) May be inoperative provided associated window heat system is verified to operate normally before each departure.
-41-02B		C	4	1	May be inoperative provided associated window heat system is inoperative.
-41-03	Window/Probe Heat Ground Test System	C	1	0	
-42-01	Windshield Wipers	C	2	0	May be inoperative provided: a) Airplane is not operated in precipitation within 5 statute miles of airport of departure or intended landing, and b) Approach minimums do not require its use.
-42-01-01	High Speed	C	-	0	May be inoperative provided associated low speed operates normally.
-42-01-02	Low Speed	C	-	0	May be inoperative provided associated high speed operates normally.
-42-01-03	Intermittent	C	2	0	
-43-01	Rain Repellent System	D	1	0	
-71-01	Drain Mast Heaters	C	-	0	(M) May be inoperative provided water supply to associated galley, lavatory sink and drinking fountain is secured OFF.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

30-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
30 ICE AND RAIN PROTECTION					
-72-01	Waste System Heaters				
-72-01-01	Drain Cap Gasket Heater	C	1	0	(M) May be inoperative deactivated.
-72-01-02	Rinse Hose Heater Boot	C	1	0	(M) May be inoperative deactivated.
-80-01	Ice Detection System				
-80-01-01	*** Advisory	D	1	0	
-80-01-02	*** Primary	C	1	0	(O) May be inoperative provided alternate procedures are established and used.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

31-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
31 INDICATING/RECORDING SYSTEMS					
-25-01	Clocks	C	2	1	
-31-01	Flight Data Recorder (FDR) System (Includes Digital Flight Data Acquisition Unit (DFDAU))				
-31-01A		C	-	1	Any in excess of those required by 14 CFR may be inoperative.
-31-01B		A	-	0	May be inoperative provided: a) Cockpit voice recorder (CVR) operates normally, b) Airplane is not dispatched from a designated airport as listed in operator's MEL unless: 1) FDR failure occurs after pushback but prior to takeoff, or 2) FDR repair was attempted but was not successful, c) In those cases where repair is attempted but not successful, aircraft may be dispatched on a flight or series of flights until next designated airport where repair must be accomplished prior to dispatch, and d) Repairs are made within 3 flight days.
-31-01-01	FDR Recording Parameters Required by 14 CFR	A	-	-	Up to three (3) recording parameters may be inoperative provided: a) Cockpit voice recorder (CVR) operates normally, and b) Repairs are made within 20 calendar days.

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	31-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
31 INDICATING/RECORDING SYSTEMS					
-31-01	Flight Data Recorder (FDR) System (Includes Digital Flight Data Acquisition Unit (DFDAU)) (Cont'd)				
-31-01-02	FDR Recording Parameters Not Required by 14 CFR	A	-	-	May be inoperative provided repairs are made prior to completion of next heavy maintenance visit.
-31-01-03	Quick Access Recorder (QAR)	D	1	0	
-35-01	Performance and Maintenance Recorder (PMR)	D	1	0	
-35-02	Airplane Integrated Data System (AIDS)	D	1	0	
-35-03	Aircraft Condition Monitoring System (ACMS)	D	1	0	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	31-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
31 INDICATING/RECORDING SYSTEMS						
-41-01 Engine Indication and Crew Alerting Systems (EICAS) (-200/-300)						
-41-01-01 Display Unit (DU)	A	2	2	1	(M)(O) Except for ER operations, one may be inoperative provided: a) Standby Engine Instruments operate normally and are turned ON, b) Cargo FIRE/OVHT test is performed before each departure, c) Electronic Engine Control or autothrottle system operates normally, d) At least one autopilot operates normally e) All EICAS computers operate normally, and f) Repairs or replacements are made within 1 flight day.	
-41-01-02 Computer	A	2	2	1	(M)(O) Except for ER operations, one may be inoperative provided: a) Standby engine Instruments operate normally and are turned ON, b) Electronic engine control or autothrottle system operates normally, c) At least one autopilot operates normally, d) SB 767-79-2 or equivalent (dual oil temperature sensors), is installed, e) Both display units operate normally, and f) Repairs or replacements are made within 1 flight day.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	31-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
31 INDICATING/RECORDING SYSTEMS						
-51-01	Master Caution/Warning Systems					
-51-01-01	Master Warning Lights (Pilot's Glare Shield)					
-51-01-01-01	-200/-300	C	2	1	One may be inoperative provided master warning aural system and all discrete warning lights operate normally.	
-51-01-01-02	-400ER	C	2	1	One may be inoperative provided master caution aural system operates normally.	
-51-01-02	Master Caution Lights (Pilot's Glare Shield)					
-51-01-02-01	-200/-300	C	2	1	One may be inoperative provided master caution aural system and all discrete caution lights operate normally.	
-51-01-02-02	-400ER	C	2	1	One may be inoperative provided master caution aural system operates normally.	
-51-02	Takeoff Configuration Check (T/O CHK) Switch					
-51-02A		C	1	0		
-51-02B		D	1	0	May be inoperative provided procedures do not require its use.	

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

31-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
31 INDICATING/RECORDING SYSTEMS					
-61-04	EICAS Status Messages				
-61-04A		C	-	0	(M)(O) May be inoperative provided associated equipment is verified to operate normally before each departure.
-61-04B		C	-	0	(M)(O) May be inoperative provided dispatch deviations for associated equipment are observed.
-61-05	EICAS Signal Consolidation Card (SCC)	C	1	0	(M) May be inoperative provided: a) Fuel quantity indication is verified to operate normally before each flight, and b) Dispatch deviations for associated equipment are observed.
-61-12	Head-Up Display (HUD)/Enhanced Flight Vision System (EFVS) (STC ST04174AT)				
-61-12-01	Head-Up Display (HUD) System				
-61-12-01A		C	1	0	(O) May be inoperative provided takeoff and approach minimums do not require its use. NOTE: Any mode that operates normally may be used.
-61-12-01B		D	1	0	May be inoperative provided procedures do not require its use. (Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 31-6
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
31 INDICATING/RECORDING SYSTEMS						
-61-12	Head-Up Display (HUD)/Enhanced Flight Vision System (EFVS) (STC ST04174AT) (Cont'd)					
-61-12-01	Head-Up Display (HUD) System (Cont'd)					
-61-12-01-01	HUD Normal/Declutter Functions (Control Wheel Switch)	C	1	0		
-61-12-01-02	HUD Guidance Annunciator					
-61-12-01-02A		C	1	0		(O) May be inoperative provided takeoff minimums do not require its use.
-61-12-01-02B		D	1	0		May be inoperative provided procedures do not require its use.
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

31-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
31 INDICATING/RECORDING SYSTEMS					
-61-12	Head-Up Display (HUD)/Enhanced Flight Vision System (EFVS) (STC ST04174AT) (Cont'd)				
-61-12-02	Enhanced Flight Vision System (EFVS)				
-61-12-02A		C	1	0	(O) May be inoperative provided takeoff and approach minimums do not require its use. Note: Any mode that operates normally may be used.
-61-12-02B		D	1	0	May be inoperative provided procedures do not require its use.
-61-12-02-01	EFVS Hide/Show Functions (Control Wheel Switch)	C	1	0	May be inoperative provided EFVS is considered inoperative.
-61-12-03	HUD Combiner Control Panel Functions				
-61-12-03-01	HUD Brightness Functions (BRT)	C	1	0	May be inoperative provided brightness is set at a usable level that is acceptable to affected crewmember.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 31-8
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
31 INDICATING/RECORDING SYSTEMS						
-61-12	Head-Up Display (HUD)/Enhanced Flight Vision System (EFVS) (STC ST04174AT) (Cont'd)					
-61-12-03	HUD Combiner Control Panel Functions (Cont'd)					
-61-12-03-02	HUD Automatic/Manual Brightness Functions (AUTO/MAN)	C	1	0		May be inoperative provided brightness is set at a usable level that is acceptable to affected crew member.
-61-12-03-02A		C	1	0		AUTO function may be inoperative provided MAN function operates normally.
-61-12-03-02B		C	1	0		MAN function may be inoperative provided AUTO function operates normally.
-61-12-03-03	EFVS Brightness/Contrast Functions (BRT/CONT)	C	1	0		May be inoperative provided brightness/contrast is set at a usable level that is acceptable to affected crew member.
-61-12-04	EFVS Window Heater	C	1	0		(O) May be inoperative provided takeoff and approach minimums do not require use of EFVS in known or forecast icing conditions.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

31-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
31 INDICATING/RECORDING SYSTEMS						
-63-01 Display Units (DU)						
-63-01-01						
-400ER	C	6	5	One may be inoperative in lower center DU position.		
-63-01-02						
Flat Panel Display (STC ST02165NY)						
-63-01-02A	C	4	3	Except for ER operations, one may be inoperative in Navigation Display (ND) position.		
-63-01-02B	B	4	3	For ER operations, one may be inoperative in Navigation Display (ND) position.		
-63-01-03						
Large Display System (STC ST01750WI)	B	3	2	Center may be inoperative provided left and right DU operate normally.		
-63-02 Control Panels						
-63-02-01						
EFIS Control Panels (-400ER)	C	2	1	(O) One may be inoperative provided associated CDU EFIS control functions are verified to operate normally.		
-63-02-02						
Flat Panel Display Control Panel (DCP) (STC ST02165NY)	C	2	1	(O) One may be inoperative provided all functions of operative DCP are verified to operate normally.		

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

31-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
31 INDICATING/RECORDING SYSTEMS					
-63-02	Control Panels (Cont'd)				
-63-02-03	Display Control Panels (DCP) (Large Display System STC ST01750WI)	A	2	1	(O) Right may be inoperative provided: a) Left DCP operates normally, b) DCP ALTN is selected using ND drop-down menu, c) Left DCP control functions are verified to operate normally for all operative DU, and d) Repairs are made within 2 flight days.
-63-02-03-01	Panel Lights	C	2	0	(O) May be inoperative provided: a) DCP switches are verified to operate normally, and b) DU operate normally.
-63-03	Display Select Panel Indicator Lights (-400ER)	C	3	0	(O) May be inoperative provided: a) Display Select Panel switches are verified to operate normally, and b) Display Units operate normally.
-63-04	Display Processing Computers (DPC)				
-63-04-01	-400ER	C	3	2	(M) Left or right may be inoperative deactivated.
-63-04-02	Large Display System (STC ST01750WI)	C	3	2	(M) Center or right may be inoperative deactivated.
-63-06	Display Control Unit Selector (DCU CTRL) (-400ER)	C	1	0	(M) May be inoperative provided: a) Selector is in AUTO position and not moved in flight, and b) Automatic source selection function is verified to operate normally.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

31-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
31 INDICATING/RECORDING SYSTEMS						
-63-07 Remote Light Sensor (RLS) System						
-63-07-01						
-400ER	C	1	0	0	May be inoperative provided all manual display brightness functions operate normally.	
-63-07-02						
Large Display System (STC ST01750WI)	C	1	0	0	May be inoperative provided all manual display brightness functions operate normally.	
-63-10 Data Concentrator Units						
-63-10-01						
Panel Data Concentrator Unit (PDCU) (-400ER)	C	2	1	1		
-63-10-02						
Flat Panel Display Data Concentrator Unit (DCU) (STC ST02165NY)						
-63-10-02A	C	3	2	2	(M) Except for ER operations, L, C, or R DCU may be inoperative provided DCU isolation is verified once each flight day.	
-63-10-02B	B	3	2	2	(M) For ER operations, L or R DCU may be inoperative provided DCU isolation is verified once each flight day.	
-63-11 Display Resource Faults (-400ER)	C	-	0	0	May be dispatched with faults indicated by DISPLAY RESOURCES status message provided all Display Processing Computers operate normally.	

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 31-12
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
			NUMBER INSTALLED		NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
31 INDICATING/RECORDING SYSTEMS					
-63-12	Display Dimming Panel (Large Display System STC ST01750WI)	C	2	0	(O) May be inoperative provided: a) Light intensity of DU is acceptable to flight crew for type and duration of operations, and b) Remote light sensor system function operates normally.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 32-1
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
32 LANDING GEAR						
-30-01	Landing Gear Actuation System	C	1	0	(M)(O) May be inoperative provided: a) Inoperative components are properly secured by an accepted procedure, and b) Airplane is dispatched in accordance with appropriate AFM Landing Gear Extended Appendix.	
-31-01	Landing Gear Lever Lock Solenoid	C	1	0	(M)(O) May be inoperative in latched position provided override mechanism is verified to operate normally.	
-31-02	Landing Gear Selector Valve Electrical Control Circuits (-400ER)	C	2	1	(M) One UP/DOWN electrical control circuit may be inoperative provided remaining UP/DOWN circuit is verified to operate normally once each flight day.	
-32-01	Main Gear Door Uplock Springs	B	4	3	(M)(O) One spring on one door uplock mechanism may be missing provided speed does not exceed 270 KIAS/0.82 Mach.	
-35-01	Landing Gear Alternate Extend System (-400ER)	C	1	0	(M)(O) May be inoperative provided: a) Landing gear are secured in down position, b) Alternate extend system is deactivated, and c) Airplane is dispatched in accordance with appropriate AFM Landing Gear Extended Appendix.	
-35-01-01	Alternate Extend Hydraulic Pressure Switch	B	1	0	(M)(O) May be inoperative open provided: a) Landing gear doors are verified to open using alternate extend system, and b) Alternate procedures are established and used.	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 32-2
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
32 LANDING GEAR						
-35-02	Ground Door Release Control System (-400ER)	C	1	0		(M) May be inoperative provided: a) Both door open control switches are verified to be open, b) Landing gear doors are verified to open using alternate extend system, and c) Landing gear doors are closed before each departure.
-35-02-01	Door Open Control Switches	C	2	0		(M)(O) May be inoperative closed provided: a) Landing gear are secured in down position, b) Alternate extend system is deactivated, and c) Airplane is dispatched in accordance with appropriate AFM Landing Gear Extended Appendix.
-41-01	Wheel Brakes					
-41-01A		C	8	7		(M)(O) One brake may be deactivated with a deactivation tool provided: a) Performance complies with AFM for one brake deactivated, and b) Antiskid operates normally on remaining wheels.
-41-01B		C	8	7		(M)(O) One brake may be deactivated by capping off brake line provided: a) Takeoff performance is based on landing gear extended, b) Takeoff and landing performance complies with AFM for one brake inoperative, c) After takeoff, gear remains extended for two minutes prior to retraction, and d) Antiskid operates normally on remaining wheels.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
32 LANDING GEAR					
-41-02	BRAKE SOURCE Indication System				
-41-02A		C	1	0	(M)(O) May be inoperative provided associated EICAS Advisory message is verified to operate normally.
-41-02B		B	1	0	(M) May be inoperative provided: a) C and R hydraulic low SYS PRESS lights operate normally, and b) Normal and alternate brake systems and brake accumulator are verified to operate normally.
-41-03	Gear Retraction Braking System	C	1	0	(O) May be inoperative provided: a) After takeoff, gear remains down for two minutes before retraction, and b) Takeoff performance is based on landing gear extended.
-42-01	Antiskid System	C	1	0	(M)(O) May be inoperative provided: a) AFM decrements are applied for antiskid inoperative operations, and b) Approach minimums do not require its use.
-42-01-01	Channels	C	8	7	(M)(O) One channel and associated brake may be inoperative (brake deactivated or line capped) provided: a) Brake is deactivated by an acceptable procedure, and b) AFM decrements are applied for selected procedure.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
32 LANDING GEAR					
-42-02	Alternate Antiskid Valves				
-42-02A		C	4	0	(M)(O) May be inoperative provided: a) Manual braking capability on alternate brake system is verified on associated wheels, and b) Normal antiskid system operates normally.
-42-02B		C	4	0	(M)(O) May be inoperative provided: a) Manual braking capability on alternate brake system is verified on associated wheels, and b) AFM decrements are applied for antiskid inoperative operations.
-42-03	ANTISKID Light				
-42-03A		C	1	0	(M) May be inoperative provided antiskid system is verified to operate normally.
-42-03B		C	1	0	(O) May be inoperative provided AFM decrements are applied for antiskid inoperative operations.
-42-04	Autobrake System				
-42-04-01	-200/-300				
-42-04-01A		C	1	0	May be inoperative provided: a) AUTO BRAKES light is not illuminated with autobrake switch OFF, and b) Approach minimums do not require its use.
(Continued)					

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
32 LANDING GEAR					
-42-04	Autobrake System (Cont'd)				
-42-04-01	-200/-300 (Cont'd)				
-42-04-01B		C	1	0	(M) May be inoperative with AUTO BRAKES light illuminated and autobrake switch OFF provided: a) Autobrake solenoid valve is verified closed, and b) Approach minimums do not require its use.
-42-04-01C		C	1	0	(M) May be inoperative with AUTO BRAKES light illuminated and autobrake switch OFF provided: a) Module is deactivated, and b) Approach minimums do not require its use.
-42-04-02	-400ER				
-42-04-02A		C	1	0	May be inoperative provided: a) AUTOBRAKES EICAS message is not annunciated with autobrake switch OFF, and b) Approach minimums do not require its use.
-42-04-02B		C	1	0	(M) May be inoperative with AUTOBRAKES EICAS message annunciated and autobrake switch OFF provided: a) Autobrake solenoid valve is verified closed, and b) Approach minimums do not require its use.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
32 LANDING GEAR					
-42-04	Autobrake System (Cont'd)				
-42-04-02	-400ER (Cont'd)				
-42-04-02C		C	1	0	(M) May be inoperative with AUTOBRAKES EICAS message annunciated and autobrake switch OFF provided: a) Module is deactivated, and b) Approach minimums do not require its use.
-42-05	Taxi Speed Indication ***	D	1	0	
-44-02	Parking Brake Valve	C	1	0	(M)(O) May be inoperative closed provided AFM performance decrements are applied for antiskid inoperative operations.
-44-03	Parking Brake Lights				
-44-03-01	PARK BRAKE Light (-200/-300)				
-44-03-01A		C	1	0	(M) May be inoperative provided: a) Parking brake valve operates normally, and b) Antiskid light is verified to operate normally once each flight day.
-44-03-01B		C	1	0	(O) May be inoperative provided AFM performance decrements are applied for antiskid inoperative operations.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
32 LANDING GEAR					
-44-03	Parking Brake Lights (Cont'd)				
-44-03-01	PARK BRAKE Light (-200/-300) (Cont'd)				
-44-03-01C		C	1	0	(O) May be inoperative provided EICAS Advisory message PARKING BRAKE is verified to operate normally.
-44-03-02	*** Nose Gear Parking Brake Status Indicator Lights (PARKING BRAKE SET/BRAKE ON/BRAKE OFF)				
-44-03-02A		C	-	0	(M)(O) May be inoperative provided alternate procedures are established and used.
-44-03-02B		D	-	0	May be inoperative provided procedures do not require its use.
-44-04	Brake Accumulator Pressure Gauge (Wheel Well)	C	1	0	May be inoperative provided associated flight deck indication operates normally.
-44-05	BRAKE PRESS Gauge (Flight Deck)	C	1	0	(M) May be inoperative provided: a) Brake accumulator charge is verified normal once each flight day, and b) Right low SYS PRESS light operates normally.
-45-01	*** Integral Tire Pressure Indicators	D	-	0	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
32 LANDING GEAR						
-45-02	Nose Wheel Spin Brakes (Snubbers)	C	2	0	(M) May be damaged or missing.	
-45-03 ***	Tire Pressure Indicating System (TPIS)	D	1	0		
-46-01 ***	Brake Temperature Monitoring System (BTMS)	D	1	0	NOTE: Brake cooling fans will be inoperative when all eight brake temperature readings are inoperative.	
-46-02 ***	Brake Cooling Fans					
-46-02-01	-200/-300	D	8	0	(O) May be inoperative provided AFM maximum quick turnaround weight penalty is observed.	
-46-02-02	-400ER	D	8	0	(M) May be inoperative provided associated fan shrouds are removed.	
-51-01	Rudder Pedal Nose Wheel Steering	B	1	0	(M)(O) May be inoperative provided: a) Approach minimums do not require its use, and b) All taxi, takeoffs and landings are made by a pilot with access to an operating tiller.	
-61-01	Landing Gear DOORS Light System (-200/-300)	C	1	0	(M) May be inoperative provided EICAS Advisory message GEAR DOORS is verified to operate normally.	

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
32	LANDING GEAR					
-61-02	Landing Gear Door Latch Proximity Sensor					
-61-02-01	System One	C	4	3	(M)(O) One may be inoperative provided: a) Appropriate performance adjustments are applied, and b) Remaining System One and all System Two sensors are verified to operate normally before each departure.	
-61-02-02	System Two (Passenger, -200PC/-200SF STC/-300BDSF)	C	4	3	(M)(O) One may be inoperative provided: a) Manual function of Passenger Notice System operates normally and procedures for its use are established and used, and b) All System One and remaining System Two sensors are verified to operate normally before each departure. NOTE: An inoperative System Two sensor will render Flight Deck Automatic Function of Passenger Notice System inoperative.	
-61-02-03	System Two (-200SF ATC/-300BCF/-300F)	C	4	3	(M) One may be inoperative provided all System One and remaining System Two sensors are verified to operate normally before each departure.	
-71-01	Tail Skid (-300/-400ER)	C	1	0	(M)(O) May be inoperative provided: a) Tail skid is secured in extended position, b) Water supplies associated with aft drain mast are secured OFF, and c) Appropriate performance adjustments are applied.	

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

32-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
32 LANDING GEAR					
-71-02	Tail Skid Indication System (-300/-400ER)				
-71-02A		C	1	0	May be inoperative provided tail skid retraction mechanism is inoperative.
-71-02B		C	1	0	(M) May be inoperative provided tail skid extend/retract function is verified to operate normally once each flight day.
-71-02C		C	1	0	(M)(O) May be inoperative provided: a) Tail skid is secured in extended position, b) Water supplies associated with aft drain mast are secured OFF, and c) Appropriate performance adjustments are applied.
-71-02-01	TAIL SKID Light (-300)	C	1	0	May be inoperative provided alternate indication operates normally.
-71-02-02	Proximity Switch System	C	1	0	(M) May be inoperative provided tail skid extend/retract function is verified to operate normally once each flight day.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	33-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-11-01	Flight Compartment and Instrument Lighting System	C	-	-	Individual lights may be inoperative provided: a) Remaining lighting system lights are sufficient to clearly illuminate all required instruments, controls, and other devices for which they are provided, b) Remaining lighting system lights are positioned so that direct rays are shielded from flight crewmembers eyes, and c) Lighting configuration and intensity is acceptable to flight crew. NOTE 1: Individual button/switch lights and/or annunciations/indications are excluded from this relief.
-11-01-01	Crew Entry Light (-200SF ATC/-300BCF/-300BDSF/-300F)	C	-	0	
-14-01 ***	Supernumerary Reading Lights	D	-	0	
-16-01	Master Dim and Test System				
-16-01-01	Test Function	C	1	0	(M) May be inoperative provided intended function of associated light(s) is verified.
-16-01-02	Dim Function	C	1	0	May be inoperative provided: a) BRT functions operate normally, and b) Light intensity is acceptable to flight crew for type and duration of operations.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
33 LIGHTS						
-20-01	Crew Rest Area Illumination System (STCs ST00973WI-D and ST02372AT)	C	-	-	May be inoperative provided remaining operative lighting is considered adequate by pilot in command.	
-20-01-01	Flashlight/Holder Assemblies	C	-	0	May be inoperative or missing provided crewmember in associated bunk has a flashlight of equivalent characteristics readily available.	
-20-02	Lower Lobe Crew Rest Illumination System					
-20-02-01	STC ST01994SE					
-20-02-01-01	Main Light	C	1	0	May be inoperative provided seat reading light operates normally.	
-20-02-01-02	Vestibule Light	C	1	0	May be inoperative provided main light operates normally.	
-20-02-01-03	Bunk Lights	C	5	-	May be inoperative provided associated bunk reading light operates normally.	
-20-02-01-04	Flashlight Holder/ Assembly	C	1	0	May be inoperative or missing provided crewmember in associated bunk has a flashlight of equivalent characteristics readily available.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 33-3
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-20-02	Lower Lobe Crew Rest Illumination System (Cont'd)				
-20-02-02	STC ST02137SE				
-20-02-02-01	Main Lights	C	3	2	One may be inoperative.
-20-02-02-02	Ladder Lights	C	4	2	Up to two lights may be inoperative provided they are not adjacent to each other.
-20-02-02-03	Bunk Lights	C	2	0	May be inoperative provided associated bunk reading light operates normally.
-20-02-02-04	Flashlight Holder/ Assembly	C	1	0	May be inoperative or missing provided crewmember in associated bunk has a flashlight of equivalent characteristics readily available.
-21-01	Cabin Interior Illumination System				
-21-01-01	Passenger Configurations with Non-Photoluminescent Emergency Escape Path Marking System	C	-	-	Individual lights may be inoperative provided: a) Sufficient lighting remains for crew members to perform their duties, and b) For night operations beyond 60 minutes of landing at a suitable airport, at least 75% of night lights operate normally.

(Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-21-01	Cabin Interior Illumination System (Cont'd)				
-21-01-02	Passenger Configurations with Photoluminescent Emergency Escape Path Marking System	C	-	-	Individual lights may be inoperative provided: <ul style="list-style-type: none"> a) Sufficient lighting remains for crew members to perform their duties, b) Minimum acceptable light levels specified in one of the following documents are maintained: <ul style="list-style-type: none"> 1) FAA engineering approval letter, 2) FAA approved report of Type Design holder, 3) Limitations and Conditions section of applicable Supplemental Type Certificate (STC), or 4) An FAA approved report incorporated in Master Drawing List for applicable STC, and c) For night operations beyond 60 minutes of landing at a suitable airport, at least 75% of night lights operate normally.
-22-10	Door Threshold Light (-200SF ATC/-300BCF/-300F)	C	1	0	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	33-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-24-01	Passenger Lighted Information Signs System (NO SMOKING/FASTEN SEAT BELT/ RETURN TO SEAT)				
-24-01A		C	-	-	(M) May be inoperative provided: a) Associated passenger seat or lavatory is not occupied from which a passenger lighted information sign is not readily legible, and b) Associated seat or lavatory must be blocked and placarded DO NOT OCCUPY.
-24-01B		C	-	-	(O) May be inoperative and associated passenger seat or lavatory may be occupied provided: a) PA system operates normally, and b) PA system is used to notify passengers and cabin crew when associated sign(s) are placed on or off.
-24-01C		C	-	0	(O) May be inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used.
-24-01-01	Aural Tone System	C	1	0	
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
33 LIGHTS						
-24-01	Passenger Lighted Information Signs System (NO SMOKING/FASTEN SEAT BELT/ RETURN TO SEAT) (Cont'd)					
-24-01-02	Flight Deck Automatic Function	C	-	0	(O) May be inoperative provided: a) Manual control function operates normally, and b) Alternate procedures are established and used.	
-24-02 ***	Supernumerary/ Courier Area Lighted Information Signs System (All Cargo Configuration)	C	-	-	(O) May be inoperative provided alternate procedures are established and used to notify couriers/supernumeraries when associated signs are placed on or off.	
-24-03	Lower Lobe Crew Rest No Smoking/ Fasten Seat Belt Signs (STCs ST01994SE and ST02137SE)	C	-	0	May be inoperative provided affected seat or bunk is placarded INOPERATIVE - DO NOT USE.	
-25-01 ***	Sterile Flight Compartment Light System					
-25-01A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-25-01B		D	1	0	May be inoperative provided procedures do not require its use.	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	33-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
33 LIGHTS						
-31-01	Main Wheel Well and Nose Wheel Well Service Area Lights	C	6	0		
-31-02 ***	Exterior Cargo Loading Area Lights	D	-	0		
-31-03	Service Lights				NOTE: Relief for the ECS bay, APU & tailcone area, and electrical equipment center service lights is moved to MMEL Item 25-20-1.	
-31-04	Electrical Equipment Center Lights				NOTE: Relief for the ECS bay, APU & tailcone area, and electrical equipment center service area lights is moved to MMEL Item 25-20-1.	
-37-01	Cargo Compartment Lights					
-37-01-01	Cockpit Entry Light (-200PC)	C	1	0		
-37-01-02	Cabin Entry Light (-200PC/-200SF STC/-200 with STCs ST01670AT-D and ST01433SE)	C	-	0		
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-37-01	Cargo Compartment Lights (Cont'd)				
-37-01-03	Main Deck Cargo Lights				
-37-01-03A		C	-	0	May be inoperative provided access to main cargo deck is prohibited in flight. NOTE: Main Cargo Deck is defined as area aft of rigid barrier or 9g net, as installed.
-37-01-03B		C	-	-	(O) May be inoperative provided: a) No two adjacent lights are inoperative, and b) Remaining illumination is adequate to perform required crew duties.
-37-01-03C		C	-	0	May be inoperative for hazardous materials designated CARGO AIRCRAFT ONLY provided main deck cargo compartment lights one position aft of hazardous material pallet/container position and forward to flight deck operate normally.
-37-01-04	Sill Lights	C	-	0	
-37-01-05	Lower Cargo Compartments	C	-	0	(O) May be inoperative provided procedures do not require their use.
-37-01-06	Light Lens	C	-	0	(M) May be broken/missing provided associated light is deactivated.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-37-02	Main Cargo Deck Crew Alerting System				
-37-02A		C	1	0	May be inoperative provided access to main cargo compartment is prohibited in flight.
-37-02B		C	1	0	(O) May be inoperative provided alternate procedures are established and used.
-41-01	Wing Illumination Lights	C	-	0	(O) May be inoperative provided ground de-icing procedures do not require their use.
-42-01	Landing Lights				
-42-01A		C	4	2	One nose gear and/or one wing mounted light may be inoperative.
-42-01B		C	4	0	May be inoperative for day operations.
-42-02	Taxi Lights ***	C	-	0	
-42-03	Runway Turnoff Lights	C	2	0	
-43-01	Position Lights (Bulbs)				
-43-01-01	-200/-300				
-43-01-01A		C	8	4	One stationary light on forward and aft tip of each wing may be inoperative.
-43-01-01B		C	8	0	May be inoperative for day operations.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-43-01	Position Lights (Bulbs) (Cont'd)				
-43-01-02	-300/-300F With Blended Winglets STC ST01920SE (LED Lights)				
-43-01-02-01	Forward Position Lights Module				
-43-01-02-01A		C	4	2	One stationary forward position light LED module on leading edge of each winglet may be inoperative.
-43-01-02-01B		C	4	0	May be inoperative for day operations.
-43-01-02-02	Aft Position Lights Module	C	2	0	May be inoperative for day operations.
-43-01-03	-400ER				
-43-01-03A		B	-	0	May be inoperative for day operations provided wing tip and tail cone white strobe lights operate normally.
-43-01-03B		C	-	3	The following may be inoperative provided all strobe lights operate normally: a) One stationary light on forward tip of each wing, and b) One stationary white bulb on tail cone.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-44-01	Anti-Collision Lights (Red Strobes/White Strobes)				
-44-01-01	-200/-300				
-44-01-01A		C	4	0	May be inoperative for day operations.
-44-01-01B		C	4	2	Upper and lower red fuselage strobe lights may be inoperative provided wing tip white strobe lights operate normally.
-44-01-01C		C	4	2	Wing tip white strobe lights may be inoperative provided upper and lower red fuselage strobe lights operate normally.
-44-01-02	-400ER				
-44-01-02A		B	5	0	May be inoperative for day operations provided all position lights operate normally.
-44-01-02B		C	5	3	Upper and lower red fuselage strobe lights may be inoperative provided wing tip and tail cone white strobe lights, and all position lights (bulbs) operate normally.
-44-01-02C		C	5	2	Wing tip and tail cone white strobe lights may be inoperative provided upper and lower red fuselage lights, and all position lights (bulbs) operate normally.
-45-01	Logo Lights	D	-	0	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	33-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-51-01	Interior Emergency Lighting System (Battery Powered)				
-51-01A		C	-	-	Light assemblies installed in ceiling above each main aisle may be inoperative provided no two adjacent (same aisle) light assemblies are inoperative
-51-01B		A	-	-	Lights/signs exclusively associated with one door, slide or emergency exit may be inoperative provided: a) Associated door, slide or emergency exit is considered inoperative, and b) Repairs are made within 1 flight day.
-51-01C		C	-	0	(O) May be inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used.
-51-01-01	Lower Lobe Crew Rest Emergency Lights (STCs ST01994SE and ST02137SE)	C	-	0	(M) May be inoperative provided: a) Lower lobe crew rest module is not used and personal items are removed, and b) Lower lobe crew rest door is closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest inspections by crewmembers.
-51-02	Exterior Emergency Lighting System (Battery Powered)	B	1	0	May be inoperative for day operations.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

33-13

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-51-03	Emergency Escape Path Marking System				
-51-03A		A	-	-	Lights/signs exclusively associated with one door, slide or emergency exit may be inoperative provided: a) Associated door, slide or emergency exit is considered inoperative, and b) Repairs are made within 1 flight day.
-51-03B		C	-	0	(O) May be inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used.
-51-03-01	Non-Photoluminescent Lighting System	C	-	-	Individual lights may be inoperative provided minimum acceptable lighting levels specified in one of the following documents are maintained: a) FAA engineering approval letter, b) FAA approved report of Type Design holder, c) Limitations and Conditions section of applicable Supplemental Type Certificate (STC), or d) An FAA approved report incorporated in Master Drawing List for applicable STC.

(Continued)

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	33-14

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
33 LIGHTS					
-51-03	Emergency Escape Path Marking System (Cont'd)				
-51-03-02	Photoluminescent Lighting System	C	-	-	Components may be inoperative provided minimum acceptable lighting levels specified in one of the following documents are maintained: a) FAA engineering approval letter, b) FAA approved report of Type Design holder, c) Limitations and Conditions section of applicable Supplemental Type Certificate (STC), or d) An FAA approved report incorporated in Master Drawing List for applicable STC.
-51-04	PowerSmart Wireless Emergency Primary Power System (WEPPS) Diagnostic Panel (STC ST03629AT)	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used to ensure 10 minutes of ON time does not occur, b) Affected emergency lights are verified to operate normally prior to first flight of each day, and c) Repairs are made within 10 flight days.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-1

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
34 NAVIGATION				
-00-01 Instrument Source Select Switches				
-00-01-01 -200/-300				
-00-01-01A	C	-	-	(O) Except for ER operations, may be inoperative provided: a) Associated instruments operate from isolated sources, and b) Inoperative switches are not moved in flight.
-00-01-01B	C	-	-	(O) May be inoperative provided: a) Associated instruments operate from isolated sources, b) Inoperative switches are not moved in flight, and c) At least one FMC, EFI, and IRS switch must operate normally.
-00-01-02 -400ER				
-00-01-02A	C	-	-	Except for ER operations, may be inoperative provided: a) Associated instruments operate from isolated sources, and b) Inoperative switches are not moved in flight.
-00-01-02B	C	-	-	(O) May be inoperative provided: a) Associated instruments operate from isolated sources, b) Inoperative switches are not moved in flight, and c) At least one FMC and IRS switch must operate normally.
				(Continued)

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
34 NAVIGATION						
-00-01	Instrument Source Select Switches (Cont'd)					
-00-01-03	Flat Panel Display STC ST02165NY	C	-	-	(O) May be inoperative provided:	<ul style="list-style-type: none"> a) Associated instruments operate from isolated sources, b) Inoperative switches are not moved in flight, and c) For ER operations, at least one FMC, EFI, IRS and DCP switch must operate normally.
-00-01-04	Large Display System (STC ST01750WI)					
-00-01-04A		C	-	-	(O) Except for ER operations, may be inoperative provided:	<ul style="list-style-type: none"> a) Associated instruments operate from isolated sources, and b) Inoperative switches are not moved in flight.
-00-01-04B		C	-	-	(O) May be inoperative provided:	<ul style="list-style-type: none"> a) Associated instruments operate from isolated sources, b) Inoperative switches are not moved in flight, and c) At least one FMC, ILS/RAD ALT, IRS and AIR DATA switch must operate normally.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	34-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
34 NAVIGATION					
-13-01 ***	MACH/Airspeed Indicators				
	-13-01-01 Mach Indicators				
	-13-01-01A	C	2	1	
	-13-01-01B	C	2	0	May be inoperative provided EFIS Mach indications are installed and operating normally at associated pilot's station.
	-13-01-01C	C	2	0	May be inoperative provided: a) Airplane remains at or below FL 300, and b) A placard with this limitation is affixed to instrument panel.
	-13-01-02 Command Airspeed Cursors	C	2	0	
	-13-01-03 Airspeed Indicators	C	2	0	May be inoperative provided EFIS airspeed indications are installed and operating normally at associated pilot's station.
	-13-01-04 External Airspeed Markers (Bugs)	C	-	0	(O) May be inoperative or missing provided alternate procedures are established and used.
	-13-02 Mach/Airspeed Warning Systems (Visual and Aural)	B	2	1	
	-13-06 Standby Altimeter Vibrator	C	1	0	May be inoperative provided VMC exists at departure and arrival airports.
	-13-07 Total Air Temperature (TAT) Indication				Deleted, MMEL Rev. 36.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-13-08 ***	Static Air Temperature (SAT) Indicator (Center Panel)	D	1	0	
-13-09 ***	True Airspeed (TAS) Indicator (Center Panel)	D	1	0	
-13-10 ***	Speed Command (Fast-Slow) Indicators	C	2	0	
-16-01	Altitude Alerting System	A	1	0	(O) May be inoperative provided: a) Autopilot with altitude hold and altitude capture operates normally, b) Enroute operations do not require its use, c) Airplane does not depart from a designated airport (as listed in operator's MEL) where repair or replacement can be made, and d) Repairs are made within 3 flight days.
-16-01-01	Aural Alert	C	-	0	May be inoperative provided: a) Visual alert operates normally, and b) Autopilot with altitude hold and altitude capture operates normally.
-16-01-02	Visual Alert	C	-	0	May be inoperative provided: a) Aural alert operates normally, and b) Autopilot with altitude hold and altitude capture operates normally.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-21-01	Inertial Reference Systems (IRS)				
-21-01-01	IRU (-200/-300)				
-21-01-01-01	Without Hydraulic Motor Generator (HMG) Installed				
-21-01-01-01A		C	3	2	(M)(O) Left may be inoperative provided: a) Approach minimums do not require its use, and b) Center is selected and isolation is verified once each flight day.
-21-01-01-01B		C	3	2	(M)(O) Right may be inoperative for day VMC flight provided center is selected and isolation is verified once each flight day.
-21-01-01-01C		C	3	2	Center may be inoperative provided approach minimums do not require its use.
-21-01-01-02	With Hydraulic Motor Generator (HMG) Installed				
-21-01-01-02A		C	3	2	(M)(O) Except for ER operations, left or right may be inoperative provided: a) Approach minimums do not require its use, b) Center is selected and isolation is verified once each flight day, and c) First officer's IRS instrument source select switch operates normally.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	34-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	3. NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-21-01	Inertial Reference Systems (IRS) (Cont'd)				
-21-01-01	IRU (-200/-300) (Cont'd)				
-21-01-01-02	With Hydraulic Motor Generator (HMG) Installed (Cont'd)				
-21-01-01-02B		C	3	2	(M)(O) Right may be inoperative provided: a) Approach minimums do not require its use, b) Center is selected and isolation is verified once each flight day, and c) First officer's IRS instrument source select switch operates normally.
-21-01-01-02C		C	3	2	Center may be inoperative for day VMC flight.
-21-01-02	*** ADIRU Inertial Reference Function				
-21-01-02A		C	3	2	(M)(O) Left or right may be inoperative provided: a) Approach minimums do not require its use, and b) Center is selected and isolation is verified once each flight day.
-21-01-02B		C	3	2	Center may be inoperative provided approach minimums do not require its use.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-21-01	Inertial Reference Systems (IRS) (Cont'd)				
-21-01-03	*** IRS Mode Selector Panel - Display and Keyboard Functions				
-21-01-03A		C	-	0	May be inoperative provided both FMCS CDUs operate normally.
-21-01-03B		C	-	0	Except for ER operations, may be inoperative provided one FMCS CDU operates normally.
-22-03	Radio Distance Magnetic Indicators (RDMI) (-200/-300)				
-22-03A		C	2	1	Right may be inoperative.
-22-03B		C	2	1	Left may be inoperative provided flight is restricted to day VMC.
-22-03C		C	2	0	May be inoperative provided standby power system powers captain's instrument bus.
-22-03-01	*** Independent ADF Radio Magnetic Indicators (RMI) (-200/-300)				
-22-03-01A		C	2	0	May be inoperative provided associated EHSI ADF bearing pointer operates normally.

(Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	34-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-22-03	Radio Distance Magnetic Indicators (RDMI) (-200/-300) (Cont'd)				
-22-03-01	*** Independent ADF Radio Magnetic Indicators (RMI) (-200/-300) (Cont'd)				
-22-03-01B		C	2	0	May be inoperative provided associated radio compass ADF system is considered inoperative.
-22-04	Flight Director Systems	C	3	0	May be inoperative provided approach minimums do not require their use.
-22-04-01	Displays	C	2	0	May be inoperative provided approach minimums do not require their use. NOTE: Windshear guidance may be unavailable.
-22-05	Electronic Flight Instrument (EFIS) Symbol Generators (-200/ -300)				
-22-05A		C	3	2	(M) Except for ER operations, one may be inoperative provided symbol generator isolation is verified once each flight day.
-22-05B		C	3	2	(M) Left or right may be inoperative provided symbol generator isolation is verified once each flight day.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	34-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34 NAVIGATION						
-22-06	EFIS Controls					
-22-06-01	*** Switches (NAV AID/ARPT/RTE DATA/WPT/WXR/TERR) (-200/-300)	C	-	-	One switch for each function may be inoperative provided procedures do not require its use.	
-22-06-02	Switches (WXR/STAWPT/ARPT/DATA/POS/TERR) (-400ER)	C	14	0		
-22-06-03	Switches (NAV AID/ARPT/RTE DATA/WPT/WXR/TER) (Flat Panel Display STC ST02165NY)	C	10	5	One switch for each function may be inoperative provided procedures do not require its use.	
-22-06-04	Switches (WXR/TFC/TERR) (Large Display System STC ST01750WI)	B	6	3	One switch for each function may be inoperative provided procedures do not require its use.	
-22-06-05	MODE/MENU Knob (Large Display System STC ST01750WI)	A	2	1	(O) Right may be inoperative provided: a) DCP ALTN is selected using ND drop-down menu, b) Left DCP MODE/MENU knob is verified to control mode functions on all operative DU, and c) Repairs are made within 2 flight days.	
(Continued)						

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	34-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
34 NAVIGATION					
-22-06	EFIS Controls (Cont'd)				
-22-06-06	RANGE Knob (Large Display System STC ST01750WI)	B	2	1	(O) Right may be inoperative provided: a) DCP ALTN is selected using ND drop-down menu, and b) Left DCP RANGE knob is verified to control range functions on all operative DU.
-22-06-07	BAROSET Knob (Large Display System STC ST01750WI)	A	2	1	(O) Right may be inoperative provided: a) DCP ALTN is selected using ND drop-down menu, b) Left DCP BAROSET knob is verified to control altitude barometric setting on all operative DU, and c) Repairs are made within 2 flight days.
-22-06-08	Decision Height Indication (DH REF) (Airplanes without PFD)	C	2	0	May be inoperative provided approach procedures do not require its use. NOTE: Flight crew use EADI DH indication.
-22-06-08-01	Without Radio Altitude Indicators (Tape) Installed	C	2	0	May be inoperative. NOTE: Flight crew use EADI DH indication.
-22-06-08-02	*** With Radio Altitude Indicators (Tape) Installed	C	2	0	May be inoperative provided radio altitude indicators (tape) are installed and operate normally. NOTE: Flight crew use EADI DH indication.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-22-06	EFIS Controls (Cont'd)				
-22-06-09	HSI Selector				
-22-06-09-01	MAP Position	B	2	1	(O) May be inoperative provided: a) Both FMCs operate normally, and b) Alternate procedures are established and used.
-22-06-09-02	PLAN Position	B	2	1	(O) May be inoperative provided: a) Both FMCs operate normally, and b) Alternate procedures are established and used.
-22-06-10	HSI Range Selector	C	2	1	May be inoperative provided both FMCs operate normally.
-22-07 ***	EFIS Speed Tape (-200/-300)				
-22-07-01	Mach Indications				
-22-07-01A		C	2	1	
-22-07-01B		C	2	0	May be inoperative provided MACH indicators are installed and operating normally at associated pilot's station.
-22-07-01C		C	2	0	May be inoperative provided: a) Airplane remains at or below FL 300, and b) A placard with this limitation is affixed to instrument panel.
(Continued)					

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-22-07 ***	EFIS Speed Tape (-200/-300)				
-22-07-02	Airspeed Indications	C	2	0	May be inoperative provided airspeed indicators are installed and operating normally at associated pilot's station.
-22-08	Pitch Limit Indicators	C	2	0	
-22-30	Heading Reference (HDG REF) Switch				
-22-30-01	TRUE Function	C	1	0	(O) May be inoperative provided enroute procedures do not require its use.
-23-01	Magnetic Compass (Standby)				
-23-01A		B	1	0	May be inoperative provided any combination of three gyro or INS (IRS) stabilized compass systems operate normally.
-23-01B		B	1	0	(O) May be inoperative provided: a) Any combination of two gyro or INS (IRS) stabilized compass systems operate normally, and b) Airplane is operated with dual independent navigation capability and under positive radar control by ATC on enroute portion of flight.
-23-01C		C	1	0	(O) May be inoperative for flights that are entirely within areas of magnetic unreliability provided at least two stabilized directional gyro systems are installed, operative, and used in conjunction with approved free gyro navigation techniques.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-13

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34 NAVIGATION						
-24-01	Standby Attitude/ILS Indicator					
-24-01-01	Attitude Display	B	1	0	May be inoperative provided: a) Operations are conducted in day VMC only, and b) Operations are not conducted into known or forecast over-the-top conditions.	
-24-01-02	Approach Mode	C	1	0		
-24-02 ***	Integrated Standby Flight Display (ISFD) System					
-24-02-01	Attitude Display	B	1	0	May be inoperative provided: a) Operations are conducted in day VMC only, and b) Operations are not conducted into known or forecast over-the-top conditions.	
-24-02-02	Approach Mode	C	1	0		
-24-02-03	Heading Display	C	1	0		
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-14

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34 NAVIGATION						
-24-02 ***	Integrated Standby Flight Display (ISFD) System (Cont'd)					
-24-02-04	Metric Altimeter Display					
-24-02-04A		C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-24-02-04B		D	1	0	May be inoperative provided procedures do not require its use.	
-24-02-05	Dedicated Battery/Charger System	C	1	0	Except for ER operations beyond 120 minutes, may be inoperative	
-24-03 ***	Electronic/Integrated Standby Instrument System (ESIS/ISIS) (STC ST02165NY)					
-24-03-01	Attitude Display	B	1	0	May be inoperative provided: a) Operations are conducted in day VMC only, and b) Operations are not conducted into known or forecast over-the-top conditions.	
-24-03-02 ***	Approach Mode	C	1	0		
-24-03-03	Heading Display	C	1	0		
-25-01 ***	Instrument Comparator Unit	D	1	0		

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	34-15

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34 NAVIGATION						
-26-01 ***	Air Data Inertial Reference System (ADIRU)					
-26-01-01	Left and Right Air Data System	C	2	1	(M)(O) One may be inoperative provided: a) Center air data is selected and operates normally, b) Center ADIRU inertial reference function is not selected OFF, and c) Air data isolation is verified.	
-26-01-02	Center Air Data System	D	1	0		
-31-01	ILS Systems	C	3	-	Any in excess of those required by 14 CFR, and not powered by a standby bus, may be inoperative.	
-32-01	Marker Beacon System	C	1	0	May be inoperative provided approach minimums do not require its use.	
-33-01	Radio Altimeter (RA) Systems (EADI)					
-33-01-01	Single Source Datalink to GPWS					
-33-01-01-01	Left RA	A	1	0	(O) May be inoperative provided: a) Approach minimums or operating procedures do not require its use, and b) Repairs are made within 2 flight days.	
-33-01-01-02	Center/Right RA	C	2	0	(O) May be inoperative provided approach minimums or operating procedures do not require its use. (Continued)	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-16

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-33-01	Radio Altimeter (RA) Systems (EADI) (Cont'd)				
-33-01-02	Multi-source Datalink to GPWS				
-33-01-02A		C	3	1	(O) May be inoperative provided: a) GPWS is supplied with altitude data, and b) Approach minimums or operating procedures do not require its use.
-33-01-02B		A	3	0	(O) May be inoperative provided: a) Approach minimums or operating procedures do not require its use, and b) Repairs are made within 2 flight days.
-33-02 ***	Radio Altitude Indicators (Altitude Tape)	D	2	0	(O) May be inoperative provided approach minimums or operating procedures do not require their use.
-35-01 ***	Para Visual Displays	D	2	0	May be inoperative provided procedures do not require their use.
-40-01 ***	Metric Altimeter (Includes IS&S 9D-80110-24 Metric/ English Altimeter)	D	-	0	May be inoperative provided operations do not require its use.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-17

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
34 NAVIGATION					
-43-01	Weather Radar Systems	D	2	1	
-43-01-01	With Windshear Alert Mode (Predictive) Installed				
-43-01-01A		B	-	0	(O) May be inoperative provided: a) Weather radar is not required by 14 CFR, and b) Alternate procedures are established and used.
					NOTE: Operator's alternate procedures should include reviewing windshear avoidance and windshear recovery procedures.
-43-01-01B		C	-	0	(O) May be inoperative provided: a) Weather radar is not required by 14 CFR, b) Alternate procedures are established and used, and c) Windshear warning and guidance system (reactive) operates normally.
-43-01-02	Without Windshear Alert Mode (Predictive) Installed	C	-	0	May be inoperative provided weather radar is not required by 14 CFR.
-43-01-03	*** Indicators	D	-	-	Any in excess of those required by 14 CFR may be inoperative.
-43-01-04	*** Autotilt/Multiscan Function	C	1	0	May be inoperative provided manual tilt function operates normally.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 34-18
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
34 NAVIGATION							
-43-01	Weather Radar Systems (Cont'd)						
-43-01-05	*** WXR ON Light	D	2	0		(O) May be inoperative provided alternate procedures are established and used.	
-43-01-06	*** GAIN UCAL Light/ BELOW CAL Lamp	D	-	-			
-43-01-07	*** Windshear Alert Mode (Predictive)						
-43-01-07A		B	-	0		(O) May be inoperative provided alternate procedures are established and used.	
						NOTE: Operator's alternate procedures should include reviewing windshear avoidance and windshear recovery procedures.	
-43-01-07B		C	-	0		(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Windshear warning and guidance system (reactive) operates normally.	
-45-01	Traffic Collision and Avoidance System (TCAS)						
-45-01A		B	-	0		(M) May be inoperative provided: a) System is deactivated and secured, and b) Enroute or approach procedures do not require its use.	
							(Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-19

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34	NAVIGATION					
-45-01	Traffic Collision and Avoidance System (TCAS) (Cont'd)					
-45-01B		C	-	0	(M) May be inoperative provided: a) Not required by 14 CFR, b) System is deactivated and secured, and c) Enroute or approach procedures do not require its use.	
-45-01-01	*** Combined Traffic Alert (TA) and Resolution Advisory (RA) Dual Display System(s)	C	2	1	May be inoperative on non-flying pilot side provided: a) TA and RA visual display operates normally on flying pilot side, and b) TA and RA audio function operates normally on flying pilot side.	
-45-01-02	Resolution Advisory (RA) Display System(s)					
-45-01-02A		C	2	1	May be inoperative on non-flying pilot side.	
-45-01-02B		C	-	0	(O) May be inoperative provided: a) Traffic Alert (TA) visual display and audio functions operate normally, b) TA only mode is selected by crew, and c) Enroute or approach procedures do not require its use.	
-45-01-03	Traffic Alert (TA) Display System(s)	C	-	0	(O) May be inoperative provided: a) RA visual display and audio functions operate normally, and b) Enroute or approach procedures do not require its use.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-20

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-45-01	Traffic Collision and Avoidance System (TCAS) (Cont'd)				
-45-01-04	Audio Functions	B	1	0	May be inoperative provided enroute or approach procedures do not require use of TCAS.
-45-01-05	*** Airspace Selection Function	C	-	0	
-46-01	Ground Proximity Warning System (GPWS)	A	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight days.
-46-01-01	Modes 1-4	A	4	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Repairs are made within 2 flight days.
-46-01-02	Test Mode	A	1	0	May be inoperative provided: a) GPWS is considered inoperative, and b) Repairs are made within 2 flight days.
-46-01-03	Glideslope Deviation (Mode 5)	B	1	0	
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-21

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-46-01	Ground Proximity Warning System (GPWS) (Cont'd)				
-46-01-04	Advisory Callouts (Mode 6)				
-46-01-04A		B	-	0	(O) May be inoperative provided alternate procedures are established and used.
-46-01-04B		C	-	0	(O) May be inoperative provided: a) Advisory callout not required by 14 CFR, and b) Alternate procedures are established and used.
-46-01-05	*** Windshear Alert Mode (Reactive) (Mode 7)				
-46-01-05A		B	1	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Operator's alternate procedures should include reviewing windshear avoidance and windshear recovery procedures.
-46-01-05B		C	1	0	(O) May be inoperative provided: a) Alternate procedures are established and used, and b) Windshear detection and avoidance system (predictive) operates normally.
-46-01-06	Terrain Awareness Function	B	1	0	(O) May be inoperative provided alternate procedures are established and used.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-22

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-46-01	Ground Proximity Warning System (GPWS) (Cont'd)				
-46-01-07	Terrain Displays				
-46-01-07A		C	-	1	
-46-01-07B		B	-	0	
-46-01-08					
***	Runway Awareness & Advisory System (RAAS)	C	1	0	
-51-01	VOR Navigation Systems	D	2	-	Any in excess of those required by 14 CFR, and not powered by a standby bus, may be inoperative.
-53-01	ATC Transponders and Automatic Altitude Reporting Systems				
-53-01A		B	-	0	May be inoperative provided: a) Operations do not require its use, and b) Prior to flight, approval is obtained from ATC facilities having jurisdiction over planned route of flight.
-53-01B		D	-	1	Any in excess of those required by 14 CFR may be inoperative.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-23

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34	NAVIGATION					
-53-01	ATC Transponders and Automatic Altitude Reporting Systems (Cont'd)					
-53-01-01	Elementary and Enhanced Downlink Aircraft Reportable Parameters not Required by 14 CFR	A	-	0	May be inoperative provided: a) Operations do not require its use, and b) Repairs are made prior to completion of next heavy maintenance visit.	
-53-01-02	*** ADS-B Squitter Transmissions					
-53-01-02A		C	2	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any ADS-B Out function that operates normally may be used.	
-53-01-02B		D	2	0	May be inoperative provided operations do not require its use.	
-55-01	Distance Measuring Equipment Systems	D	2	-	Any in excess of those required by 14 CFR may be inoperative.	
-57-01	Radio Compass (ADF) Systems	D	-	-	Any in excess of those required by 14 CFR may be inoperative.	

AIRCRAFT:	REVISION NO: 37	PAGE:
BOEING B-767	DATE: 03/27/2015	34-24

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			
		NUMBER REQUIRED FOR DISPATCH			
		REMARKS OR EXCEPTIONS			
34 NAVIGATION					
-58-01 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) System	D	-	0	May be inoperative provided it is not required by 14 CFR. NOTE: If ADS-B is installed in lieu of or as a replacement for 14 CFR required equipment, repair category in operator's MEL will be same as that of 14 CFR required equipment.
-58-01-01	Link and Display Processor Unit (LDPU)	D	-	0	
-58-01-02	Cockpit Display and Traffic Information (CDTI)	D	-	0	NOTE: Cockpit Display Traffic Information (CDTI) display of data from other aircraft systems may be used.
-58-01-03	CDTI Control Panel	D	-	0	May be inoperative provided: a) Flight ID can be set, and b) Screen display is acceptable to flight crew.
-58-01-04	Data Link Transmitter(s)	D	-	0	NOTE: In some aircraft data link transmission is an integral part of transponder and relief is provided in that section.
-58-01-05	Data Link Receiver(s)	D	-	0	
-58-01-06	ADS-B Applications	D	-	0	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-25

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34 NAVIGATION						
-58-02	ACSS Surveillance Processor (STC ST02126LA)	B	1	0	(M) May be inoperative provided: a) Automatic Dependent Surveillance-Broadcast (ADS-B) is considered inoperative, and b) TCAS is considered inoperative.	
-58-02-01 ***	Automatic Dependent Surveillance-Broadcast (ADS-B) Functionality	D	1	0	May be inoperative provided: a) It is not required by 14 CFR, b) Procedures do not require its use, and c) Merging & Spacing and CAVS operations are prohibited. NOTE: If ADS-B is installed in lieu of or as a replacement for 14 CFR required equipment, repair category in operator's MEL will be same as that of 14 CFR required equipment.	
-58-02-01-01	Cockpit Display of Traffic Information (CDTI) Functionality	D	1	0	May be inoperative provided: a) Procedures do not require its use, and b) Merging & Spacing and CAVS operations are prohibited. NOTE: ADS-B data transmissions may continue.	
-58-02-01-02	ADS-B Guidance Display (AGD)	D	1	0	May be inoperative provided: a) Procedures do not require its use, and b) Merging & Spacing and CAVS operations are prohibited.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	34-26

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
34	NAVIGATION				
-60-03 ***	Global Positioning Systems (GPS)				
-60-03A		C	2	0	May be inoperative provided: a) Enroute operations do not require their use, and b) IRUs operate normally.
-60-03B		D	2	1	One may be inoperative provided enroute operations do not require its use.
-60-03-01	ACSS Surveillance Processor (STC ST02126LA)	D	2	0	May be inoperative provided: a) Procedures do not require its use, and b) Merging & Spacing and CAVS operations are prohibited
-61-01	Flight Management Computer Systems (FMCS)				
-61-01-01	FMC (Including CDU/HMCDU/MCDU) (-200/-300)				
-61-01-01A		C	2	1	(M)(O) Except for ER operations, one may be inoperative provided enroute operations do not require its use.
-61-01-01B		C	2	0	(M)(O) Except for ER operations, may be inoperative provided: a) Both Fuel Quantity Indicating System (FQIS) processor channels are verified to operate normally, b) All flight deck fuel quantity indications operate normally, and c) Enroute operations do not require its use.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

34-27

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
34 NAVIGATION						
-61-01	Flight Management Computer Systems (FMCS) (Cont'd)					
-61-01-01	FMC (Including CDU/HMCDU/MCDU) (200/-300) (Cont'd)					
-61-01-01C		C	2	1	(M)(O) For long-range navigation operation, one FMC may be inoperative provided other approved means of navigation is available. NOTE: An associated HMCDU or MCDU, if operative, may be used to meet navigation requirements.	
-61-01-02	FMC (-400ER)	C	2	1	(M)(O) One may be inoperative provided enroute operations do not require its use.	
-61-01-03	Center MCDU (-400ER)	C	1	0		
-61-01-04	FMC MCDU (Large Display System STC ST01750WI)	C	2	1	(O) Except for ER operations, right may be inoperative provided enroute operations do not require its use. (Continued)	

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 34-28
----------------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
34 NAVIGATION						
-61-01	Flight Management Computer Systems (FMCS) (Cont'd)					
-61-01-05	Navigation Databases	C	-	-		(O) May be out of currency provided: a) Current aeronautical charts are used to verify navigation fixes prior to dispatch, b) Procedures are established and used to verify status and suitability of navigation facilities used to define route of flight, and c) Approach navigation radios are manually tuned and identified.
-61-01-06	FMC Annunciator Light (-200/-300)	C	1	0		(M) May be inoperative provided CDU MSG light and EICAS advisory message FMC MESSAGE are verified to operate normally.
-61-03	ACSS Surveillance Processor TCAS Functionality (STC ST02126LA)					
-61-03A		B	-	0		(O) May be inoperative provided: a) Function is secured according to an approved procedure, and b) Enroute or approach procedures do not require its use.
-61-03B		C	-	0		(O) May be inoperative provided: a) Not required by 14 CFR, b) Function is secured according to an approved procedure, and c) Enroute or approach procedures do not require its use.
(Continued)						

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	34-29

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
34 NAVIGATION					
-61-03	ACSS Surveillance Processor TCAS Functionality (STC ST02126LA) (Cont'd)				
-61-03-01	Resolution Advisory (RA) Display System(s)				
-61-03-01A		C	2	1	May be inoperative on non-flying pilot side.
-61-03-01B		C	2	0	(O) May be inoperative provided: a) Traffic Alert (TA) visual display and audio functions operate normally, b) TA only mode is selected by crew, and c) Enroute or approach procedures do not require its use.
-61-03-02	Traffic Alert (TA) Display System	C	1	0	(O) May be inoperative provided: a) RA visual display and audio functions operate normally, and b) Enroute or approach procedures do not require its use.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

35-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
35 OXYGEN					
-11-02	Crew Oxygen System				
-11-02-01	Pressure Indication (EICAS)	B	1	0	(M) May be inoperative provided oxygen supply is verified to be above minimum required before each departure.
-11-02-02	Cylinder Gages				
-11-02-02-01	One Cylinder System	C	1	0	May be inoperative provided pressure indication (EICAS) operates normally.
-11-02-02-02	Two Cylinder System	C	2	0	(M) May be inoperative provided pressure indication (EICAS) operates normally.
-11-02-02-03	Three Cylinder System	C	3	0	(M) May be inoperative provided pressure indication (EICAS) operates normally.
-11-02-03	Supernumerary Oxygen Masks				
-11-02-03A		C	-	0	May be inoperative provided associated seat is not occupied.
-11-02-03B		C	-	0	May be inoperative provided flight is not conducted above 10,000 feet MSL.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

35-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
35 OXYGEN					
-11-02	Crew Oxygen System (Cont'd)				
-11-02-04	Pressure Regulators				
-11-02-04-01	Two Cylinder System	C	2	1	(M) May be inoperative provided: a) Line to inoperative pressure regulator is disconnected and plugged, b) Cylinder gage on remaining cylinder operates normally, and c) Oxygen supply is verified to be above minimum required before each departure.
-11-02-04-02	Three Cylinder System	C	3	1	(M) May be inoperative provided: a) Line to inoperative pressure regulator(s) is disconnected and plugged, b) Cylinder gage on remaining cylinder operates normally, and c) Oxygen supply is verified to be above minimum required before each departure.
-11-02-05	Overboard Discharge Indicator Discs	C	-	0	(O) May be damaged or missing.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

35-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
35	OXYGEN				
-11-02	Crew Oxygen System (Cont'd)				
-11-02-06	Crew Cylinder Pressure Regulator (-200SF STC/300BDSF)	C	1	0	(M) May be inoperative provided: <ul style="list-style-type: none"> a) One way interconnect line from supernumerary system is installed and operates normally, b) Pressure regulator on supernumerary cylinder operates normally. c) Line to inoperative pressure regulator is disconnected and plugged, d) Cylinder gage on supernumerary cylinder operates normally, e) Oxygen supply is verified to be above minimum required before each departure, and f) All supernumerary area seats are not occupied.
-11-03	Supernumerary Oxygen System (-200SF STC/-300BDSF)	C	1	0	May be inoperative provided supernumerary seats are not occupied.
-11-03-01	Pressure Indication				
-11-03-01-01	EICAS	B	1	0	(M) May be inoperative provided oxygen supply is verified to be above minimum required before each departure.
-11-03-01-02	Cylinder Gage	C	1	0	May be inoperative provided EICAS pressure indication operates normally.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

35-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
35 OXYGEN					
-11-03	Supernumerary Oxygen System (-200SF STC and -300BDSF) (Cont'd)				
-11-03-02	Oxygen Masks				
-11-03-02A		C	-	0	May be inoperative provided associated seat is not occupied.
-11-03-02B		C	-	0	May be inoperative provided flight is not conducted above 10,000 feet MSL.
-11-03-03	Pressure Regulator	C	1	0	May be inoperative provided supernumerary seats are not occupied.
-20-01	PBE Smoke Hoods	D	-	-	Any in excess of those required by 14 CFR may be inoperative or removed provided location placarding is removed or obscured.
-21-01	Passenger Oxygen System				
-21-01A		B	1	0	(O) May be inoperative provided: a) Flight is not conducted where minimum enroute altitude is above 14,000 feet MSL, b) Both air conditioning packs operate normally, c) All other components of pressurization system operate normally, d) Airplane remains at or below FL 250, e) Portable oxygen units are provided for 10% of passengers, and f) Passengers are appropriately briefed.

(Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

35-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
35 OXYGEN					
-21-01	Passenger Oxygen System (Cont'd)				
-21-01B		B	1	0	May be inoperative provided flight is conducted at or below 10,000 feet MSL.
-21-01-01	Passenger Service Units (PSUs)				
-21-01-01A		B	-	-	(M) May be inoperative with no flight altitude restriction provided: a) Associated seats are blocked and placarded to prevent occupancy, b) Associated flight attendant seat is considered inoperative, and c) Associated lavatory door is locked closed and placarded INOPERATIVE - DO NOT ENTER.
-21-01-01B		B	-	-	(O) May be inoperative provided: a) Altitude limitations comply with 14 CFR, b) Portable oxygen supplies comply with 14 CFR, c) Both air conditioning packs operate normally, d) Pressurization system operates normally, e) Both engine bleed systems operate normally, and f) Passengers are appropriately briefed.

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 35-6
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
35 OXYGEN							
-21-01	Passenger Oxygen System (Cont'd)						
-21-01-02	Automatic Presentation System	B	1	0		(M) May be inoperative provided: a) Manual deployment system is verified to operate normally, and b) Airplane remains at or below FL 300.	
-21-01-03	Crew Rest Oxygen Modules (STC ST00973WI-D)						
-21-01-03A		B	5	0		(M) May be inoperative with no flight altitude restriction provided affected bunks are blocked and placarded INOPERATIVE - DO NOT USE.	
-21-01-03B		B	5	0		(M) May be inoperative provided: a) Portable oxygen bottle and mask are available for associated bunk occupant, b) Crew rest oxygen warning horn system is verified to operate normally, and c) Airplane remains at or below FL 300.	
-21-01-04	Crew Rest Oxygen Warning Horn Systems (STC ST00973WI-D)	B	2	0		(M) May be inoperative with no flight altitude restriction provided: a) Associated crew rest is not used and personal items are removed, and b) Associated crew rest door is locked and placarded INOPERATIVE - DO NOT ENTER.	
NOTE: These provisos are not intended to prohibit crew rest inspections by crewmembers.							
(Continued)							

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	35-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
35	OXYGEN				
-21-01	Passenger Oxygen System (Cont'd)				
-21-01-05	Lower Lobe Crew Rest Passenger Service Units (STCs ST01994SE and ST02137SE)	B	-	0	(M) May be inoperative with no flight altitude restriction provided affected seats/bunks are blocked and placarded INOPERATIVE - DO NOT USE.
-21-01-06	Lower Lobe Crew Rest Altitude Alert Horn (STCs ST01994SE and ST02137SE)	B	1	0	(M) May be inoperative with no flight altitude restriction provided: a) Lower lobe crew rest module is not used and personal items are removed, and b) Lower lobe crew rest door is locked and placarded INOPERATIVE - DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest inspections by crewmembers.
-31-01	Portable Oxygen Dispensing Units (Cylinder and Mask)	D	-	-	(M) Any in excess of those required by 14 CFR may be unserviceable or missing provided: a) Required distribution of serviceable cylinders is maintained throughout aircraft, and b) Cylinders not properly serviced are replaced, serviced, or removed at next available maintenance facility.

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 36-1
-------------------------------	---	-------------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-00-01	Air Supply Control and Test Unit (ASCTU) (-400ER)				
-00-01-01	Primary (Digital) Control Channels				
-00-01-01A		C	2	1	(M)(O) One may be inoperative deactivated provided: a) Associated ASCTU backup (analog) channel is verified to operate normally, b) Both associated cabin temperature controller channels are verified to operate normally once each flight day, c) Both packs operate normally, d) Remaining (opposite) engine bleed system operates normally, e) Associated HPSOV is verified closed, f) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, g) Hydraulic Motor Generator (HMG) is not required, h) Associated thrust reverser is considered inoperative, i) Associated fan air modulation valve is secured in intermediate position, and j) Appropriate performance adjustments are applied.
-00-01-01B		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative deactivated provided: a) Associated ASCTU backup (analog) channel is verified to operate normally, b) Both associated cabin temperature controller channels are verified to operate normally once each flight day, c) Both packs operate normally,

(Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-2

SYSTEM & SEQUENCE NUMBERS	1. ITEM		2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-00-01	Air Supply Control and Test Unit (ASCTU) (-400ER) (Cont'd)				
-00-01-01	Primary (Digital) Control Channels (Cont'd)				
-01-01-01B	(Cont'd)				<ul style="list-style-type: none"> d) Remaining (opposite) engine bleed system operates normally, e) Associated HPSOV is verified closed, f) Airplane is not operated in known or forecast icing conditions, g) Hydraulic Motor Generator (HMG) is not required, h) Associated thrust reverser is considered inoperative, and i) Appropriate performance adjustments are applied.
-00-01-02	Backup (Analog) Channels	C	2	1	(M)(O) One may be inoperative deactivated provided: <ul style="list-style-type: none"> a) Associated ASCTU primary (digital) channel is verified to operate normally, b) Associated CTC operates normally, c) Both packs operate normally, and d) Remaining (opposite) engine bleed system operates normally.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	36-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
36 PNEUMATIC					
-11-01	ENG BLEED Pressure Regulating and Shutoff Valves (PRSOV)				
-11-01-01	JT9D/ CF6-80A/A2				
-11-01-01A		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: a) PRSOV is secured closed, b) Associated ENG bleed air switch remains OFF, c) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, d) Airplane is not operated in known or forecast icing conditions, e) APU is used as air source for ADP for takeoff, f) Remaining (opposite) engine bleed system operates normally, g) Airplane remains at or below FL 350, and h) Center Hydraulic Motor Generator (HMG) is not required.
-11-01-01B		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: a) PRSOV is secured closed, b) Associated ENG bleed air switch remains OFF, c) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, d) Airplane is not operated in known or forecast icing conditions, e) ADP inoperative penalties are applied, f) Remaining (opposite) engine bleed system operates normally,
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 36-4
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-11-01	ENG BLEED Pressure Regulating and Shutoff Valves (PRSOV) (Cont'd)				
-11-01-01	JT9D/CF6-80A/A2 (Cont'd)				
-11-01-01B	(Cont'd)				g) Airplane remains at or below FL 350, and h) Center Hydraulic Motor Generator (HMG) is not required.
-11-01-02	CF6-80C2/PW4000				
-11-01-02A		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: a) PRSOV is secured closed, b) Associated ENG bleed air switch remains OFF, c) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, d) Airplane is not operated in known or forecast icing conditions, e) APU is used as air source for ADP for takeoff, f) Remaining (opposite) engine bleed system operates normally, g) Airplane remains at or below FL 350, h) Center Hydraulic Motor Generator (HMG) is not required, and i) Appropriate performance adjustments are applied for either of following conditions: 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.

(Continued)

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	36-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
36 PNEUMATIC					
-11-01	ENG BLEED Pressure Regulating and Shutoff Valves (PRSOV) (Cont'd)				
-11-01-02	CF6-80C2/PW4000 (Cont'd)				
-11-01-02B		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: <ul style="list-style-type: none"> a) PRSOV is secured closed, b) Associated ENG bleed air switch remains OFF, c) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, d) Airplane is not operated in known or forecast icing conditions, e) ADP inoperative penalties are applied, f) Remaining (opposite) engine bleed system operates normally, g) Airplane remains at or below FL 350, h) Center Hydraulic Motor Generator (HMG) is not required, and i) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	36-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC							
-11-01	ENG BLEED Pressure Regulating and Shutoff Valves (PRSOV) (Cont'd)						
-11-01-03	RB211						
-11-01-03A		C	2	1		(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: <ul style="list-style-type: none"> a) PRSOV is secured closed, except for engine start, b) Associated ENG bleed air switch remains OFF, c) Start valve on remaining (opposite) engine operates normally, d) Airplane is not operated in known or forecast icing conditions, e) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, f) APU is used as air source for ADP for takeoff, g) Remaining (opposite) engine bleed system operates normally, h) Flight remains at or below FL 350, and i) Center Hydraulic Motor Generator (HMG) is not required. 	
-11-01-03B		C	2	1		(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative provided: <ul style="list-style-type: none"> a) PRSOV is secured closed, except for engine start, b) Associated ENG bleed air switch remains OFF, c) Start valve on remaining (opposite) engine operates normally, d) Airplane is not operated in known or forecast icing conditions, 	
(Continued)							

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-7

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC				
-11-01	ENG BLEED Pressure Regulating and Shutoff Valves (PRSOV) (Cont'd)			
-11-01-03	RB211 (Cont'd)			
-11-01-03B (Cont'd)				<ul style="list-style-type: none"> e) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, f) ADP inoperative penalties are applied, g) Remaining (opposite) engine bleed system operates normally, h) Flight remains at or below FL 350, and i) Center Hydraulic Motor Generator (HMG) is not required.
-11-02	High Pressure Shutoff Valve (HPSOV) Systems			
-11-02-01	All Except CF6-80C2	C	2	1
				<p>(M)(O) One may be inoperative provided:</p> <ul style="list-style-type: none"> a) Valve is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, and d) Center Hydraulic Motor Generator (HMG) is not required. <p>(Continued)</p>

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
36 PNEUMATIC					
-11-02	High Pressure Shutoff Valve (HPSOV) Systems (Cont'd)				
-11-02-02	CF6-80C2	C	2	1	(M)(O) One may be inoperative provided: a) Valve is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, d) Center Hydraulic Motor Generator (HMG) is not required, e) Associated thrust reverser is considered inoperative, and f) Appropriate performance adjustments are applied.
-11-03	Intermediate Pressure Check Valves (IPCV)				
-11-03-01	All Except CF6-80C2	C	2	1	(M)(O) One may be inoperative open provided: a) Associated HPSOV is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, and d) Center Hydraulic Motor Generator (HMG) is not required.
(Continued)					

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	36-9

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
36 PNEUMATIC					
-11-03	Intermediate Pressure Check Valves (IPCV)				
-11-03-02	CF6-80C2	C	2	1	(M)(O) One may be inoperative open provided: a) Associated HPSOV is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, d) Center Hydraulic Motor Generator (HMG) is not required, e) Associated thrust reverser is considered inoperative, and f) Appropriate performance adjustments are applied.
-11-04	APU BLEED Valve	C	1	0	(M) May be inoperative provided: a) Valve is closed, and b) Bleed switch remains OFF. NOTE: APU may be used for electrical power.
-11-05	APU BLEED Check Valve	C	1	0	May be inoperative provided APU bleed valve remains closed, except for engine start.
-11-06	L and R Bleed ISLN Valves	C	2	1	(M) Except for ER operations beyond 120 minutes, one may be inoperative provided: a) Valve is closed except for engine start, b) Airplane is not operated in known or forecast icing conditions, and c) Both engine bleed valves operate normally.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	36-10

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
36 PNEUMATIC						
-11-07	Center Bleed Isolation Valve					
-11-07A		C	1	0	(M) (O) May be inoperative provided: a) Valve remains closed except for engine start, b) APU is used as air source for ADP for takeoff and landing, c) Both center electrical hydraulic pumps operate normally, d) Airplane remains at or below FL 270, and e) Center Hydraulic Motor Generator (HMG) is not required.	
-11-07B		C	1	0	(M) (O) May be inoperative provided: a) Valve remains closed except for engine start, b) ADP inoperative penalties are applied, c) Both center electrical hydraulic pumps operate normally, d) Airplane remains at or below FL 270, and e) Center Hydraulic Motor Generator (HMG) is not required.	

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-11

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC				
-11-08 Engine Pressure Regulating Valve (PRV) Systems				
-11-08-01 CF6-80C2				
-11-08-01A	C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative secured closed provided: <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Airplane is not operated in known or forecast icing conditions, d) APU is used as air source for ADP for takeoff, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, g) Center Hydraulic Motor Generator (HMG) is not required, h) Associated thrust reverser is considered inoperative, and i) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open. (Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-12

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC				
-11-08	Engine Pressure Regulating Valve (PRV) Systems (Cont'd)			
-11-08-01	CF6-80C2 (Cont'd)			
-11-08-01B	C	2	1	<p>(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative secured closed provided:</p> <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Airplane is not operated in known or forecast icing conditions, d) ADP inoperative penalties are applied, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, g) Center Hydraulic Motor Generator (HMG) is not required, h) Associated thrust reverser is considered inoperative, and i) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open. <p>(Continued)</p>

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 36-13
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-11-08	Engine Pressure Regulating Valve (PRV) Systems (Cont'd)				
-11-08-01	CF6-80C2 (Cont'd)				
-11-08-01-01	-200/-300				
-11-08-01-01A		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative open provided: <ul style="list-style-type: none"> a) Associated HPSOV is secured closed, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Associated pressure regulating valve will open fully pneumatically, d) APU is used as air source for ADP for takeoff, e) Associated ENG bleed air switch remains OFF, except when alternate procedures require its use, f) Airplane remains at or below FL 350, g) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, h) Center Hydraulic Motor Generator (HMG) is not required, i) Associated thrust reverser is considered inoperative, j) Remaining (opposite) engine bleed system operates normally, and k) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open. (Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-14

SYSTEM & SEQUENCE NUMBERS	1. ITEM	1.	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-11-08 Engine Pressure Regulating Valve (PRV) Systems (Cont'd)					
-11-08-01 CF6-80C2 (Cont'd)					
-11-08-01-01 -200/-300					
-11-08-01-01B	C	2	1		(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative open provided: <ul style="list-style-type: none"> a) Associated HPSOV is secured closed, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Associated pressure regulating valve will open fully pneumatically, d) ADP inoperative penalties are applied, e) Associated ENG bleed air switch remains OFF, except when alternate procedures require its use, f) Airplane remains at or below FL 350, g) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, h) Center Hydraulic Motor Generator (HMG) is not required, i) Associated thrust reverser is considered inoperative, j) Remaining (opposite) engine bleed system operates normally, and k) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open. (Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	36-15

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-11-08	Engine Pressure Regulating Valve (PRV) Systems (Cont'd)				
-11-08-01	CF6-80C2 (Cont'd)				
-11-08-01-02	-400ER				
-11-08-01-02A		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative open provided: a) Associated HPSOV is secured closed, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Associated pressure regulating valve is verified open, d) APU is used as air source for ADP for takeoff, e) Associated ENG bleed air switch remains OFF, except when alternate procedures require its use, f) Airplane remains at or below FL 350, g) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, h) Center Hydraulic Motor Generator (HMG) is not required, i) Associated thrust reverser is considered inoperative, j) Remaining (opposite) engine bleed system operates normally, and k) Appropriate performance adjustments are applied.

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 36-16
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC							
-11-08	Engine Pressure Regulating Valve (PRV) Systems (Cont'd)						
-11-08-01	CF6-80C2 (Cont'd)						
-11-08-02	-400ER (Cont'd)						
-11-08-01-02B		C	2	1		(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative open provided:	<ul style="list-style-type: none"> a) Associated HPSOV is secured closed, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Associated pressure regulating valve is verified open, d) ADP inoperative penalties are applied, e) Associated ENG bleed air switch remains OFF, except when alternate procedures require its use, f) Airplane remains at or below FL 350, g) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, h) Center Hydraulic Motor Generator (HMG) is not required, i) Associated thrust reverser is considered inoperative, j) Remaining (opposite) engine bleed system operates normally, and k) Appropriate performance adjustments are applied.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	36-17

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
36 PNEUMATIC					
-11-08	Engine Pressure Regulating Valve (PRV) Systems (Cont'd)				
-11-08-02	PW4000				
-11-08-02A		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative secured closed provided: <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Airplane is not operated in known or forecast icing conditions, d) APU is used as air source for ADP for takeoff, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, g) Center Hydraulic Motor Generator (HMG) is not required, and h) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 36-18
-------------------------------	---	--------------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-11-08	Engine Pressure Regulating Valve (PRV) Systems (Cont'd)				
-11-08-02	PW4000 (Cont'd)				
-11-08-02B		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative secured closed provided: a) Associated ENG bleed air switch remains OFF, b) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, c) Airplane is not operated in known or forecast icing conditions, d) ADP inoperative penalties are applied, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, g) Center Hydraulic Motor Generator (HMG) is not required, and h) Appropriate performance adjustments are applied for either of following conditions: 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.
-11-08-02C		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative open provided: a) Associated HPSOV is secured closed, b) Associated pressure regulating valve will open fully pneumatically, (Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-19

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-11-08	Engine Pressure Regulating Valve (PRV) Systems (Cont'd)				
-11-08-02	PW4000 (Cont'd)				
-11-08-02C (Cont'd)					<ul style="list-style-type: none"> c) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, d) Remaining (opposite) engine bleed system operates normally, and e) Center Hydraulic Motor Generator (HMG) is not required.
-11-09	Engine Firewall Shutoff Valves (FWSOV) (RB211)				
-11-09A		C	2	1	<p>(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative secured closed provided:</p> <ul style="list-style-type: none"> a) Associated ENG bleed air switch remains OFF, b) Associated engine bleed isolation valve is opened after takeoff, and closed before approach and landing, c) Airplane is not operated in known or forecast icing conditions, d) APU is used as air source for ADP for takeoff, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, and g) Center Hydraulic Motor Generator (HMG) is not required.

(Continued)

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	36-20

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
36 PNEUMATIC					
-11-09	Engine Firewall Shutoff Valves (FWSOV) (RB211)				
-11-09B		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative secured closed provided: a) Associated ENG bleed air switch remains OFF, b) Associated engine bleed isolation valve is opened after takeoff, and closed before approach and landing, c) Airplane is not operated in known or forecast icing conditions, d) ADP inoperative penalties are applied, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, and g) Center Hydraulic Motor Generator (HMG) is not required.
-11-09C		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, one may be inoperative open provided: a) FWSOV opens fully pneumatically, b) Associated HPSOV is secured closed, c) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, d) Remaining (opposite) engine bleed system operates normally, and e) Center Hydraulic Motor Generator (HMG) is not required.
-11-10	High Stage (HP) Check Valves (RB211)	C	2	0	May be inoperative open.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	36-21

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC						
-12-01	Precoolers					
-12-01-01	JT9D/CF6-80A/A2					
-12-01-01A		C	2	1		(M)(O) Except for ER operations beyond 120 minutes, airplane may be dispatched with damage to one precooler and associated ducting between HPSOV, IPCV and PRSOV provided: <ul style="list-style-type: none"> a) Associated HPSOV is secured closed, b) Associated PRSOV is secured closed, c) Associated low pressure bleed duct is blocked by an approved tool, d) Airplane is not operated in known or forecast icing conditions, e) Center Hydraulic Motor Generator (HMG) is not required, f) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, g) Remaining (opposite) engine bleed system operates normally, h) Airplane remains at or below FL 350, i) APU is used as air source for ADP for takeoff, and j) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.
-12-01-01B		C	2	1		(M)(O) Except for ER operations beyond 120 minutes, airplane may be dispatched with damage to one precooler and associated ducting between HPSOV, IPCV and PRSOV provided: <ul style="list-style-type: none"> a) Associated HPSOV is secured closed, b) Associated PRSOV is secured closed,

(Continued)

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-22

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC				
-12-01 Precoolers (Cont'd)				
-12-01-01 JT9D/CF6-80A/A2 (Cont'd)				<ul style="list-style-type: none"> c) Associated low pressure bleed duct is blocked by an approved tool, d) Airplane is not operated in known or forecast icing conditions, e) Center Hydraulic Motor Generator (HMG) is not required, f) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, g) Remaining (opposite) engine bleed system operates normally, h) Airplane remains at or below FL 350, i) ADP inoperative penalties are applied, and j) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.
-12-01-01B (Cont'd)				
-12-01-02 CF6-80C2				
-12-01-02A	C	2	1	(M)(O) Except for ER operations beyond 120 minutes, airplane may be dispatched with damage to one precooler and associated ducting between PRV and PRSOV provided: <ul style="list-style-type: none"> a) Associated PRV is secured closed, b) Associated PRSOV is secured closed, (Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	36-23

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
36 PNEUMATIC					
-12-01	Precoolers (Cont'd)				
-12-01-02	CF6-80C2 (Cont'd)				
-12-01-02A (Cont'd)					<ul style="list-style-type: none"> c) Airplane is not operated in known or forecast icing conditions, d) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, g) APU is used as air source for ADP for takeoff, h) Center Hydraulic Motor Generator (HMG) is not required, i) Associated thrust reverser is considered inoperative, and j) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.
-12-01-02B		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, airplane may be dispatched with damage to one precooler and associated ducting between PRV and PRSOV provided: <ul style="list-style-type: none"> a) Associated PRV is secured closed, b) Associated PRSOV is secured closed, c) Airplane is not operated in known or forecast icing conditions, d) Associated bleed isolation valve is opened after takeoff and closed before approach and landing,

(Continued)

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-24

SYSTEM & SEQUENCE NUMBERS	1. ITEM	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
36 PNEUMATIC				
-12-01	Precoolers (Cont'd)			
-12-01-02	CF6-80C2 (Cont'd)			
-12-01-02B (Cont'd)				<ul style="list-style-type: none"> e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, g) ADP inoperative penalties are applied, h) Center Hydraulic Motor Generator (HMG) is not required, i) Associated thrust reverser is considered inoperative, and j) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.
-12-01-03	PW4000			
-12-01-03A	C	2	1	(M)(O) Except for ER operations beyond 120 minutes, airplane may be dispatched with damage to one precooler and associated ducting between PRV and PRSOV provided: <ul style="list-style-type: none"> a) Associated PRV is secured closed, b) Associated PRSOV is secured closed, c) Airplane is not operated in known or forecast icing conditions, d) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350,
				(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	36-25

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2.	3.	4.
		NUMBER INSTALLED			NUMBER REQUIRED FOR DISPATCH
					REMARKS OR EXCEPTIONS
36 PNEUMATIC					
-12-01	Precoolers (Cont'd)				
-12-01-03	PW4000 (Cont'd)				
-12-01-03A	(Cont'd)				
-12-01-03B		C	2	1	(M)(O) Except for ER operations beyond 120 minutes, airplane may be dispatched with damage to one precooler and associated ducting between PRV and PRSOV provided: <ul style="list-style-type: none"> a) Associated PRV is secured closed, b) Associated PRSOV is secured closed, c) Airplane is not operated in known or forecast icing conditions, d) Associated bleed isolation valve is opened after takeoff and closed before approach and landing, e) Remaining (opposite) engine bleed system operates normally, f) Airplane remains at or below FL 350, g) ADP inoperative penalties are applied, h) Center Hydraulic Motor Generator (HMG) is not required, and i) Appropriate performance adjustments are applied for either of following conditions: <ul style="list-style-type: none"> 1) Associated fan air modulation valve secured in intermediate position, or 2) Associated fan air modulation valve open.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	36-26

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH		4. REMARKS OR EXCEPTIONS
36	PNEUMATIC						
-12-02	Fan Air (Precooler) Control Systems						
-12-02-01	JT9D/CF6/PW4000	C	2	0			(M)(O) Except for ER operations beyond 120 minutes, may be inoperative provided: a) Associated fan air modulation valve is secured in an intermediate position, and b) Appropriate performance adjustments are applied.
-12-02-01-01	-200/-300	C	2	0			(M)(O) Except for ER operations beyond 120 minutes, may be inoperative provided: a) Associated fan air modulation valve is secured full open, b) Appropriate performance adjustments are applied, and c) Airplane is not operated in known or forecast icing conditions.
-12-02-01-02	RB211	C	2	0			(M)(O) Except for ER operations beyond 120 minutes, may be inoperative provided: a) Associated fan air modulation valve is secured full open, and b) Airplane is not operated in known or forecast icing conditions.
-21-01	Bleed Air DUCT PRESS Indicating System						
-21-01-01	DUCT PRESS Indicators (P5 Panel)	C	2	1			
-21-01-02	Manifold Pressure Sensing Systems (-400ER)	C	2	1			(M) One may be inoperative provided associated pack flow control valve inlet pressure sensor is verified to operate normally.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-27

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
36 PNEUMATIC					
-21-02	Engine Bleed Air OFF Lights	C	2	0	
-21-03	Intermediate Pressure Sensing Systems (-400ER)	C	2	1	(M)(O) One may be inoperative provided: a) Associated PRV operates normally, b) Associated HPSOV is verified closed, c) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, d) Remaining (opposite) engine bleed system operates normally, e) Hydraulic Motor Generator (HMG) is not required, f) Associated thrust reverser is considered inoperative, and g) Appropriate performance adjustments are applied.
-22-01	BLEED Lights (-200/-300)				
-22-01-01	All Except CF6-80C2	C	2	1	(M)(O) One may be inoperative provided: a) Associated HPSOV is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, and d) Center Hydraulic Motor Generator (HMG) is not required.
(Continued)					

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-28

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
36 PNEUMATIC					
-22-01	BLEED Lights (-200/-300) (Cont'd)				
-22-01-02	CF6-80C2	C	2	1	(M)(O) One may be inoperative provided: a) Associated HPSOV is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, d) Center Hydraulic Motor Generator (HMG) is not required, and e) Associated thrust reverser is considered inoperative, and f) Appropriate performance adjustments are applied.
-22-02	HI STAGE Lights (JT9D/CF6-80A/A2)	C	2	1	(M)(O) One may be inoperative provided: a) Associated HPSOV is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, and d) Center Hydraulic Motor Generator (HMG) is not required.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

36-29

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
36 PNEUMATIC					
-22-03	OVHT Lights (CF6-80C2/PW4000/ RB211)				
-22-03-01	-200/-300				
-22-03-01-01	PW4000/RB211	C	2	1	(M)(O) One may be inoperative provided: a) Associated HPSOV is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, and d) Center Hydraulic Motor Generator (HMG) is not required.
-22-03-01-02	CF6-80C2	C	2	1	(M)(O) One may be inoperative provided: a) Associated HPSOV is secured closed, b) A minimum of 70% (55% below 10,000 feet MSL) N1 is maintained on associated engine in icing conditions, c) Remaining (opposite) engine bleed system operates normally, d) Center Hydraulic Motor Generator (HMG) is not required, and e) Associated thrust reverser is considered inoperative, and f) Appropriate performance adjustments are applied.
-22-03-02	-400ER	C	2	0	(O) May be inoperative.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	36-30

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
36 PNEUMATIC					
-22-04	L and R Bleed ISLN VALVE Lights				
-22-04-01	-200/-300	C	2	1	(O) One may be inoperative provided associated duct pressure indicator operates normally.
-22-04-02	-400ER	C	2	0	
-22-05	C Bleed ISLN VALVE Light	C	1	0	
-22-06	APU Bleed VALVE Light	C	1	0	
-22-07	Manifold Temperature Sensing Systems (-400ER)	C	2	0	(M) May be inoperative provided associated pack inlet temperature sensor is verified to operate normally.

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	38-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
38 WATER/WASTE					
-10-01	Potable Water Systems				
-10-01A		C	-	-	(M) Individual components may be inoperative provided: a) Associated components are deactivated or isolated, and b) Associated system components are verified not to have leaks. NOTE: Any portion of system that operates normally may be used.
-10-01B		C	-	-	(M) May be inoperative provided: a) System is drained, and b) Procedures are established to ensure that system is not serviced.
-30-01	Lavatory/Galley Waste Systems (Including Wheelchair Accessible Lavatories)				
-30-01A		C	-	-	(M) Individual components may be inoperative provided: a) Associated components are deactivated or isolated, and b) Associated system components are verified not to have leaks. NOTE: Any portion of system that operates normally may be used. (Continued)

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	38-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
38 WATER/WASTE					
-30-01	Lavatory/Galley Waste Systems (Including Wheelchair Accessible Lavatories) (Cont'd)				
-30-01B		C	-	-	(M) Associated lavatory may be inoperative provided: a) Associated components are deactivated or isolated to prevent leaks, and b) Associated lavatory door is locked closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisions are not intended to prohibit inspections by crewmembers.
-32-01 ***	Tank Precharge Control Systems	D	2	0	(M) May be inoperative provided applicable precharge control valve is secured in open position.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	46-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
46 INFORMATION SYSTEMS						
-20-01 ***	Electronic Flight Bag (EFB) Systems					
-20-01-01 ***	Class 3					
-20-01-01A		C	2	1	NOTE: Any function, program or document that operates normally may be used.	
-20-01-01B		C	2	0	(O) May be inoperative provided alternate procedures are established and used. NOTE: Any function, program or document that operates normally may be used.	
-20-01-01C		D	2	0	May be inoperative provided procedures do not require its use.	
-20-01-02 ***	Data Connectivity (Class 2)					
-20-01-02A		C	-	-	(O) May be inoperative provided alternate procedures are established and used.	
-20-01-02B		D	-	0	May be inoperative provided procedures do not require its use.	
-20-01-03 ***	Power Connection (Class 1 & 2)					
-20-01-03A		C	-	-	(O) May be inoperative provided alternate procedures are established and used.	
-20-01-03B		D	-	0	May be inoperative provided procedures do not require its use.	
(Continued)						

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

46-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
46 INFORMATION SYSTEMS					
-20-01 ***	Electronic Flight Bag (EFB) Systems (Cont'd)				
-20-01-04 ***	Mounting Device (Class 2)				
-20-01-04A		C	-	0	(M)(O) May be inoperative provided: a) Associated EFB and hardware is secured by an alternate means or removed from aircraft, and b) Alternate procedures are established and used.
-20-01-04B		D	-	0	(M)(O) May be inoperative provided: a) Associated EFB and hardware is secured by an alternate means or removed from aircraft, and b) Procedures do not require its use.
-20-01-05 ***	Airport Moving Map Database				
-20-01-05-01	STC ST02126LA	D	2	0	(O) May be out of date provided alternate procedures are established and used.
-20-01-06 ***	Navigation Database				
-20-01-06-01	STC ST02126LA				
-20-01-06-01A		D	1	0	May be out of date provided Merging & Spacing operations are prohibited.
-20-01-06-01B		C	1	0	(O) May be out of date provided merge waypoint is not inserted for Merging & Spacing function.

AIRCRAFT:	BOEING B-767	REVISION NO: 37a	PAGE:
		DATE: 03/27/2015	47-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
47 INERT GAS SYSTEM						
-11-01 ***	Nitrogen Generation System (NGS)	A	1	0	(M) May be inoperative provided: a) NGS shutoff valve is deactivated closed, and b) Repairs are made within 10 flight days.	
-11-01-01	Nitrogen Generation Performance	C	1	0		

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

49-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
			1	0		3. NUMBER REQUIRED FOR DISPATCH
						1
49 AIRBORNE AUXILIARY POWER						
-11-01	Auxiliary Power Unit (APU)					
-11-01A		C	1	0	(O) Except for ER operations, may be inoperative provided: a) Both engine generators operate normally, and b) Procedures do not require its use.	
-11-01B		B	1	0	(M) (O) Except for ER operations beyond 120 minutes, may be inoperative provided: a) Both engine generators operate normally, b) Hydraulic Motor Generator (HMG) is verified to operate normally, and c) Procedures do not require its use.	
-11-01-01	Pneumatic Function	C	1	0	(M) May be inoperative provided procedures do not require its use.	
-15-01	APU Air Intake Door Actuation System	C	1	0	(M) May be inoperative secured closed provided APU is considered inoperative.	
-15-01-01	-200/-300					
-15-01-01A		C	1	0	(M)(O) May be inoperative provided: a) Door is deactivated in full open position, and b) AFM performance decrements are applied.	
(Continued)						

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

49-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
49 AIRBORNE AUXILIARY POWER					
-15-01 APU Air Intake Door Actuation System (Cont'd)					
-15-01-01 -200/-300 (Cont'd)					
-15-01-01B	C	1	0		(O) May be inoperative with door in any position provided: a) Procedures do not require use of APU, b) APU is not used, c) Flight remains within 120 minutes of landing at a suitable airport, and d) AFM performance decrements are applied.
-15-01-02 -400ER					
-15-01-02A	C	1	0		(O) May be inoperative partially open provided: a) APU is considered inoperative, and b) Appropriate performance adjustments are applied.
-15-01-02B	C	1	0		(M)(O) May be inoperative provided door is secured in flight position.
-61-01 APU External Control System					
-61-01A	C	1	0		May be inoperative and APU used, provided a qualified operator remains in vicinity of flight deck APU control.
-61-01B	C	1	0		(M) May be inoperative and APU used, provided an APU automatic fire extinguishing system is installed and verified to operate normally.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

49-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
49	AIRBORNE AUXILIARY POWER					
-61-02	APU Controller Faults (-400ER)	C	-	0	May be dispatched with faults annunciated by APU CONTROL status message.	
-70-01	APU FAULT Light	C	1	0		
-70-02	APU RUN Light	C	1	0	(O) May be inoperative provided another acceptable means to verify APU condition is available and used.	
-71-01	APU EGT Indication	C	1	0		
-72-01 ***	APU Hourmeter System					
-72-01A		C	1	0	(M) May be inoperative provided alternate procedures are established and used.	
-72-01B		D	1	0	May be inoperative provided procedures do not require its use.	
-72-02 ***	APU Cyclemeter System					
-72-02A		C	1	0	(M) May be inoperative provided alternate procedures are established and used.	
-72-02B		D	1	0	May be inoperative provided procedures do not require its use.	
-73-01 ***	APU RPM Indication	D	1	0		
-94-01	APU OIL QTY Indication					
-94-01A		C	1	0	May be inoperative provided APU is considered inoperative.	
-94-01B		D	1	0	(M) May be inoperative provided oil quantity is verified by alternate means.	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	49-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
49 AIRBORNE AUXILIARY POWER						
-94-02	APU OIL TEMP Indication System (-400ER)	C	1	0		

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
52 DOORS					
-11-01	Main Entry/Service Door Armed Indicators	C	-	0	(M) May be inoperative provided a procedure is used to verify that mode select mechanism is in "slide armed" mode before each departure and in "slide disarm" mode before a non-emergency opening.
-11-02 ***	Main Entry/Service Door Arming Lever Hinged Covers	D	-	0	May be damaged or missing.
-11-03 ***	Entry Door Power Opening Assist	C	-	0	
-11-04	Main Entry Doors/Slides/ Emergency Exits				
-11-04-01	Passenger Configuration				
-11-04-01A		A	-	-	(M)(O) One may be inoperative or slide missing provided: a) All other main entry doors/exits are fully operational, b) Affected door is not used for passenger loading, c) A conspicuous barrier strap or rope and a placard stating that door is inoperative shall be placed across inoperative door, d) Emergency exit sign and floor proximity lights associated with inoperative exit must be covered to obscure signs and lights, e) Passengers must be briefed not to use affected door,

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 52-2
-------------------------------	---	-------------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED	3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
52 DOORS					
-11-04	Main Entry Doors/Slides/Emergency Exits (Cont'd)				
-11-04-01	Passenger Configuration (Cont'd)				
-11-04-01A	(Cont'd)				<p>f) All passenger seats halfway to next exit in each direction from inoperative door, across entire width of airplane, shall be blocked off with conspicuous tapes or ropes that contrast with interior prior to loading passengers. Only seats in these areas shall be blocked: main passenger aisles, cross aisles, and exit areas must not be blocked. (For an inoperative forward door/slide, blocked seating area shall extend from forward cabin end, rearward to a line halfway between inoperative forward door and next set of doors aft of inoperative one. For an inoperative rear door/slide, blocked seating area shall extend forward from aft cabin end to a line halfway between inoperative door and next set of doors forward of inoperative one),</p> <p>g) Conspicuous signs and placards shall be placed in appropriate locations indicating these seats are not to be occupied by passengers,</p> <p>h) Seated capacity must not exceed rated capacity of remaining pairs of exits,</p> <p>i) For extended range/overwater operations, occupancy shall not exceed normal rated capacity of slide/rafts, or remaining slide/rafts or rated overload capacity of slide/rafts remaining after loss of one additional slide/raft of greatest capacity, whichever is least,</p>

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 52-4
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
52 DOORS							
-11-04	Main Entry Doors/Slides/ Emergency Exits (Cont'd)						
-11-04-01	Passenger Configuration (Cont'd)						
-11-04-01B (Cont'd)							f) Each person carried has unobstructed access from their seat to an operative door, g) Safety briefing includes location of inoperative doors and instructions not to use them, and e) Alternate procedures are established and used.
-11-04-02	All Cargo Configuration						
-11-04-02-01	All Doors Except L1/R1	C	-	0			All doors/slides may be inoperative or slides missing.
-11-04-02-02	Doors L1/R1	C	2	1			One door/slide may be inoperative or slide missing.
-11-04-03	Combination Passenger/Cargo Configurations	C	-	-			All doors/slides in cargo area may be inoperative or slide missing.

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 52-5
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
52 DOORS					
-30-01	Lower Cargo Doors				
-30-01-01	Cargo Door Lift/Latch Mechanisms (Std. Door-Passenger/-200PC/-200SF STC/-200SF ATC/-300BCF/-300BDSF)				
-30-01-01A		C	-	-	Either manual or electric mode on each door may be inoperative.
-30-01-01B		C	-	0	(M) Manual and electric modes may be inoperative provided associated door is verified closed and locked before each departure.
-30-01-02	Cargo Door Hinge Power Units and Manual Hinge Drive Systems (Std. Door-Passenger/-200PC/-200SF STC/-200SF ATC/-300BCF/-300BDSF)				
-30-01-02A		C	-	-	Either manual or electric mode on each door may be inoperative.
-30-01-02B		C	-	0	(M) Manual and electric modes may be inoperative provided associated door is verified closed and locked before each departure.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	52-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
52 DOORS						
-30-01	Lower Cargo Doors (Cont'd)					
-30-01-03	Cargo Door Hook/Latch System Electrical Function (Large Door-Passenger/-200PC/-200SF STC/-300BCF/-300BDSF) (Lower Doors -300F)	C	-	0	(M) May be inoperative provided:	
					a) Manual function operates normally,	
					b) There is no damage to hook/latch mechanism,	
					c) There is no damage to latch lock mechanism,	
					d) Door is closed and locked using an accepted maintenance manual procedure, and	
					e) All latch cams are visually confirmed to be in closed position before each departure.	
-30-01-04	Cargo Door Lift System (Large Door-Passenger/-200PC/-200SF STC/-300BCF/-300BDSF) (Lower Doors -300F)					
-30-01-04A		C	-	-	Either manual or electric mode on each door may be inoperative.	
-30-01-04B		C	-	0	(M) Manual and electric modes may be inoperative provided associated door is verified closed and locked before each departure.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-7

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
52 DOORS						
-30-03	Cargo Door Control Panel Indicating Systems					
-30-03-01	DOOR OPEN Light (Std. Door – Passenger/-200PC/-200SF STC/-300BDSF/-200SF ATC/-300BCF)	C	-	0	May be inoperative provided DOOR CLOSE light operates normally.	
-30-03-02	DOOR CLOSE Light (Std. Door – Passenger/-200PC/-200SF STC/-300BDSF/-200SF ATC/-300BCF)	C	-	0	(M) May be inoperative provided: a) Door indication system for associated door is verified to operate normally, and b) Door is visually verified closed, latched, and locked before each departure.	
-30-03-03	DOOR OPEN and DOOR CLOSE Lights (Large Door – Passenger/-200PC/-200SF STC/-300BDSF/-300BCF) (Lower Doors -300F)	C	-	0	(M) May be inoperative provided door is visually verified closed, latched, and locked before each departure.	
-30-03-04	Main Deck Cargo Door Lights	C	5	0	(M) May be inoperative provided door is visually verified closed, latched, and locked before each departure.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-8

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
52 DOORS						
-32-01	Main Deck Cargo Door					
-32-01-01	Cargo Door Hook/Latch System (Electric)	C	1	0	(M) May be inoperative provided: a) Manual function operates normally, b) There is no damage to hook/latch mechanism, c) There is no damage to lock mechanism, d) Door is closed and locked using an accepted maintenance manual procedure, and e) All latch cams are visually confirmed in closed position before each departure.	
-32-01-02	Cargo Door Lift System (Manual and Electric)	C	1	0	(M) May be inoperative provided door is verified closed, latched and locked before each departure.	
-32-01-03	Cargo Door Lock System (Electric)	C	1	0	(M) May be inoperative provided: a) Manual function operates normally, b) There is no damage to hook/latch mechanism, c) There is no damage to lock mechanism, d) Door is closed and locked using an accepted maintenance manual procedure, and e) All latch cams are visually confirmed in closed position before each departure.	
-34-01	Cargo Door Stop Fitting Bearing Plates (Std. Doors Only)	C	-	-	One on forward and aft side of each cargo door frame may be missing.	
-35-01	Bulk Cargo Door Balance Mechanism	C	1	0	(M) May be inoperative provided a safety hold open device is used when door is in open position.	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 52-9
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
52 DOORS						
-50-01	Crew Rest Doors (STC ST00973WI-D)	C	3	0		May be inoperative provided: <ul style="list-style-type: none"> a) Associated crew rest area is not used and personal items are removed, and b) Associated crew rest area door is locked closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.
-50-01-01	Flight Crew Rest Door	C	1	0	(M)	May be inoperative provided: <ul style="list-style-type: none"> a) Door is removed, and b) Crew rest area is not used for required crewmember rest.
-50-01-02	Attendant Crew Rest Doors	C	2	0	(M)	May be inoperative provided: <ul style="list-style-type: none"> a) Both attendant crew rest area doors are removed, and b) Crew rest area is not used for required crewmember rest.
-50-02	Lower Lobe Crew Rest Doors (STCs ST01994SE and ST02137SE)					
-50-02-01	Main Entry	C	2	0		Either or both main entry door and main entry hatch may be inoperative provided: <ul style="list-style-type: none"> a) Associated crew rest area is not used and personal items are removed, and b) Crew rest area main entry door is secured closed and placarded INOPERATIVE – DO NOT ENTER. NOTE: These provisos are not intended to prohibit crew rest area inspections by crewmembers.

(Continued)

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 52-10
---------------------------	-------------------------------------	----------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
52 DOORS						
-50-02	Lower Lobe Crew Rest Doors (STCs ST01994SE and ST02137SE) (Cont'd)					
-50-02-02	Emergency Escape Hatch	C	1	0		(M) May be inoperative provided: a) Associated crew rest area is not used and personal items are removed, b) Associated crew rest area main entry door is locked closed and placarded INOPERATIVE – DO NOT ENTER, and c) Emergency escape hatch is verified secured closed.
-51-01 ***	Flight Deck Door Lock System (Not 14 CFR 25.795 Compliant)					
-51-01A		C	1	0		(M) May be inoperative provided: a) Door can be locked and unlocked manually, and b) Door lock solenoid is deactivated in extended position.
-51-01B		C	1	0		May be inoperative provided supplemental flight deck door security device is installed and operates normally.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-11

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
52 DOORS						
-51-02	Rigid Barrier Access Door Latch System(s) (-200SF ATC/-300BCF/-300F/-300BDSF)					
-51-02-01	Primary	C	1	0	(M) May be inoperative provided: a) Door can be locked and unlocked manually with secondary latch system, and b) Access to main cargo deck is prohibited in flight.	
-51-02-02	Secondary	C	1	0	May be inoperative provided primary latch system operates normally.	
-51-03 ***	Boeing Enhanced Flight Deck Security Door Automatic Locking System (14 CFR 25.795 Compliant)	A	1	0	(M)(O) May be inoperative provided: a) Automatic locking system is deactivated, b) Door dead bolt operates normally and is used to lock door, c) Alternate procedures are established and used for locking and unlocking door using dead bolt, and d) Repairs are made within 2 flight days.	
-51-03-01	Flight Deck Access Panel System (Keypad, Door Chime)	B	1	0	(M)(O) May be inoperative provided: a) Keypad is deactivated, and b) Alternate procedures are established and used.	
-51-03-01-01	LEDs	C	3	0	(O) May be inoperative provided alternate procedures are established and used. (Continued)	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-12

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
52 DOORS						
-51-03 ***	Boeing Enhanced Flight Deck Security Door Automatic Locking System (14 CFR 25.795 Compliant) (Cont'd)					
-51-03-01	Flight Deck Access Panel System (Keypad, Door Chime) (Cont'd)	B	1	0	(M)(O) May be inoperative provided: a) Keypad is deactivated, and b) Alternate procedures are established and used.	
-51-03-01-02 ***	Door Bell Mode	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-51-03-01-03	Switch Guard	C	1	0	May be inoperative or missing provided flight deck door LOCK FAIL light operates normally.	
-51-03-02	Flight Deck Door LOCK FAIL Light	B	1	0	(M) May be inoperative provided automatic lock controls are verified to operate normally.	
-51-03-03	Flight Deck Door AUTO UNLK Light	B	1	0	(M) May be inoperative provided: a) Automatic lock controls are verified to operate normally, and b) Door chime operates normally.	
-51-03-04	Fight Deck Door Lock Control Selector	B	1	0	(M)(O) May be inoperative provided: a) Keypad is deactivated, b) Automatic lock is verified to operate normally, and c) Alternate procedures are established and used.	
(Continued)						

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-13

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
52 DOORS						
-51-03 ***	Boeing Enhanced Flight Deck Security Door Automatic Locking System (14 CFR 25.795 Compliant) (Cont'd)					
-51-03-05	Pressure Rate-of-Change Sensing Module	A	1	0	(M) May be inoperative provided: a) Pressure sensing module is deactivated, and b) Repairs are made within 2 flight days.	
-51-04 ***	Boeing Enhanced Flight Deck Security Door Dead Bolt (14 CFR 25.795 Compliant)	C	1	0	May be inoperative provided automatic lock controls operate normally.	
-51-05 ***	JAMCO Flight Deck Security Door Automatic Locking System (14 CFR 25.795 Compliant)	C	1	0	(M)(O) May be inoperative provided: a) Automatic locking system is deactivated, b) Mechanical catch (latch) pin lock operates normally and is used to lock door, and c) Alternate procedures are established and used for locking and unlocking flight deck door using mechanical catch (latch) pin lock.	
-51-05-01	Door Automatic Locking Solenoids	C	2	1	(M) One may be inoperative provided remaining locking solenoid is verified to operate normally. (Continued)	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-14

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
52 DOORS					
-51-05 ***	JAMCO Flight Deck Security Door Automatic Locking System (14 CFR 25.795 Compliant) (Cont'd)				
-51-05-02	Door Warning System				
-51-05-02-01 ***	Speakers	C	2	1	(M)(O) One may be inoperative provided remaining speaker is verified to operate normally once each flight day.
-51-05-02-02 ***	LED (Green Indicator Lights)	C	2	0	
-51-05-02-03 ***	Aural Warning System	C	1	0	(M)(O) May be inoperative provided: a) Door AUTO UNLK light is verified to operate normally, and b) Alternate procedures are established and used.
-51-05-03	Door Control Panel				
-51-05-03-01 ***	Door LOCK FAIL Light	C	1	0	(M) May be inoperative OFF provided automatic lock controls are verified to operate normally.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	52-15

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
52 DOORS					
-51-05 ***	JAMCO Flight Deck Security Door Automatic Locking System (14 CFR 25.795 Compliant) (Cont'd)				
-51-05-03 ***	Door Control Panel (Cont'd)				
-51-05-03-02 ***	Door AUTO UNLK Light	C	1	0	(M)(O) May be inoperative OFF provided: a) Automatic lock controls are verified to operate normally, b) Aural warning system operates normally, and c) Alternate procedures are established and used.
-51-05-03-03 ***	Door HARD LOCK Light	C	1	0	(M)(O) May be inoperative provided: a) Automatic lock controls are verified to operate normally, and b) Alternate procedures are established and used.
-51-05-03-04 ***	Door UNLKD Switch/UNLK Switch Position	C	1	0	(M)(O) May be inoperative provided: a) Door can be opened manually from flight deck, b) Remaining automatic lock controls are verified to operate normally, and c) Alternate procedures are established and used.
					(Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	52-16

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
52 DOORS						
-51-05 ***	JAMCO Flight Deck Security Door Automatic Locking System (14 CFR 25.795 Compliant) (Cont'd)					
-51-05-03 ***	Door Control Panel (Cont'd)					
-51-05-03-05 ***	Door UNLKD Light	C	1	0	(M)(O) May be inoperative provided: a) Automatic lock controls are verified to operate normally, and b) Aural warning system operates normally.	
-51-05-03-06 ***	Door EMRG ENTRY ACTIVE Light	C	1	0	(M) May be inoperative provided door aural warning system is verified to operate normally.	
-51-05-03-07 ***	Door OPEN Light	C	1	0	(M)(O) May be inoperative provided automatic lock controls are verified to operate normally.	
-51-05-04 ***	FLIGHT DECK DOOR Warning/ Caution Light	C	1	0		
-51-05-05 ***	Cabin Pushbutton Entry Pad/Keypad	C	1	0	(O) May be inoperative provided alternate procedures are established and used.	
-51-05-05-01 ***	Keypad Indicator Lights	C	3	0	(M)(O) May be inoperative provided: a) Keypad is verified to operate normally, and b) Alternate procedures are established and used.	

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

52-17

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
52 DOORS						
-51-06 ***	JAMCO Flight Deck Security Door Mechanical Catch (Latch) Pin Lock (14 CFR 25.795 Compliant)	C	1	0	(M) May be inoperative provided automatic lock system is verified to operate normally.	
-51-07	Smoke Barrier Access Door Latch System(s) (-200SF STC)					
-51-07-01	Primary	C	1	0	May be inoperative provided door can be locked and unlocked with secondary latch system.	
-51-07-02	Secondary	C	1	0	May be inoperative provided primary latch system operates normally.	
-71-01	Door Indication Systems					
-71-01-01	All Doors Except Main Deck Cargo Door	C	-	0	(M) May be inoperative provided associated door(s) is verified closed, latched, and locked before each departure.	
-71-01-02	Main Deck Cargo Door (All Except -200SF ATC and -300BCF)	C	1	0	(M) May be inoperative provided associated door(s) is verified closed, latched, and locked before each departure.	
-73-01 ***	Entry/Service Door Slide Armed Indicating Light System	D	1	0		

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	56-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
56 WINDOWS							
-31-01 ***	Entry/Service Door Viewport Heated Pane(s)	B	-	0		(M) May be inoperative provided heated panes are deactivated.	

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

73-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
73 ENGINE FUEL AND CONTROL						
-14-01	Fuel Filter Heater Systems (JT9D)					
-14-01A		C	2	0	(M)(O) May be inoperative provided: a) Heater valve is verified closed or a blanking plate is installed, b) Fuel temperature indication operates normally, and c) Airplane is not operated with fuel temperature at or below -20 degrees C with IDG(s) on associated engine(s) operating normally.	
-14-01B		C	2	0	(M)(O) May be inoperative provided: a) Heater valve is verified closed or a blanking plate is installed, b) Fuel temperature indication operates normally, and c) Airplane is not operated with fuel temperature at or below +5 degrees C with IDG(s) on associated engine(s) inoperative.	
-14-01-01	Automatic Function	C	2	0	(O) May be inoperative.	
-14-02	Fuel Heater VALVE Lights (JT9D)	C	2	0	(O) May be inoperative.	
-14-03	Fuel FILTER Bypass Lights (JT9D)	C	2	1	(M)(O) May be inoperative provided: a) Associated fuel filter heater system operates normally, and switch remains in AUTO, b) Associated fuel filter pressure switch operates normally, and c) Associated fuel filter is checked for presence of contaminants before each departure.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	73-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
73 ENGINE FUEL AND CONTROL					
-21-01	Electronic Engine Control (EEC) Systems				
-21-01-01	JT9D/CF6 PMC				
-21-01-01A		A	2	0	(O) May be inoperative provided: a) Both EECs are OFF, and b) Repairs are made within 3 flight days.
-21-01-01B		C	2	0	(O) Except for ER operations, may be inoperative provided both EECs are OFF.
-21-01-02	EEC NORM Mode (PW4000/RB211)	C	2	1	(O) One may be inoperative provided: a) Both engines are operated in alternate (ALTN) mode, and b) Appropriate procedures, AFM limitations and performance decrements are applied.
-21-01-03	EEC NORM Mode (CF6 FADEC)	C	2	0	(O) May be inoperative provided both engines are operated in alternate (ALTN) mode.
-21-01-04	EEC C1 Faults (PW4000)	A	-	-	May be dispatched with C1 faults provided repairs are made in accordance with times established by PW engine Type Certificate Data Sheet number E24NE, note 19.
-21-01-05	EEC C1 Faults (CF6 FADEC)	A	2	0	May be dispatched with C1 faults provided repairs are made in accordance with times established by CF6-80C2 Engine Manual GEK 92451, Task 05-51-73-200-801.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	73-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
73 ENGINE FUEL AND CONTROL						
-21-01	Electronic Engine Control (EEC) Systems (Cont'd)					
-21-01-06	EEC C1 Faults (RB211)	A	2	0	May be dispatched with C1 faults provided repairs are made in accordance with times established by RR engine Type Certificate Data Sheet number E30NE, note 17.	
-21-02	Electronic Engine Control (EEC) INOP/NORM/ALTN Lights					
-21-02-01	EEC INOP (JT9D/CF6 PMC)					
-21-02-01A		C	2	0	(O) Except for ER operations, may be inoperative provided both EECs are OFF.	
-21-02-01B		A	2	0	(O) May be inoperative provided: a) Both EECs are OFF, and b) Repairs are made within 3 flight days.	
-21-02-02	EEC NORM/ALTN Lights (PW4000/RB211)	C	2	0	(O) May be inoperative provided: a) Both EECs are operated in alternate (ALTN) mode, and b) Appropriate procedures, AFM limitations and performance decrements are applied.	
(Continued)						

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	73-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
73 ENGINE FUEL AND CONTROL						
-21-02	Electronic Engine Control (EEC) INOP/NORM/ALTN Lights (Cont'd)					
-21-02-03	EEC NORM/ALTN Lights (CF6 FADEC)					
-21-02-03-01	-200/-300	C	2	0	(O) May be inoperative provided both EECs are operated in alternate (ALTN) mode.	
-21-02-03-02	-400ER	C	2	0		
-21-03	Fuel Control ENG VALVE Indication System					
-21-03-01	Fuel Control ENG VALVE Lights (-200/-300)	C	2	0	(M) May be inoperative provided associated engine fuel valve is verified to operate normally.	
-21-03-02	Fuel Control ENG FUEL VAL Indication System (CF6 FADEC/PW4000)	C	2	1	(M)(O) One may be inoperative provided: a) Associated engine fuel valve is verified to operate normally, and b) Associated EICAS message is deactivated.	
-21-06	Turbine Overspeed Systems (RB211)	C	2	0		
-21-07	Hydromechanical N2 Speed Governors (CF6 FADEC)	C	2	1		

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

73-5

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
73 ENGINE FUEL AND CONTROL						
-21-08	Approach Idle/Minimum Idle Systems					
-21-08-01	Minimum Ground Idle (RB211/JT9D/CF6 PMC)	C	2	0	(O) May be inoperative provided: a) Flight idle operates normally, and b) Appropriate performance adjustments are applied.	
-21-08-02	Minimum Ground Idle (PW4000/CF6 FADEC)	C	2	0	(M)(O) May be inoperative provided: a) Flap actuated approach idle is verified to operate normally, and b) Appropriate performance adjustments are applied.	
-21-08-03	Continuous Ignition Actuated Approach Idle (PW4000/CF6 FADEC)	C	2	0	(M)(O) May be inoperative provided flap actuated approach idle is verified to operate normally.	
21-09	Engine Supplemental Control Units (PW4000)	C	-	0	(M) May be inoperative provided affected unit(s) is deactivated.	

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	73-6

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
73 ENGINE FUEL AND CONTROL					
-31-01	Fuel Flow Indications				
-31-01-01	JT9D	C	2	1	(M) One may be inoperative provided: a) Associated N1, N2, and EPR indications operate normally, b) Main tank fuel quantity indicators operate normally, c) On airplanes with Simmonds FQIS PN S345N001-032, right and left main tank densitometers are disconnected for ER operations, and d) Autothrottle is not used.
-31-01-02	CF6	C	2	1	(M) One may be inoperative provided: a) Associated N1 and N2 indications operate normally, b) Main tank fuel quantity indicators operate normally, and c) On airplanes with Simmonds FQIS PN S345N001-032, right and left main tank densitometers are disconnected for ER operations.
-31-01-03	PW4000	C	2	1	(M) One may be inoperative provided: a) Associated N1, N2, and EPR indications operate normally, b) Main tank fuel quantity indicators operate normally, and c) On airplanes with Simmonds FQIS PN S345N001-032, right and left main tank densitometers are disconnected for ER operations.
(Continued)					

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 73-7
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
73 ENGINE FUEL AND CONTROL						
-31-01 Fuel Flow Indications (Cont'd)						
-31-01-04 RB211		C	2	1		(M) One may be inoperative provided: a) Associated N1, N2, N3 and EPR indications operate normally, b) Main tank fuel quantity indicators operate normally, and c) On airplanes with Simmonds FQIS PN S345N001-032, right and left main tank densitometers are disconnected for ER operations.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

74-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
74 IGNITION						
-00-01 Ignition Systems						
-00-01A	A	4	3		(O) One may be inoperative provided: a) Ignition selector remains in BOTH position, b) Engine anti-ice system operates normally on associated engine, and c) Repair is made within 1 flight day.	
-00-01B	C	4	2		(O) Except for ER operations, one per engine may be inoperative provided: a) Ignition selector remains in BOTH position, and b) Engine anti-ice systems operate normally on associated engine(s).	
-00-02 Auto Ignition (RB211)	C	2	0		(O) May be inoperative provided start selector switch(es) AUTO position is placarded INOP, and that position is not used.	

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

75-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
75 BLEED AIR					
-21-01	IDG Air/Oil Cooler Valves				
-21-01-01	JT9D/CF6-80A/A2	C	2	0	(M) May be inoperative open.
-21-01-02	CF6-80C2	C	2	0	(M)(O) May be inoperative provided: a) Valve(s) is deactivated open, and b) Appropriate performance adjustments are applied.
-21-01-03	PW4000				
-21-01-03A		C	2	0	(M)(O) May be inoperative provided: a) If engine AOC operates normally and IDG is connected, fuel tank temperature remains above -42 degrees C throughout flight, b) Valve(s) is deactivated open, and c) Appropriate performance adjustments are applied.
-21-01-03B		C	2	0	(M)(O) May be inoperative provided: a) If engine AOC operates normally and IDG is disconnected, fuel tank temperature remains above -36 degrees C throughout flight, b) Valve(s) is deactivated open, and c) Appropriate performance adjustments are applied.
(Continued)					

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

75-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
75 BLEED AIR						
-21-01	IDG Air/Oil Cooler Valves (Cont'd)					
-21-01-03	PW4000 (Cont'd)					
-21-01-03C		C	2	0	(M)(O) May be inoperative provided: a) If engine AOC is inoperative open and IDG is connected, fuel tank temperature remains above -34 degrees C throughout flight, b) Valve(s) is deactivated open, and c) Appropriate performance adjustments are applied.	
-21-01-03D		C	2	0	(M)(O) May be inoperative provided: a) If engine AOC is inoperative open and IDG is disconnected, fuel tank temperature remains above -30 degrees C throughout flight, b) Valve(s) is deactivated open, and c) Appropriate performance adjustments are applied.	
-21-01-04	RB211	C	2	0	(M) May be inoperative deactivated open.	
-21-02	Engine Air /Oil Cooler Valves (PW4000)					
-21-02A		C	2	0	(M)(O) May be inoperative provided: a) If IDG is connected, fuel tank temperature remains above -34 degrees C throughout flight, b) Valve(s) is deactivated open, and c) Appropriate performance adjustments are applied.	
(Continued)						

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	75-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3.	NUMBER REQUIRED FOR DISPATCH	
75 BLEED AIR					
-21-02	Engine Air /Oil Cooler Valves (PW4000) (Cont'd)				
-21-02B		C	2	0	(M)(O) May be inoperative provided: a) If IDG is disconnected, fuel tank temperature remains above -30 degrees C throughout flight, b) Valve(s) is deactivated open, and c) Appropriate performance adjustments are applied.
-23-01	Nacelle Zone Ventilation Valves (PW) and Core Compartment Cooling Valves (GE)				
-23-01-01	JT9D/CF6-80C2	C	2	0	(M) May be inoperative provided affected valve remains open.
-23-01-02	PW4000	C	2	0	(M)(O) May be inoperative provided: a) Affected valve remains open, and b) Appropriate performance adjustments are applied.
-24-01	Turbine Case Cooling Systems (JT9D/CF6-80A/A2/PW4000/CF6 FADEC)	C	2	0	(M)(O) May be inoperative provided: a) Associated turbine case cooling valve remains closed, and b) Appropriate performance adjustments are applied.

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 75-4
---------------------------	-------------------------------------	---------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
75 BLEED AIR						
-24-02 ***	Turbine Cooling Air Systems					
-24-02-01	Turbine Vane and Blade Cooling (TVBC) Systems (PW4000)	C	2	0		(M) May be inoperative provided associated turbine cooling valves are deactivated open.
-24-02-02	Eleventh Stage Cooling Valve (ESCV) Systems (CF6 FADEC)	C	2	0		(M) May be inoperative provided associated turbine cooling valves are deactivated open.

AIRCRAFT: BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

77-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
77 ENGINE INDICATING					
-00-01	Target Parameter Indications	C	-	0	(O) May be inoperative provided an alternate means of achieving desired values is available and used.
-11-01	Engine Pressure Ratio (EPR) Systems				
-11-01-01	JT9D	C	2	1	(O) EICAS and/or STANDBY indications for one engine may be inoperative provided: <ul style="list-style-type: none"> a) Appropriate procedures, AFM limitations, and performance decrements are applied, b) N1 and N2 EICAS indications for associated engine operate normally, c) N1 STANDBY indications for associated engine operate normally, d) Fuel flow systems for associated engine operate normally, and e) Approach minimums do not require its use.
-11-01-02	PW4000	C	2	1	(O) EICAS and/or STANDBY indications for one engine may be inoperative provided: <ul style="list-style-type: none"> a) Both EECs are switched to ALTN mode, b) Appropriate procedures, AFM limitations, and performance decrements are applied, c) N2 EICAS indications for both engines operate normally, d) Fuel flow indications for associated engine operate normally, and e) Approach minimums do not require its use.
(Continued)					

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

77-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
77 ENGINE INDICATING					
-11-01	Engine Pressure Ratio (EPR) Systems (Cont'd)				
-11-01-03	RB211	C	2	1	(O) EICAS and/or STANDBY indications for one engine may be inoperative provided: a) Both EECs are switched to ALTN mode, b) Appropriate procedures, AFM limitations, and performance decrements are applied, c) N2 EICAS indications for both engines operate normally, d) N3 EICAS indications for both engines operate normally, e) Fuel flow indications for associated engine operate normally, and f) Approach minimums do not require its use.
-12-01	N1 Tachometer Systems (JT9D)	B	2	1	(O) EICAS and/or STANDBY indications for one engine may be inoperative provided: a) EPR (EICAS and STANDBY) indications for both engines operate normally, b) N2 EICAS indications for associated engine operate normally, and c) Fuel flow indications for associated engine operate normally.
-12-02	N2 Tachometer Systems (EICAS) (-200/-300)	B	2	1	(O) One N2 indication may be inoperative provided only indication function is inoperative.
-12-04	N3 Tachometer Systems (EICAS) (RB211)	B	2	1	(O) One N3 indication may be inoperative provided only indication function is inoperative.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

77-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
77 ENGINE INDICATING					
-21-01	EGT Indications (Standby Engine Indicator) (-200/-300)				
-21-01-01	JT9D	C	2	1	One may be inoperative provided: a) EGT EICAS indication operates normally, b) N1 EICAS and Standby indications for both engines operate normally, c) N2 EICAS indications for both engines operate normally, and d) EPR EICAS indications for both engines operate normally.
-21-01-02	CF6	C	2	1	One may be inoperative provided: a) EGT EICAS indication operates normally, and b) N2 EICAS indications for both engines operate normally.
-21-01-03	PW4000	C	2	1	One may be inoperative provided: a) EGT EICAS indication operates normally, b) N2 EICAS indications for both engines operate normally, and c) EPR EICAS indications for both engines operate normally.
-21-01-04	RB211	C	2	1	One may be inoperative provided: a) EGT EICAS indication operates normally, b) N2 EICAS indications for both engines operate normally, c) N3 EICAS indications for both engines operate normally, and d) EPR EICAS indications for both engines operate normally.

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	77-4

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
77 ENGINE INDICATING					
-22-01	Engine Turbine Overheat Detection Systems (RB211)				
-22-01-01	Loops	C	4	2	One Loop per engine may be inoperative.
-31-01	Vibration Indicating Systems	C	2	1	
-31-01-01	Compressor Rear Frame (CRF) Accelerometers (CF6 FADEC)	C	2	0	(M) May be inoperative deactivated.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT: BOEING B-767	REVISION NO: 37 DATE: 03/27/2015	PAGE: 78-1
-------------------------------	---	-------------------

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		3. NUMBER REQUIRED FOR DISPATCH	4. REMARKS OR EXCEPTIONS
78 ENGINE EXHAUST						
-31-01	Thrust Reversers	C	2	1	(M)(O) One may be inoperative provided: a) Inoperative reverser is secured in forward thrust position, and b) Appropriate performance adjustments are applied.	
						NOTE: During landing roll-out, differential braking may be required to maintain directional control.
-34-01	REV ISLN Valve Light (-200/-300)	C	1	0	(M)(O) May be inoperative provided reverser isolation valve and reverser unlock indications are verified to operate normally.	
-34-02	Engine Reverse Lever Interlocks (RB211/PW4000/CF6 FADEC)	C	2	1	(O) One may be inoperative extended or retracted provided appropriate performance adjustments are applied.	
						NOTE: Associated reverser thrust is limited to reverse idle when inoperative retracted.
-34-03	Thrust Reverser Air System (RB211/CF6-80C2)					
-34-03-01	Thrust Reverser PRSOV (CF6-80C2)	C	2	1	(M)(O) One may be inoperative provided associated thrust reverser is considered inoperative.	
-34-03-02	Thrust Reverser Air Motor Shutoff Valves (RB211)	C	2	1	(M)(O) One may be inoperative provided associated thrust reverser is considered inoperative.	
-36-01	REV Unlock Indications	C	2	1	(M)(O) One may be inoperative provided: a) No thrust reverser damage exists that would adversely affect airplane operation, b) Associated thrust reverser is considered inoperative.	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE: 78-2
	DATE: 03/27/2015	

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
78 ENGINE EXHAUST						
-36-02	Full REV Position Indications	C	2	0		May be inoperative provided associated reverser unlock indication operates normally.
-36-03	Reverser Position Sensing Systems (RB211/PW4000/CF6 FADEC)	C	2	1		(M)(O) One may be inoperative provided associated thrust reverser is considered inoperative.

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

79-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			2.	3. NUMBER REQUIRED FOR DISPATCH	
79	ENGINE OIL				
-31-01	OIL QTY Indications				
-31-01-01	-200/-300	B	2	1	(M) One may be inoperative provided: a) Oil tank is filled to recommended capacity before each departure, b) There is no evidence of above normal oil consumption or leakage, c) Associated ENG OIL PRESS and OIL TEMP indications operate normally, and d) Associated low ENG OIL PRESS light operates normally.
-31-01-02	-400ER	B	2	1	(M) One may be inoperative provided: a) Oil tank is filled to recommended capacity before each departure, b) There is no evidence of above normal oil consumption or leakage, and c) Associated ENG OIL PRESS and OIL TEMP indications operate normally.
-32-01	L/R Oil Press Sensor Select Module (OPSSM) (RB211)	C	1	0	(O) May be inoperative.
-33-01	Low ENG OIL PRESS Indication System (-200/-300)				
-33-01-01	All except JT9D without SB767-78-8 Installed, and CF6-80A/A2 without SB767-78-8 Installed	C	2	1	May be inoperative provided associated OIL PRESS, TEMP and QTY indications operate normally.
					(Continued)

U.S. DEPARTMENT OF TRANSPORTATION

MASTER MINIMUM EQUIPMENT LIST

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:	BOEING B-767	REVISION NO: 37	PAGE:
		DATE: 03/27/2015	79-2

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS	
						3. NUMBER REQUIRED FOR DISPATCH
79	ENGINE OIL					
-33-01	Low ENG OIL PRESS Indication System (-200/-300) (Cont'd)					
-33-01-02	JT9D without SB767-78-8 Installed, CF6-80A/A2 without SB767-78-8 Installed	C	2	1	(M) May be inoperative provided: a) Associated OIL PRESS, TEMP and QTY indications operate normally, and b) Thrust reverser is verified to operate normally.	
-34-01	Engine Bearing No. 3 Scavenge Oil Temperature Indications (PW4000)					
-34-01-01	L/R SCAV TEMP1	A	2	1	(M) May be dispatched with one message displayed provided repairs are made within 3 flight days.	
-34-01-02	L/R SCAV TEMP2	A	2	1	(M) May be dispatched with one message displayed provided repairs are made within 10 flight days.	
-34-02	ENG OIL TEMP Sensing Elements (JT9D/CF6-80A/A2/CF6-80C2 PMC)	C	-	2	(O) One sensing element on each engine may be inoperative provided both engine oil temperature indications are available from one EICAS computer.	
-35-01	Engine Oil Filter Bypass Warning Systems (PW/GE)	B	2	0	(M) May be inoperative provided: a) It is verified that malfunction is in alerting system, and b) Main oil screen is checked for contaminants before each departure.	

AIRCRAFT: BOEING B-767	REVISION NO: 37	PAGE:
	DATE: 03/27/2015	79-3

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED			4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH			
79 ENGINE OIL						
-35-02	Engine High Pressure Oil Filter Warning Indication (Approaching Blockage) (RB211)	C	2	1		(M) One may be inoperative provided: a) It is verified that malfunction is in alerting system, b) Pressure filter is replaced, and c) Magnetic Chip Detector is checked for contaminants before each departure.
-35-03	Engine Fine Scavenge Oil Filter Warning Indications (Impending Bypass) (RB211)	C	2	1		(M) One may be inoperative provided: a) It is verified that malfunction is in alerting system, b) Fine scavenge oil filter is replaced, and c) Magnetic chip detector is checked for contaminants before each departure.

AIRCRAFT:

BOEING B-767

REVISION NO: 37

PAGE:

DATE: 03/27/2015

80-1

SYSTEM & SEQUENCE NUMBERS	ITEM	1.	2. NUMBER INSTALLED		4. REMARKS OR EXCEPTIONS
			3. NUMBER REQUIRED FOR DISPATCH		
80 STARTING					
-00-01	Engine Start VALVE Lights				
-00-01-01					
-200/-300		C	2	1	(O) One may be inoperative provided associated valve is verified closed after engine start.
-00-01-02					
-400ER		C	2	0	
-00-02	Engine Start Valves				
-00-02-01					
-200/-300		C	2	1	(M)(O) One may be inoperative provided: a) Associated start VALVE light operates normally, and b) Manual override start procedures are used.
-00-02-02					
-400ER		C	2	1	(M)(O) One may be inoperative provided manual override start procedures are used.
-11-02	Starter Switch Holding/Cutout Systems				
		C	2	0	(O) May be inoperative provided alternate procedures are established and used.