



U.S. Department
of Transportation

**Federal Aviation
Administration**

October 07, 2020

B/E Aerospace

Dear B/E Aerospace:

The Aircraft Evaluation Group (AEG) has reviewed your request for Supplemental Type Certificate (STC) relief that may be included in an operator's FAA approved MEL. The AEG finds your relief submission allowable as documented in the relief section of this letter. This relief is valid when an operator installs the listed STC on an aircraft that is listed in the Aircraft Model List (AML) below. No other application of this relief is allowed. The STC holder must contact the AEG when the STC is amended, revised or revoked.

Operators may use this relief letter to incorporate the relief listed below into their Minimum Equipment List (MEL) upon publication of this letter and in accordance with the MEL approval process in FAA Order 8900.1. The relief granted remains valid indefinitely with possession of this letter unless the relief is specifically revoked or revised by the Administrator.

STC Applicant	B/E Aerospace
STC Number	ST02929AT
STC Description	Installation of an Artex Model C406- 1 Emergency Locator Transmitter (EL T) in accordance with EMTEQ Master Drawing List(s) (MDL) as contained in EMTEQ Approved Model List (AML), Document No. 2- 22566-002, Revision IR, Dated September 29, 2004, or later FAA approved revision.
Aircraft Model List	B757-200

Sincerely,

Dale Bosselmann
FOEB Chair,
Aircraft Evaluation Group

Approved STC Relief

System	Item	Category	Installed	Required	Remarks-Exceptions
25	Fixed ELTs	A	-	0	(M) May be inoperative provided: a) System is deactivated, and b) Repairs are made within 90 consecutive calendar-days.
25	Fixed ELTs	A	-	0	May be missing provided: a) Placard stating "ELT not installed" is placed in view of the pilot, and b) Repairs are made within 90 consecutive calendar-days.
25	Fixed ELTs	D	-	-	(M) Any in excess of those required by 14 CFR may be inoperative provided system is deactivated.
25	Fixed ELTs	D	-	-	Any in excess of those required by 14 CFR may be missing.